

RNP AR BRIEFING CARD B737

PRE-APPROACH PREPARATION

Airplane equipment required to begin the approach:

- **EGPWS**
- 2 **FMCs**
- 2 **CDUs**
- 2 **GPS** Receivers
- 2 **Radio Altimeters**
- 2 **ADIRUs, IRSs** in **NAV** mode
- 2 **EFIS/MAP** or **PFD/ND** displays (as installed)
- 1 **A/P** and 2 F/Ds capable of LNAV and VNAV (for RNP 0.15 or greater)
- 2 **A/P** and 2 F/Ds capable of LNAV and VNAV (for RNP less than 0.15)

Limitations & Requirements

- Both pilots have received the required RNP AR training.
- All required equipment must be serviceable.
- Display Source 1 or 2 not displayed on either PFD.
- Approach must be selected from the database.
- RNP AR approaches must be flown with autopilot engaged while operating in IMC conditions & until suitable visual reference is established.
- Use the highest lateral RNP & minimums appropriate for the weather.
- Deviations for weather prohibited after the FAF or on an RF leg.
- Direct to intercepts to an RF leg are prohibited.
- VNAV PTH must be used for all segments with coded G/P.
- LNAV must be selected prior to the FAF.
- Procedure is not authorized using QFE.

RNP AR – MAX IAS (KTS) for each segment of the approach as determined by aircraft category and applicable regulatory airspeed requirements.

RNP AR – MAX IAS (KTS)		
App Segment	CAT C	CAT D
IAF to FAF	250	250
FAF to DA	140	165
Missed App (DA to MAHF)	240	265
Charted Airspace Restriction	As specified	

RNP AR BRIEFING CARD B737

Procedure Memory Aid

- set current local altimeter (**remote altimeter settings not allowed**)
- verify that the approach RNP is equal to or greater than:
 - 9J-ZAD, ET-APK - ET-AQQ, ET-ASJ, ET-AWC - ET-AWS, ET-BAG - P2-PXA
0.10 (A/P or F/D)
 - ET-ALK - ET-ALN, ET-ARB, ET-AVX, ET-AYL, ET-AYP **0.11** (A/P)
- Set lateral RNP Value on **RNP PROGRESS 4/5**. (Note: It may be required to update RNP value during a missed approach.
- Set vertical RNP to **125ft** on RNP PROGRESS 4/5.
- verify that the wind is within limits published for the approach (if applicable)
- verify that the reported airport temperature is within published limits for the approach
- Select or Verify NAV OPTIONS
 - **VOR UPDATE OFF**
 - **DME UPDATE** (per NOTAM)
 - **GPS UPDATE ON**
- Confirm FMC approach track is within 3^0 , distance between waypoints is within 0.1 NM & vertical GP is within -0.01^0 to $+0.1^0$ of charted values.
- PF to select TERR & map display range to 10 NM, or less, prior to the FAF.
- PF to select FMC CDU to **ACT RTE LEGS.**

Mandatory Go-Around

- Do the Go-Around & Missed Approach Procedure for any of the following items unless suitable visual reference is established & maintained:
 - **UNABLE REQD NAV PERF-RNP**
 - **FMC DISAGREE**
 - Any **VERIFY POSITION** alerting message.
 - **Lateral tracking exceeds more than 1 x RNP.**
 - Past the FAF **vertical deviation exceeds 75 feet.**
 - Altimeter crosscheck at FAF **exceeds 100 feet.**

Note: Please refer to the latest FCOM supplementary procedure and Bulletins for detailed information on specific aircraft limitations.

Note: SB Changes ET-AVI - ET-AVM, ET-BAQ, ET-BAR Warning for FMC Software U14 and above.