

## The ARM Instruction Set



## **Processor Modes**

- \* The ARM has six operating modes:
  - *User* (unprivileged mode under which most tasks run)
  - FIQ (entered when a high priority (fast) interrupt is raised)
  - IRQ (entered when a low priority (normal) interrupt is raised)
  - *Supervisor* (entered on reset and when a Software Interrupt instruction is executed)
  - *Abort* (used to handle memory access violations)
  - *Undef* (used to handle undefined instructions)
- \* ARM Architecture Version 4 adds a seventh mode:
  - System (privileged mode using the same registers as user mode)



# The Registers

- \* ARM has 37 registers in total, all of which are 32-bits long.
  - 1 dedicated program counter
  - 1 dedicated current program status register
  - 5 dedicated saved program status registers
  - 30 general purpose registers
- \* However these are arranged into several banks, with the accessible bank being governed by the processor mode. Each mode can access
  - a particular set of r0-r12 registers
  - a particular r13 (the stack pointer) and r14 (link register)
  - r15 (the program counter)
  - cpsr (the current program status register)

### and privileged modes can also access

• a particular spsr (saved program status register)



# **Register Organisation**

#### **General registers and Program Counter**

User32 / System	FIQ32	Supervisor32	Abort32	IRQ32	Undefined32
r0	r0	r0	r0	r0	r0
r1	r1	r1	r1	r1	r1
r2	r2	r2	r2	r2	r2
r3	r3	r3	r3	r3	r3
r4	r4	r4	r4	r4	r4
r5	r5	r5	r5	r5	r5
r6	r6	r6	r6	r6	r6
r7	r7	r7	r7	r7	r7
r8	r8_fiq	r8	r8	r8	r8
r9	r9_fiq	r9	r9	r9	r9
r10	r10_fiq	r10	r10	r10	r10
r11	r11_fiq	r11	r11	r11	r11
r12	r12_fiq	r12	r12	r12	r12
r13 (sp)	r13_fiq	r13_svc	r13_abt	r13_irq	r13_undef
r14 (lr)	r14_fiq	r14_svc	r14_abt	r14_irq	r14_undef
r15 (pc)	r15 (pc)	r15 (pc)	r15 (pc)	r15 (pc)	r15 (pc)

### **Program Status Registers**

cpsr

cpsr spsr\_fiq cpsr spsr\_svc cpsr spsr\_abt

cpsr spsr\_irq cpsr spsr\_undef