
RESP
send 3–4 B
'P','S'
IDLE
'C'
C_ARM
record 2^14
last
'T'
'D'
full
T header
bank, n
D header
bank, gain, n
C_RD..C_HI
send samples
3 B
4 B
CLRW
clear chain
T
D
T_RUN
n samples
D_RUN
n PDM bytes
n sent
all in
FINISH
restart live
idle
D_DRAIN
wait
IDLE
live again