

Ahsanullah University of Science & Technology Department of Computer Science & Engineering

Course No : CSE3108

Course Title : Microprocessors Sessional

Assignment No : 07

Date of Submission : 28-08-2021

Submitted To : Ms. Qamrun Nahar Eity & Ms. Tahsin Aziz

Submitted By-

Group : B₂

Name: S. M. Tasnimul Hasan

Id: 180204142

Section : B

Question: Draw the given shape in the dot matrix display and show the initials of the shape in the seven segment display and glow the four LEDs according to the initials.

Forz "Plus Sign" P > Glow Red 2

S > Glow Red 1

Scanned with CamScanner

Answerz:

DSEG SEGMENT DATA'

DSEG ENDS

SSEG SEGMENT STACK 'STACK'

DW 100h DUP (?)

SSEG ENDS

CSEG SEGMENT 'CODE'

START PROC FAR

PUSH DS

MOV AX, O

PUSH AX

MOV AX, DSEG

MOV DS, AX

MOV ES, AX

MOV BX, 0

MAINLOOP :

MOV DX, 2003H

MOV AL, 0000 0001 b

OUT DX, AL

MOV CX, 100H

L1: LOOP L1

MOV DX, 2003 H

MOV AL, 0000 00116

JA , XA TUO

MOV CX, 100H

L2: LOOP L2

MOV PX, 2030H

; 1st seven segment Display

MOV AL, 0010 0000b

OUT DX, AL

MOV DX, 2003 H

MOV AL, 0000 01116

MOV CX, 100 H

L3: LOOP L3

MOV DX, 2002H

MOV AL, 0000 01006

OUT DX, AL

MOV CX, 100H

L4: LOOP L4

MOV DX, 2030H

MOV AL, 0011 0000b

OUT DX, AL

MOV DX, 2001 H

MOV AL, 0000 01006

OUT DX, AL

MOV CX, 100H

L5 : LOOP L5

MOV DX, 2001 H

MOV AL, 0000 11006

Scanned with CamScanner

MOV CX, 100H

L6: L00P L6

MOV DX, 2030 H

MOV AL, 0011 00016

OUT DX, AL

MOV DX, 2001 H

MOV AL, 00011100b

OUT DX, AL

MOV CX, 100H

L7: LOOP L7

MOV DX, 2002H

MOV AL, 0001 0100b

OUT DX, AL

MOV CX, 100H

T8: TOOD T8

MOV DX, 2030H

MOV AL, 001100116

Scanned with CamScanner

MOV DX, 2003H

MOV NL, 0001 01116

JA X4 TUO

MOV CX, 100H

L9: LOOP L9

MOV DX, 2003 H

MOV AL, 0011 01116

OUT DX, AL

MOV CX, 100H

L10: LOOP L10

MOV DX, 2030 h

MOV AL, 0111 00116

OUT DX, AL

MOV DX, 2070H

; R2

Scanned with CamScanner

MOV AL, 0000 1000b

OUT PX, AL

MOV DX, 2003H

MOV AL, 0111 01116

OUT DX, AL

MOV CX, 100 H

L11: LOOP L11

MOV DX, 2004H

MOV AL, 0100 0000b

OUT DX, AL

MOV CX, 100H

L12: LOOP L12

MOV DX, 2070H

; R2 & R1

MOV AL, 0000 10016

OUT DX, AL

MOV PX, 2031h

; 2nd Seven Segment Display

Scanned with CamScanner

MOV AL, 0000 00016

OUT DX, AL

MOV PX, 2005h

MOV AL, 0100 00006

MOV CX, 100H

L13: LOOP L13

MOV DX, 2005H

MOV AL, 0110 00006

OUT DX, AL

MOV CX, 100H

L14: LOOP L14

MOV DX, 2031H

MOV AL, 001000016

OUT DX, AL

MOV DX, 2005H

MOV AL, 0111 0000b

OUT DX, AL

MOV CX, 100H

L15: LOOP L15

MOV DX, 2006H

MOV AL, 0001 0000b

Scanned with CamScanner

MOV CX, 100H

L16: LOOP L16

MOV DX, 2031h

MOV AL, 0110 00016

OUT DX, AL

MOV DX, 2007H

MOV AL, 0001 0000b

OUT DX, AL

MOV CX, 100H

L17: LOOP L17

MOV DX, 2007H

MOV AL, 000110006

OUT DX, AL

MOV CX, 100H

L18: LOOP L18

MOV DX, 2031h

MOV AL, 011001016

Scanned with CamScanner

MOV DX, 2007 H

MOV AL, 000111006

OUT DX, AL

MOV CX, 100H

L19: LOOP L19

MOV DX, 2006H

MOV AL, 0001 01006

OUT DX, AL

MOV CX, 100H

L20: LOOP L20

MOV DX, 2031H

MOV AL, 0110116

OUT DX, AL

MOV DX, 2005H

MOV AL, 011101006

OUT DX, AL

MOV CX, 100H

L21: LOOP L21

Scanned with CamScanner

MOV DX, 2005H

MOV AL, 01110110b

OUT DX, AL

MOV CX, 100H

L22: LOOP L22

MOV DX, 2005 H

MOV AL, 011101116

OUT DX, AL

MOV CX, 100H

L23: LOOP L23

MOV DX, 2004H

MOV AL, 010000016

OUT DX, AL

MOV CX, 100H

L24: LOOP L24

MOV DX, 2001H

MOV AL, 0000 0000b

Scanned with CamScanner

MOV DX, 2002H

MOV AL, 0000 0000 b

OUT DX, AL

MOV DX, 2003H

MOV AL, 0000 0000b

OUT DX, AL

MOV DX, 2004H

MOV AL, 0000 00006

OUT DX, AL

MOV DX, 2005 H

MOV AL, 0000 0000b

OUT DX, AL

MOV DX, 2006H

MOV AL, 0000 00006

OUT DX, AL

MOV DX, 2007H

MOV AL, 0000 00006

Scanned with CamScanner

MOV DX, 2030H

MOV AL, 0000 00006

OUT DX, AL

MOV DX, 2031 H

MOV AL, 0000 0000b

OUT DX, AL

MOV DX, 2070H

MOV AL, 0000 00006

OUT DX, AL

ADD BX, 1

CMP BX, 5

JL MAINLOOP

RET

START ENDP

CSEG ENDS

END START

Scanned with CamScanner