

Ahsanullah University of Science & Technology Department of Computer Science & Engineering

Course No : CSE3108

Course Title : Microprocessors Sessional

Assignment No : 08

Date of Submission : 12-09-2021

Submitted To : Ms. Qamrun Nahar Eity & Ms. Tahsin Aziz

Submitted By-

Group $: B_2$

Name: S. M. Tasnimul Hasan

Id: 180204142

Section : B

Question: Show the letters and digits of the PDF in the Dot Matrix Display and Seven segment Display and glow the LEDs.

1 S 4 T 2
R1 R1 G R2 R2

Scanned with CamScanne

Answerz:

SSEG SEGMENT STACK STACK'

100h DUP(?)

SSEG ENDS

CSEGMENT 'CODE'

START PROC FAR

PUSH DS

MOV AX, O

PUSH AX

MOV AX, DSEG

MOV DS AX

MOV ES, AX

; 1

MOV DX, 2000H

MOV AL, 0000 0100b

OUT DX, AL

MOV DX, 2001 H

MOV AL, 0000 00106

OUT DX, AL

MOV DX, 2002H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2002H

MOV AL, 0000 00-116

OUT DX, AL

MOV DX, 2030H

; 1st Seven Segment Display

MOV AL, 0000 00106

OUT DX, AL

MOV DX, 2070H

; 1st LED Display (R1)

Scanned with CamScanner

MOV AL, O1h

MOV DX, 2002H

MOV AL, 0000 01116

OUT DX, AL

MOV PX, 2002H

MOV AL, 0000 11116

OUT DX, AL

MOV DX, 2002H

MOV AL, 0001 1111b

OUT DX, AL

MOV DX, 2002H

MOV AL, 0011 11116

OUT DX, AL

MOV DX, 20.30H

MOV AL, 0000 0110 6

OUT DX, AL

MOV DX, 2000H

MOV AL, 0100 01006

Scanned with CamScanner

MOV DX, 2001 H

MOV AL, 0100 00106

OUT DX, AL

MOV DX, 2002H

MOV AL, 0111 11116

OUT DX, AL

MOV DX, 2003H

MOV AL, 0100 00006

OUT DX, AL

MOV DX, 2004H

MOV AL, 0100 0000b

OUT DX, AL

; 5

MOV DX, 2009H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2008H

MOV AL, 0000 00016

Scanned with CamScanne

MOV DX, 2007H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2031H

MOV AL, 0000 00016

OUT DX, AL

MOV. DX, 2006H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2005H

MOV AL, 0000 00106

OUT DX, AL

MOV DX, 2031 H

MOV AL, 0010 00016

OUT DX, AL

MOV DX, 2005 H

MOV AL, 0000 01106

Scanned with CamScanner

MOV DX, 2006H

MOV AL, 0000_10016

OUT DX, AL

MOV DX, 2031 H

MOV AL, 0110 00016

OUT DX, AL

MOV DX, 2070H

MOV AL, OIL

OUT DX, AL

MOV DX, 2007 H

MOV AL, 0000 10016

OUT DX, AL

MOV DX, 2008H

MOV AL, 0000 10016

OUT DX, AL

MOV DX, 2031H

MOV AL, 011001016

Scanned with CamScanner

MOV DX, 2009H

MOV AL, 0001 00016

OUT DX, AL

MOV DX, 2009H

MOV AL, 0011 00016

OUT DX, AL

MOV DX, 2008H

MOV AL, 0100 10016

OUT DX, AL

MOV DX, 2031H

MOV AL, 011011016

OUT DX, AL

MOV DX, 2007H

MOV AL, 0100 10016

OUT DX, AL

MOV DX, 2006H

MOV AL, 010010016

MOV DX, 2005H

MOV AL, 0100 0110b

OUT DX, AL

; 4

MOV DX, 200DH

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 200CH

MOV AL, 0000 00106

OUT DX, AL

MOV DX, 200BH

MOV AL, 0000 0100b

OUT DX, AL

MOV DX, 2032H

MOV AL, 00100006

OUT DX, AL

MOV DX, 200AH

MOV AL, 0000 10006

MOV DX, 200BH

MOV AL, 0000 11006

OUT DX, AL

MOV DX, 200CH

MOV AL, 0000 1010b

OUT DX, AL

MOV DX, 2032H

MOV AL, 0110 0000b

OUT DX, AL

MOV DX, 200D H

MOV AL, 0000 10016

OUT DX, AL

MOV DX, 200EH

MOV AL, 0000 1000b

OUT DX, AL

MOV DX, 200D H

MOV AL, 0000 10116

Scanned with CamScanner

MOV DX, 2032H

MOV AL, 0110 00106

OUT DX, AL

MOV DX, 2070H

MOV AL, O5h

OUT DX, AL

MOV. DX, 200DH

MOV AL, 0000 11116

OUT DX, AL

MOV DX, 200DH

MOV AL, 0001 11116

OUT DX, AL

MOV DX, 200DH

MOV AL, 0011 11116

OUT DX, AL

MOV DX, 2032H

MOV AL, 0110 0110 b

MOV DX, 200DH

MOV AL, 0111 111 b

OUT DX, AL

; T

MOV DX, 200FH

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2010 H

Mov AL, 0000 00016

OUT DX, AL

MOV DX, 2033H

MOV AL, 0010 0000b

OUT DX, AL

MOV DX, 2011 H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2012H

MOV AL, 0000 0001 b

Scanned with CamScanner

MOV DX, 2033H

MOV AL, 0011 00006

OUT DX, AL

MOV DX, 2013H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2011 H

MOV AL, 0000 00116

OUT DX, AL

MOV DX, 2033 H

MOV AL, 0011 10006

OUT DX, AL

MOV DX, 2070H

MOV AL, ODh

OUT DX, AL

MOV DX, 2011H

MOV AL, 0000 01116

Scanned with CamScanner

MOV DX, 2011 H

MOV AL 0000 11116

OUT DX, AL

MOV DX, 2033H

MOV AL, 0111 10006

OUT DX, AL

MOV DX, 2011H

MOV AL, 0001 11116

OUT DX, AL

MOV DX, 2011 H

MOV AL, 0011 11116

OUT DX, AL

MOV DX, 2011H

MOV AL, 0111 1116

OUT DX, AL

; 2

MOV DX, 2014 H

MOV AL, 0000 00106

MOV DX, 2015 H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2016 H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2034H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2017 H

MOV AL, 0000 00016

OUT DX, AL

MOV DX, 2018 H

MOV AL, 0000 0010b

OUT DX, AL

MOV DX, 2018 H

MOV AL, 0000 01106

OUT DX, AL

MOV DX, 2070 H

MOV AL, ODh

MOV DX, 2034 H

MOV AL, 0000 00116

OUT DX, AL

MOV DX, 2017 H

MOV AL, 0000 10016

OUT DX, AL

MOV DX, 2016 H

MOV AL, 0000 10016

OUT DX, AL

MOV DX, 2015H

MOV AL, 0000 10016

OUT DX, AL

MOV DX, 2034H

MOV AL, 0100 00116

OUT DX, AL

MOV DX, 2014H

MOV AL, 0001 00106

OUT DX, AL

MOV DX, 2014 H

MOV AL, 001100106

Scanned with CamScanne

MOV DX, 2034H

MOV AL, 0101 00116

OUT DX, AL

MOV DX, 2014 H

MOV AL, 0111 00106

OUT DX, AL

MOV DX, 2015 H

MOV AL, 010010016

OUT DX, AL

MOV DX, 2016 H

MOV AL, 0100 10016

OUT DX, AL

MOV DX, 2034H

MOV AL, 0101 10116

OUT DX, AL

MOV bx, 2017 H

MOV AL, 010010016

OUT DX, AL

MOV PX, 2018 H

MOV AL, 0100 01106

MOV SI, 5

PUSH SI

SLIDESHOW:

MOV BX, 0

MAINLOOP:

MOV SI, O

MOV CX, 25

MOV DX, 2018H

ROTATE:

MOV AL, DM [BX][SI]

OUT DX, AL

DEC DX

INC SI

CMP SI, 25

LOOPNE ROTATE

ADD BX, 25

CMP BX, 625

JL MAINLOOP

MOV DX, 2070H

MOV AL, OOH

OUT DX, AL

MOV BX, O

MOV DX, 2030H

SEVENSEGMENT:

MOV AL, OOH

OUT DX, AL

INC DX

ADD BX, 1

CMP BX, 5

JL SEVENSEGMENT

MOV DX, 2070H

MOV AL, ODH

OUT DX, AL

MOV BX, 0

MOV DX, 2030H

SSD_LED_REPEAT:

MOV AL, SSD [BX]

OUT DX, AL

INC DX

ADD BX, 1

CMP BX, 5

JL SSD_LED_REPEAT

POP SI

DEC SI

PUSH SI

CMP SI, 0

JNZ SLIDESHOW

; ALL SEGMENTS CLEAR

MOV AL, OOH

MOV DX, 2070H

OUT DX, AL

MOV CX, 5

MOV DX, 2030H

SSDZERO:

MOV AL, OOH

OUT DX, AL

INC DX

DEC CX

CMP CX, 0

JNZ SSDZERO

MOV CX, 25

MOV DX, 2000H

DMZERO:

MOV AL, OOH

OUT DX, AL

INC DX

DEC CX

cmp cx, 0

JNZ DMZERO

RET

START ENDP

CSEG ENDS

END START