

Acme Electrical

Unit 4, 12 Volt Place, East Tamaki, Auckland 2013
GST No. 113-456-787

TAX INVOICE

Document No.	E-11002	Dated	04.09.26
Balance due by	18.09.26		
Installation address	22 Ash Street, Glen Innes, Auckland 1072		
Ref	Smoke alarms to standard		

Work report

- 1. Removed three ionisation smoke alarms (hallway, bedroom 1, bedroom 2).
- 2. Fitted three 10-year photoelectric alarms within 3 m of each bedroom door, as the tenancy standard requires.
- 3. Tested every alarm with the test button and with smoke spray; all sounded.
- 4. Checked the switchboard: RCD protection present on all lighting and power circuits.
- 5. RCD trip test: 22 ms at rated current, within limits.
- 6. Insulation resistance test, all circuits: above 200 megaohms.
- 7. Earth continuity: main earth 0.12 ohm, bonding to water pipes present.
- 8. Polarity checked at every socket outlet.
- 9. No faults found. Electrical safety certificate ES-55120 issued to the owner.
- 10. Photos of each alarm location are on file under the document number.

Charges follow on the next page.

Description	Qty	Unit	Ext.
Photoelectric smoke alarm, 10-year (supply)	3	48.00	144.00
Install and test alarms (hours)	1.5	72.00	108.00
Electrical safety check, whole house	1	60.00	60.00
		Nett	312.00
		GST	46.80
		Balance due	\$358.80

Pay to 02-0500-0123456-001, reference E-11002.