



A-A (1 : 1)




Passung	Höchstmaß	Mindestmaß
7,5G7	7,520	7,505
Ø20H7	Ø20,021	Ø20,000
Ø26M7	Ø26,000	Ø25,979
Ø32f7	Ø31,975	Ø31,950
Ra	= Ort der Oberflächenprüfung	
Oberflächen nach DIN EN ISO 1302		


Z (2 : 1)



X (2 : 1)



Y (2 : 1)



alle nicht bemassten Radien R2

$\pm 0,05$

DIN ISO 13715

(Ra 1.6) (Ra 0.8)