Standard Operating Procedure

SOP – AZ 102 Environmental Control Alert System Process			
Author:	**Ruben Urias**	(SIGNATURE)	Date:
Revised By:	**Ruben Urias**	(SIGNATURE)	Date: 5/7/2024

Review & Approval

Functional Manager	**Corbin Christian**	(SIGNATURE)	Date:

1.0 Scope:
This procedure applies to all HubStarr Logistics facilities storing clients finished goods and/or raw materials.

2.0 Purpose:
The purpose of this procedure is to establish a documented process to provide roles and responsibilities during environmental device alerts for offline and control limits.

3.0 Responsibility:
HubStarr Logistics management is responsible for ensuring compliance with this procedure.

4.0 References:
None

5.0 Definitions and Abbreviations:
None

6.0 Process:

6.1. It is the responsibility of HubStarr Logistics to monitor and record ambient temperatures per HubStarr Logistics SOP-AZ 101 Environmental Climate Controls

6.2. In the event of an offline alert during normal business hours the facilities person at each site will restart device

6.3. If the device displays online nothing else is needed

6.4. If the device remains off-line the staff member at affected site will call Compliance Manager and confirm that there are no systems password changes

6.5. Onsite staff (facilities/Ops Manager) Offsite Quality will monitor until issue is resolved

6.6. For any downtime **>2 hours** a manual logbook will be used to document Temp and RH% if applicable, this data will be scanned and provided to client with Monthly reporting if applicable

6.7 After Hours

6.7.1. Same process as above except the process will start when staff member is onsite

6.8 In the event of a Temp/RH% e-mail alert:

6.8.1 All HubStarr Logistics warehouses will independently monitor Temp or RH% alerts, understanding that seasonal and local environmental variation will cause fluctuation and instances of Max limit violations.

6.8.2 We will track the system variation and confirm that there are no equipment issues during these periods.

7.0 In the first month of each quarter, we will conduct a validation of the online alert system.

8.0 For future calibration, IT will coordinate a Date/Time when all devices will be taken offline. Once systems are validated IT will confirm. During this time each sensor will be compared to a purchased calibrated Thermometer.

All temperature and humidity data will be maintained for at least three (3) years.

9.0 Document History:

Revision	Change	Effective date
ORG	**Original Issue**	10/10/20
Rev A	**Update company change of name and Logo,** all references of Axle to HubStarr. Process Reviewed.	5/7/2024

This process is required to be reviewed, at a minimum, on a 3-year cycle. If there are no changes to the previous revision the signature below is evidence of the review and approval of this procedure.

Reviewed By: _____ Date _____

Reviewed By: _____ Date_____