

#	Pre-reqs	Milestone	
Complete function <code>sensorFunction(*)</code> - Total 11 Marks			
1.1		Compute the pose of the lidar sensor.	3 marks
1.2		Check whether the laser beam's value is infinity, if yes, skip this beam measurement.	1 mark
1.3		Check whether a failure measurement is detected, i.e., max range is detected. If yes, update the probability	1 mark
1.4	1.1	Process a beam with range measurement less than the maximum value.	6 marks

Jeremy Miraflores 22199126

Samuel Petrović 22118192