



Invoice Number : INV29453 **Date** : 22/01/2026

Client Name : Menkind Ltd

Address : The Atrium
Curtis Road

Dorking
RH4 1XA

Site Name : Menkind Worcester **Site Code**

Job Number : RM105798	Clients Ord Ref. : Called through	Start Date : 14/01/2026	Date Completed : 14/01/2026
------------------------------	--	--------------------------------	------------------------------------

Work Type : Electrical **Description** : Lamp changing

Comments : The store has reported a light on the shop floor which is sparking.

Work Started	Comments	Quantity	Unit Cost	Nett	VAT Rate	VAT	Total
14/01/2026 13:45	Electrician attended site to investigate report of failed lighting to the shop floor which is showing sparks as instructed. On inspection found cabling to the back of the lighting brittle & worn away causing it to arc. Undertook necessary repairs to make safe & isolate. All left in good safe order.	1.00	£132.30	£132.30	20.00%	£26.46	£158.76
Job Totals				£132.30		£26.46	£158.76

Payment due 30 days from date of invoice.

For BACS Payment: Sort Code 30-97-13 Account Number:
57839160

Invoice Totals	Nett	Vat	Total
	£132.30	£26.46	£158.76

Store Maintenance Ltd Registered in England no: 2530014 VAT
Registration Number 597 0426 15

Store Maintenance
Offices 8 & 13
Regency House
1 Miles Gray Road
Basildon
Essex SS14 3RW



Address: Reactive on Call FM Limited, Unit 5 Ashley industrial estate, Elmfield Road, Morley, West Yorkshire , LS27 0EL

Telephone: 0330 223 7221

Email: helpdesk@rocfm.co.uk

VAT Number: 494132192

Company Number: 16477368

Customer Details

Store Maintenance Ltd
Offices 8 & 13 , Regency House, 1 Miles Grey Road,
Basildon
Basildon
Essex
SS14 3RW

Site Details

Menkind
Unit 34 Chapel Walk
Worcester
Worcestershire, England
WR1 3LD

Call Slip

Job Number: C0011629

Job Type: Call out

Job Category:

Order Number: PO54047

Telephone:

Date Logged: 14/01/2026 11:57

Contact Name: info

Date Complete: 14/01/2026 14:00

Description

Lamp changing, The store has reported a light on the shop floor which is sparking - see image attached. Please attend urgently to investigate and repair.

Visits

Visit Date	Engineer	Customer	Status	Visit Complete
13:45 14/01/2026	Dave Smith	Store Maintenance Ltd	Complete	14:00 14/01/2026

Customer Signature

Engineer Signature

Print Name:

Lewis



Engineer Comments: One of the cables in the back of the light had become brittle and worn away causing it to arc on the metal on the back of the light. I have disconnected the light now and everything is safe. Cut out size is 150mm.
Store has many lights of various cut out sizes which aren't working at the moment but Manager Lewis had told me that after a recent visit from an area manager these are all in hand and in progress of being replaced. Job complete

Attachments

Added: 14/01/2026



Added: 14/01/2026



Added: 14/01/2026

