Riverside Auto — Repair Estimate

Synthetic repair estimate
Issued: 15 August 2026
Estimate total: $8,740

Parts

Front bumper assembly $2,180; right headlamp $1,320; sensor bracket $460.

Labor

Body and paint labor $2,640; mechanical alignment $640.

Calibration

Driver-assistance sensor calibration $1,500. Photographic support was not attached to this estimate.

This document is entirely fictional and was generated for a product demonstration.