1. Write a complete assembly program to read 8 numbers (use scan_num). Calculate the average (Use bit-shift instructions) and display them on the screen.

2. Write a complete assembly program to read 8 numbers (use scan_num). . Calculate the lowest and highest score and display them on the screen.