Geometric and Stiffness Modeling and Design of Calibration Experiments for the 7 dof Serial Manipulator KUKA iiwa 14 R820

Sami Sellami, Victor Massagué Respall

1 Introduction

The present project deals with the elastostatic modeling and calibration experiment of spacial industrial manipulators using optimal selection of measurements pose [1], for the calibration procedure, the optimal pose selection aims to the efficiency improvement of identification procedure for serial manipulators which reduces noise impact on the parameters identification precision, it is usually used for planar manipulators, our work is mainly to extend the approach for a more complicated manipulator in 3D space using a wise decomposition of the spacial manipulator into a set of serial sub-chains [2], the optimal pose configuration is then used in the calibration procedure using the complete and irreducible model for the 7 dof serial manipulator [3]. The methodology is illustrated with the anthropomorphic industrial robot KUKA iiwa14 R820 for which, we performed the calibration and constructed the stiffness modeling using two different approaches namely VJM (Virtual Joint Modeling) and MSA (Matrix Structural Analysis).

2 Related Works

In contrast to previous works for calibration the proposed in [1] yields simple geometrical patterns that allow users to take into account the joint and workspace constraints and to find measurement configurations without tedious computations. The main theoretical results are expressed as a set of several properties and rules, which allow user to obtain optimal measurement configurations without any computation, just using superpositions and permutations of the proposed patterns. They presented an example for a 6 dof manipulator showing the efficiency.

Similarly, [4] proposes simple rules for the selection of manipulator configurations that allow the user to essentially improve calibration accuracy and reduce identification errors. The results are mainly for planar manipulators(two-, three- and four-link planar manipulators), but they can be used as a base for more complicated ones. The main contributions have been obtained for the planar case, the developed rule has been heuristically generalized for articulated robots. However, a strict theoretical proof of this approach remains unsolved for calibration of non-planar serial and parallel manipulators.

In contrast to previous works, [3] developed calibration technique based on the direct measurements only. To improve the identification accuracy, it is proposed to use several reference points for each manipulator configuration. The obtained theoretical results have been successfully applied to the geometric and elastostatic calibration of serial industrial robot employed in the machining work-cell for for aerospace industry.

3 Methodology

3.1 Elastostic Modeling:

VJM model: To build the extended stiffness model of the KUKA iiwa robot, we are going to use the simplifications shown in Figure 1




Figure 1: VJM base modeling of manipulator components

In the case of our manipulator, we have 6 elastic links and 7 actuated joints, the robot model approximation is shown in Figure 2



Figure 2: Robot model approximation of Kuka iiwa 14 R820

Each elastic link is represented as a rigid link and a 6 dof virtual spring, similarly, each joint is represented as an actuated joint and a 1 dof virtual spring. The final VJM model is given by Figure 3




Figure 3: VJM model of Kuka iiwa 14 R820

This VJM model correpond to the following extended model equation:

$$T_{ext} = T_{base} \cdot R_{z,q_1} \cdot R_{z,\theta_1} \cdot T_{z,d_1} \cdot H_{3D,\theta_7} \cdot R_{x,q_2} \cdot R_{x,\theta_8} \cdot T_{z,d_2} \cdot H_{3D,\theta_{14}} \cdot R_{z,q_3} \cdot R_{z,\theta_{15}} \cdot T_{z,d_3} \cdot H_{3D,\theta_{21}} \cdot R_{x,q_4} \cdot R_{x,\theta_{22}} \cdot T_{z,d_4} \cdot H_{3D,\theta_{28}} \cdot R_{z,q_5} \cdot R_{z,\theta_{29}} \cdot T_{z,d_5} \cdot H_{3D,\theta_{35}} \cdot R_{x,q_6} \cdot R_{x,\theta_{36}} \cdot T_{z,d_6} \cdot H_{3D,\theta_{42}} \cdot R_{z,q_7} \cdot R_{z,\theta_{43}} \cdot T_{Tool}$$
(1)

The general equation between increments is as follows:

$$\begin{bmatrix} 0 & J_{\theta} & J_{q} \\ J_{\theta}^{T} & -K_{\theta} & 0 \\ J_{q}^{T} & 0 & 0 \end{bmatrix} \cdot \begin{bmatrix} F \\ \theta \\ \Delta q \end{bmatrix} = \begin{bmatrix} \Delta t \\ 0 \\ 0 \end{bmatrix}$$
 (2)

The cartesian stiffness matrix has the final expression given by equation 3

$$K_C = K_C^0 - K_C^0 \cdot J_q \cdot K_{Cq} \tag{3}$$

where: $K_C^0 = (J_\theta \cdot K_\theta^{-1} \cdot J_\theta^T)^{-1}$ is the classical cartesian stiffness matrix

and:
$$K_{Cq} = (J_q^T \cdot (K_C^0)^{-1} \cdot J_q)^{-1} \cdot J_q^T \cdot (K_C^0)^{-1}, K_{C\theta} = K_{\theta}^{-1} \cdot J_{\theta}^T \cdot K_C$$

MSA model: The basic expression for stiffness model is: $W = K \cdot \Delta t$ Using the cantilever beam representation of a link, one can write the expression of the stiffness matrix as follow:

$$K = \begin{bmatrix} \frac{E \cdot S}{L} & 0 & 0 & 0 & 0 & 0\\ 0 & \frac{12E \cdot I_z}{L^3} & 0 & 0 & 0 \frac{-6E \cdot I_z}{L^2} \\ 0 & 0 & \frac{12E \cdot I_y}{L^3} & 0 & \frac{6E^I I_y}{L^2} & 0\\ 0 & 0 & 0 & \frac{G \cdot J}{L} & 0 & 0\\ 0 & 0 & \frac{6E \cdot I_y}{L^2} & 0 & \frac{4E \cdot I_y}{L} & 0\\ 0 & \frac{-6E \cdot I_z}{I^2} & 0 & 0 & 0 & \frac{4E \cdot I_z}{I} \end{bmatrix}$$
 (4)

We need to transform this model into a global coordinates system:

$$\begin{bmatrix} K_{11}^{global} & K_{12}^{global} \\ K_{21}^{global} & K_{22}^{global} \end{bmatrix} = \begin{bmatrix} R & 0 & 0 & 0 \\ 0 & R & 0 & 0 \\ 0 & 0 & R & 0 \\ 0 & 0 & 0 & R \end{bmatrix} \begin{bmatrix} K_{11}^{local} & K_{12}^{local} \\ K_{21}^{local} & K_{22}^{local} \end{bmatrix} \begin{bmatrix} R^T & 0 & 0 & 0 \\ 0 & R^T & 0 & 0 \\ 0 & 0 & R^T & 0 \\ 0 & 0 & 0 & R^T \end{bmatrix}$$
(5)

Then, the general expression of the wrenches applied in both sides of the link is:

$$\begin{bmatrix} W_1 \\ W_2 \end{bmatrix} = \begin{bmatrix} K_{11} & K_{12} \\ K_{21} & K_{22} \end{bmatrix}_{12 \times 12} \begin{bmatrix} \Delta t_1 \\ \Delta t_2 \end{bmatrix}$$
 (6)

Where:

$$K_{22} = K$$

$$K_{11} = \begin{bmatrix} R_z^{\pi} & 0_{3 \times 3} \\ 0_{3 \times 3} & R_z^{\pi} \end{bmatrix}^T \cdot K \cdot \begin{bmatrix} R_z^{\pi} & 0_{3 \times 3} \\ 0_{3 \times 3} & R_z^{\pi} \end{bmatrix}$$

$$K_{12} = -\begin{bmatrix} I_{3 \times 3} & 0_{3 \times 3} \\ [L \times]^T & I_{3 \times 3} \end{bmatrix} \cdot K_{22}$$

$$K_{21} = -\begin{bmatrix} I_{3 \times 3} & 0_{3 \times 3} \\ (L \times) & I_{3 \times 3} \end{bmatrix} \cdot K_{11}$$

The MSA model of the robot is shown in Figure 4




Figure 4: MSA model of Kuka iiwa 14 R820

The details for each joint modeling is depicted below:

1. elastic support 0,1:

$$\lambda_{*01}^{r} = \begin{bmatrix} 1 & 0 & 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 \end{bmatrix}, \, \lambda_{*01}^{e} = \begin{bmatrix} 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix}$$
(8)

$$\lambda_{*01}^r \cdot \Delta t_1 = 0_{5 \times 1} \qquad K_e \cdot \lambda_{*01}^e \cdot \Delta t_1 - \lambda_{*01}^e \cdot W_1 = 0 \tag{9}$$

2. elastic joints with rotation about x-axis 2,3 6,7 10,11:

$$\lambda_{*ij}^{r} = \begin{bmatrix} 1 & 0 & 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix}, \lambda_{*ij}^{e} = \begin{bmatrix} 0 & 0 & 0 & 1 & 0 & 0 \end{bmatrix}$$
(10)

$$\begin{bmatrix} \lambda_{*ij}^{e} & 0_{6\times6} & K_{ij}^{e} \cdot \lambda_{*ij}^{e} & -K_{ij}^{e} \cdot \lambda_{*ij}^{e} \\ I_{6\times6} & I_{6\times6} & 0_{6\times6} & 0_{6\times6} \\ 0_{6\times6} & 0_{6\times6} & \lambda_{*ij}^{r} & -\lambda_{*ij}^{r} \end{bmatrix} \begin{bmatrix} W_{i} \\ W_{j} \\ \Delta_{i} \\ \Delta_{j} \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \\ 0 \end{bmatrix}$$
 (11)

3. elastic joints with rotations about the z-axis 4,5 8,9 12,13:

$$\lambda_{*ij}^{r} = \begin{bmatrix} 1 & 0 & 0 & 0 & 0 & 0 \\ 0 & 1 & 0 & 0 & 0 & 0 \\ 0 & 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 1 & 0 \end{bmatrix}, \, \lambda_{*ij}^{e} = \begin{bmatrix} 0 & 0 & 0 & 0 & 0 & 1 \end{bmatrix}$$

$$(12)$$

$$\begin{bmatrix} \lambda_{*ij}^{e} & 0_{6\times6} & K_{ij}^{e} \cdot \lambda_{*ij}^{e} & -K_{ij}^{e} \cdot \lambda_{*ij}^{e} \\ I_{6\times6} & I_{6\times6} & 0_{6\times6} & 0_{6\times6} \\ 0_{6\times6} & 0_{6\times6} & \lambda_{*ij}^{r} & -\lambda_{*ij}^{r} \end{bmatrix} \begin{bmatrix} W_{i} \\ W_{j} \\ \Delta_{i} \\ \Delta_{j} \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \\ 0 \end{bmatrix}$$
 (13)

4. Aggregated model:

$$\begin{bmatrix}
-I_{84\times84} & K_{links} \\
0_{35\times84} & A_{agr} \\
B_{agr} & 0_{36\times84} \\
C_{agr} & D_{agr} \\
E_{agr} & 0_{6\times84}
\end{bmatrix} \begin{bmatrix}
W_{agr} \\
\Delta t_{agr}
\end{bmatrix} = \begin{bmatrix}
0_{168\times1} \\
W_{e}
\end{bmatrix}$$
(14)

(15)

Equation 14 can be written in the form:

$$\begin{bmatrix} A & B \\ C & D \end{bmatrix} \cdot \begin{bmatrix} \mu \\ \Delta t_e \end{bmatrix} = \begin{bmatrix} b \\ W_e \end{bmatrix} \tag{16}$$

And the final expression of K_c is given by

$$K_C = D - C \cdot A^{-1} \cdot B$$

3.2 Geometric Calibration:

The basic equations for the identification using full pose measurements is

$$t = g(q, \pi) \tag{17}$$

where: $t_i = (p_{xi}, p_{yi}, p_{zi}, \phi_{xi}, \phi_{yi}, \phi_{zi})^T$ is six dimensional location vector, g is the manipulator extended geometric model, q is the vector of actuated coordinates and $\pi = \pi + \Delta \pi$ is the vector of parameters.

The goal is the identification of robot model parameters using direct measurement only without using orientation components, the basic equation for identification is:

$$\sum_{i=1}^{m} \sum_{j=1}^{n} ||p_{ij} - g_{0ij}^{(p)} - J_{\pi ij}^{(p)} \Delta \pi||^2 \longrightarrow min$$
 (18)

The geometric model obtained via homogeneous transformations can be presented by the matrix product:

$$T_i^j = T_{base} T_{robot}(q_i, \pi) T_{tool}^j \tag{19}$$

The cartesian coordinates of reference points p_i^j , j=1,...n corresponding to the configuration q_i can be expressed in the following form:

$$p_i^j = p_{base} + R_{base} p_{robot}(q_i, \pi) + R_{base} R_{robot}(q_i, \pi) p_{tool}^j$$
(20)

Where: $p_{base}, R_{base}, p_{tool}^{j}, \pi$ are unknown parameters

The procedure of identification is divided into two steps [3]:

1. **Step1**: parameters identification of tool and base transformations $p_{base}, R_{base}, p_{tool}^{j}$

$$[p_{base} \quad r_{base} \quad u_{tool}, \dots \quad u_{tool}^{n}] = (\sum_{i=1}^{m} A_{i}^{jT} A_{i}^{j})^{-1} (\sum_{i=1}^{m} A_{i}^{jT} \Delta \pi)$$
(21)

$$\text{Where: } A_i^j = \left[\begin{array}{cccccc} I & [p_{\tilde{b}ase}^{-1}]^T & R_{robot}^i & 0 & & 0 \\ I & [p_{\tilde{b}ase}^{-1}]^T & 0 & R_{robot}^i & & 0 \\ ... & ... & ... & ... & & ... \\ I & [p_{\tilde{b}ase}^{-1}]^T & 0 & 0 & & R_{robot}^i \end{array} \right]$$

and
$$p_{tool}^j = R_{base}^T \cdot u_{tool}^j$$

2. **Step2:** Identification of the Electrostatic and geometric parameters of the manipulator π Basic equation of identification: $p_i^j = p_{robot}^i + J_{\pi i}^{j(p)} \pi$, where π are the unknown parameters to be identified

The solution of the identification problem is given by

$$\pi = \left(\sum_{i=1}^{m} J_i^{j(p)T} J_i^{j(p)}\right)^{-1} \left(\sum_{i=1}^{m} J_i^{j((p)T} \Delta \pi_i^j\right)$$
 (22)

3.3 Modeling:

To perform the identification task, one need to develop a suitable geometric model, which properly describe the relation between the manipulator geometric parameters (link length and joint angles) and the end effector location (position and orientation), for this, we construct the complete and obviously irreducible model in the form of homogeneous matrices product

- The base transformation is $T_{base} = [T_x T_y T_z R_x R_y R_z]$
- The joint and link transformations (for revolute joint) $T_{joint,j}T_{link,j} = R_{e,j}(q_j, \pi_{qj})[T_uT_vR_uR_v]$ Where e_j is the joint axis and u_j and v_j are the axes orthogonal to e_j
- The tool transformation $T_{tool} = [T_x T_y T_z R_x R_y R_z]$

The next step is the elimination of non identifiable and semi identifiable parameters in accordance with specific rules for different nature and structure of consecutive joints

- In the case of consecutive revolute joints $R_{e,j}(q_j, \pi_{qj})$
 - if $e_j \perp e_{j-1}$ eliminate the term $R_{u,L_{j-1}}$ or $R_{v,L_{j-1}}$ that correspond to $R_{e,j}$
 - if $e_j \parallel e_{j-1}$ eliminate the term $T_{u,L_{j-k}}$ or $T_{v,L_{j-k}}$ that define the translation orthogonal to the joint axes for which k is minimum $(k \ge 1)$

3.4 Design of calibration experiments:

In the case of serial manipulator with revolute joints, the expression of end effector position is computed using the following formula:

$$x^{k} = \sum_{i=0}^{n} (l_{i}^{0} + \Delta l_{i}) \cos(\theta_{i}^{0} + \Delta \theta_{i}) \qquad y^{k} = \sum_{i=0}^{n} (l_{i}^{0} + \Delta l_{i}) \sin(\theta_{i}^{0} + \Delta \theta_{i})$$
 (23)

Where: l_i^0 are the nominal links lengths and Δl_i their deviations, q_j^0 are nominal joints coordinates, θ_i are defined as $\theta_i = \sum_{k=1}^i q_k^0$ and $\Delta \theta_i = \sum_{k=1}^i \Delta q_k^0$ are the joints offsets

To take into account the impact of measurement noise, the calibration equation derived from 23 becomes:

$$x^{k} = \sum_{i=0}^{n} (l_i^0 + \Delta \theta_i) \cos(\theta_i^0 + \Delta \theta_i) + \epsilon_x^{k} \qquad y^{k} = \sum_{i=0}^{n} (l_i^0 + \Delta \theta_i) \sin(\theta_i^0 + \Delta \theta_i) + \epsilon_y^{k}$$
(24)

To find the desired parameters using the noise corrupted measurements, the least square technique is applied, this approach aims at minimizing the square sum of the residuals in 24 simultaneously

$$\sum_{k=1}^{m} \left(\sum_{i=0}^{n} (l_i^0 + \Delta l_i) \cos(\theta_i^0 + \Delta \theta_i) - x_k \right)^2 + \sum_{k=1}^{m} \left(\sum_{i=0}^{n} (l_i^0 + \Delta l_i) \sin(\theta_i^0 + \Delta \theta_i) - y_k \right)^2 \longrightarrow min$$
(25)

Collecting the unknown parameters Δl_i and $\Delta \theta_i$ into the vector $\Delta \pi$ and the measurements into the vector ΔP^k equation 23 can be rewritten as:

$$\Delta P^k = J^k \Delta \pi \tag{26}$$

Where J is the jacobian matrix, then one can get the unknown parameters using the least squares technique that leads to

$$\Delta \pi = \left(\sum_{k=1}^{m} J^{kT} J^k\right)^{-1} \sum_{k=1}^{m} J^{kT} \Delta P^k \tag{27}$$

Where the subscript k indicate the experiment number and m is the number of measurements Considering that each measurement is corrupted by an unbiased random Gaussian noise with standard deviation σ , the identification accuracy of the parameters $\Delta \pi$ can be evaluated via the covariance matrix, which is computed as follow:

$$cov(\Delta \pi) = \sigma^2 (\sum_{k=1}^m J^{kT} J^k)^{-1}$$
 (28)

With this expression, it is possible to choose the measurement configuration that yield parameters less sensitive to measurement noise, this procedure is referred to as design of calibration experiments, the optimality condition for the calibration plan proposed in [5] where one need to ensure that the information matrix is diagonal yields to the D-optimal plan of experiments that is satisfied when:

$$\sum_{k=1}^{m} \cos(\sum_{s=1}^{i} q_s^k - \sum_{k=1}^{j} q_s^k), \quad \forall i > j$$

$$\sum_{k=1}^{m} \sin(\sum_{s=1}^{i} q_s^k - \sum_{k=1}^{j} q_s^k), \quad \forall i > j$$
(29)

The above presented equations define the desired set of optimal measurements configurations.

3.5 Geometrical patterns for measurement pose selection:

In the following we are going to introduce some important properties of the optimality condition 29 that allow us to reduce the problem complexity [1]

- 1. Superposition of optimal plans also gives an optimal plan for this; this is due to the additivity of the the operations included in 29. Using this property, it is possible to generate optimal plan with a large number of measurements configurations using simple sets.
- 2. The angles $q_1, q_2, ..., q_n$ can be rearranged in the optimal plan in an arbitrary way without loss of the optimality condition 29
- 3. Optimal plan for n-link manipulator can be obtained using two lower-order optimal plans for n1- and n2-link manipulators, where $n_1 + n_2 = n + 1$, This property gives an elegant technique to generate optimal plan of calibration experiments without straightforward solution of the system 29

the following present geometrical patterns for typical serial manipulators that can be used to generate optimal plans. In the frame of these patterns, all variables $\alpha_i\beta_i$ and γ and δ are treated as arbitrary angles:

For n = 3, m = 3, the geometrical pattern can be presented as

$$q_1^1 = \alpha_1 \qquad q_2^1 = \beta \qquad q_3^1 = \gamma q_1^2 = \alpha_2 \quad q_2^2 = \beta + 2\pi/3 \quad q_3^2 = \gamma + 2\pi/3 q_1^3 = \alpha_3 \quad q_2^3 = \beta - 2\pi/3 \quad q_3^3 = \gamma - 2\pi/3$$

$$(30)$$

For n = 4, m = 4, the geometrical pattern can be presented as

$$q_{1}^{1} = \alpha_{1} \quad q_{2}^{1} = \beta_{1} \quad q_{3}^{1} = \gamma \quad q_{4}^{1} = \delta$$

$$q_{1}^{2} = \alpha_{2} \quad q_{2}^{2} = \beta_{1} + \pi \quad q_{3}^{2} = \gamma \quad q_{4}^{2} = \delta + \pi$$

$$q_{1}^{3} = \alpha_{3} \quad q_{2}^{3} = \beta_{2} \quad q_{3}^{3} = \gamma + \pi \quad q_{4}^{3} = \delta + \beta_{1} - \beta_{2}$$

$$q_{1}^{4} = \alpha_{4} \quad q_{2}^{4} = \beta_{2} + \pi \quad q_{3}^{4} = \gamma + \pi \quad q_{4}^{3} = \delta + \beta_{1} - \beta_{2} + \pi$$

$$(31)$$

	Number of	Configurations						
Manipulator	measurement configurations	Configuration #1	Configuration #2	Configuration #3	Configuration #4			
2-link manipulator	<i>m</i> = 2	(0°, 90°)	(0°, -90°)					
n = 2	<i>m</i> = 3	(0°, 0°)	(0°, 120°)	(0°, -120°)				
3-link manipulator n = 3	<i>m</i> = 3	(0°, 0°, 0°)	(0°, 120°, 120°)	(0°, -120°, -120°)				
	<i>m</i> = 4	(0°, -60°, 60°)	(0°, -120°, -60°)	(0°, 120°, -120°)	(0°, 60°, 120°)			
4-link manipulator n = 4	m = 4	(0°, -60°, 60°, -60°)	(0°, -120°, -60°, -120°)	(0°, 120°, -120°, 120°)	(0°, 60°, 120°, 60°)			

Figure 5: Optimal measurement configurations for typical planar manipulators [2]

3.6 Extension to the 3D case:

The simplest way to extend the proposed "rule of thumb" to the 3D case is to apply the following procedure:

Step (a): decompose the spatial manipulator into a set of planar serial sub-chains;

Step (b): apply the developed rule to each sub-chain separately, without assigning certain values to the joint coordinates that can be selected arbitrary;

Step (c): aggregate the obtained sub-chain joint coordinates in order to find configurations of

the entire manipulator (where some values are still arbitrary);

Step (d): apply the developed rule to the each set of the arbitrary coordinates, i.e. ensuring that the sums of sines and cosines are equal to zero for all of them.

4 Case study: calibration of the 7 dof manipulator KUKA IIWA

4.1 Calibration experiment:

Let us consider the 7 dof. serial manipulator with seven revolute joints and six links, Kuka IIWA 14 R820 depicted in Figure 6




Figure 6: LBR iiwa 14 R820 working envelope, side view

To complete the identification task, the irreducible model in the form of homogeneous matrix product as described before was build for Kuka iiWA:

$$\begin{split} T &= [T_x T_y T_z R_x R_y R_z]_b R_z (q_1 + \Delta q_1) [T_x T_y \cancel{\mathbb{R}}_x R_y] R_x (q_2 + \Delta q_2) [T_y T_z R_y \cancel{\mathbb{R}}_z] R_z (q_3 + \Delta q_3) \\ & [T_x T_y \cancel{\mathbb{R}}_x Ry] R_x (q_4 + \Delta q_4) [T_y T_z R_y \cancel{\mathbb{R}}_z] R_z (q_5 + \Delta q_5) [T_x T_y \cancel{\mathbb{R}}_x R_y] R_x (q_6 + \Delta q_6) [T_y T_z R_y \cancel{\mathbb{R}}_z] \\ & R_z (q_7 + \Delta q_7) [\cancel{\mathbb{R}}_x \cancel{\mathbb{R}}_y \cancel{\mathbb{R}}_z] [\cancel{\mathbb{R}}_x \cancel{\mathbb{R}}_y \cancel{\mathbb{R}}_z] \\ & T_{robot} = R_z (q_1) \cdot T_x (\Delta l_{1x}) \cdot T_y (\Delta l_{1y}) \cdot R_y (\Delta q_{1y}) \cdot R_x (q_2 + \Delta q_2) \cdot T_y (\Delta l_{2y}) \cdot T_z (d_1 + \Delta l_{2z}) \cdot R_y (\Delta q_{2y}) \cdot \\ & R_z (q_3 + \Delta q_3) \cdot T_x (\Delta l_{3x}) \cdot T_y (\Delta l_{3y}) \cdot R_y (\Delta q_{3y}) \cdot R_x (q_4 + \Delta q_4) \cdot T_y (\Delta l_{4y}) \cdot T_z (d_2 + \Delta l_{4z}) \cdot R_y (\Delta q_{4y}) \cdot \\ & R_z (q_5 + \Delta q_5) \cdot T_x (\Delta l_{5x}) \cdot T_y (\Delta l_{5y}) \cdot R_y (\Delta q_{5y}) \cdot R_x (q_6 + \Delta q_6) \cdot T_y (\Delta l_{6y}) \cdot T_z (\Delta l_{6z}) \cdot R_y (\Delta q_{6y}) \cdot R_z (q_7) \end{split}$$




Figure 7: Representation of the 7dof manipulator KUKA iiwa

To simulate the calibration procedure, we take ideal parameters for which we add some random noise and we compute the calibration procedure described before using a *Matlab* code, Figure 8 shows the results obtained for three different trajectories (trajectory obtained with and without calibration).




Figure 8: Trajectories obtained with and without calibration (target trajectory(blue), trajectory without calibration (red), trajectory with calibration (yellow)

We can clearly see the trajectory with calibration follow better the desired trajectory in all three cases, especially in the last two pictures where the trajectories are almost colinear.

Table 1 shows the results of the parameters identification with and without calibration, the

parameters obtained after calibration are more accurate and closer to the real ones.

Parameter	Real value	Calibration	No	Improvement	
			Calibration	Factor	
p_{x1}	-0.0051	-0.0088	0.0000	1.37	
p_{y1}	-0.0023	0.0187	0.0000	1.10	
ϕ_{y1}	-0.0049	-0.0049	0.0000	236.95	
Δq_2	0.0089	0.0088	0.0000	178.35	
p_{y2}	-0.0058	-0.0380	0.0000	0.17	
p_{2z}	423.8028	423.7902	420.0000	301.81	
ϕ_{y2}	-0.0023	-0.0024	0.0000	56.69	
Δq_3	-0.0058	-0.0058	0.0000	500.43	
p_{x3}	0.0074	-0.0046	0.0000	0.61	
p_{y3}	-0.0097	-0.0132	0.0000	2.82	
ϕ_{y3}	-0.0052	-0.0052	0.0000	76.20	
Δq_4	0.0036	0.0035	0.0000	45.79	
p_{y4}	0.0035	-0.0196	0.0000	0.15	
p_{z4}	399.3576	399.3678	400.0000	62.98	
ϕ_{y4}	-0.0050	-0.0050	0.0000	127.71	
Δq_5	0.0063	0.0064	0.0000	62.00	
p_{x5}	-0.0046	-0.0283	0.0000	0.18	
p_{y5}	-0.0057	-0.0111	0.0000	1.03	
ϕ_{y5}^{gg}	$6.762e^{-4}$	0.0007	0.0000	12.81	
Δq_6	0.0023	0.0024	0.0000	22.00	
p_{y6}	0.0048	0.0096	0.0000	1.00	
p_{z6}	0.0048	0.6044	0.0000	0.00	
ϕ_{y6}	-0.0041	-0.0041	0.0000	201.38	
base x	0.0000	-0.0098	0.0000	0.00	
base y	0.0000	-0.0192	0.0000	0.00	
base z	365.5582	365.5518	360.0000	537.78	
tool 1x	0.0000	0.0030	0.0000	0.00	
tool 1y	0.0000	-0.0111	0.0000	0.00	
tool 1z	89.6944	89.0951	90.0000	0.50	
tool 2x	0.0000	-0.0014	0.0000	0.00	
tool 2y	-77.5044	-77.5058	-77.9423	336.76	
tool 2z	-44.7472	-45.3375	-45.0000	0.42	
tool 3x	0.0000	0.0204	0.0000	0.00	

Table 1: Results of the parameters identification with and without calibration

Average:

78.6877

-46.0641

77.9423

-45.0000

497.93

 $0.68 \\ 93.36$

tool 3y

 $tool \; 3z$

78.6892

-45.4312

4.2 Calibration using design of experiments:

In order to find the optimal pose configuration for the manipulator, the first thing to do is to decompose the spatial manipulator into a set of planar kinematic serial sub-chains, we define each joint of the manipulator as q_n where n denotes the joint number of the robot. According to the geometrical pattern presented above, and by studying the robot structure, we naturally divide the manipulator into the two following planar sub-chains:

- 1. (q_1, q_3, q_5, q_7)
- 2. $(q_{virtual}, q_2, q_4, q_6)$

Note that, because the first angle doesn't appear in the system 29 (the calibration plan is invariant with respect to the first joint), we added a virtual joint at the beginning of the second sub-chain. Using this decomposition, the property 3 described above and the results of previous works shown in Figure 5 [2] corresponding to the 4-link manipulator with m=4 (equation 31), we built 16 configurations that reflect all the possible poses obtained when combining the two sub-chains. (table2)

q_1	$\boldsymbol{q_2}$	q_3	$\boldsymbol{q_4}$	q_5	q_6	q_7
α_1	ϵ_1	β_1	χ	γ	ϕ	δ
α_1	$\epsilon_1 + \pi$	β_1	χ	γ	$\phi + \pi$	δ
α_1	ϵ_2	β_1	$\chi + \pi$	γ	$\phi + \epsilon_1 - \epsilon_2$	δ
α_1	$\epsilon_2 + \pi$	β_1	$\chi + \pi$	γ	$\phi + \epsilon_1 - \epsilon_2 + \pi$	δ
α_2	ϵ_1	$\beta_1 + \pi$	χ	γ	ϕ	$\delta + \pi$
α_2	$\epsilon_1 + \pi$	$\beta_1 + \pi$	χ	γ	$\phi + \pi$	$\delta + \pi$
α_2	ϵ_2	$\beta_1 + \pi$	$\chi + \pi$	γ	$\phi + \epsilon_1 - \epsilon_2$	$\delta + \pi$
α_2	$\epsilon_2 + \pi$	$\beta_1 + \pi$	$\chi + \pi$	γ	$\phi + \epsilon_1 - \epsilon_2 + \pi$	$\delta + \pi$
α_3	ϵ_1	β_2	χ	$\gamma + \pi$	ϕ	$\delta + \beta_1 - \beta_2$
α_3	$\epsilon_1 + \pi$	β_2	χ	$\gamma + \pi$	$\phi + \pi$	$\delta + \beta_1 - \beta_2$
α_3	ϵ_2	β_2	$\chi + \pi$	$\gamma + \pi$	$\phi + \epsilon_1 - \epsilon_2$	$\delta + \beta_1 - \beta_2$
α_3	$\epsilon_2 + \pi$	β_2	$\chi + \pi$	$\gamma + \pi$	$\phi + \epsilon_1 - \epsilon_2 + \pi$	$\delta + \beta_1 - \beta_2$
α_4	ϵ_1	$\beta_2 + \pi$	χ	$\gamma + \pi$	ϕ	$\delta + \beta_1 - \beta_2 + \pi$
α_4	$\epsilon_1 + \pi$	$\beta_2 + \pi$	χ	$\gamma + \pi$	$\phi + \pi$	$\delta + \beta_1 - \beta_2 + \pi$
α_4	ϵ_2	$\beta_2 + \pi$	$\chi + \pi$		$\phi + \epsilon_1 - \epsilon_2$	$\delta + \beta_1 - \beta_2 + \pi$
α_4	$\epsilon_2 + \pi$	$\beta_2 + \pi$	$\chi + \pi$	$\gamma + \pi$	$\phi + \epsilon_1 - \epsilon_2 + \pi$	$\delta + \beta_1 - \beta_2 + \pi$

Table 2: Optimal Plan for the entire manipulator with 16 measurements configurations

Also, to build the final optimal plan, a *Matlab* code was developed to set the still remaining arbitrary angles that satisfy the optimality condition 29 for the entire manipulator. Taking into account the joint limits, the arbitrary angles have been set to: $\alpha_1 = 0^{\circ}$, $\alpha_2 = 0^{\circ}$, $\alpha_3 = 0^{\circ}$, $\alpha_4 = 0^{\circ}$, $\epsilon_1 = -90^{\circ}$, $\epsilon_2 = -90^{\circ}$, $\beta_1 = -90^{\circ}$, $\beta_2 = -130^{\circ}$, $\chi = -110^{\circ}$, $\gamma = -160^{\circ}$, $\phi = -110^{\circ}$, $\delta = -170^{\circ}$, and the Table 3 was built which shows 16 optimal configurations for our robot. One point that one should noted is that, because the calibration plan is invariant with respect to the first joint like stated before, we can arbitrarily assign joint q_1 to make the end effector facing the direction where the laser tracker should be positioned when performing the experiment.

Optimal Pose Measurements

Configuration	Joint 1	Joint 2	Joint 3	Joint 4	Joint 5	Joint 6	Joint 7
1	-20°	-90°	-110°	-160°	-110°	-110°	-170°
2	40°	90°	-90°	-110°	-160°	70°	-170°
3	135°	-90°	-90°	70°	-160°	-110°	-170°
4	-140°	90°	-90°	70°	-160°	70°	-170°
5	20°	-90°	90°	-110°	-160°	-110°	10°
6	-45°	90°	90°	-110°	-160°	70°	10°
7	-140°	-90°	90°	70°	-160°	-110°	10°
8	-140°	90°	90°	70°	-160°	70°	10°
9	-165°	-90°	-130°	-110°	20°	-110°	-130°
10	165°	90°	-130°	-110°	20°	70°	-130°
11	0°	-90°	-130°	70°	20°	-110°	-130°
12	10°	90°	-130°	70°	20°	70°	-130°
13	165°	-90°	50°	-110°	20°	-110°	50°
14	-160°	90°	50°	-110°	20°	70°	50°
15	0°	-90°	50°	70°	20°	-110°	50°
16	-15°	90°	50°	70°	20°	70°	50°

Table 3: Optimal measurement configurations for Kuka IIWA R14 820 $\,$

We simulated the configuration poses to make sure they are safe for the robot and any collision with the surroundings is avoided, Figure 9 shows three of these configurations




Figure 9: Three different optimal configurations in the simulator RoboDK

We performed the calibration simulation once again using the optimal pose selection, the following figure shows the results obtained (trajectory obtained with optimal and random pose), We can clearly see that the optimal plan trajectory follows better the desired trajectory compared to the random plan.




Figure 10: Trajectory obtained before and after calibration (using optimal and random plan) (target trajectory(blue), trajectory without calibration (black), trajectory with random plan calibration (red), trajectory with optimal plan calibration (green)

Table 4 shows the identification accuracy for different plans of calibration experiments, we can see that the accuracy with optimal plan is better compared to the random plan, Hence the simulation results confirm the advantages of the calibration using optimal pose selection

Design of experiments							
Parameter	Real value	Optimal	Random	Improvement			
		Plan	Plan	Factor			
p_{x1}	0.0063	0.0003	0.0034	0.48			
p_{y1}	0.0081	0.0003	0.0156	0.96			
ϕ_{y1}°	-0.0075	2.1908e-06	-0.0074	0.01			
Δq_2	0.0083	0.00060	0.0083	0.00			
p_{y2}	0.0026	-0.0488	0.0128	0.20			
p_{2z}	415.9754	415.9700	415.9723	0.57			
ϕ_{y2}	-0.0044	-0.0044	-0.0045	2.41			
Δq_3	0.0009	0.0010	0.0009	0.00			
p_{x3}	0.0092	0.0141	-0.0045	2.82			
p_{y3}	0.0093	0.0069	0.0088	0.21			
ϕ_{y3}	-0.0068	-0.0070	-0.0068	0.00			
Δq_4	0.0094	0.0094	0.0094	0.00			
p_{y4}	0.0091	0.0096	0.0160	12.90			
p_{z4}	399.8538	399.8500	399.8661	3.24			
ϕ_{y4}	0.0060	0.0062	0.0059	0.48			
Δq_5	-0.0072	-0.0072	-0.0072	0.00			
p_{x5}	-0.0016	-0.0002	-0.0120	7.21			
p_{y5}	0.0083	0.0146	0.0112	0.46			
ϕ_{y5}	0.0058	0.0058	0.0059	2.87			
Δq_6	0.0092	0.0092	0.0091	31.25			
p_{y6}	0.0031	0.0093	0.0054	0.37			
p_{z6}	-0.0093	0.0038	-1.7009	129.28			
ϕ_{y6}	0.0070	0.0069	0.0069	0.67			
base x	0.0000	0.0004	0.0223	60.06			
base y	0.0000	0.0003	0.0011	3.56			

Table 4: Results of the parameters identification using optimal and random measurement configuration plan

Average:

0.0000

0.0006

-0.0488

415.9700

-0.0044

0.0010

0.0141

0.0069

-0.0070

0.0094

364.3303

-0.0009

0.0138

91.3873

-0.0005

-77.5138

-43.0611 0.0084

78.7003

-43.7463

0.00

1.48

0.28

0.01

0.11

0.00

0.04

1.21

0.00

0.04

7.52

base z

tool 1x

tool 1y

 $tool \ 1z$

 $tool\ 2x$

tool 2y

 $tool\ 2z$

tool 3x

tool 3y

 $tool \; 3z$

364.3399

0.0000

0.0000

89.6944

0.0000

-77.5044

-44.7472

0.0000

78.6892

-45.4312

5 Conclusion:

The project present the elastostatic modeling and the design of calibration experiment for the spatial anthropomorphic manipulator KUKA iiwa 14 R820, first, for the stiffness modeling we used two approaches to build the cartesian stiffness matrix namely VJM and MSA modeling, then for the calibration, using wise decomposition of the manipulator structure into two planar serial sub-chains, and the properties depicted in [1], we were able to build 16 measurements configurations describing the optimal pose

The complete and irreducible model of the robot was established to perform the calibration simulation, the latter showed clear improvement in the parameters identification with the optimal plan obtained which confirms the efficiency of the approach used.

References

- [1] A. Klimchik, D. Daney, S. Caro, and A. Pashkevich, "Geometrical patterns for measurement pose selection in calibration of serial manipulators," in *Advances in Robot Kinematics*, pp. 263–271, Springer, 2014.
- [2] A. Klimchik, S. Caro, and A. Pashkevich, "Optimal pose selection for calibration of planar anthropomorphic manipulators," *Precision Engineering*, vol. 40, pp. 214–229, 2015.
- [3] A. Klimchik, Y. Wu, S. Caro, B. Furet, and A. Pashkevich, "Geometric and elastostatic calibration of robotic manipulator using partial pose measurements," *Advanced Robotics*, vol. 28, no. 21, pp. 1419–1429, 2014.
- [4] Y. Wu, A. Klimchik, S. Caro, B. Furet, and A. Pashkevich, "Geometric calibration of industrial robots using enhanced partial pose measurements and design of experiments," *Robotics and Computer-Integrated Manufacturing*, vol. 35, pp. 151–168, 2015.
- [5] W. Y. C. S. P. A. Klimchik, A., "Design of experiments for calibration of planar anthropomorphic manipulators," *Advanced Intelligent Mechatronics (AIM)*, p. 576–581, 2011.