

Q1)

L	PIR	D	C	EM	LH	LM	
0	0	0	0	0	0	0	0
0	0	0	0	0	1	0	1
0	0	0	0	1	0	1	1
0	0	0	0	1	1	1	1
0	0	0	1	0	0	0	0
0	0	0	1	0	1	0	1
0	0	0	1	1	0	1	1
0	0	0	1	1	1	1	1
0	1	0	0	0	0	0	0
0	1	0	0	0	1	0	1
0	1	0	0	1	0	1	1
0	1	0	0	1	1	1	1
0	1	1	1	0	0	0	0
0	1	1	1	0	1	0	1
0	1	1	1	1	0	1	1
0	1	1	1	1	1	1	1
1	0	0	0	0	0	0	0
1	0	0	0	0	1	0	1
1	0	0	0	1	0	1	1
1	0	0	0	1	1	1	1
1	0	1	0	0	0	0	1
1	0	1	1	0	1	0	1
1	0	1	1	1	0	1	1
1	0	1	1	1	1	1	1
1	1	0	0	0	0	1	0
1	1	0	0	0	1	1	1
1	1	0	0	1	0	1	1
1	1	0	0	1	1	1	1
1	1	1	1	0	0	1	1
1	1	1	1	0	1	1	1
1	1	1	1	1	0	1	1
1	1	1	1	1	1	1	1

Q2)

suppose $P \Rightarrow PIR$, $E \Rightarrow EM$.

$$LH = L'P'C + L'PC + LP'C + LPC' + LPC$$

$$LM = (L'+D'+C'+E') \cdot (L'+D+C'+E') \cdot (L+D'+C'+E')$$

$$LE = EM$$


Q3)

$$LH = C+LP$$

$$LM = C+E +LD$$

$$LE = E$$

Q4)



https://www.tinkercad.com/things/ibzz6W2qIIw-surprising-wluff/editel?returnTo=https%3A%2F%2Fwww.tinkercad.com%2Fdashboard&sharecode=QuslBlH61TOi_m0g6kEvgAPyQooQD6FP11kHatgI7rw