

Practical 2025/01/08

1)

L	PIR	D	C	EM	LH	LM	LE
0	0	0	0	0	0	0	0
0	0	0	0	1	0	1	1
0	0	0	1	0	1	1	0
0	0	0	1	1	1	1	1
0	0	1	0	0	0	0	0
0	0	1	0	1	0	1	1
0	0	1	1	0	1	1	0
0	0	1	1	1	1	1	1
0	1	0	0	0	0	0	0
0	1	0	0	1	0	1	1
0	1	0	1	0	1	1	0
0	1	0	1	1	1	1	1
0	1	1	0	0	0	0	0
0	1	1	0	1	0	1	1
0	1	1	1	0	1	1	0
0	1	1	1	1	1	1	1
1	0	0	0	0	0	0	0
1	0	0	0	1	0	1	1
1	0	0	1	0	1	1	0
1	0	0	1	1	1	1	1
1	0	1	0	0	0	1	0
1	0	1	0	1	0	1	1
1	0	1	1	0	1	1	0
1	0	1	1	1	1	1	1
1	1	0	0	0	1	0	0
1	1	0	0	1	1	1	1
1	1	0	1	0	1	1	0
1	1	0	1	1	1	1	1
1	1	1	0	0	1	1	0
1	1	1	0	1	1	1	1
1	1	1	0	0	1	1	0
1	1	1	1	0	1	1	0
1	1	1	1	1	1	1	1
1	1	1	1	0	1	1	0
1	1	1	1	1	1	1	0
1	1	1	1	1	1	1	1

2) 3)

2) $P = L\bar{R}$ $E = EM$

$$LH = \bar{L}\bar{P}C + \bar{L}PC + L\bar{P}C + LPC$$

$$LM = (L + D + C + E) \cdot (L + \bar{D} + C + E) \cdot (L + D + C + E)$$

$$LE = E$$

3)

		PC			
		00	01	11	10
L	0	0	1	1	0
1	1	0	1	1	1


$$LH = LP + C$$

		CE			
		00	01	11	10
L	0	0	1	1	1
1	1	0	1	1	1

$$LE = E$$

$$LM = (L + C + E) \cdot (D + C + E)$$

4)



<https://www.tinkercad.com/things/df3gl2UwINp-ele-practical->