Vehicle Cost Estimate

2026/10/29
CES-007

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/19/2026 7:48:11AM

Detailed Description

4W BRAKE RELINE NEW FLYER 40FT - CALIPER AND CHAMBER PROGRAM

Vehicle Series

NEW FLYER 40FT HYBRID SR2734 7200-7333

Number of Vehicles 134
Estimate Number 4771

Make NEW FLYER
Model XCELSIOR
Year 2022

LABOUR TASK SUMMARY

Task	CC	Labour Definition	Time	Wrench Time
CALIPER/CHAMBER/PADS	05H3	COACH TECHNICIAN	20:00	16:40
MATERIAL SUPPORT	05H3	COACH TECHNICIAN	0:30	0:25
STEAM JENNY	05H3	COMPONENT CLEANER	0:25	0:21
			20:55	**20:55**

LABOUR HOURS SUMMARY

Cost Centre	Total Hours
05H3	20:55
Total Labour Hours	**20:55**

MATERIAL COST SUMMARY

Cost Centre	Total Cost
05H3	$7,233.67
Total Material Cost (Excl Tax)	**$7,233.67**

Labour Total (Incl. Non Productive Adj.):	$1,050.86
Labour Overhead	$767.13
Material Cost (Excluding Tax):	$7,233.67
Total Material Cost (Excluding Tax):	$7,233.67
Total Cost (Excluding Tax) :	**$9,051.66**
Tax Total:	$0.00
Total Cost with Tax:	**$9,051.66**

Vehicle Cost Estimate

2026/10/29
CES-008

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/19/2026 7:48:11AM

Detailed Description

4W BRAKE RELINE NEW FLYER 40FT - CALIPER AND CHAMBER PROGRAM

Vehicle Series

NEW FLYER 40FT HYBRID SR2734 7200-7333

Number of Vehicles 134
Estimate Number 4771

Make NEW FLYER
Model XCELSIOR
Year 2022

Rebuilt Parts Material List

STOCK CODE	DESCRIPTION	UNIT COST	QTY	USAGE (%)	TOTAL
				TOTAL REBUILT PART MATERIALS COST	**$0.00**

Vehicle Cost Estimate

2026/10/29
CES-008

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/19/2026 7:48:11AM

Detailed Description

4W BRAKE RELINE NEW FLYER 40FT - CALIPER AND CHAMBER PROGRAM

Vehicle Series

NEW FLYER 40FT HYBRID SR2734 7200-7333

Number of Vehicles 134
Estimate Number 4771

Make NEW FLYER
Model XCELSIOR
Year 2022

Stock Coded Material List

STOCK CODE	DESCRIPTION	MMS_COST	CC	QTY	USAGE (%)	TOTAL
074950	TYPE: DISC BRAKE CALIPER ASM WITHOUT BRAKE PADSLOCATION: FRONT STREETSIDE / REAR CURBSIDEOTHER: FOR BRAKE PADS USE NF PN 6447341	985.00	05H3	2	100.00 %	$1,970.00
074951	TYPE: DISC BRAKE CALIPER ASM WITHOUT BRAKE PADSLOCATION: FRONT CURBSIDE / REAR STREETSIDEOTHER: FOR BRAKE PADS USE NF PN 6447341	1,221.00	05H3	2	100.00 %	$2,442.00
074954	TYPE: HUB BEARING ASMLOCATION: REAR HUB - ROADSIDE & CURBSIDEOTHER: INCLUDES O-RING 109.2 X 5.7 B-NBR	390.56	05H3	2	5.00 %	$39.06
075747	TYPE: SLOTTED NUTLOCATION: REAR AXLE HUB - ROADSIDE & CURBSIDESIZE: M100 X 1.5	81.44	05H3	20	10.00 %	$162.88
076116	TYPE: REAR BRAKE HOSELOCATION: RELAY VALVE TO BRAKE CHAMBER - ROADSIDEOTHER: 3808 FL 60.81	31.75	05H3	1	25.00 %	$7.94
076117	TYPR: BRAKE CHAMBER ASMLOCATION: REAR BRAKE - ROADSIDE & CURBSIDE	598.70	05H3	2	100.00 %	$1,197.40
076928	TYPE : REAR BRAKE HOSELOCATION : MODULATOR VALVE TO BRAKE CHAMBER CURBSIDE & ROADSIDEOTHER : 3808 FL 26.00	24.11	05H3	2	25.00 %	$12.06
077277	TYPE: ABS SENSORLOCATION: FRONT ROADSIDE & CURBSIDERELATED TTC CODE(S): CLAMP RING SLEEVE SC 082520	170.00	05H3	2	10.00 %	$34.00
077299	AKE CHAMBER	263.44	05H3	1	100.00 %	$263.44
077312	SIDE FRONT BRAKE CHAMBER	265.00	05H3	1	100.00 %	$265.00
077313	TYPE: BRAKE HOSELOCATION:FRONT BRAKE:FROM BRAKE MODULATOR VALVEOTHER:3808 FL45.1	30.85	05H3	2	25.00 %	$15.43
077442	TYPE: TORX BOLT - BLACKLOCATION: ROADSIDE & CURBSIDE - KNUCKLE TO CALIPERSIZE: M18 X 1.5 X 60 BLACK	21.00	05H3	10	50.00 %	$105.00
081204	TYPE: CALIPER HEX BOLT (6 PER SIDE)LOCATION: REAR CALIPER - ROADSIDE AND CURBSIDESIZE: M18 X 1.5 X 65	13.25	05H3	12	100.00 %	$159.00

Vehicle Cost Estimate

2026/10/29
CES-008

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/19/2026 7:48:11AM

Detailed Description

4W BRAKE RELINE NEW FLYER 40FT - CALIPER AND CHAMBER PROGRAM

Vehicle Series

NEW FLYER 40FT HYBRID SR2734 7200-7333

Number of Vehicles 134
Estimate Number 4771

Make NEW FLYER
Model XCELSIOR
Year 2022

STOCK CODE	DESCRIPTION	MMS_COST	CC	QTY	USAGE (%)	TOTAL
082519	CLUDES PADS FOR RS & CS - PAD, PIN, WASHER, CLIP, PIN, SPRING, RETAINER, ADAPTER & CAP	264.10	05H3	2	100.00 %	$528.20
083049	TYPE:VALVE ASSEMBLY, BRAKE MODULATOR LOCATION: BRAKE VALVE	234.60	05H3	2	5.00 %	$23.46
083050	TYPE:REAR BRAKE HOSE, 3808 FL 66.19 - MAXI TO SR7 - CS LOCATION: REAR BRAKE	35.19	05H3	1	25.00 %	$8.80
					TOTAL STOCK CODED MATERIALS COST	**$7,233.67**

Non Stock Coded Material List

ORIG. SUPPLIER NUM	ORIG. SUPPLIER NAME	UNIT COST	CC	QTY	USAGE (%)	TOTAL
					TOTAL NON STOCK CODED MATERIALS COST	

Vehicle Cost Estimate

2026/10/29
CES-008

LAST MODIFIED BY: BMOONEY
LAST MODIFIED ON: 6/19/2026 7:48:11AM

Detailed Description

4W BRAKE RELINE NEW FLYER 40FT - CALIPER AND CHAMBER PROGRAM

Vehicle Series

NEW FLYER 40FT HYBRID SR2734 7200-7333

Number of Vehicles 134

Estimate Number 4771

Make NEW FLYER

Model XCELSIOR

Year 2022

Total Rebuilt Material Cost	**$0.00**
Total Stock Coded Material Cost	**$7,233.67**
Total Non Stock Material Cost	**$0.00**
Total Material Cost	**$7,233.67**