



Vehicle Cost Estimate

2026/10/06

CES-007

LAST MODIFIED BY: WPERERA
LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)**Number of Vehicles** 40**Make** ORION**Estimate Number** 207**Model** 6**Year** 1997

LABOUR TASK SUMMARY

<u>Task</u>	<u>CC</u>	<u>Labour Definition</u>	<u>Freq. Of Use</u>	<u>Time</u>	<u>Wrench Time</u>
RE & RE BRAKE SHOES 4 WHEEL	05H3	COACH TECHNICIAN	100 %	12:00	9:15
MATERIAL MOVER FORKLIFT	05H3	MECHANICAL SERVICEPERSON	100 %	0:50	0:38
BRAKE DRUM REPLACEMENT	05H3	MECHANICAL SERVICEPERSON	33 %	1:00	0:46
COMPONENT CLEANING	05H4	COMPONENT CLEANER	100 %	0:50	0:38
				14:40	11:17

LABOUR HOURS SUMMARY

<u>Cost Centre</u>	<u>Total Hours</u>
05H1	0:01
05H3	14:50
05H4	1:10
Total Labour Hours	16:01

MATERIAL COST SUMMARY

<u>Cost Centre</u>	<u>Total Cost</u>
05H1	\$3.03
05H3	\$2,751.08
Total Material Cost (Excl Tax)	\$2,754.11

Labour Total (Incl. Non Productive Adj.):	\$759.80
Labour Overhead	\$554.65

OEM Kit Total (Excluding Tax):	\$0.00
Material Cost (Excluding Tax):	\$2,754.11
Total Material Cost (Excluding Tax):	\$2,754.11

Total Cost (Excluding Tax) :	\$4,068.56
-------------------------------------	-------------------

Tax Total:	\$0.00
-------------------	--------

Total Cost with Tax:	\$4,068.56
-----------------------------	-------------------



Vehicle Cost Estimate

2026/10/06
CES-008

LAST MODIFIED BY: WPERERA

LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)

Number of Vehicles 40

S.O.P. Number DPR-BR02-04

Make ORION

Model 6

Year 1997

Rebuilt Parts Material List

<u>STOCK CODE</u>	<u>DESCRIPTION</u>	<u>UNIT COST</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>TOTAL</u>
011981	CHAMBER	151.25	2	1.00 %	\$3.03
	MAXI-BRAKE, PAINTED " WHITE", TYPE 3075, R				
5H3-06	SHOE	190.61	4	100.00 %	\$762.44
	16.5 X 8.625 INCH ZF CAST BRAKE SHOE				
TOTAL REBUILT PART MATERIALS COST					<u>\$765.47</u>



Vehicle Cost Estimate

2026/10/06
CES-008

LAST MODIFIED BY: WPERERA
LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)

Number of Vehicles 40
S.O.P. Number DPR-BR02-04

Make ORION
Model 6
Year 1997

Stock Coded Material List

STOCK CODE	DESCRIPTION	MMS	COST	CC	QTY	USAGE (%)	CORE COST	TOTAL
010294	COUPLING TYPE: ANGLE REDUCTION, LOCATION: CPL AUTOMATIC LUBRICATION SYSTEM SIZE: 1/8 DEGREES: 90 DEGREE	4.75	05H3		2	1.00 %	\$0.00	\$0.10
015055	CUP TYPE: INNER BEARING LOCATION: REAR HUB, MATES TO 015054-BEARING	41.33	05H3		2	15.00 %	\$0.00	\$12.40
009125	DRUM TYPE: BRAKE LOCATION: REAR AXLE	241.43	05H3		2	100.00 %	\$0.00	\$482.86
010282	EXTENSION et	1.38	05H3		2	1.00 %	\$0.00	\$0.03
010283	EXTENSION TYPE: 1/8 - 1-1/2" LOCATION: CPL AUTOMATIC LUBRICATION SYSTEM	1.22	05H3		4	1.00 %	\$0.00	\$0.05
012055	FITTING TYPE: STRAIGHT GREASE FITTING LOCATION: FOR STEERING/BRAKE COMPONENT SIZE: 1/8" PIPE THREAD SEE CODE: 511816 317086~	0.32	05H3		4	1.00 %	\$0.00	\$0.01
009781	GASKET TYPE: COVER LOCATION: REAR HUB, ORION 6 BUSES	3.92	05H3		2	100.00 %	\$0.00	\$7.84
009140	KIT TYPE: KIT BRAKE SHOE LOCATION: ZF ORION VI REAR AXLE OTHER: BLOCK IS RIVETED TO SHOE	546.48	05H3		2	15.00 %	\$0.00	\$163.94
009698	KIT TYPE: BRAKE ROLLER REPAIR LOCATION: ORION 6 BUSES	127.35	05H3		2	100.00 %	\$0.00	\$254.70
009699	KIT TYPE: BRAKE CAMSHAFT REPAIR LOCATION: ORION 6 BUSES	106.43	05H3		2	33.00 %	\$0.00	\$70.24
026304	LOOM TYPE: PLASTIC SPLIT LOOM DIAMETER: 1/4" DIA	5.32	05H3		1	1.00 %	\$0.00	\$0.05
006881	METER TYPE: WHEEL HUB ODO-METER SIZE: 4" X 4" SPEED: 480 RPM OTHER: TO BE USED WITH MOUNTING BRACKET 610-0011	55.00	05H3		1	1.00 %	\$0.00	\$0.55
009470	NUT TYPE: HALDEX SLACK ADJUSTER BRACKET OTHER: METRIC SIZE: 1" X 1"	0.13	05H3		2	100.00 %	\$0.00	\$0.26



Vehicle Cost Estimate

2026/10/06

CES-008

LAST MODIFIED BY: WPERERA

LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)

Number of Vehicles 40

S.O.P. Number DPR-BR02-04

Make ORION

Model 6

Year 1997

001271	PIN - FS 12015797 & #12015799 WHICH MATES WITHWEATHER PACK SEAL PT. #12015323. FOR ALRV BKA20 HARNESSMETAL: TIN PLATED BRASS	0.19 05H3	4	100.00 %	\$0.00	\$0.76
009135	PLATE TYPE: PLATE ANCHORLOCATION: ZF ORION VI REAR AXLE	2,072.92 05H3	2	1.00 %	\$0.00	\$41.46
009779	PLATE TYPE: REAR BRAKES	29.75 05H3	2	33.00 %	\$0.00	\$19.64
009132	RING TYPE: RING CENTERINGLOCATION: ZF ORION VI REAR AXLE	45.13 05H3	2	1.00 %	\$0.00	\$0.90
009133	RING TYPE: O-RINGSIZE: 224 X 3LOCATION: FOR ZF ORION VI REAR AXLE	103.50 05H3	2	1.00 %	\$0.00	\$2.07
009134	RING TYPE: O-RINGSIZE: 44 X 2LOCATION: FOR ZF ORION VI REAR AXLE	8.57 05H3	2	1.00 %	\$0.00	\$0.17
010339	RING TYPE: O-RINGLOCATION: REAR HUB	1.97 05H3	2	1.00 %	\$0.00	\$0.04
009044	SCREW TYPE: SCREW SHAPE: HEXSIZE: M8 X 14 DIN 933GRADE: 8.8	0.47 05H3	4	1.00 %	\$0.00	\$0.02
016610	SCREW 4~	0.26 05H3	20	100.00 %	\$0.00	\$5.20
762722	SCREW - FS TYPE: SCREW HEX CAP 8.8SIZE: M8 X 20MMTTC DRAWING/SPEC: 21003, SHEET #9	0.09 05H3	2	50.00 %	\$0.00	\$0.09
005845	SEAL SXL wire gauge: 16	0.15 05H3	4	100.00 %	\$0.00	\$0.60
010198	SEAL TYPE: SEALOTHER: REAR AXLE SHAFT	69.12 05H3	2	100.00 %	\$0.00	\$138.24
010338	SEAL TYPE: SEALOTHER: OUTPUT SHAFTLOCATION: REAR BRAKES	19.07 05H3	2	100.00 %	\$0.00	\$38.14
010408	SENSOR TYPE: SENSOR BRAKE FRICTION WEARLOCATION: ORION 6 BUSES	49.17 05H3	2	100.00 %	\$0.00	\$98.34
026363	SHAFT TYPE: OUT PUT SHAFT FORLOCATION: REAR HUB AND DRUM ASSEMBLY ORION 6 ZF LOW FLOOR REAR AXLE.	952.85 05H3	2	1.00 %	\$0.00	\$19.06
010142	SPRING TYPE: SMALLLOCATION: BRAKES	8.51 05H3	2	100.00 %	\$0.00	\$17.02



Vehicle Cost Estimate

2026/10/06
CES-008

LAST MODIFIED BY: WPERERA
LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)

Number of Vehicles 40

S.O.P. Number DPR-BR02-04

Make ORION

Model 6

Year 1997

010143	SPRING TYPE: BRAKESIZE: LARGELOCATION: ORION 6 BUSES	15.52 05H3	2	100.00 %	\$0.00	\$31.04
012292	TUBING TYPE: GREASE TUBINGSIZE: 6MMLOCATIONS: SINGLE CPL AUTOMATIC LUBRICATION SYSTEM	114.12 05H3	1	1.00 %	\$0.00	\$1.14
009045	WASHER TYPE: WASHERLOCATION: SPRING (M8 DIN 7980)	0.18 05H3	4	1.00 %	\$0.00	\$0.01
009136	WASHER TYPE: WASHERLOCATION: LOCATING ZF ORION VI REAR AXLE	1.71 05H3	2	100.00 %	\$0.00	\$3.42
010337	WASHER TYPE: TABLOCATION: REAR BRAKES	7.51 05H3	2	100.00 %	\$0.00	\$15.02
009107	YOKE TYPE: BRAKE CHAMBERLOCATION: YOKE AND CLEVIS PIN ZF	22.02 05H3	2	1.00 %	\$0.00	\$0.44
011129	ADJUSTER TYPE: SLACKSIDE: REAR ZF AXLE	90.84 05H3	2	50.00 %	\$0.00	\$90.84
015053	BEARING TYPE: ASSEMBLY, BEARINGLOCATION: DIFF CARRIER SIDE BEARING	32.53 05H3	2	15.00 %	\$0.00	\$9.76
030379	BEARING TYPE: ROLLER BEARING FOR ZF AXLEOTHER: FLANGE SHAFT REAR (ASSEMBLY CONE 27695 & CUP 27620)	82.63 05H3	2	15.00 %	\$0.00	\$24.79
009100	BRACKET TYPE: WEAR SENSORLOCATION: ZF FRONT AXLE	11.74 05H3	2	1.00 %	\$0.00	\$0.23
013343	BRACKET TYPE: HUBOMETER BRACKET	19.25 05H3	1	1.00 %	\$0.00	\$0.19
009782	CAMSHAFT TYPE: BRAKELOCATION: REAR, ROAD SIDE	586.96 05H3	1	33.00 %	\$0.00	\$193.70
009783	CAMSHAFT TYPE: BRAKELOCATION: REAR, CURB SIDE	588.34 05H3	1	33.00 %	\$0.00	\$194.15
009778	CLIP TYPE: CIRCLIPLOCATION: REAR BRAKES	2.47 05H3	8	100.00 %	\$0.00	\$19.76
017906	CLIP TYPE: RING, TO RETAIN ORION 6 ZF REAR AXLE BRAKE SHOE WEAR SENSORS MATERIAL: BRASS	2.29 05H3	2	100.00 %	\$0.00	\$4.58
017907	CLIP TYPE: TO RETAIN ORION 6 REAR AXLE BRAKE SHOE WEAR SENSORS INTO SHOE	0.85 05H3	2	100.00 %	\$0.00	\$1.70
015054	CONE TYPE: INNER BEARINGLOCATION: REAR HUB	64.96 05H3	2	15.00 %	\$0.00	\$19.49



Vehicle Cost Estimate

2026/10/06
CES-008

LAST MODIFIED BY: WPERERA

LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)

Number of Vehicles 40

S.O.P. Number DPR-BR02-04

Make ORION

Model 6

Year 1997

001275	CONNECTOR AMPSOTHER: PT.#12010182 OR #12033674 WHICH MATES WITH CAVITY PT.#12010973RELATED TTC SC: 036923, 001271, 005843MATERIAL: NYLON	0.75	05H3	2	100.00 %	\$0.00	\$1.50
001276	CONNECTOR ATERIAL: DOUBLE NYLON CAVITYAMPERAGE: MAX CURRENT 20 AMPSRELATED TTC SC: 036922, 001272, 005844	0.50	05H3	2	100.00 %	\$0.00	\$1.00
010285	CONNECTOR TYPE: 1/8 PIPE COUPLINGLOCATION: CPL AUTOMATIC LUBRICATION SYSTEM	1.51	05H3	4	1.00 %	\$0.00	\$0.06
010286	CONNECTOR TYPE: ANGLE 1/8-6MM CONNECTORLOCATION: CPL AUTOMATIC LUBRICATION SYSTEMSIZE: 1" X 2"	9.66	05H3	4	1.00 %	\$0.00	\$0.39
010287	CONNECTOR TYPE: STRAIGHT 1/8-6MMLOCATION: CPL AUTOMATIC LUBRICATION SYSGTEM	7.65	05H3	2	1.00 %	\$0.00	\$0.15
010288	CONNECTOR TYPE: STRAIGHT MALELOCATION: M6-6MM TUBING CPL AUTOMATIC LUBRICATION SYSTEM	9.84	05H3	2	1.00 %	\$0.00	\$0.20
010289	CONNECTOR TYPE: TUBING 6 MMLOCATION: CPL AUTOMATIC LUBRICATION SYSTEM	0.65	05H3	2	1.00 %	\$0.00	\$0.01
012051	CONNECTOR TYPE: STRAIGHT, M6-6MM LININGLOCATION: CPL AUTOMATICE LUBRICATION SYSTEM	12.19	05H3	2	1.00 %	\$0.00	\$0.24
010293	COUPLING TYPE: ANGLE REDUCTION,LOCATION: CPL AUTOMATIC LUBRICATION SYSTEMSIZE: 1/8-1/4	2.64	05H3	2	1.00 %	\$0.00	\$0.05
TOTAL STOCK CODED MATERIALS COST							\$1,988.64

Non Stock Coded Material List

<u>ORIG. SUPPLIER NUM</u>	<u>ORIG. SUPPLIER NAME</u>	<u>UNIT COST</u>	<u>CC</u>	<u>QTY</u>	<u>USAGE (%)</u>	<u>CORE COST</u>	<u>TOTAL</u>
TOTAL NON STOCK CODED MATERIALS COST							



Vehicle Cost Estimate

2026/10/06

CES-008

LAST MODIFIED BY: WPERERA

LAST MODIFIED ON: 7/3/2008 7:55:55AM

Detailed Description

2W REAR BRAKE RELINE ORION 6 LF CNG

Vehicle Series

ORION6 CNG LF (9200-9249)

Number of Vehicles 40

S.O.P. Number DPR-BR02-04

Make ORION

Model 6

Year 1997

Total Rebuilt Material Cost	\$765.47
Total Stock Coded Material Cost	\$1,988.64
Total Non Stock Material Cost	\$0.00
Total Material Cost	\$2,754.11
Total Core Cost	\$0.00
Total Material Cost	\$2,754.11