

Day Shift

* J. Pronovost ▼

Signed

Jean Pronovost

Grinding Line 1

Tonnes Milled 129 Balls added 37%

SAG 37%

BM: Rec 37%

Pur: Rec 37%

New 37%

Downtime

Incidents / Accidents - Nil

Primary air compressor inspection and restart procedure training completed Crew 100

Incidents / Safety Notifications

Incidents / Accidents - Nil

Primary air compressor inspection and restart procedure training completed Crew 100

Next

Day Shift

* J. Pronovost T

Signed

Jean Pronovost

Grinding Line 2

Tonnes Milled 129

Balls added 37%

SAG 37%

BM: Rec 37%

Pur: Rec 37% New

37%

Downtime

Incidents / Accidents - Nil

Primary air compressor inspection and restart procedure training completed Crew 100

Incidents / Safety Notifications

Incidents / Accidents – Nil

Primary air compressor inspection and restart procedure training completed Crew 100

Next

Day Shift

* J. Pronovost ▼

Signed

Jean Pronovost

Gravity Line 1

Falcons Running

2

1

Falcons on Mtce

Falcons Spares

3

3

Gravity Line 2

Falcons Running

Falcons Spares

Falcons on Mtce

2

1 2 3

Incidents / Safety Notifications


Incidents / Accidents - Nil

Primary air compressor inspection and restart procedure training completed Crew 100

Incidents / Safety Notifications

Incidents / Accidents – Nil

Primary air compressor inspection and restart procedure training completed Crew 100



Day Shift

* J. Pronovost

Signed

Jean Pronovost

Elution

Incidents /	Safety	Notifica	ations

Incidents / Accidents – nil

Acid Wash	Empty -
Strip Vessel 1	Loaded ▼
Kiln Hopper 1	45%
Quench 1 Level	35%
Strip Vessel 2	Empty ~
Kiln Hopper 2	29%
Quench 2 Level	35%

•

Day Shift

* J. Pronovost ▼

Signed

Jean Pronovost

REAGANTS

CuSo4 Bags Mixed	0
#NaCN Isotainers Mixed	0
Floc Bags Mixed	0
Lime Silo Level	35%
Cyanide Distribution LevI	45%
SO2 Tank 1 Level	50%
Antiscalant Tank Level	25%
Caustic Tank Level	78%
SO2 Tank 2 Level	35%

Incidents / Safety Notifications

Nil Report

Next

