

INSP-2026-003 — Internal Inspection Finding

Site: Ardley Park **Equipment:** GRN-2100 **Document type:** inspection finding **Revision:** Rev 1 **Status:** OPEN

Synthetic document created for demonstration purposes. Fictional site, equipment, and finding. Contains no patient, proprietary, or personally identifiable information. This file is a PDF so that the Mistral OCR ingestion path is exercised end to end.

1. Finding

During the internal quality systems audit conducted 2026-04-15, the auditor identified that the controlled document system contained two concurrently effective revisions of SOP-CL-004 (Rev 3, effective 2025-08-12 and Rev 4, effective 2026-03-02), with neither marked as superseded.

2. Classification

Field	Value
Finding reference	INSP-2026-003
Audit	Internal quality systems audit, 2026-04-15
Auditor	Quality Assurance, Ardley Park
Classification	Major
Affected equipment	GRN-2100, Line 2 Granulation
Status	OPEN
Linked records	DEV-2026-047, CAPA-2026-019, CC-2026-011

3. Requirement Not Met

The site document control procedure requires that, on the effective date of a new revision, the preceding revision is marked superseded and withdrawn from point of use. This was not performed when SOP-CL-004 Rev 4 was issued.

4. Observed Consequence

The two revisions specify materially different cleaning requirements. It is therefore not established which requirements applied to cleaning operations performed on GRN-2100 after 2026-03-02.

Requirement	Rev 3	Rev 4
Maximum clean hold time	72 hours	120 hours
Swab sampling locations	6	4

5. Response Required

A formal response is required within 30 days of the finding date. **No response has been received at the time of this record.** The finding remains open and the associated CAPA-2026-019 is overdue.

6. Note

This finding does not constitute a determination of regulatory compliance or non-compliance. Assessment of product impact and of any reporting obligation rests with qualified quality personnel.