
Analysis of Structures (Frames)

Vector Mechanics-Chapter 6

Part - 3: Frames

Truss and Frames

Two force members



Multi force members





Illustration through example




Members ACE and BCD are connected by a pin at C and by the link DE.

Determine:


- 1) the force in link DE
- 2) the components of the force exerted at C on member BCD.

Illustration through example




 $\Sigma \mathbf{F} = 0$ $\Sigma \mathbf{M} = 0$

Analysis through example



Analysis through example



Design analysis of a simple frame is demonstrated