

Maintenance Record

Valve inspection completed on 2026-05-14.

Valve pressure rose to 18 kPa Replacement gasket fitted.

Inspect the eastern line.

Safety review¹

Archive referenceⁱ

1 Pressure was measured with a synthetic test gauge.

- i Record generated for CC0 parser fixtures.