दूरभाष /Tele: 248306

सम्मिश्र जांच दल/ Composite Trials Team द्वारा नेवी कार्यालय/ c/o Navy Office मुख्यालय/ Headquarter अन्डमान एवं निकोबार कमान/ Andaman & Nicobar Command पोर्ट ब्लेयर/ Port Blair - 744 102

CTT/300/11/03/TECH

20 Jan 23

The Commander - in - Chief {for CTO(Marine)/ SSO(Refit)} Headquarters Andaman & Nicobar Command Port Blair – 744 102

## STAFF SEA CHECKS STAGE - I (INS CORADIVH)

- 1. Refer to ANCO (Tech) chapter 5 (Art 0508(a)) regarding Post Refit Trials.
- 2. Updated Staff Sea Checks Stage I report as on 20 Jan 23 is forwarded herewith as **Enclosure**.

(जगन्नाथ गूरुमूर्ति /Jagannath Gurumurthy) लेफ़्टिनेंट कमांडर / Lieutenant Commander प्रभारी अधिकारी/ Officer-in-Charge(AOL)

## Copy to:-

The Commodore Superintendent {for DGM (Refit)} Naval Ship Repair Yard c/o Navy Office Port Blair – 744 102

The Naval Component Commander {for SSO(Tech)} c/o Navy Office Andaman & Nicobar Command Port Blair – 744 102

The Commanding Officer INS Cora Divh c/o Navy Office Port Blair-744 102

## SSC-I REPORT- INS CORA DIVH REPORT BY CTT (Pbr) - AS ON 20 JAN 23

## Status of Machinery Equipment:-

Ser.	Machinery/ Equipment		hecks oleted	Sat/Unsat/ Sub-Optimal	<u>Remarks</u>
Pil.		Yes	No		
1.	Stbd Main Engine	1		SAT(WITH OBS)	Cold and Hot SDC from 27-28 Dec 22.  GB LO pressure low alarm operated at 0.2 bar instead of 0.3 bar.
2.	Port Main Engine	1		SAT(WITH OBS)	Cold and Hot SDC on 27-28 Dec 22. Following observed: -  (a) GB LO pressure low alarm operated at 0.2 bar instead of 0.3 bar.  (b) Push button of 'ready for operation' in LOP Non Ops.
3.	Centre Main Engine	√ 	Valori	SAT(WITH OBS)	Cold and Hot SDC on 27-28 Dec 22. Following observed: -  (a) GB LO pressure low alarm operated at 0.2 bar instead of 0.3 bar.  (b) Visual alarm Non Ops.
4.	Diesel Alternator (Stbd) (80 kW)	1		UNSAT	Hot SDC on 10 Nov 22 and Load trial on 27 Dec 22. Following observed: -  (a) Engine free end axial & vertical and engine driven end horizontal vibration UNSAT.  (b) Calibration certificate not available for meters in SWBD.
	Diesel Alternator (Port) (80 kW)	1		UNSAT	Cold SDC carried out on 03 Nov 22 and Hot SDC on 21 Nov 22 & Load trial on 08 Jan 23. Following observed: -  (a) Engine free end vertical and engine driven end horizontal vibration UNSAT.  (b) Calibration certificate not available for meters in SWBD.

Ser.	Machinery/ Equipment	Cold checks completed		Sat/Unsat/ Sub-Optimal	<u>Remarks</u>
		Yes	No	*	
5.	Diesel Alternator (Centre) (80 kW)	٧		SAT (WITH OBS)	SDC carried out on 05 Dec 22 and load trial on 12 Dec 22. Following observed: -  (a) Emergency stop push button cover not held.
					<ul> <li>(b) Attenuation checks across two mounts at 100% load UNSAT.</li> <li>(c) Minor sea water leakage observed from sea water pump.</li> <li>(d) Calibration certificate not available for meters in SWBD.</li> </ul>
6.	AC Plant No.1	1		514 D 3 187	SDC carried out on 28 Nov 22. Following observed: -  (a) Calibration certificate of
7.	AC Plant No.2	√ *		SAT(WITH OBS)	<ul> <li>(a) Calibration certificate of instrumentation not held.</li> <li>(b) Sea water pump safety guard not fitted.</li> <li>(c) Condenser relief valve calibration certificate of both ACs not held.</li> </ul>
8.	HP Air compressor Port		1	60 T 183	Not offered by SS.
9.	HP Air compressor Stbd		1		Not offered by SS.
10.	RO plant		1	47)	Not offered by SS.
11.	Fire Main pump No.1 & 2		1	90 72 De	Not offered by SS.
12.	Salvage Pump No 1 & 2		1		Not offered by SS.
13.	Bilge Pump No 1	57,000	1		Not offered by SS.
14.	Fresh water pump no. 1&2	17.	1		Not offered by SS.
15.	Dirty oil transfer pump	- Lotte	1		Not offered by SS.
16.	Fuel oil transfer pump		1	KA-	Not offered by SS.

	Equipment	completed		Sub-Optimal	
		Yes	No		
17.	Fuel centrifuge no. 1 & 2		√ ,		Not offered by SS.
18.	Misc. observation	-	_	aNico.	Inter cooler line of HP air compressor not secured.
19.	Basin trial	-	-		Basin trial of all three Main Engines conducted on 04 Jan 23. Following observed: -  (a) Exhaust flap position indication of SME non-ops, sensor defective.  (b) Minor lub oil leakage from lub oil filter of CME.  (c) Corrosion on auxiliary system pipelines of all three MEs.  (d) Stbd shaft plummer block temperature indication non-ops.  (e) Sea Water leakage from thermometer of Fresh Water of cooler discharge line of PME.