दूरभाष /Tele: 248306

सम्मिश्र जांच दल/ Composite Trials Team द्वारा नेवी कार्यालय/ C/o Navy Office मुख्यालय/ Headquarter अन्डमान एवं निकोबार कमान/ Andaman & Nicobar Command पोर्ट ब्लेयर/ Port Blair - 744 102

CTT/300/03/13/TECH

17 Jan 23

The Commander-in-Chief {for CTO(Marine)/SSO(Refit)} Headquarters Andaman & Nicobar Command Port Blair – 744 102

SAFETY DEVICE CHECKS - IN LCU L 55

- 1. IN LCU 55 is currently undergoing Short Refit. Cold and Hot SDCs of DA No 3 were undertaken on 10 and 16 Jan 23 respectively.
- 2. <u>Observations</u>. Detailed report is placed at **Enclosure** to this letter. Following are the salient observations:-
 - (a) Bilge plates not secured.
 - (b) Bilge hygiene not maintained.
 - (c) Vacuum indicator not visible clearly.
- 3. It is requested that observations mentioned above be liquidated.

(जगन्नाथ गूरुमूर्ति /Jagannath Gurumurthy) लेफ़्टिनेंट कमांडर / Lieutenant Commander प्रभारी अधिकारी/ Officer-in-Charge(AOL)

Encl. As above

Copy to.

The Commodore Superintendent {for DGM (Refit)} Naval Ship Repair Yard C/o Navy Office Port Blair – 744 102

The Naval Component Commander {for SSO(Tech)} Headquarters Naval Component c/o Navy Office Port Blair – 744 102

The Commanding Officer IN LCU L 55 C/o Navy Office Port Blair – 744 102

SAFETY DEVICE CHECKS - IN LCU 55

1. Trial Inspectors : (a) Vipin Kumar, ERA-3

(b) Ambesh Kumar, LME

2. Date and Time : (a) 10 Jan 23 (1100 - 1330 Hrs)

(b) 16 Jan 23 (1000 - 1245 Hrs)

3. Details of DG No 3 SDCs are as follows: -

Ser	Description	Unit	Design Value	DA 3 (350 KW)	Remarks
(i)	Low LO Pr Alarm	Bar	1.2	1.2	SAT
(ii)	Low LO Pr Trip	Bar	0.8	0.8	
(iii)	High FW temp Alarm	°C	90 ± 2	91	
(iv)	High FW temp Trip	°C	96 ± 2	97	
(v)	High LO temp Alarm	°C	120	119	
(vi)	Crash stop Local		Ops/ Non-ops	Ops	
(vii)	Crash stop Remote	-	Ops/ Non-ops	Ops	
(viii)	Low SW Pressure Alarm	Kg/cm ²	0.2	0.2	
(ix)	High Exhaust temp alarm	°C	575	575	
(x)	Over Speed Trip	RPM	1650	1650	