

**FIGURE 3.17 Floating-point multiplication.** The normal path is to execute steps 3 and 4 once, but if rounding causes the sum to be unnormalized, we must repeat step 3. Copyright © 2009 Elsevier, Inc. All rights reserved.