

Sub-Assembly Index				
Index	Operation	Part Name	Part No.	Rev.

Evaluation Warning : The document was created with Spire.XLS for Python

Assembly Pic	Remarks

Evaluation Warning : The document was created with Spire.XLS for Python

OP-30						Painting (DOOR, ASSY, LH, 952NX-92244728) (Power Tan -Std-86628042)			
10		▶			Transportation to pretreatment (Material through trolley)	Transport Trolley	Sub Assemblies : OP-10 B,OP-20-1Nos		USE METALIC TROLLY FOR DOOR MOVEMENTS
20	●				Knock of Degrease	Tank			Chemical Name : 1. Bondrite AK - 5055 (Make-Henkel) 2. Bondrite C-AD 550 (Make-Henkel)
30	●				Degrease	Tank			Chemical Name : 1. Bondrite AK - 5055 (Make-Henkel) 2. Bondrite C-AD 550 (Make-Henkel)
40	●				Water Rinse 1	Tank			Chemical Name : Industrial Water (Make-AKVN)
50	●				Water Rinse 2	Tank			Chemical Name : Industrial Water (Make-AKVN)
60	●				Surface Activation	Tank			Chemical Name : 1. Bondrite AC 50 (Make-Henkel) 2. Neutralizer 565 (Make-Henkel) 3. DM Water
70	●				Phosphate	Tank			Chemical Name : 1. Bondrite mad-131 (Make-Henkel) 2. Bondrite 2030 A (Make-Henkel) 3. Bondrite 2030 E (Make-Henkel) 4. Neutralizer 565 (Make-Henkel) 5. Bondrite C 16 (Make-Henkel)
80	●				Water Rinse 03	Tank			Chemical Name : DM Water (Make-Inhouse)
90	●				Water Rinse 04	Tank			Chemical Name : DM Water (Make-Inhouse)
100	●				PTRCDM	Tank			Chemical Name : DM Water (Make-Inhouse)
110	●				CED Coating	Tank			Chemical Name : 1. Additive - M (Make-Burger) 2. Additive - S (Make-Burger) 3. HG 350 E Pigment Paste F-1 (Make-Burger) 4. HG 350 E Resin Emulsion F-2 (Make-Burger)
120	●				Ultra Filtration	Tank			Use DM Water to remove extra paint form part surfaces
130	●				EDRCDM	Tank			Chemical Name : DM Water (Make-Inhouse)
140	●				Unloading	Through Crane			UNLOADING THE DOOR AFTER CED COMPLITION.
150	●				Baking	Ovan			Chemical Name : PNG (Make-Avantika)
160	●				Putty Application & Finishing	Manual / Sander			PUTTY APPLICATION TO BE DONE FOR PROPER FINISHING OF THE DOOR SURFACES AND FINISH THE SURFACES WITH EMERY PAPER AND SANDERING
170	●				Cleaning				1.AIR CLEANING 2.TAGORAT CLEANING

Evaluation Warning : The document was created with Spire.XLS for Python

180			■		Inspection (Quality Gate No.-2 & 3)				1. SEALANT APPLICATION INSPECTION. 2. BEFORE TOP COAT INSPECTION.
190	●				Final Paint	Paint Spray Gun			1.APROVED SOURCE PAINT WILL BE USED ONLY. 2.PAINT, HARDENER AND THINNER MIXTUR AS PER WORK INSTRUCTION
200	●				Baking	Oven			1.TEMPERATURE TO BE MAINTAIN AS PER WORK INSTRUCTION 2.BACKING TIME TO BE FOLLOWED AS PER WORK INSTRUCTION
210			■		Inspection (Quality Gate No.-4)				AFTER TOP COAT INSPECTION
220				▼	Storage	N/A			STORE ALL MATERIALS AT IDENTIFIED STORE LOCATION
230		▶			Move to next process	N/A			MOVE SUB ASSEMBLY IN DECIDED STATION FOR NEXT PROCESS
OP-40						FINAL ASSEMBLY (92187158-DOOR, ASSY, LH, 952NX) Rev-C			
10	●				Child part collection	N/A	Sub Assemblies : OP-30 Part No. : 92244737		1.ENSURE ALL CHILD PARTS AVAILABILITY. 2.ENSURE ALL PARTS ARE OK
20				▼	RUBBER TRACK, BEADING-ASSEMBLY	N/A			1.ENSURE RUBBER TRACK, BEADING PROPER FIT 3.ENSURE RUBBER TRACK, BEADING WILL DO IN SPECIFIED AREA. 4.OK PARTS MOVED FOR FINAL INSPECTION 5.NOT OK MATERIAL TO BE REWORK AND THEN SEND FOR FINAL INSPECTION 6.REJECTED MATERIAL TO BE REJECT AND THEN SEND IN SCRAP AREA.
30		▶			Move for Next Process				MOVE SUB ASSEMBLY IN DECIDED STATION FOR NEXT PROCESS
OP-50						FINAL INSPECTION (92187158-DOOR, ASSY, LH, 952NX) Rev-C			
10			■		Inspection (Quality Gate no.-5)	Check Sheets / Measuring Instruments			1. PART FITMENT INSPECTION OF THE DOOR ASSEMBLY.
20	●				Finishing/Cleaning	Cleaner / Cloths			1.ENSURE NO EXTRA WELDING OR WELDING MISSING ON DOOR.
30	●				PDI	PDI Check Sheet			1.FINAL INSPECTION OF THE DOOR AS PER PDI CHECK SHEET 2.PAST OK STICKER IN DOOR ASSY AND THEN MOVE THE DOOR FOR DISPATCH 3.NOT OK DOOR ASSY SEND FOR REWORK
40		▶			Move To Dispatch	N/A			DOOR ASSY TO BE DISPATCH AS PER PACKAGING STANDARD
CFT Team Members									
Prepared By:	Development		Production		Quality		Purchase		Approved By :
Revision History									
Date	Revision Number		CHANGES				Prepared By		Approved By
s			Initial for revision no.						
MAPL/PPW/CNH/PFD/92187158/SA						Note :- Refer next PFD's of Q - Sheetmetal Parts, R - Tubular Parts, S - Round Tube, Bars & Angles, T - BOP & Hardwares.			

Evaluation Warning : The document was created with Spire.XLS for Python

10	●			Raw Material Procurement	N/A	Sheetmetal Parts : 92187151-1Nos 92187148-1Nos 92187147-1Nos 92281502-1Nos 92187149-1Nos 92187145-1Nos 92218240-1Nos 92218241-1Nos 92217650-1Nos 92217651-1Nos 92217652-1Nos 92281539-1Nos	1.BUGHT ALL MATERIALS FROM APPROVED SOURCE ONLY 2.APPROVED SOURCE MATERIAL WILL MOVE IN RQC FOR INSPECTION 3.REJECTED AND SEND BACK MATERIAL TO SUPPLIER AND INFORM TO PURCHASE IF ANY MATERIAL RECEIVED FROM NON-APPROVED SOURCE	
20		■		Incoming Inspection	Measuring Instruments	Sheetmetal Parts : 92187151-1Nos 92187148-1Nos 92187147-1Nos 92281502-1Nos 92187149-1Nos 92187145-1Nos 92218240-1Nos 92218241-1Nos 92217650-1Nos 92217651-1Nos 92217652-1Nos 92281539-1Nos	1.INCOMING OF MATERIAL 2.MATERIAL OFFER TO RQC 3.QUALITY INSPECTION FOR INCOMING PARTS 4.OK MATERIAL MOVED TO STORE 5.REJECTED MATERIAL SEND TO SUPPLIER END. 6.IF ANY REWORK FOUND THEN INFORM TO SUPPLIER FOR REWORK AND AFTER REWORK INSPECTION WILL BE DONE FOR 100% PARTS BY RQC	
30			▼	STORAGE		Parts List for Storage : 92187151-1Nos 92187148-1Nos 92187147-1Nos 92281502-1Nos 92187149-1Nos 92187145-1Nos 92218240-1Nos 92218241-1Nos 92217650-1Nos 92217651-1Nos 92217652-1Nos 92281539-1Nos	1.STORE ALL MATERIALS AT IDENTIFIED STORE LOCATION 2.ENSURE STORAGE AREA SHOULD BE FREE FROM MOISTURE AND DUST 3.FIFO TO BE MAINTAIN	
40	●			Laser Cutting	Laser Cutting m/c	Laser Cutting Parts List : 92187151-1Nos 92187148-1Nos 92187147-1Nos 92281502-1Nos 92187149-1Nos 92187145-1Nos 92218240-1Nos 92218241-1Nos 92217650-1Nos 92217651-1Nos 92217652-1Nos	1.USE OF APPROVED DXF PROGRAM AS PER CURRENT REVISION LEVEL FOR LASERCUTTING. 2.LASERCUTTING. MACHINE PM AS PER PM PLAN. 3.OK MATERIAL MOVED IN NEXT PROCESS. 4.MOVED REJECTED MATERIAL IN SCRAP AREA.	
50	●			Oxy Cutting	Oxy Cutting m/c	Oxy / Plasma Cutting Parts List : 92281539-1Nos	1.USE OF APPROVED DXF PROGRAM AS PER CURRENT REVISION LEVEL FOR OXYCUTTING. 2.OXYCUTTING MACHINE PM AS PER PM PLAN. 3.OK MATERIAL MOVED IN NEXT PROCESS. 4.MOVED REJECTED MATERIAL IN SCRAP AREA.	
60	●			Drilling	Drilling M/C.	Drilling Parts List : 92187145-1Nos 92281539-1Nos	ENSURE DRILLING PARAMETERS BEFORE DRILLING	
70	●			Tapping	Tapping done by Manual	Tapping Parts List : 92187145-1Nos 92281539-1Nos	ENSURE TAPPING PARAMETERS BEFORE TAPPING	
80	●			Chamfer	Bevel Chamfering M/C.	Chamfering Parts List :	ENSURE CHAMFERING PARAMETERS BEFORE CHAMFERING	
90	●			Straightening	Rolling M/C.	Straightening Parts List :	ENSURE STRAIGHTENING SETTING IS OK	
100	●			Bending/ Forming	CNC Press Brake Bending / Roll Bending	Bending Parts List : 92187148-1Nos 92187147-1Nos 92281502-1Nos 92218240-1Nos 92217650-1Nos	1.BENDING MACHINE PM AS PER PM PLAN. 2.OK MATERIAL MOVED IN NEXT PROCESS. 3.NOT OK MATERIAL REWORK TO BE DONE AND THEN INSPECTION. 4.REJECTED MATERIAL MOVED IN SCRAP AREA.	
110			▼	Storage	N/A	Parts List for Storage : 92187151-1Nos 92187148-1Nos 92187147-1Nos 92281502-1Nos 92187149-1Nos 92187145-1Nos 92218240-1Nos 92218241-1Nos 92217650-1Nos 92217651-1Nos 92217652-1Nos 92281539-1Nos	STORE ALL MATERIALS AT IDENTIFIED STORE LOCATION	
120		▶		Move for Next Process	N/A		MOVE ALL MATERIALS IN DESIDED STATION FOR WELDMENT ASSEMBLY	
CFT Team Members								
Prepared By:		Development		Production		Quality	Purchase	Approved By :
Revision History								
Date	Revision Number	CHANGES				Prepared By		Approved By
		Initial for revision no.						

Evaluation Warning : The document was created with Spire.XLS for Python

Evaluation Warning : The document was created with Spire.XLS for Python

	METALMAN AUTO PVT LTD.						Format No. : F/NPD/06				
	PLOT NO. 116, SECTOR-3 PITHAMPUR						Released on :-				
	PROCESS FLOW DIAGRAM						Revised on :-				
							Revision No. :-				
Part Description		DOOR PWRTAN, LH, 952NX		Part Number		92187158		Revision Number :-			
Core Team								Rev. Date		23-04-2026	
								Last Review Date		23-04-2026	
Operation No	OPERATION	MOVEMENT	INSPECTION	STORE	Operation Description	Machine, Device, Jig, Tools for mfg	T - BOP & Hardwares				
								Part Number	92187158		
10	●				Brought-out Material Procurement	N/A	BOP Part No. : 90451393-3Nos 92244737-2Nos		1.BOUGHT ALL MATERIALS FROM APPROVED SOURCE ONLY 2.APPROVED SOURCE MATERIAL WILL MOVE IN RQC FOR INSPECTION 3.REJECTED AND SEND BACK MATERIAL TO SUPPLIER AND INFORM TO PURCHASE IF ANY MATERIAL RECEIVED FROM NON-APPROVED SOURCE		
20	●				INCOMING MATERIAL Standard Hardwares-Bolts/Screws/Rivit/Hinge)	Measuring Instruments	BOP Part No. : 90451393-3Nos 92244737-2Nos		1.INCOMING OF MATERIAL 2.MATERIAL OFFER TO RQC 3.QUALITY INSPECTION FOR INCOMING PARTS 4.OK MATERIAL MOVED TO STORE 5.REJECTED MATERIAL SEND TO SUPPLIER END. 6.IF ANY REWORK FOUND THEN INFORM TO SUPPLIER FOR REWORK AND AFTER REWORK INSPECTION WILL BE DONE FOR 100% PARTS BY RQC		
					Sheet Metal	Measuring Instruments					
30				▼	Storage	N/A	For all				
40		▶			Move for Next Process	N/A	For all				
		CFT Team Members									
		Development		Production		Quality		Purchase		Approved By :	
Prepared By :											
Revision History											
Date		Revision Number		CHANGES				Prepared By		Approved By	
				Initial for revision no.							
MAPL/PPW/CNH/PFD/92187158/T						Note :- Refer next PFD's of Q - Sheetmetal Parts, R - Tubular Parts, S - Round Tube, Bars & Angles, T - BOP & Hardwares.					

Evaluation Warning : The document was created with Spire.XLS for Python

Spire.XLS for Python
e-iceblue Inc. 2002-2026 All rights reserved

Home page
<https://www.e-iceblue.com>

Contact US
<mailto:support@e-iceblue.com>

Buy Now!
<https://www.e-iceblue.com/Buy/Spire.XLS-Python.html>

Evaluation Warning : The document was created with Spire.XLS for Python