
Procedure of Biolyte 2000 Transfer Data to Computer


Requirement:

 RS232 Cable (Female 9-PIN and male 25-PIN), or 1 male 25-PIN cable with an adapter.





2. HyperTerminal Program.



Procedure:

1. Connect Computer with Biolyte 2000 (RS232 Cable)








2. Run HyperTerminal program.



3. Choose the correct path (COM1 or COM2)



4. Speed is 9600 bps.



5. Run Data Transfer.

(Path: Menu →3.Data →2.Transfer)

Then you will see this screen.

6. When data are transferring press **ALT + 6 (Numerical Keyboard)** to receive each data.



7. You can find the result on your PC monitor.

