


Reproducibility is engineered along the whole measurement chain



A single pass through this chain is one measurement of the measurand.

Three reproducibility checks apply to the whole chain

