

Op	T ₀ (cm)	✓	Suplementos	T _A (cm)	^{REDONDEO} T _A (cm)	T _A (min)
3	230	90	1, 11	229,77	230	2,3
4	228	90	1, 11	227,772	228	2,28
5	197	90	1, 11	196,803	197	1,97
6	245	100	1, 11	271,95	272	2,72
7	200	110	1, 11	244,2	245	2,45

$$100 \text{ cm} = 1 \text{ min}$$

Capacidades

• Soldadura = $33,33 \frac{\text{pz}}{\text{hs}}$

• Puesto 1: $\text{Op 3} = 2,3 \text{ min/pz}$
 $\text{Op 4} = 2,28 \text{ min/pz}$

$$2,3 \text{ min} \text{ — } 1 \text{ pz}$$

$$60 \text{ min} \text{ — } x = 26,07 \frac{\text{pz}}{\text{hs}}$$

• Puesto 2: $\text{Op 5} = 1,97 \text{ min/pz}$
 $\text{Op 6} = 2,72 \text{ min/pz}$

$$2,72 \text{ min} \text{ — } 1 \text{ pz}$$


$$60 \text{ min} \text{ — } x = 22,06 \frac{\text{pz}}{\text{hs}}$$

$$x = 22,0588... \text{ hs}$$

• Puesto 3: $\text{Op 7} = 2,45 \text{ min/pz}$

$$2,45 \text{ min} \text{ — } 1 \text{ pz}$$

$$60 \text{ min} \text{ — } x = 24,49 \frac{\text{pz}}{\text{hs}}$$



Capacidades

$$33,33 \frac{\text{pz}}{\text{hs}}$$

$$26,07 \frac{\text{pz}}{\text{hs}}$$

$$22,05882353...$$

$$22,06 \frac{\text{pz}}{\text{hs}}$$

$$24,49 \frac{\text{pz}}{\text{hs}}$$

La capacidad más baja = CB

dictará el ritmo de producción

Producción diaria máxima: $22,05882353...$

$$22,06 \frac{\text{pz}}{\text{hs}} \cdot 24 \text{ hs} = 529,44$$

$$529,4417...$$

$$\Rightarrow 529 \frac{\text{pz}}{\text{día}}$$