

```

Load impedance = 100.000000 angle 30 degrees ohms
-Point of attachment = 43.500000 cms
-Length of the short circuited stub = 202.000000 cms
-----
Load impedance = 150.000000 angle 30 degrees ohms
-Point of attachment = 48.100000 cms
-Length of the short circuited stub = 189.000000 cms
-----
Load impedance = 200.000000 angle 30 degrees ohms
-Point of attachment = 51.100000 cms
-Length of the short circuited stub = 182.000000 cms
-----
Load impedance = 250.000000 angle 30 degrees ohms
-Point of attachment = 53.200000 cms
-Length of the short circuited stub = 177.000000 cms
-----
Load impedance = 300.000000 angle 30 degrees ohms
-Point of attachment = 54.900000 cms
-Length of the short circuited stub = 174.000000 cms
-----
Load impedance = 350.000000 angle 30 degrees ohms
-Point of attachment = 56.300000 cms
-Length of the short circuited stub = 172.000000 cms
-----
-->

```

```

Characteristic impedance = 600.000000 ohms
-Point of attachment = 18.500000 cms
-Length of the short circuited stub = 128.000000 cms
-----
Characteristic impedance = 800.000000 ohms
-Point of attachment = 16.200000 cms
-Length of the short circuited stub = 132.000000 cms
-----
Characteristic impedance = 1000.000000 ohms
-Point of attachment = 14.600000 cms
-Length of the short circuited stub = 134.000000 cms
-----
Characteristic impedance = 1200.000000 ohms
-Point of attachment = 13.400000 cms
-Length of the short circuited stub = 135.000000 cms
-----
Characteristic impedance = 1400.000000 ohms
-Point of attachment = 12.500000 cms
-Length of the short circuited stub = 137.000000 cms
-----
Characteristic impedance = 1600.000000 ohms
-Point of attachment = 11.700000 cms
-Length of the short circuited stub = 138.000000 cms
-----
Characteristic impedance = 1800.000000 ohms
-Point of attachment = 11.100000 cms
-Length of the short circuited stub = 138.000000 cms
-----
--> |

```