irq: Original Run Fails with a Timeout

PHASE	TEST	STATUS
Phase 2	irq	FAIL (timeout)




Figure 9. Terminal output of make clean; make in tests-standalone/irq

What this shows

- The testbench printed `Monitor: Timeout, Test IRQ (RTL) Failed` at 1,249,987,500 ps (about 1.25 ms), `irq_tb.v` line 63.
- The limit is the same 50 x 1000 cycles as in the timer test, but the cause is different (see the next two images).

Conclusion. The test did not finish in time. Status: FAIL, cause not yet resolved.