






rust + ESC



ster + ESC





pH Sensor



Buc









Buck (Vbat -> 3.3V)

Battery(Vbat)

