Internal Memo: New Limits on Remote Fault Resets and Return to Service

Rongnam Lift Engineering Co., Ltd., Hat Yai · Ref. RLE-OPS-MEMO-2026-11 · 21 September 2026

To: All dispatchers, field technicians, field supervisors and contract managers
From: Narumon Kaewprasert, Head of Service Operations (Room 2C, ext. 220)
Subject: Which faults may be reset through the UpSight portal, effective Monday 5 October 2026

1. Background

At 01:40 on 3 September 2026 a night dispatcher used the UpSight remote monitoring portal to reset a door lock fault on passenger lift L3 at a multi-storey car park on Phetkasem Road. The lift returned to service and ran for 26 minutes while the landing door at level 4 was not fully locked. Nobody was hurt. UpSight logs show 214 remote resets from January to August 2026, 37 of them for door circuit faults.

2. Decision

From Monday 5 October 2026, every fault shown in UpSight is placed in one of three categories, and what a dispatcher may do depends on the category. Until 4 October 2026 the old rule applies: a dispatcher may make up to 2 remote resets per lift in any 24 hours, for any type of fault.

2.1 Category A – safety faults (never reset remotely)

Category A covers door lock and landing door contact faults, safety circuit open, overspeed governor trip, brake monitoring faults, safety gear operation, pit stop switch, and any fault that occurs while the car is more than 300 mm away from a floor level. A Category A fault may only be cleared by a technician standing at the lift. The dispatcher sends the nearest available technician at once.

2.2 Category B – drive and control faults (supervisor approval)

Category B covers inverter overheating, drive communication loss, encoder faults, levelling errors of 15 mm or more, and repeated door reopening caused by the door motor. A dispatcher may make one remote reset of a Category B fault per lift in any 24 hours, and only after the duty field supervisor has approved it by phone. After any approved Category B reset, a technician must visit the lift within 48 hours to find the cause. If the same Category B fault returns within those 24 hours, it is treated as a Category A fault.

2.3 Category C – comfort faults (dispatcher may reset)

Category C covers car lighting, the ventilation fan, the floor display and voice announcer, the car intercom test warning, and levelling errors below 15 mm. A dispatcher may reset a Category C fault remotely without approval, at most 3 times per lift in any 24 hours. A fourth one is left for the next routine maintenance visit.

> **Note.** UpSight version 4.2 will be installed on the night of Sunday 4 October 2026. From that version the portal greys out the reset button for every Category A fault. Until the update, dispatchers must apply these rules by hand from 5 October.

Fictional document created for testing a question-answering system. All names, figures and organisations are invented.

3. Trapped passengers

A remote reset must never be used to release trapped passengers, whatever the category of the fault. When the intercom or the building reports an entrapment, the dispatcher keeps voice contact with the passengers every 10 minutes and sends a technician under the rescue procedure RP-04. Our target attendance times for entrapments are 30 minutes for hospital lifts, 45 minutes elsewhere in Hat Yai municipality, and 90 minutes for sites outside the municipality, including Sadao and Songkhla city.

4. Returning a lift to service after a Category A fault

1. The technician corrects the cause and tests the door locks on every landing.
2. The technician runs the lift for at least 5 complete trips from the lowest to the highest floor with no passengers.
3. The technician makes a video call to the duty field supervisor and shows the repaired part and the final test run. The supervisor confirms the return to service on the call.
4. The technician completes return-to-service form RS-2 in UpSight, including the supervisor's confirmation time, before switching the lift back to normal operation.

If the supervisor cannot be reached within 20 minutes, the lift stays out of service and the technician calls the Head of Service Operations.

5. Responsibilities

- **Dispatch Lead** (Somkiat Rattanaphol, Control Room 1B, ext. 110): makes sure every shift follows the categories, checks the reset log each morning at 08:00 and reports any breach to the Head of Service Operations the same day.
- **Duty field supervisor**: approves or refuses Category B resets and confirms every Category A return to service.
- **Field technicians**: attend Category A faults, carry out the test runs and complete form RS-2.
- **Safety Officer**: audits 10 randomly chosen RS-2 forms each month and reports the result to the monthly safety meeting.

6. Charges to customers

Customers with a Comprehensive contract pay nothing extra for any callout. Customers with a Basic contract pay a callout charge for every visit made outside contract hours (Monday to Friday, 08:00 to 17:00). From 1 July 2026 this out-of-hours callout charge is 1,800 baht per visit; until 30 June 2026 it was 1,500 baht. Basic contract customers will not be charged for the follow-up visit required after an approved Category B reset. Callouts for Category A faults are charged as normal.

7. Briefings and transition

Dispatchers and field supervisors must attend one briefing in Training Room 3B on 29 or 30 September 2026, 13:30 to 15:30. Technicians are briefed at depot toolbox talks. Contract managers send customer letter CL-09 to all building managers by Friday 2 October 2026.

Fictional document created for testing a question-answering system. All names, figures and organisations are invented.