
MIL Test


(c-rate = 0.5)

Discharging:


With no cell balancing:





with cell balancing:




Charging:


measPackVoltage
12.8*
StateOfCharge(1,1)
GroundTruthCellSOCs(1,1)
1.00
1.00*
measPackCurrent
0*
measCellVoltages(1,1)
measCellVoltages(2,1)
measCellVoltages(3,1)
4.29*
4.29*
4.24*
ChargeCurrentCmd
ChargeCurrentLimit
0.15
0
measCellTemperatures(1,1)
measCellTemperatures(2,1)
measCellTemperatures(3,1)
303.2*
303.2
303.2*
1.408e+4



measPackVoltage
12.89*
StateOfCharge(1,1)
GroundTruthCellSOCs(1,1)
1.00
1.00*
measPackCurrent
0*
measCellVoltages(1,1)
measCellVoltages(2,1)
measCellVoltages(3,1)
4.30*
4.30*
4.30*
ChargeCurrentCmd
ChargeCurrentLimit
0.14
0
measCellTemperatures(1,1)
measCellTemperatures(2,1)
measCellTemperatures(3,1)
303.2*
303.2*
303.2*
1.328e+4


measPackVoltage
12.84*
StateOfCharge(1,1)
GroundTruthCellSOCs(1,1)
0.99
1.00*
measPackCurrent
0*
measCellVoltages(1,1)
measCellVoltages(2,1)
measCellVoltages(3,1)
4.29*
4.30*
4.25*
ChargeCurrentCmd
ChargeCurrentLimit
0.15
0
measCellTemperatures(1,1)
measCellTemperatures(2,1)
measCellTemperatures(3,1)
303.2*
303.2*
303.2*
1.299e+4



measPackVoltage
12.84*
StateOfCharge(1,1)
GroundTruthCellSOCs(1,1)
0.99
1.00*
measPackCurrent
0*
measCellVoltages(1,1)
measCellVoltages(2,1)
measCellVoltages(3,1)
4.29*
4.30*
4.25*
ChargeCurrentCmd
ChargeCurrentLimit
0.15
0
measCellTemperatures(1,1)
measCellTemperatures(2,1)
measCellTemperatures(3,1)
303.2*
303.2*
303.1*
1.328e+4

SIL Test


Discharging:



Charging:



Cycling:


ChargeCurrentCmd_SIL
ChargeCurrentCmd
BmsOperationalState_SIL
BmsOperationalState
Discharging
Charging
Standby
StateOfCharge_SIL(1)
StateOfCharge(1,1)
measCellVoltages(1,1)
measCellVoltages(2,1)
measCellVoltages(3,1)
BalanceCommand_SIL(1)
BalanceCommand(1)
InverterContactorCommand_SIL
InverterContactorCommand