

HOT WORK PERMIT



Permit No:	PTW-399415	Status:	WORK IN PROGRESS
Facility:	HQ-01	Location:	Boiler Room Platform
Issuing Dept:	Maintenance	Equipment:	Pump P-101
Execution Team:	[Internal] Supervised By: Alex Turner (Ph:) Workers: Sarath Chandra	Validity:	2026-04-09 to 2026-04-09 08:00 - 18:00

1. DESCRIPTION OF WORK

PTW tutorial pump guard replacement 1776499801553

2. WORK METHOD STATEMENT (WMS)

#	Step / Activity	Possible Hazard	Control / Precaution
1	Remove the damaged pump guard and install the replacement assembly.	Spark exposure, contact with moving parts, and dropped tools.	Isolate the area, maintain a fire watch, and use the required PPE.

3. REQUIRED PPE

Hard Hat, Safety Glasses, Safety Shoes

4. PRE-WORK VERIFICATION

- ☐ Fire extinguisher/fire hose available
- ☐ Combustible materials removed (>10m)
- ☐ Gas test done (LFL < 10%)
- ☐ Fire watcher assigned
- ☐ Welding screens used
- ☐ Adequate ventilation for fumes
- ☐ Sparks contained

SPECIALIZED CONTROLS

Fire Watcher Name:	N/A
--------------------	-----

5. DUAL AUTHORIZATION SIGNATURES

By signing, I confirm the area is safe, precautions are implemented, and workers are briefed.

REQUESTED BY:

Name: **test1@email.com**

Sign: _____

ENGINEERING APPROVAL:

Name: **test1@email.com**

Status: Approved

Sign: _____

PRODUCTION APPROVAL:

Name: **test1@email.com**

Status: Approved

Sign/Time: _____

SYSTEM GENERATED DOCUMENT - VERIFY LIVE STATUS VIA QR CODE