


❖ **To Check Power Supply Unit (Wyse):**



- Unplug the AC adapter from the Wyse.
- Check the AC adapter and cables (including the power cable) for any signs of physical damage or overheating.
- Check if the pin inside the plug or adapter port is bent, broken, or damaged.
- If there is a damage in the adapter, then it is advised to replace it with another one.

❖ **To Diagnose LAN Port:**



- Try deleting the network device in Device Manager, remove the driver and then scan for hardware changes
- If the cord blinks yellow or red lights, there is a problem.
- If the light doesn't light up at all, the port may be broken or the cord is bad.
- Try replacing the new Patch Cord.
- If none of these steps work, then need to get another Ethernet adapter.

PiscesER1 Marine Infotech Pvt. Ltd.

CIN U74999MH2016PTC274416

405, Vakratunda Corporate Park, Goregaon (E), Mumbai - 400063. Maharashtra, India.

Voice: [+91-22-62215299](tel:+91-22-62215299) Email: operations@pisceser1marine.com Website: www.pisceser1marine.com