CrispBites BBQ Quality Review

Review date: July 18, 2025 | Product: CrispBites BBQ 150 g | Lot: BB-2407A

Issue summary

Customer reports for lot BB-2407A rose during the week of July 7. In the inspected sample, the return rate was 4.6%, compared with the normal 1.2% threshold. The most common report was a package seal that opened before the best-before date.

Inspection measurements

Measure	Observed	Reference
Customer return rate	4.6%	Normal threshold: 1.2%
Seal temperature	168 C	Target: 175 C
Reports mentioning open seal	83%	Share of reviewed claims
Affected production lot	BB-2407A	Packed July 2 - July 4

Containment and follow-up

The quality team placed the remaining BB-2407A inventory on hold and increased seal-integrity sampling from 5 to 20 packs per production hour. The line supervisor should verify heater calibration and record seal temperature at shift start and after any line stop.

Decision note

The temperature gap and complaint pattern are consistent with a possible sealing issue, but they do not prove causation. Compare retained samples from adjacent lots before extending the hold.