SOP-DEC-004 Bench Decontamination with Bleach

DEMO DATA - written for the SmartLab AI demonstration. This is not an approved laboratory procedure.

1. Working Solution
Prepare a 1% w/v sodium hypochlorite working solution fresh each day by diluting the stock bleach with water. Apply it to the surface and leave a contact time of 10 minutes, then wipe the surface with water.

2. Safety
Never mix bleach with acids, ammonia or alcohols such as ethanol: toxic gases or chlorinated by-products can form. Wear gloves and safety glasses and work with good ventilation. Use 70% ethanol only after the bleach has been fully wiped off with water.