

## केन्द्रीय प्रदूषण नियंत्रण बोर्ड CENTRAL POLLUTION CONTROL BOARD

पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार

SPEED POST INISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

F. No. B-29016(SC)/1(56-IV)/19/WM-II Div/

July 04, 2019

To.

The Regional Director
Central Pollution Control Board,

Parivesh Bhawan, Opp. VMC Ward Office No. 10

Subhanpura, Vadodara-390023

Sub: Direction issued under section 5 of the Environment (Protection) Act, 1986 to M/s Gujarat Enviro Protection & Infrastructure Ltd, Village Gabheni, Near Sachin GIDC, Dist-Surat, Gujarat-reg.

Ref:

(i) CPCB letter no. B-29016(SC)/56/10/HWMD/5162 dated 27/10/2010

(ii) CPCB letter no. B-29016(SC)/1(56)/17/WM-II/4553 dated 19/06/2017(copy enclosed)

(iii) GPCB letter no. GPCB/HAZ/CCA-SRT-618(14)/426634 dated 02/11/2017 (copy enclosed)

(iv) CPCB letter no. B-29016(SC)/56/18/WM-II/16949 dated 08/02/2018(copy enclosed)

(v) CPCB letter no. B-29016(SC)/56/18/WM-II/7145 dated 12/07/2018(copy enclosed)

Sir,

This has reference to the above referred directions dated 27/10/2010 issued under section 5 of Environment (Protection) Act, 1986, by CPCB to M/s Gujarat Enviro Protection & Infrastructure Ltd, Surat, Gujarat.

CPCB vide letter dated 19/06/2017, requested Gujarat PCB to submit the current status of said facility including management of leachate from closed secured landfill and storage/disposal of 3475.50 MT stored hazardous waste (as per the inspection report of RD Vadodara conducted in May, 2015).

In this regard, GPCB vide letter dated 02/11/2017 has informed about disposal of said 3475.50 MT of stored hazardous waste to M/s Recycling Solution Pvt Ltd, Panoli and M/s Geohybrid Industrial Solutions Privat Limited, Surat, which was also verified by the officials of GPCB. However, during the visit of GPCB, about 350 MT contaminated fly ash, 50 MT saw dust and 40 MT discarded containers were found stored in the storage shed. In this context, it was also informed that the facility operator vide letter dated 09/08/2017 claimed that the said waste has been sold and transferred to their sister concern unit located at Panoli.

Accordingly, GPCB vide above referred letter dated 08/02/2018 followed by reminder letter dated 12/07/2018 requested to verify the claims made by the operator and also provide the details on management of leachate collected from leachate collection wells. However, no response has been received from Gujarat PCB so far.

In view of above, it is requested to kindly visit the said facility for verification of claims made by the operator and also provide the status/details on management of leachate collected from leachate collection wells at the earliest to enable this office in taking appropriate action on the aforesaid directions dated 27/10/2010.

Yours faithfully,

(Abhey S. Soni)

Additional Director & Head Waste Management-II Division

Encl: as above Copy to:

The Member Secretary
 Gujarat Pollution Control Board
 Paryavaran Bhawan, Sector-10A
 Gandhinagar-382 010

(Abhey S. Soni)

## SPEED POST

F.No. B-29016(SC)/56/18/WM-II/

16949

February 08, 2018

To

The Member Secretary Gujarat Pollution Control Board Paryavaran Bhawan, Sector 10-A Gandhi Nagar-382010

Sub.: Directions issued under Section 5 of the Environment (Protection) Act, 1986, to M/s Gujarat Enviro Protection & Infrastructure, Surat, Gujarat-regarding.

Ref: Gujarat PCB letter no. GPCB/HAZ/CCA-SRT-618 (14)/426634 dated 02/11/2017 Sir,

This has reference to the above referred letter dated 02/11/2017 regarding status of modified directions issued by CPCB vide direction dated 27/10/2010 to M/s Gujarat Enviro Protection & Infrastructure Ltd, Surat, Gujarat.

Vide above referred letter dated 02/11/2017, it has been informed that during the visit of GPCB officials (i.e on 09/08/2017) about 350 MT contaminated fly ash, 50MT saw dust and 40 MT discarded containers were found stored in storage sheds. The unit has claimed vide letter dated 09/08/2017 that the same has been sold and transferred to their sister concern unit located at Panoli. It has also been informed that the operator has provided three leachate collection wells for management of leachate from closed secured landfill.

In this regard, it is requested that Gujarat PCB may kindly verify the aforesaid claims of the operator w.r.t transfer/disposal of contaminated fly ash, saw dust and discarded containers. Further, details on management of leachate collected from leachate collection wells may also kindly be provided to enable CPCB in taking appropriate action on the said directions dated 27/10/2010, please.

Yours faithfully,

(Bharat K Sharma)
Additional Director & Head
Waste Management-II Division

Copy to:

The Regional Director
 Central Pollution Control Board
 Parivesh Bhawan, Opp. VMC Ward Office No.
 10, Subhanpura, Vadodara-390023

(Bharat K Sharma)

010

08/02/18



## GUJARAT POLLUTION CONTROL BOARD

PARYAVARAN BHAVAN

Sector-10-A, Gandhinagar 382 010

Phone: (079) 23222425

(079) 23232152

Fax: (079) 23232156

Website: www.gpcb.gov.in

By.RPAD

Date:

2 NOV 2017

No: GPCB/HAZ/CCA-SRT-618 (14)/ 4 2 6624

To.

Shri Bharat K Sharma

Additional Director & Divisional Head,

Hazardous Waste Management Division-II

Central Pollution Control Board

'Parivesh Bhawan', East Arjun Nagar

Delhi - 110032

Sub: Current status of M/s Gujarat Enviro Protection &Infrastructure Ltd, Gabheni site-

Ref: CPCB letter No: F.No: B-29016 (SC)/1(56)/17 WM-II/4553 dated: 19/06/2017

Respected Sir,

With regard to above mentioned subject and reference, it is kindly be informed that the Board has issued one time permission for disposal of hazardous waste @ 3500 MT from M/s Gujarat Enviro Protection & Infrastructure Ltd, Gabheni to M/s Recycling Solution Pvt Ltd, Panoli and M/s Geohybrid Industrial Solutions Private Limited, Surat dated: 17/04/2014.

In context to that, M/s Gujarat Enviro Protection & Infrastructure Ltd, Gabheni has disposed the earlier stored hazardous waste at above said facility which has been also verified by the officials of GPCB during visit dated 9/8/2017. However, during visit about - 350MT contaminated fly ash, 50 MT saw dust and 40MT discarded containers were found stored in storage sheds. The photographs of the same are attached herewith for your reference. Unit has submitted vide letter dated 9/8/2017 that the same has been sold and transferred to their sister concern unit located at Panoli. Also the facility has provided three leachate collection wells for management of leachate from closed secured landfill.

This is for your information and necessary actions.

Thanking you,

(K.C.MISTRY)

MEMBER SECRETARY

Please examine and put up.

Clean Gujarat Green Gujarat

ISO-9001-2008 & ISO-14001 - 2004 Certified Organisation



## केन्द्रीय प्रदूषण नियंत्रण बोर्ड CENTRAL POLLUTION CONTROL BOARD

पर्यावरण, वन एवं जलवाय परिवर्तन मंत्रालय भारत सरकार

MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

F.No. B-29016(SC)/56/18/WM-II/

July 12, 2018

To.

The Member Secretary
Gujarat Pollution Control Board
Paryavaran Bhawan, Sector 10-A
Gandhi Nagar-382010

Sub: Directions issued under Section 5 of the Environment (Protection) Act, 1986, to M/s Gujarat Enviro Protection & Infrastructure, Surat, Gujarat-regarding.

Ref: CPCB letter no. B-29016(SC)/56/18/WM-II/16949 dated 08/02/2018 (copy enclosed)

Sir,

This has reference to the modified directions issued by CPCB vide direction 27/10/2010 to M/s Gujarat Enviro Protection & Infrastructure, Surat, Gujarat. Vide the above referred letter dated 08/02/2018 it was requested to verify the claims of the operator of M/s Gujarat Enviro Protection & Infrastructur, Surat w.r.t. transfer/disposal of contaminated fly ash, saw dust and discarded containers. Further, it was also requested to provide the details on management of leachate collected from leachate collection wells. The same have not been received so far.

It is requested to kindly provide the above details at the earliest to enable CPCB in taking appropriate action on the said directions dated 27/10/2010, please.

Yours faithfully

Encl: as above

(Bharat K Sharma)
13 (Additional Director & Head
Waste Management-II Division

Copy to:

 The Regional Director, Central Pollution Control Board, Parivesh Bhawan, Opp. VMC Ward Office No. 10, Subhanpura, Vadodara – 390023

(3.17/18

(Bharat K Sharma)

'परिवेश भवन' पूर्वी अर्जुन नगर, दिल्ली-110032 Parivesh Bhawan, East Arjun Nagar, Delhi-110032 दुरभाष/Tel: 43102030. 22305792. वेबसाईट/Website: www.cncb.nic.in To

The Member Secretary Gujarat Pollution Control Board Paryavaran Bhawan, Sector 10-A Gandhi Nagar – 382010

Sub: Directions issued under Section 5 of Environment (Protection) Act, 1986, to common TSDFs - Reg

Sir,

This has reference to the modified directions No. B-29016(SC)/1(56)/17/HWMD/5162-65 dated 27.10.2010 issued to M/s Gujarat Environ Protection Infrastructure Limited (GEPIL), Surat, Gujarat, pertaining to non-compliance observed with respect to operation of Common Hazardous Waste Incinerator and secured landfill at M/s GEPIL, Surat, Gujarat.

Subsequently, Gujarat PCB issued directions dated 30.11.2011 to M/s GEPIL, Surat, Gujarat not to receive any hazardous waste followed by withdrawal of consolidated Consent & Authorization (CCA) vide directions dated 05.03.2012.

The inspection report of Regional Directorate, CPCB, Vadodara (Inspection conducted in May 2015) reveals that the facility was not found operational since the facility is closed down. The Incineration system was scraped/dismantled. It was also reported that about 3476.50 tons of hazardous waste were found to be stored which were supposed to be disposed in other facility. Further, storage of the same was improper.

It is requested to kindly arrange to send current status of the facility including management of leachate from closed secured landfill and storage/disposal of the said stored waste, so as to enable CPCB in taking appropriate action with respect to the said modified direction dated 25.10.2010. The said current status may kindly be sent at the earliest, preferably by June 30, 2017.

Yours faithfully,

(Bharat K Sharma)
AD & I/C WM-II

Copy to:

 The Regional Director Central Pollution Control Board Parivesh Bhawan, Opp. VMC Ward Office No. 10, Subhanpura, Vadodara-390 023

Encl. copy of Dix u/s 5 of EDA, 1986

: for kind information and necessary follow up with Gujarat PCB, as above, please.

0/4

201 b/1A

(Bharat K Sharma )

Ms. PXS,Sc.C