

केन्दीय प्रदूषण नियंत्रण बोर्ड CENTRAL POLLUTION CONTROL BOARD

पर्यावरण, वन एवं जलवायु परिवर्तन मंत्रालय भारत सरकार MINISTRY OF ENVIRONMENT, FOREST & CLIMATE CHANGE GOVT. OF INDIA

E-mail/ Speed Post

CPCB-B 33014/295A /2018/IPC-II/

October 03, 2018

To

M/s. Thakur Prasad Sao & Sons Pvt Ltd., Lahandabud, P.O. H. Kantapali, Dist Jharsuguda, Odisha - 768202.

Sub: Direction issued to M/s. Thakur Prasad Sao & Sons Pvt Ltd., Lahandabud, P.O. H. Kantapali, Dist Jharsuguda, Odisha dated 23.07.2018- Reg.

Ref:

- 1. CPCB letter No. CPCB-B 33014/295A/2018/IPC-II/10006, dated 17.08.2018.
- 2. CPCB letter No. CPCB-B 33014/295A/2018/IPC-II/11012, and email dated 24.09.2018.
- 3. Your letter Ref. No.: TPSL Unit-IV/JSG/CPCB/166, dated 06.09.2018 and email dated 24.09.2018.

Sir.

Please refer to the aforementioned direction issued by CPCB and your letter and email dated 06.09.2018 and 24.09.2018 to this office respectively. In this regard, it is to inform you that the compliance submitted by you w.r.t. port holes for monitoring facilities as per CPCB emission regulation Part-III are partial. It is observed from the photographs that the port holes are without flange. Therefore, you are required to take immediate action and shall report this office within 2 days along with photographs i.e. by 05.10.2018.

Div. Head, IPC-II

Copy to:

The Regional Directorate (East) Central Pollution Control Board 502. Southend Conclave 1582, Rajdanga Main Road Kolkata - 700 107

: For information and take necessary action for compliance verification w.r.t. aforesaid unit and you letter vide No. EZO/TECH/F-817/MSC(ZO)/2018/70 dated 26.07.2018.

