# INDIAN INSTITUTE OF SPACE SCIENCE AND TECHNOLOGY

#### Department of Avionics

#### AV121 - Basic Electronics

#### First Year (common to all branches)

Quiz #3 (II semester)

07/04/2015


Maximum Marks: 30

Answer ALL Questions

#### (Answer Part A and Part B in separate sheets)

#### Part-A

A. Draw the  $r_e$  model of the given CC amplifier shown in Fig.1. Compute the value of voltage gain, input impedance and output impedance. (assume  $V_T=26mV$ ) [6]



- 2. A particular enhancement MOSFET for which  $V_t=1V$  and K=0.05 mA/V<sup>2</sup> is to be operated in the saturation region. If  $I_D$  is to be 0.2mA find the required  $V_{OS}$  and minimum required  $V_{DS}$ ?
- 3. A certain JFET data sheet gives  $(V_{GS})_{off}$ =-8V and  $I_{DSS}$ =10mA. When  $V_{GS}$  =0, what is  $I_D$  for values of  $V_{DS}$  above switch off?  $V_{DD}$ =15V.
- A. For the JFET shown below in Fig.2, Vp=4v and I<sub>DS3</sub>=12mA Determine the minimum value of V<sub>DD</sub> required to put the device in saturation region. [4]





Fig.2



101 Typo

RIEL

1. Add BCD numbers

[2]

- a. 0100 + 0101
- b. 1001+0111
- 2. What do you understand by the term 0-level and 1-level noise margin of a standard TTL IC. Explain with proper figures and specifications for a standard TTL IC. [3]
- What do you understand by the term "A debounce switch". Use SET/RESET NOR flip flop to avoid debouncing.
- 4. Assuming that Q=0 initially, apply the SET and RESET waveforms shown in Figure 1 to the SET and RESET input of a NAND and NOR flip flop, and determine the Q and  $\bar{Q}$  waveforms.

5. Explain following terms

[4]

[3]

- a. TTL fan-out
- b. Time propagation LOW-to-HIGH
- c. Difference between Active high mode and active low mode.
- d. "High Impedance state" using modified totem pole

abun.

.....END.....


power

# PH 121 PHYSICS - II

THIRD QUIZ Date: 08.04.2015 TIME: 09.00 hrs to 10.00 hrs B.Tech (all branches) (attempt all questions)

- 1. Using the magnetic vector potential A of an infinite solenoid having n-turns per unit length, radius R and current I, find the magnetic field inside and outside the solenoid and also find divergence of A. (05)
- 2. Find the magnetic dipole moment of the spinning spherical shell (Fig. 1). Using that show, for points  $r \geq R$  the magnetic field is that of a perfect dipole. (05)
- 201 8 3. A long cylinder of radius R carries a magnetization  $\mathbf{M} = \mathbf{k} \rho^2 \hat{\phi}$ , where k is a constant,  $\rho$  is the distance from the axis. Find the magnetic field due to M, for points inside and outside the cylinder. (05)
- 4. A circular toroidal coil (N-turn) is driven by an alternating current  $I = I_0 cos \omega t$ . Inside the toroidal coil, a circular loop of wire of radius s/2 and resistance R is placed inside co-axial with it (Fig. 2). Find the induced current in the loop as a function of time. (05)

NoI



### INDIAN INSTITUTE OF SPACE SCIENCE AND TECHNOLOGY THIRUVANANTHAPURAM 695 547

#### Quiz III - April 2015

B. Tech - II Semester

MA121 - Vector Calculus and Differential Equations

Date: 09/04/2015

Time: 9.00 am - 10.00 am

Max. Marks: 15

#### Attempt all questions

1. (2). Evaluate the following limit with appropriate justification:

[2]

$$\lim_{n \to \infty} \int_0^1 \frac{n + e^x}{n + x^2} dx.$$

- (b). Check whether the function  $f(x) = \sum_{n=1}^{\infty} \frac{\cos^n x}{n^3}$  is differentiable on  $(-\infty, +\infty)$ .

  [3]
- 2. (a) Define directional derivative of a real valued function f defined on a domain  $D \subset \mathbb{R}^2$ .
  - (b) Let  $f: \mathbb{R}^2 \longrightarrow R$  be given by

y se

$$f(x,y) = \begin{cases} \frac{x^2y}{x^4 + y^2} & if (x,y) \neq (0,0) \\ 0 & otherwise \end{cases}$$

Suppose  $\vec{v} = (v_1, v_2)$  be an vector in  $\mathbb{R}^2$  such that  $v_1 \neq 0 \neq v_2$ . Show that  $D_x f|_{(0,0)}$ ,  $D_y f|_{(0,0)}$  and  $D_{\vec{v}} f|_{(0,0)}$  exist. Is it possible to express  $D_{\vec{v}} f|_{(0,0)}$  in terms of the partial derivatives? Is f is differentiable at (0,0)? Justify your answer. [2.5 + 0.5 + 1]

3. For each of following vector fields  $\vec{F}$ , find a scalar field f, if possible, such that  $\nabla f = \vec{F}$  indicating the domain of  $\vec{F}$ . Justify, if you claim that no such f exists.

 $\vec{F}(x,y,z) = (2x + y\sin z, \ y + x\sin z - \sin y, \ xy\cos z) \qquad \text{age}^{2}$ [3]

$$xe^{2} = e^{2} + \frac{\partial}{\partial y}(_{1}(y_{1}z), \qquad f = \pi y e^{2} + \frac{\partial}{\partial y}(_{1}(y_{1}z), q_{2}z)$$

2(2-1) - 2((1))

# INDIAN INSTITUTE OF SPACE SCIENCE AND TECHNOLOGY

# THIRUVANANTHAPURAM

# Quiz III - April 6, 2015

# CH 121- Materials Science and Metallurgy

#### Second Semester

# Answer all questions 1. (a) What are pre-ceramic polymers? Give an example. (b) What are ferroelectric ceramics? Give an example. Why poling is important in a ferroelectric ceramic? (a) The density and lattice parameter of FCC Palladium are 11.98 g/cc and 3.8902 A°, respectively. Calculate the fraction of lattice points that are vacant. The atomic mass of Palladium is 106.4 g/cc. (b) Why ionic crystals are brittle even though they contain dislocations (3+2) 3. (a) What are ultrahigh temperature ceramics? Give examples and application (b) Give two examples to show the defects in crystals are useful (2.5 + 2.5)

4. 916 KDM (trademark) gold has cadmium and/or copper added intentionally to the jewellery. Justify the above statement. (2)

5. Though possessing 48 slip systems, BCC metals are stronger than FCC metals that have only 12 slip systems? Why

 Solve for the critically resolved shear stress along the slip plane and slip direction.

7. Sketch the distribution of normal and shear stress on a plane oriented at angles of 25, 45, 75, 90, 120, 145, 165, 180 to the normal axis. Superimpose the two curves on the same graph

farre winout deformar.

Ag , Au

e		N-> 2	es N	5.
		25	0.821	0.383
	90 050	45	0.5	2.0
£(0)	150.	75	0.066	0,25
	180	90	0	0 3 3
		120	0.25	-0.433
	240	165	0.433	-0.21
	330	(80,	1	0.
			· ·	90" 18
1			9, 41	10 / 18