

FIELD INSPECTION FORM

Inspection Ref:	INSP-2026-005
Inspection Date:	2026-08-22
Site Location:	Refinery Zone C
Inspector Name:	David K
Asset Ref:	AST-99001
Inspection Status:	NEEDS_ATTENTION
Observation Finding:	Vibration noise in pump motor.
Action Required:	Lubricate bearings.
Followup Date:	2026-09-05
Form Completeness:	COMPLETE