

إقت باس الإعلانات الملاحية البريطانية REPRINT OF ADMIRALTY NOTICE TO MARINERS

EDITION	2/22	الإصدار
ADMIRALTY NOTICES FOR WEEKS	(4+5)	الإعلانات الملاحية البريطانية للأسابيع
30 JAN 2022	_	30 يناير 2022م

<u>CONTENTS</u>		المحتويات
CHARTS AND PUBLICATIONS AFFECTED INDEX	3-4	فهرس الخرائط والمنشورات المتأثرة
CORRECTIONS TO BA CHARTS	5-7	تعديلات الخرانط الأدميرالية البريطانية
TEMPORARY AND PRELIMINARY NOTICE	7-15	الإعلانات الملاحية المؤقتة والتمهيدية
CORRECTIONS TO ADMIRALTY PUBLICATIONS	15-50	تعديسلات المنشورات الأدميرالية البريطانية
PUBLISHED HALF MONTHLY BY THE OMAN NATIONAL HYDROGRAPHIC OFFICE (TEL: +968 24326671, FAX:24326709)		تصدر كل نصف شهر من قبل المكتب الهيدروغرافي الوطني العماني (هاتف 24326709)
Web Site:		الموقع الإلكتروني:

https://mod.gov.om/ar-RNO/HydrographicOceanicServices/Pages/notice_to_mariner.aspx

1

GENERAL NOTES FOR REPRINT OF BRITISH NOTICE TO MARINERS.

- 1. A TWO Weekly reprint of weekly edition of British Admiralty notices covers British admiralty charts and nautical publications (NPs) published by the UK and used by RNOVs and establishments complied by the Oman National Hydrographic Office (ONHO).
- 2. Notices issued by other authorities such as the US National Imagery and Mapping Agency (NIMA) will be re-issued as Oman Notices to Mariners as required.
- 3. Authorities and individuals are requested to report to the Ministry of Transport, Communications and Information Technology with a copy to the (ONHO) of any new dangers to navigation, changes or defects in Navigational Aids (lights, Buoys, Radio Signals etc) or corrections to charts and publications produced by the ONHO or by other nations. Such information affects the safety of international shipping so is always of great value. The ONHO will forward corrections to other nation's products to the authorities responsible for them (see the reporting form).
- 4. This edition is protected by the Sultanate of Oman Copyright. However, the Notice herein may be copied and redistributed without permission in the interests of the safety of navigation.
- 5. all corrections to BA charts are listed separately for each chart affected. Correction number is entered in the bottom left hand margin of a chart, e.g. (for BA 2888):

2002 – 150 – 187 – 260 – **2003** – 20 – 50 – 96

2 BA (3+4)22

1. INDEX OF CHARTS AND PUBLICATIONS AFFECTED

a. Index of BA Chart Notices and RNO Folios affected by this Edition:

CHARTS	NOTICE No.	RNO FOLIOS
38	362(P)22	1-10
158	362(P)22	6
159	362(P)22	6
2375	362(P)22 + 333	6
2444	362(P)22	5
2837	271(P)22	4
2847	305	5
2851	362(P)22	1-2-3-8-9-10
2858	271(P)22	1-10
2882	362(P)22	5-10
2883	362(P)22	5-10
2884	305 + 362(P)22	5-10
2886	362(P)22	5-10
2887	271(P)22 + 362(P)22	4-7-10
2888	271(P)22 + 362(P)22	1-2-7-10
2889	271(P)22 + 362(P)22	4
3171	362(P)22	5
3172	362(P)22	5
3174	362(P)22	1-2-3-7-10
3175	271(P)22 + 362(P)22	4
3176	271(P)22 + 362(P)22	4
3177	283 + 354	4
3178	354	5
3179	278 + 333	5
3413	333	5
3520	362(P)22	1-3-7-10
3713	283	4
3723	362(P)22	1-3-10
3736	362(P)22	5
3737	362(P)22 + 366	5
3738	362(P)22	5
3774	362(P)22	5
3775	362(P)22	5
3788	362(P)22	5
3790	362(P)22	5

b. New Admiralty Charts and Publications:

NIL

c. New Editions of Admiralty Charts and Publication:

NIL

d. : Admiralty Charts and Publications to be Published

NIL

e. Admiralty Charts and Publications Permanently Withdrawn:

NIL

2. CORRECTION TO ADMIRALTY CHARTS

Source: Abu Dhabi Ports NM 13/2021

Chart 3179 (INT 7229) [previous update 3074/21] WGS84 DATUM

Delete symbol, Red and Black pillar buoy, Fl.R.3s 24° 28′ ·28N., 52° 17′ ·80E.

♣ Fl.2s (3 Buoys) 24° 28′·13N., 52° 19′·92E.

Chart 3951 (INT 7241) [previous update 3074/21] WGS84 DATUM

Delete symbol, Red and Black pillar buoy, Fl.R.3s 24° 28′·28N., 52° 17′·80E.

♣ Fl.2s (3 buoys) 24° 28′·23N., 52° 19′·89E.

283* UNITED ARAB EMIRATES - Harbour limits. Legends.

Source: Abu Dhabi Ports

Delete

Insert

Chart 3177 (INT 7222) [previous update 3460/21] WGS84 DATUM

legend, Mīnā' Zāyid Port Limit, along NE side of:

former harbour limit, pecked line, joining:

harbour limit, pecked line, joining:

former harbour limit, pecked line, and associated legend,

Insert harbour limit, pecked line, joining: 24° 30′·56N., 54° 22′·20E.

24° 30′·50N., 54° 22′·25E.

24° 30′·39N., 54° 22′·07E. 24° 30′·73N., 54° 21′·47E.

24° 30′ ·95N., 54° 21′ ·43E.

24° 31′·20N., 54° 21′·49E.

and

(a) 24° 31′·81N., 54° 20′·99E.

(b) 24° 35′·58N., 54° 15′·92E.

(a)-(b) above

Mīnā' Zāyid Port Limit, joining: 24° 29′ ·29N., 54° 18′ ·85E.

4

(a) above

24° 30′·13N., 54° 21′·61E.

24° 29′ · 96N., 54° 21′ · 75E.

24° 30′·557N., 54° 22′·200E.

24° 30′·500N., 54° 22′·250E.

(a) 24° 30′·390N., 54° 22′·070E.

24° 30′·730N., 54° 21′·470E. 24° 30′·950N., 54° 21′·430E.

24° 31′·200N., 54° 21′·490E.

and

(c) 24° 31′·810N., 54° 20′·990E.

(d) 24° 32′·026N., 54° 20′·700E.

(a)-(b) above

(c)-(d) above

24° 31′·467N., 54° 20′·700E.

(c) above

Delete former harbour limit, pecked line, and associated legend,

legend, Mīnā' Zāyid Port Limit, along NE side of:

Mīnā 'Zāyid Port Limit, joining:

BA (3+4)22

283* UNITED ARAB EMIRATES - Harbour limits. Legends. (continued)

Chart 3713 (INT 7223) (Panel, The Free Port) [previous update 31/22] WGS84 DATUM

Insert harbour limit, pecked line, joining: 24° 30′·56N., 54° 22′·20E.

24° 30′·50N., 54° 22′·25E.

(a) 24° 30′·39N., 54° 22′·07E.

(b) 24° 30′·73N., 54° 21′·47E. 24° 30′·95N., 54° 21′·43E.

24° 31′·20N., 54° 21′·49E.

and

(c) 24° 31′·81N., 54° 20′·99E.

(d) 24° 35′·58N., 54° 15′·92E.

legend, Mīnā 'Zāyid Port Limit, along NE side of:

(*a*)-(*b*) above (*c*)-(*d*) above

Delete former legend, Mīnā 'Zāyid Port Limit, centred on:

24° 34′·77N., 54° 16′·34E.

former harbour limit, pecked line, and associated legend, *Mīnā' Zāyid Port Limit*, joining:

24° 29′ · 29N., 54° 18′ · 85E.

(c) above

former harbour limit, pecked line, joining:

24° 30′·06N., 54° 21′·66E. 24° 29′·96N., 54° 21′·74E.

305 IRAN - Marine farm.

Source: Iranian Notice 14/21

Chart 2847 (INT 7018) [previous update 249/22] WGS84 DATUM

Insert

29° 47′·5N., 50° 03′·3E.

Chart 2884 (INT 7278) [previous update 4416/21] WGS84 DATUM

Insert

 $[\emptyset]$

29° 47′·5N., 50° 03′·3E.

333* UNITED ARAB EMIRATES - Restricted area. Legend.

Source: MENAS Notice 13/21

Chart 2444 (INT 7239) [previous update 2123/21] WGS84 DATUM

Insert circular limit of restricted area, radius 500m (0·27M), TTTT,

centred on: 25° 08′ · 45N., 52° 48′ · 48E.

Chart 3179 (INT 7229) [previous update 278/22] WGS84 DATUM

Insert circular limit of restricted area, radius 500m (0·27M), TTTT,

centred on: 25° 08′·45N., 52° 48′·48E.

Chart 3413 (INT 7227) (Panel C, Approaches to Jazīrat Dās) [previous update 4804/21] WGS84 DATUM

Insert circular limit of restricted area, radius 500m (0·27M), TTTT,

centred on: (a) 25° 08′·45N., 52° 48′·48E.

legend, Restricted Area (see Note), close SE of: (a) above

354* UNITED ARAB EMIRATES - Depths. Legend.

Source: Abu Dhabi Maritime

Insert

Chart 3177 (INT 7222) [previous update 283/22] WGS84 DATUM

Insert 24° 06′ · 56N., 53° 29′ · 80E. Delete legend, 8m, close W of: (a) above

Chart 3178 (INT 7226) [previous update 2977/21] WGS84 DATUM

Insert depth, 6_6 24° 09′·61N., 53° 27′·11E.

depth, 77, close SW of: Delete (a) above

Insert depth, 2_9 24° 06′·56N., 53° 29′·80E.

Delete legend, 8m, close W of: (b) above

366 BAHRAIN - Submarine pipeline. Legends. Quay. Alongside depth. Depth. Buoyage. Light-beacon. Source: Bahraini Chart 1501

Chart 3734 (INT 7261) [previous update 340/20] WGS84 DATUM

Insert	submarine pipeline,	, joining:		
	• • •		(a)	26° 12′·444N., 50° 41′·952E.
			(b)	26° 12′ ·020N., 50° 41′ ·032E.

legend, Buried 30m, along: (*a*)-(*b*) above (c) 26° 11′·573N., 50° 40′·921E. wharf, single firm line, joining:

26° 11′·533N., 50° 40′·945E. 26° 11′ · 492N., 50° 40′ · 861E.

26° 11′ · 534N., 50° 40′ · 838E.

legend, SULB Wharf, within: (c)-(f) above

Delete charted detail, within: (c)-(f) above Insert

alongside depth, \bullet (95), enclosed by 10m contour 26° 11′·361N., 50° 42′·629E.

> depth, 11_4 26° 09′ ·804N., 50° 42′ ·943E. N light-buoy to, Fl.Y.4s 26° 10′ · 059N., 50° 39′ · 750E.

Amend Replace $\stackrel{\star}{\smile}$ Fl. Y.4s S with $\stackrel{\star}{\smile}$ Iso. Y S 26° 09′ ·941N., 50° 39′ ·800E.

Move \bigtriangleup *Q.R BS2*, from:

26° 11′·397N., 50° 40′·906E. 26° 11′·320N., 50° 40′·821E.

Delete 26° 09′·180N., 50° 40′·435E.

> $L \supset Fl.R.2s$ 26° 09′·126N., 50° 40′·472E.

Chart 3737 (INT 7255) [previous update 1556/20] WGS84 DATUM

Insert alongside depth, \bullet (95), enclosed by 10m contour 26° 11′·36N., 50° 42′·63E.

Move Q.R, from: 26° 11′·40N., 50° 40′·90E.

26° 11′·32N., 50° 40′·85E.

BA (3+4)22 6

400* UNITED ARAB EMIRATES - Buoyage. Legend.

Source: AMRO

Chart 2887 (INT 7232) [previous update 5078/21] WGS84 DATUM

Delete legend, (marked by buoys), centred on: 25° 35′·6N., 55° 17′·7E.

Chart 2888 (INT 7199) [previous update 5282/21] WGS84 DATUM

Delete legend, (marked by buoys), centred on: 25° 35′·6N., 55° 17′·7E.

Chart 2889 (INT 7211) [previous update 4596/21] WGS84 DATUM

Delete legend, (marked by buoys), centred on: 25° 35′ 6N., 55° 17′ 7E.

Chart 3175 (INT 7212) [previous update 30/22] WGS84 DATUM

Delete $\int_{V}^{A} Fl.Y.4s$ 25° 35′ 06N., 55° 21′ · 57E.

25° 35′·23N., 55° 20′·42E. 25° 35′·48N., 55° 19′·70E. 25° 35′·68N., 55° 18′·58E. 25° 35′·93N., 55° 17′·57E. 25° 36′·16N., 55° 16′·52E.

25° 36′·44N., 55° 15′·46E. 25° 36′·60N., 55° 14′·52E.

25° 36′ ·88N., 55° 13′ ·45E.

3. TEMPORARY AND PRELIMINARY NOTICE TO MARINERS

a. Temporary and Preliminary Notices to Mariners In Force:

(Former In Force List dated 24 December 2021 is cancelled)

Cancelled Notices

Area Notice No.

11 4071(P)/21, 4564(P)/21

12 460(P)/19, 5062(T)/21, 5240(T)/21, 5244(T)/21, 5470(P)/21, 5525(T)/21, 5528(T)/21

No. of No- Charts affected Locality & Subject Folio(s)

tice

11. RED SEA, ARABIA, IRAQ AND IRAN

2035(T)/13	2884	IRAN: Wreck; Buoy	40
3234(T)/13	1229	IRAQ: Wreck	40
5236(T)/14	2523, 2883, 2886,	QATAR: Buoyage	40
	2887, 3950		
1182(T)/16	333, 2374	EGYPT, Red Sea Coast: Platform; Light	32
4281(P)/16	63	SAUDI ARABIA, Red Sea Coast: Harbour developments; Depths	32
4492(P)/16	11, 1268, 2882,	IRAN: Platforms; Submarine cables; Submarine pipelines	40
	2884, 3774		
5105(P)/16	16	SAUDI ARABIA, Red Sea Coast: Depths; Wrecks; Submarine pipeline;	32
		Rocks; Coral	
2363(P)/17	6, 12, 15, 143, 157,	RED SEA: Routeing measures	32
	158, 159, 164, 452,		
	453, 1925, 2375,		
	2658, 2659, 2964		

7

11. RED SEA, ARABIA, IRAQ AND IRAN - continued

2822(T)/17	2523, 3790	QATAR: Buoy	40
3559(P)/17	2837, 2889, 3178,	UNITED ARAB EMIRATES: Submarine pipeline; Obstruction	40
	3179, 3413		
4031(P)/17	1265, 3842, 3843,	IRAQ: Channel; Depths; Wrecks	40
. ,	3844, 3845, 3846		
5287(T)/17	1235, 1265	ARABIA: Buoyage	40
5518(P)/17	1228	IRAQ: Jetty; Dolphins; Mooring buoys; Floating dock; Dredged area	
` '			
1453(T)/18	1235, 1265, 3773	ARABIA, Shaţţ al'Arab: Buoyage	
2528(T)/18	2133, 2373	EGYPT, Red Sea Coast: Buoy	
4030(P)/18	3772, 3781	QATAR: Depths; Buoyage	
994(P)/19	1229, 1235, 2847,	IRAQ: Works; Buoyage; Channel	40
	2884		
1646(P)/19	3737, 3738, 3759	BAHRAIN: Works	40
1855(P)/19	3759	BAHRAIN: Works; Lights; Breakwater; Buoyage; Channel; Restricted area;	40
()		Submarine pipeline; Submarine cable; Radar beacon	
1937(T)/19	333, 2374	EGYPT, Red Sea Coast: Buoy	
2208(T)/19	2523, 2837, 2847,	QATAR: Buoy	
2200(1)/19		QATAK. Buoy	40
	2886, 3772, 3950		
3126(P)/19	2837, 2889, 3178,	UNITED ARAB EMIRATES: Works; Offshore installations	. 40
	3179		
3154(P)/19	3176, 3412	UNITED ARAB EMIRATES: Restricted area	. 40
3202(P)/19	3812	SAUDI ARABIA, East Coast: Depths	. 40
6162(T)/19	2523	QATAR: Buoy	
6524(T)/19	11	IRAN: Buoy	
` '	3718	SAUDI ARABIA, East Coast: Works; Buoyage; Dredged area	
6699(P)/19			
163(P)/20	2884	KUWAIT: Works; Buoyage; Causeways	
1822(T)/20	2854	OMAN: Wreck	
2062(T)/20	3736	BAHRAIN: Buoyage	. 40
3127(P)/20	15, 16	SAUDI ARABIA, Red Sea Coast: General information	. 32
3623(P)/20	27, 2884	IRAN: Channel; Buoyage; Dredged depths; Light-beacons; Dredged areas;	40
. ,		Dolphins; Reclamation area; Coastline; Swinging circle; Anchor berths	
4448(P)/20	12	SAUDI ARABIA, Red Sea Coast: Depths; Obstruction; Dredged areas;	32
(1)/20	12	Coastline; Beacons	
4469(T)/20	3812	SAUDI ARABIA, East Coast: Buoy	
()		<u>.</u>	
4569(P)/20	3736	BAHRAIN: Floating barriers; Lights	
4645(P)/20	2132, 2133, 2373	EGYPT, Red Sea Coast: Works; Lights; Dredged area; Virtual aids to	32
		navigation	
5242(T)/20	1214, 3773	KUWAIT: Light-beacon; Lights	
6028(P)/20	3175	UNITED ARAB EMIRATES: Works; Restricted area; Outfall; Buoyage	. 40
6265(P)/20	2837, 2847, 2883,	BAHRAIN: Marine Reserve	. 40
	2886, 3738, 3788,		
	3790		
121(T)/21	3777, 3812	SAUDI ARABIA, East Coast: Wreck; Buoyage	. 40
361(T)/21	3763, 3785	OMAN: Works	
1563(P)/21	3752	UNITED ARAB EMIRATES: Buoyage; Works	
		• • •	
2031(T)/21	1223, 2882, 2884,	KUWAIT: Lights	. 40
2052(D) (21	3773	VINTED AND IN COLUMN AND AND AND AND AND AND AND AND AND AN	4.0
3072(P)/21	3778, 3779, 3780	UNITED ARAB EMIRATES: Works; Restricted areas; Buoyage	
3318(P)/21	2523, 2837, 2847,	QATAR: Works; Offshore installation	. 40
	2886		
3623(P)/21	2577	SAUDI ARABIA, Red Sea Coast: Depths	. 32
3693(T)/21	3520, 3723	UNITED ARAB EMIRATES: Buoy	
3859(T)/21	2523, 2837, 2847,	BAHRAIN: Buoy	
· (- <i>)</i> ,	2858, 2886, 3738,	,	-
	3790		
4000 		VII. VIII. D. D. D. VII. VIII. T.	4.0
4008(T)/21	2837, 2887, 2888,	UNITED ARAB EMIRATES: Buoy	40
	3174		
4070(P)/21	8054	UNITED ARAB EMIRATES: Buoyage; Light-beacons; Restricted areas	
4104(T)/21	2882, 2883, 3719,	SAUDI ARABIA, East Coast: Obstruction	40
	3775, 3788		

8

11. RED SEA, ARABIA, IRAQ AND IRAN - continued

4429(P)/21	8101	UNITED ARAB EMIRATES: Buoy	40
4609(T)/21	8054	UNITED ARAB EMIRATES: Breakwater	
4611(P)/21	8054	UNITED ARAB EMIRATES: Light; Works; Buoyage; Breakwaters; Channel	
. ,	8054		
4615(P)/21		UNITED ARAB EMIRATES: Anchorage area; Maritime limit	
5210(T)/21	3734, 3736, 3737	BAHRAIN: Works; Submarine pipeline	
5369(T)/21		EGYPT, Red Sea Coast: Works	
271(P)/22	2442, 2837, 2858, 2887, 2888, 2889, 3175, 3176	UNITED ARAB EMIRATES: Restricted area	40
272(P)/22	8101	UNITED ARAB EMIRATES: Light	40
362(P)/22	12, 38, 58, 158, 159, 327, 801, 1268, 2375, 2441, 2442, 2443, 2444, 2523, 2599, 2658, 2659, 2851, 2882, 2883, 2884, 2886, 2887, 2888, 2889, 2895, 3171, 3172, 3174, 3175, 3176, 3520, 3723, 3734, 3736, 3737, 3738, 3759, 3760, 3761, 3774, 3775, 3786, 3788, 3790, 3842, 3950	ARABIAN SEA: Submarine cables; Works	32,40,41
12. INDIAN		N, INDIA, SRI LANKA, BANGLADESH AND BURMA	
4002(P)/12	569	INDIA, East Coast: Port developments	43
2877(T)/17	IN 2036	INDIA, West Coast: Buoyage	
5395(T)/17	39, 707, 4705	PAKISTAN: Wreck	
2839(P)/18	IN 3010, IN 3041	INDIA, East Coast: Anchorage areas; Submarine pipelines; Restricted area	
2951(T)/18	90	BANGLADESH: Obstruction	
3911(P)/18	IN 2016, IN 2076	INDIA, West Coast: Works	-
4921(T)/18	90	BANGLADESH: Wreck	
5442(T)/18	1488, IN 207,	INDIA, West Coast: Dredging areas	_
3112(1)/10	IN 253, IN 254	17.511, West Coust. Dieuging treus	
5548(P)/18	IN 206, IN 253	INDIA, West Coast: Works	41
	920	INDIAN OCEAN, Chagos: Restricted areas; Anchorage areas; Depths	
6120(P)/18	3265, 3700	SRI LANKA, South Coast: Depths; Rocks	
105(P)/19	319	INDIA, East Coast: Channel limit; Buoyage; Dredged depths; Berth; Floating	
103(1)/17	31)	dock; Pilot boarding places	15
1066(T)/19	84, 90	BANGLADESH: Wrecks; Buoy	43
1217(P)/19	IN 292	INDIA, West Coast: Traffic separation scheme	
1600(T)/19	84, 90	BANGLADESH: Wrecks	
2078(P)/19	IN 3012	INDIA, East Coast: Works	43
	IN 211, IN 255,	INDIA, West Coast: Works; Buoyage	41
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	IN 292, IN 293, IN 2016, IN 2076		
2556(T)/19	732	BANGLADESH: Wreck	43
2869(P)/19	IN 203, IN 2013, IN 2031	INDIA, West Coast: Works	
2871(P)/19	IN 220, IN 259, IN 2004, IN 2029, IN 2045	INDIA, West Coast: Works	41
3115(P)/19	IN 203, IN 2033, IN 2083	INDIA, West Coast: Works	41

9

12. INDIAN OCEAN, PAKISTAN, INDIA, SRI LANKA, BANGLADESH AND BURMA - continued

3861(T)/19	833	BURMA: Buoy	43
3935(T)/19	IN 2002, IN 2359	INDIA, West Coast: Buoy	41
3986(T)/19	722	INDIAN OCEAN, Seychelles: Beacon	36
4184(T)/19	84, 90	BANGLADESH: Wreck	
4267(T)/19	1885	BURMA: Buoy	43
4326(P)/19	1488, IN 207,	INDIA, West Coast: Works	
	IN 253, IN 254,	,	
	IN 292		
4612(T)/19	84, 90	BANGLADESH: Wrecks	43
4977(T)/19	84	BANGLADESH: Works	
5223(T)/19	90	BANGLADESH: Obstruction	
5331(T)/19	84, 90	BANGLADESH: Wreck	
. ,	,		
5332(T)/19	90	BANGLADESH: Wreck	
5363(T)/19	830	BURMA: Works	
5373(T)/19	3877, 3895, 4701,	INDIAN OCEAN, Comores: Volcanic activity	36,38
	4702		
5624(T)/19	90, 732	BANGLADESH: Buoyage	
6550(P)/19	84, 90	BANGLADESH: Submarine pipelines	
468(T)/20	90, 817	BANGLADESH: Wreck	43
579(P)/20	IN 254, IN 292	INDIA, West Coast: Depths	41
1004(T)/20	90	BANGLADESH: Wreck	43
1168(P)/20	69, IN 262	INDIA, East Coast: Depths; Recommended anchorage; Buoyage	
1380(T)/20	IN 223, IN 260,	INDIA, West Coast: Buoyage	41
	IN 261		
1802(P)/20	IN 211, IN 255,	INDIA, West Coast: Bridge; Jetty	41
	IN 2016, IN 2076		
2164(P)/20	725, 727	INDIAN OCEAN, Chagos: Rocks; Obstructions	38
2332(T)/20	IN 214, IN 215,	INDIA, West Coast: Buoyage	41
	IN 2022		
2821(T)/20	2760, 4070, 4071,	INDIAN OCEAN: Buoyage	35,42,46
	4073, 4707		
3168(P)/20	IN 3037, IN 3038	INDIA, East Coast: Dredging area; Channel limits; Buoyage	43
3175(T)/20	823, 826, 833	BURMA: Wreck	43
3503(T)/20	39, 58	PAKISTAN: Quarantine anchorage	41
3630(T)/20	709, 4703, 4706,	INDIA, East Coast: Buoyage	42
	4707		
4221(T)/20	90, IN 31	BANGLADESH: Dredging area	43
4277(P)/20	711, 3048	INDIAN OCEAN, Mauritius: Depths	38
4292(P)/20	1470, IN 203	INDIA, West Coast: Depths; Drying heights	41
4378(P)/20	IN 33	INDIAN OCEAN, Nicobar Islands: Depths; Obstructions; Lights	42
4980(P)/20	IN 203	INDIA, West Coast: Buoy; Depths	41
5051(T)/20	2741, 2756	INDIAN OCEAN, Comores: Light	
5101(T)/20	817, 4706, IN 31	BURMA: Offshore installations	
5786(T)/20	IN 22, IN 211,	INDIA, West Coast: Works	
	IN 255, IN 292,	,	,
	IN 293, IN 2015,		
	IN 2016, IN 2076		
6303(P)/20		BURMA: Submarine cable; Works	43,45
220(P)/21	709, 813, 1013,	SRI LANKA, West Coast: Submarine cable	
` /	3323, 3700, 4703,	•	
	4706, 4707, IN 32,		
	IN 263		
603(T)/21	IN 22, IN 32, IN 220,	INDIA, West Coast: Measuring instruments	41,42
	IN 259		

10

12. INDIAN	N OCEAN, PAKISTAI	N, INDIA, SRI LANKA, BANGLADESH AND BURMA - continued	
605(T)/21	317, 319, 514, 569, 707, 709, 716, 717, 721, 740, 742, 1398, 1470, 2069, IN 22, IN 31, IN 33, IN 205, IN 206, IN 211, IN 212, IN 213, IN 215, IN 216, IN 219, IN 221, IN 223, IN 253, IN 257, IN 258, IN 259, IN 260, IN 261, IN 262, IN 261, IN 272, IN 273, IN 292, IN 293, IN 308, IN 351, IN 352, IN 473, IN 2008, IN 3002, IN 3035	INDIAN OCEAN: Buoyage	36,38,41 42,43
874(P)/21	12, 15, 159, 164, 263, 264, 333, 818, 830, 2375, 2441, 2442, 2760, 3784, 3943, 4705, 4706, IN 273, IN 293, IN 2036	INDIAN OCEAN: Submarine cables	32,40,41 42,43,45 46
879(T)/21 982(T)/21 1025(T)/21	2069, IN 32	INDIA, East Coast: Scientific instruments INDIA, East Coast: Buoyage INDIA, West Coast: Obstructions; Scientific instruments	43
1276(T)/21 1431(P)/21	39, 58IN 3010	PAKISTAN: Wrecks	
1953(P)/21	6, 143, 151, 153, 157, 158, 159, 167, 171, 240, 264, 265, 327, 333, 355, 356, 452, 453, 616, 644, 646, 666, 671, 674, 716, 717, 721, 722, 740, 742, 964, 1180, 1196, 1704, 1705, 1913, 1925, 1926, 1998, 2116, 2122, 2123, 2124, 2133, 2373, 2374, 2375, 2573, 2574, 2578, 2926, 2930, 2949, 2964, 2968, 3310, 3361, 3795, 3797, 3877, 3878, 4146, 4148, 4150, 4151, 4152, 4156, 4157, 4169, 4171, 4177, 4178, 4179, 4180	INDIAN OCEAN: Works; Submarine cables	24,25,26, 32,34,35, 36,38

12. INDIAN OCEAN, PAKISTAN, INDIA, SRI LANKA, BANGLADESH AND BURMA - continued

2203(T)/21	84, 90	BANGLADESH: Wreck	43
2269(P)/21	318, IN 31, IN 32	INDIA, East Coast: Buoy	42,43
2317(T)/21	317, 318, 319, 2069, 4706, IN 31, IN 32, IN 33, IN 308, IN 352	INDIA, East Coast: Obstructions; Scientific instruments	42,43
2409(P)/21	33, 38	PAKISTAN: Depths; Lights	41
2620(T)/21	813, IN 263	SRI LANKA, West Coast: Wreck	
2825(P)/21	IN 203, IN 2068, IN 2079, IN 2106	INDIA, West Coast: Berth; Works	41
3514(P)/21	Q 6099, Q 6111	INDIAN OCEAN: Maritime limit	
3518(P)/21	IN 32, IN 223, IN 262	INDIA, East Coast: Works	
3779(T)/21	84	BANGLADESH: Wreck; Buoy	43
4020(P)/21	732	BANGLADESH: Drying heights; Depths; Wrecks; Buoyage; Lights; Coastline; Ferry route	43
4122(T)/21	84, 90	BANGLADESH: Wreck	43
4125(T)/21	IN 211, IN 255, IN 292, IN 293, IN 2016, IN 2076	INDIA, West Coast: Works	41
4222(T)/21	90	BANGLADESH: Wrecks; Buoy	43
4544(P)/21	84, 90	BANGLADESH: Depths; Drying heights; Islets; Wrecks; Platform; Restricted areas; Buoyage; Submarine pipeline; Jetties; Signal station; Lights; Leading lights; Beacons; Landmarks; Tide gauge; Pontoons; Piers; Automatic Identification Systems; Virtual aids to navigation	
4834(T)/21	90, IN 31	BANGLADESH: Buoy	43
5362(T)/21	58, 59	PAKISTAN: Buoy	41
5413(T)/21	84	BANGLADESH: Wreck; Buoy	43
5497(T)/21	84	BANGLADESH: Wreck	43
92(T)/22	2760, 2781, 2785, 3877, 4070, 4071, 4072, 4073, 4104, 4115, 4202, 4203, 4209, 4215, 4216, 4508, 4510, 4701, 4702, 4703, 4706, 4707, 4708, 4714, 4806, 4810, IN 31	INDIAN OCEAN: Buoyage	35,36,38 42,43,46 47,53,64 87,89,92 95
221(T)/22	707, 709, 4703, 4705, 4706, 4707, IN 22, IN 273, IN 292		
222(T)/22	317, 830, 1398, 2069, 4706, 4707, IN 31, IN 32, IN 33, IN 313, IN 472, IN 473, IN 3001, IN 3004	INDIA, East Coast: Data buoys	
237(T)/22	90, IN 31	BANGLADESH: Wreck	43
13. MALAG	CCA STRAIT, SINGA	PORE STRAIT AND SUMATERA	
1030(T)/16	1140, 3946	MALAYSIA, Peninsular Malaysia, West Coast: Obstruction	45
2152(T)/17	3831, 3833, 4041	SINGAPORE STRAIT: Buoy	
4448(P)/17	8232, 8233	MALAYSIA, Peninsular Malaysia, West Coast: Maintained channel	
1401(P)/18	1312, 2422, 2435, 2436, 2470, 2868, 2870, 3947	INDONESIA, Sumatera: Submarine cables	
4349(P)/18	8233	MALACCA STRAIT: Anchorage areas	45
4527(P)/18	8233	MALACCA STRAIT: Note	
4673(P)/18	2873, 3947	INDONESIA, Sumatera: Submarine cable	
4930(P)/18	8284	MALAYSIA, Peninsular Malaysia, West Coast: Pilot boarding place	

12. INDIAN OCEAN, PAKISTAN, INDIA, SRI LANKA, BANGLADESH AND BURMA - continued

461(P)/19	8232, 8233	MALAYSIA, Peninsular Malaysia, West Coast: Dredged depth	45
637(T)/19	3471	INDONESIA, Sumatera: Buoy	46
1082(P)/19	8175	SINGAPORE: Maritime limit	45
1335(T)/19	3949	INDONESIA, Sumatera: Wreck	46
1939(P)/19	8176	SINGAPORE: Light	45
2617(P)/19	8177	SINGAPORE: Light	45
3628(P)/19	8232	MALAYSIA, Peninsular Malaysia, West Coast: Note	45
4676(T)/19	2152, 2155	MALAYSIA, Peninsular Malaysia, West Coast: Buoyage	45
5772(P)/19	8175	SINGAPORE: Buoy	45
6060(P)/19	1146, 3946, 3947.	MALAYSIA, Peninsular Malaysia, West Coast: Depths	45
1226(P)/20	8176	SINGAPORE: Dredged depths	45
1282(P)/20	8175	SINGAPORE: Dredged areas; Dredged depths; Jetty	45
1558(P)/20	8175	SINGAPORE: Maritime limits; Buoy	45
2024(P)/20	3940, 3946, 3947	MALACCA STRAIT: Submarine cable	45
2031(P)/20	3833	SINGAPORE STRAIT: Anchorage areas	45
2218(P)/20	3833, 8175	SINGAPORE: Works	45
2221(P)/20	3833	SINGAPORE: Submarine cables	45
2529(T)/20	3948	INDONESIA, Sumatera: Wreck	46
2629(P)/20	8175, 8176	SINGAPORE: Dredged depths	45
2741(T)/20	2403, 3833, 3902,	INDONESIA, Sumatera: Wreck	45,46
	3948		
2752(P)/20	8285	SINGAPORE: Automatic Identification System	45
3077(P)/20	8284	MALAYSIA, Peninsular Malaysia, West Coast: Anchorage area	45
3146(P)/20	8175	SINGAPORE: Dredged depths	45
3438(P)/20	8176	SINGAPORE: Vertical clearance	45

b. Temporary and Preliminary Notices to Mariners Issued During Half Month:

271(P)/22 UNITED ARAB EMIRATES - Restricted area.

Source: Dubai Maritime City Authority

1. A new marine conservation reserve has been established in the approaches to Dubai, bounded by the following positions:

```
25° 18′ 93N., 54° 37′ 75E.
25° 20′ 77N., 54° 40′ 02E.
25° 17′ 34N., 54° 43′ 50E.
25° 15′ 43N., 54° 41′ 10E.
```

- 2. Entry into Marine Conservation Areas are affected by numerous restrictions and prohibitions. For further details, please consult the local Port Authorities.
- 3. Charts will be updated when full details are available.
- 4. Mariners are advised to navigate with caution in the area. (WGS84 DATUM)

Charts affected - 2442 - 2837 (INT 7017) - 2858 (INT 750) - 2887 (INT 7232) - 2888 (INT 7199) - 2889 (INT 7211) - 3175 (INT 7212) - 3176 (INT 7216)

362(P)/22 ARABIAN SEA - Submarine cables. Works.

Source: UKHO

Segment

1. Cable installation works are taking place in the Persian Gulf, Arabian Sea and Red Sea to install telecoms cables joining the following approximate positions:

Approximate Positions

	Segment	Approximate I ostions
	Persian Gulf to Arabian Sea	21° 42′·000N., 62° 48′·178E.
		22° 34′·705N., 62° 24′·765E.
		23° 03′·941N., 61° 44′·953E.
		23° 00′ 908N., 60° 21′ 305E.
		24° 04′·031N., 58° 08′·677E.
		23° 57′·494N., 57° 55′·645E.
		24° 55′·027N., 56° 38′·656E.
		25° 11′·436N., 56° 48′·192E.
		26° 32′·409N., 56° 32′·360E.
		25° 27′·315N., 54° 59′·199E.
		25° 23′·567N., 53° 02′·695E.
		26° 00′·325N., 52° 15′·453E.
		26° 32′·199N., 51° 12′·939E.
		27° 09′·600N., 50° 46′·450E.
		29° 08′·718N., 49° 00′·059E.
		29° 54′·782N., 48° 30′·207E.
	Kuwait	29° 08′·718N., 49° 00′·059E.
		29° 11′·216N., 48° 21′·357E.
		29° 20′·251N., 48° 05′·721E.
	Saudi Arabia East	27° 09′ 600N., 50° 46′ 450E.
		26° 59′ 462N., 50° 42′ 724E.
		26° 39′·618N., 50° 21′·691E.
		26° 14′·253N., 50° 18′·711E.
		26° 14′·592N., 50° 13′·227E.
_		20 14 3)211., 30 13 2272.
2.		
	D-1	269 227 100N 519 127 020E
	Bahrain	26° 32′·199N., 51° 12′·939E.
		26° 23′·680N., 50° 49′·331E.
		25° 58′ 382N., 50° 36′ 903E.
		25° 58′·363N., 50° 36′·815E.
	Qatar	26° 00′·325N., 52° 15′·453E.
		25° 44′·267N., 51° 59′·663E.
		25° 37′·569N., 51° 32′·837E.
	United Arab Emirates	24° 55′·032N., 56° 38′·647E.
		25° 04′·118N., 56° 21′·628E.
	Oman 1	23° 57′·494N., 57° 55′·645E.
		23° 44′·677N., 57° 48′·851E.
	Oman 2	17° 00′·590N., 54° 09′·302E.
		14° 48′·251N., 55° 21′·333E.
	Pakistan 1	24° 51′·711N., 66° 51′·039E.
		23° 48′-921N., 62° 24′-678E.
		23° 07′·093N., 61° 43′·128E.
		23° 03′ 941N., 61° 44′ 953E.
	Pakistan 2	23° 48′ 921N., 62° 24′ 678E.
		25° 11′·732N., 62° 16′·592E.
	Arabian Sea 1	17° 30′·002N., 62° 51′·030E.
		18° 46′·176N., 63° 27′·932E.
		21° 33′·991N., 62° 52′·119E.
	Arabian Sea 2	18° 46′·176N., 63° 27′·932E.
	muonin Dou 2	18° 30′ 983N., 66° 10′ 000E.
	Vaman	10° 55′ 400NT 55° 07′ 440E
	Yemen	12° 55′·422N., 55° 27′·443E.

362(P)/22 ARABIAN SEA - Submarine cables. Works. (continued)

 $\begin{array}{c} 13^{\circ}\ 05^{'}\cdot 632\mathrm{N.}\ 56^{\circ}\ 29^{'}\cdot 050\mathrm{E.} \\ 13^{\circ}\ 24^{'}\cdot 432\mathrm{N.}\ 56^{\circ}\ 48^{'}\cdot 995\mathrm{E.} \\ \\ \text{Gulf of Aqaba to Red Sea} \\ 21^{\circ}\ 33^{'}\cdot 5\mathrm{N.}\ 39^{\circ}\ 06^{'}\cdot 7\mathrm{E.} \\ 21^{\circ}\ 37^{'}\cdot 9\mathrm{N.}\ 38^{\circ}\ 48^{'}\cdot 8\mathrm{E.} \\ 23^{\circ}\ 55^{'}\cdot 8\mathrm{N.}\ 37^{\circ}\ 32^{'}\cdot 0\mathrm{E.} \\ 27^{\circ}\ 08^{'}\cdot 9\mathrm{N.}\ 35^{\circ}\ 12^{'}\cdot 8\mathrm{E.} \\ 27^{\circ}\ 56^{'}\cdot 6\mathrm{N.}\ 34^{\circ}\ 27^{'}\cdot 9\mathrm{E.} \\ 29^{\circ}\ 18^{'}\cdot 0\mathrm{N.}\ 34^{\circ}\ 56^{'}\cdot 9\mathrm{E.} \\ \\ \text{Saudi Arabia West 1} \\ 27^{\circ}\ 08^{'}\cdot 9\mathrm{N.}\ 35^{\circ}\ 12^{'}\cdot 8\mathrm{E.} \\ 27^{\circ}\ 21^{'}\cdot 3\mathrm{N.}\ 35^{\circ}\ 40^{'}\cdot 4\mathrm{E.} \\ \\ \text{Saudi Arabia West 2} \\ 23^{\circ}\ 55^{'}\cdot 8\mathrm{N.}\ 37^{\circ}\ 32^{'}\cdot 0\mathrm{E.} \\ 24^{\circ}\ 04^{'}\cdot 8\mathrm{N.}\ 38^{\circ}\ 01^{'}\cdot 4\mathrm{E.} \\ \end{array}$

Mariners are advised to navigate with caution in these areas.

Charts will be updated when works are complete.

Former Notice 4071(P)/21 is cancelled.

NOTE: Content of Notice unchanged, re-issued to include Chart 2441.

(WGS84 DATUM)

Charts affected - 12 (INT 7142) - 38 (INT 7019) - 58 (INT 7314) - 158 (INT 7008) - 159 (INT 7010) - 327 (INT 7145) - 801 (INT 7143) - 1268 - 2375 (INT 7132) - 2441 (INT 7233) - 2442 - 2443 (INT 7238) - 2444 (INT 7239) - 2523 (INT 7250) - 2599 (INT 7150) - 2658 (INT 7149) - 2659 (INT 7148) - 2851 - 2882 (INT 7264) - 2883 (INT 7260) - 2884 (INT 7278) - 2886 (INT 7243) - 2887 (INT 7232) - 2888 (INT 7199) - 2889 (INT 7211) - 2895 - 3171 - 3172 - 3174 (INT 7209) - 3175 (INT 7212) - 3176 (INT 7216) - 3520 (INT 7200) - 3723 - 3734 (INT 7261) - 3736 (INT 7258) - 3737 (INT 7255) - 3738 (INT 7254) - 3759 - 3760 - 3761 - 3774 (INT 7275) - 3775 - 3786 - 3788 (INT 7265) - 3790 (INT 7252) - 3842 (INT 7292) - 3950 (INT 7244)

4. CORRECTION TO ADMIRALTY PUBLICATIONS:

. Amendments to Sailing Direction Correction:

NP63 Persian Gulf Pilot (2021 Edition)

Iran - Gulf of Oman - Khalīj-e Chābahār -Chābahār — Depths

103

Paragraph 4.20 1 Replace by:

Controlling depths:

A minimum depth of $10.7\,$ m can be maintained in the approaches to Shahid Beheshti Port.

The approach channel to Shahid Kalantari Port is dredged to a depth of 12.5 m (2004).

Tidal levels. Mean maximum range about 1.8 m; mean minimum range about 0.9 m. For further information, see *ADMIRALTY Tide Tables Volume 3*.

Local weather. Prevailing winds are the NE and SW monsoons. SSE winds cause a heavy sea to break on the shores of the bay except in the vicinity of the town which is well sheltered.

ENC IR6TZE01 (1.000); ENC IR586021 (1.000)

[NP63-No 38-Wk 04/22]

15

Iran - Kalat to Bushehr - Directions; wrecks

133

Paragraph 6.67 4 lines 1-7 Replace by:

SW of a stranded wreck (28°57'·17N 50°44'·95E), marked by a light buoy (W cardinal).

The track then leads to a position SW of Būshehr $(28^{\circ}58'\cdot00N~50^{\circ}50'\cdot00E)$. A wreck $(28^{\circ}57'\cdot33N~50^{\circ}44'\cdot16E)$ lies close S of the outer end of the Būshehr approach channel.

ENC IR47307C (2.000)

[NP63-No 39-Wk 04/22]

Iran - Būshehr - Directions; leading lights

134

Paragraph 6.81 including heading Replace by:

Approach channel 6.81

- From a position SW of the outer end of the approach channel, the track leads NE for about 5 miles through Khowr-e Deyreh, marked by light buoys (lateral).
- When abeam the inner anchorage (6.82), the track leads SE into Khowr-e Baḥrānī, also marked by light buoys (lateral), for 2½ miles until reaching the turning basin.

ENC IR47307C (2.000)

[NP63-No 40-Wk 04/22]

b. Amendments to Admiralty List of Light and Fog Signals:

NP77, Vol D Edition 2021. Weekly Edition No. 4, Dated 27 January 2022. *Last Updates: Weekly Edition No. 3, dated 20 January* 2022.

D1584 ES, I, 01642	- Llanes. Osa Breakwater. Head	43 25·30 N 4 44·81 W	FI G 5s	13	5 Green round concrete tower 5	e fl 0·5. TE 2021
D6370-2 ZA, , Z5986	- Struis Bay Harbour. Dir Lt 268°	34 47·91 S 20 03·42 E	Dir WRG	7	3 Red post	F G254°-266°(12°). F W266°-270°(4°). F R270°-282°(12°). TE 2021

NP77, Vol D Edition 2021. Weekly Edition No. 5, Dated 03 February 2022. *Last Updates: Weekly Edition No. 4, dated 27 January 2022.*

D2616 MA, , 17800 ES, I, 13760 FR, L2, 17940	Sidi Ifni	29 22·81 N 10 10·69 W	Fl(3+1)W 30s	57	25 Yellow square tower on building 13	(fl 0·3, ec 3·4) x 2, (fl 0·3, ec 11) x 2. FR lights on 4 posts 2·2M to the ENE. TE 2021
*		*				*
D3085·4 FR, L2, 21652	- Port Kamsar. KCT Jetty. NW Corner	10 39·05 N 14 37·14 W	Fl R 3s			
*	*	*	*	*	* *	*
D3085·5 FR, L2, 21654	- Port Kamsar. KCT Jetty. SW Corner	10 39·03 N 14 37·14 W	Fl R 3s			
*	*	**	*	*	* *	*
D3086·4 FR, L2, 21642	- Port Kamsar. GAC Jetty. NA-01	10 38·16 N 14 37·84 W	Fl(3)R 5s		5 Red □ on beacon	••
*	*	ής	*	*	* *	*
D3086·5 FR, L2, 21644	- Port Kamsar. GAC Jetty. NA-02	10 38·04 N 14 37·88 W	Fl(3)G 5s		5 Green △ on beacon	
*	*	**	*	*	* *	*
D7354·2	- Lee Breakwater. Head. No 2	25 22·01 N 55 22·24 E	Fl W 3s	15	7 Red and white metal framework tower 12	
			*			

BA (3+4)22 16

c. Amendments to Admiralty List of Radio Signals:

VOLUME 2, NP282(1), Second Edition, 2021

Published Wk 11/21 (Last Updates: Weekly Edition No. 3 dated 20 January 2022)

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 80, CROATIA, below Rt Marjan Lt Buoy.

Insert:

t Oštra Lt 42°23′.59N 18°31′.86E	992381720	Real	21
---	-----------	------	----

(former update 11/21)

Croatian Notice 12/17/21 (RSDRA2021000002323) 4/22

PAGE 146, SPAIN (Mediterranean Coast), below Montjuich Lt.

Insert

Port de Llançà North Breakwater Lt Bn	42°22′·43N 3°09′·78E	992241144	Real	
Port de Llançà South Breakwater Lt Bn	42°22′·47N 3°09′·76E	992241143	Real	

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de Arenys de Mar West Breakwater Lt Bn.

Insert:

Puerto de Blanes Inner Breakwater Lt Bn	41°40′-40N 2°47′-84E	992241129	Real	
Puerto de Blanes Outer Breakwater Lt Bn	41°40′·35N 2°47′·80E	992241128	Real	

(former update 22/21)

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de Garraf West Breakwater Lt Bn.

Insert:

Puerto de la Selva Muelle de Punta Trench Lt Bn	42°20′-44N 3°12′-01E	992241136		Real	
--	----------------------	-----------	--	------	--

(former update 22/21)

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de Málaga ODAS Lt Buoy.

Insert

Puerto de Palamós Inner Breakwater Lt Bn	41°50′-61N 3°07′-44E	992241146	Real	
Puerto de Palamós Outer Breakwater Lt Bn	41°50′-50N 3°07′-20E	992241145	Real	

(former update 38/21)

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 146

, SPAIN (Mediterranean Coast), below Puerto de Roses Lt. Insert:

Puerto de Roses North Breakwater Lt Bn	42°15′-26N 3°10′-57E	992241148	Real	
Puerto de Roses South Breakwater Lt Bn	42°15′-09N 3°10′-62E	992241147	Real	

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de Sagunto Lt.

Insert:

Puerto de San Feliú de Guíxols Breakwater Lt Bn	41°46′·61N 3°01′·98E	992241153		Real	
--	----------------------	-----------	--	------	--

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 148, SPAIN (Mediterranean Coast), below Puerto de Vallcarca Breakwater Lt.

Insert:

Puerto Deportivo de L'Estartit East Breakwater Lt Bn	42°03′·04N 3°12′·34E	992241141	Real	
Puerto Deportivo de L'Estartit West Breakwater Lt Bn	42°03′·04N 3°12′·24E	992241142	Real	

(former update 22/21)

Spanish Bulletin 1/22 (RSDRA2022000002384) 4/22

PAGE 148, SPAIN (North Coast), below Bajo Picamillo Lt Bn.

Insert:

Biscay Marine Energy Platform Lt Buoy B1	43°27′·09N 2°53′·90W	992241016	Real	
Biscay Marine Energy Platform Lt Buoy No 2	43°27′·09N 2°52′·83W	992241015	Real	
Biscay Marine Energy Platform Lt Buoy No 3	43°27′-63N 2°52′-30W	992241014	Real	
Biscay Marine Energy Platform Lt Buoy No 4	43°28′·16N 2°51′·76W	992241013	Real	

Spanish Bulletin 52/21 (RSDRA2021000355215) 4/22

VOLUME 6, NP286(8), Second Edition, 2021

Published Wk 13/21

(Last Updates: Weekly Edition No. 52 dated 30 December 2021)

PAGES 205 to 208, UNITED ARAB EMIRATES, DAS, JAZĪRAT (DAS ISLAND).

Delete entry and replace by:

DAS, JAZĪRAT (DAS ISLAND) UNCTAD LOCODE: AE DAS

25°09'N 52°53'E

Pilots

HOURS: H24

PROCEDURE:

- (1) $\textbf{Pilotage is compulsory} \ \text{for all vessels navigating within port limits}.$
- (2) **Pilot boards** in position 25°10′·00N 52°56′·00E (Das Zirkū North)

Vessel Traffic and Information Service

AREA:

The Das/Zirkū sector of Das VTIS is bounded by the following positions:

- (1) 25°16'-60N 53°03'-00E
- (2) 25°08'·10N 53°03'·70E
- (3) 25°02'·20N 53°08'·30E
- (4) 25°04'·00N 53°18'·70E
- (5) 25°11′·24N 53°27′·10E (6) 25°07′·70N 53°30′·70E
- (7) 24°48′-90N 53°11′-00E
- (8) 24°48′-90N 53°04′-80E
- (9) 25°00'·00N 52°53'·30E
- (10) 25°04′·50N 52°48′·00E
- (11)25°14′·00N 52°48′·00E
- (12)25°26′·50N 53°14′·00E (13)25°24′·92N 53°17′·40E

continued on next page

18

SERVICES:

Das VTIS provides the following services:

- (1) Information Service
- (2) Traffic Organisation Service
- (3) Navigational Assistance Service

CONTACT DETAILS:

Call: Das VTIS

VHF Channel: Ch 16; 12 **23** Telephone: +971(0)2 6021727 +971(0)2 6021728

Fax: +971(0)2 6021600 E-mail: vtisdas@adnoc.ae Website: https://ppa.adnoc.ae https://adnoc.ae/en

HOURS: H24

PROCEDURE:

- (1) **Active Participant Vessels:** The following vessels, calling at any of the Petroleum Ports, for whatever purpose, in passage through the VTIS Area shall be designated as an "Active Participant":
 - (a) Vessels of 50m LOA or above
 - (b) Vessels carrying dangerous cargo, irrespective of its size
 - (c) Vessels carrying passengers, irrespective of its size
- (2) **Passive Participant Vessels:** The following vessels shall be designated as a "Passive Participant":
 - (a) Vessels less than 50m LOA, calling at any of the petroleum ports, not carrying dangerous cargoes, or passengers
 - (b) Vessels on passage through the PPA-VTIS Area

REPORTING (ACTIVE PARTICIPANT):

- (1) Active Participant vessels shall submit SP-1 and SP-2 reports, in writing through their agent or direct to the applicable VTIS sector.
- (2) Any changes to the Sailing Plan shall be immediately reported to the VTIS without any delay.
- (3) Reports shall be properly prepared in the standard format and sent to the VTIS in a timely manner.
- (4) Vessels shall maintain a record of reporting details and all information provided by the VTIS in the ship's log.
- (5) Sailing Plan-1 (SP-1 report) shall be provided:
 - (a) 72h before entering the VTIS sector
 - (b) 2h before departure from the port
- (6) Sailing Plan-2 (SP-2 report) shall be provided:
 - (a) 48h before entering the VTIS sector
 - (b) 24h before entering the VTIS sector
- (7) All Active Participants shall report through their agent or directly to the relevant VTIS sector.

continued on next columnn

- (8) Reporting can also be carried out on the respective VHF channel of each sector when within range:
 - (a) 6h before entering the VTIS Area/Sector, (by VHF, or as soon as in range)
 - (b) 2h or 20 n miles (whichever comes first), thereafter at the time of entry into VTIS Sectors
 - (c) 2h before leaving the Terminal and entering VTIS Area through agent and/or by VHF directly to the VTIS
- (9) SP-1 reports are submitted using the following format:
 - (a) Vessel's name
 - (b) Vessel's call sign and IMO number.
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Request a Pilot (Y/N), Pilot Station (East Ghashā/Ghashā)
 - (e) Port/terminal bound for
 - (f) Reporting position (name of Reporting Point)
 - (g) Any deficiencies
- (10) SP-2 reports are submitted using the following format:
 - (a) Vessel's name
 - (b) Vessel's position
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Any deficiencies
- (11) **Reporting Points:** Active Participant vessels in passage through the VTIS area should provide a Call Point Position Report via VHF, to the VTIS, at the positions designated. Furthermore, vessels should provide this report on any change of sector. The following format should be used:
 - (a) Vessel's name
 - (b) Position

(12) Inward-bound vessels using the Das Deep Water Approach Channel report at the following positions:

Name	Position	Description
RP 1	25°27′·00N 53°20′·00E	Das Approach Channel Lt buoy
RP 2	25°25′-20N 53°12′-40E	Lt buoy No.1
RP 3	25°20′-60N 53°04′-85E	Das Deep Water Channel Lt buoy No.5
RP 4	25°17′-76N 53°01′-24E	Das Deep Water Channel Lt buoy No.7
RP 5	25°14′-36N 52°56′-86E	Das Deep Water Channel Lt buoy No.9

(13) Outward-bound vessels using the Das Deep Water Approach Channel report at the following positions:

Name	Position	Description
RP 1	25°14′·16N 52°59′·73E	Lt buoy No.10
RP 2	25°19′-21N 53°06′-09E	Lt buoy No.6
RP 3	25°24′·73N 53°15′·11E	Lt buoy No.2
RP 4	25°27′·00N 53°20′·00E	Das Approach Channel Lt buoy

REPORTING (PASSIVE PARTICIPANT):

- (1) Passive Participant Vessels are required to actively participate in the VTIS reporting and are advised to communicate their movements to the relevant VTIS centre, such vessels shall continuously monitor the VHF channel of the relevant VTIS and shall ensure that the advice given by the VTIS is followed.
- (2) Passive Participant vessels shall submit a Sailing Report through their agent or on VHF directly to the VTIS 2h prior to and upon entering the VTIS area, in the following format:
 - (a) Vessel's name, call sign and flag
 - (b) Vessel's position
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Any deficiencies

19

continued on next page

Port

CONTACT DETAILS:

Port Control

Call: Das Port Control VHF Channel: Ch 16; 12 Telephone: +971(0)2 6021726 +971(0)2 6028996 +971(0)2 8733029 E-mail: pctas.offshore@adnoc.ae

Hr Mr/PFSO

Telephone: +971(0)2 6021722 +971(0)2 6021723 Fax: +971(0)2 6028950 E-mail: ppadas@adnoc.ae

Senior Vice President Petroleum Ports Authority - Abu Dhabi

Telephone: +971(0)2 7071222 E-mail: jalkhamiri@adnoc.ae Website: https://ppa.adnoc.ae https://adnoc.ae/en

Das Island Agency (ADMA-OPCO)

VHF Channel: Ch 16; 12
Telephone: +971(0)2 6063415
+971(0)2 6063897
Fax: +971(0)2 6068188
F-mail: oscdas offshore@adnos

E-mail: oscdas.offshore@adnoc.ae oasciidas.offshore@adnoc.ae

HOURS: H24 PROCEDURE:

- (1) **Notice of ETA:** Vessels should advise ETA to the Das Hr Mr by e-mail at least 72h prior to arrival.
- (2) Vessels should confirm or amend such information 48h, 24h and 12h prior to arrival.
- (3) Vessels should confirm their final ETA to Port Control on VHF Ch 16 or 12, 4h prior
- (4) Vessels anchoring should advise Port Control on VHF Ch 16 or 12 of the following:
 - (a) Anchoring time (LT)
 - (b) Anchoring position (bearing and distance from Tanker Berth No 6 (SPM) (25°08'.04N 52°55'.63E))
- (5) All vessels at anchor should maintain a continuous listening watch on VHF Chs 16 and 12.
- (6) Vessels departing from the anchorage must obtain prior approval from Port Control by stating the following information:
 - (a) Intended time of heaving up anchor
 - (b) Reason for departure
 - (c) Time of departure

NOTE

Station is operated by Abu Dhabi National Oil Co, Petroleum Ports Authority (ADNOC-PPA).

ADNOC correspondence, (RSDRA2022000002921), 4/22

PAGES 227 to 229, UNITED ARAB EMIRATES, ZIRKŪ (JAZĪRAT ZARAKKŪH).

Delete entry and replace by:

ZIRKŪ (JAZĪRAT ZARAKKŪH)

24°53'N 53°05'E

UNCTAD LOCODE: AE ZUR

Pilots

HOURS: H24

PROCEDURE:

- (1) Pilotage is compulsory for all vessels navigating within port limits.
- (2) Pilot boards in the following position 25°00'.00N 53°02'.50E (Das Zirkū South)

Vessel Traffic and Information Service

ADEA

The Das/Zirkū sector of Das VTIS is bounded by the followiing positions:

(1) 25°16'.60N 53°03'.00E

(2) 25°08'·10N 53°03'·70E

(3) 25°02'·20N 53°08'·30E

(4) 25°04′·00N 53°18′·70E

(5) 25°11'·24N 53°27'·10E

(6) 25°07'·70N 53°30'·70E

(7) 24°48′·90N 53°11′·00E (8) 24°48′·90N 53°04′·80E

(9) 25°00′·00N 52°53′·30E

(10)25°04'.50N 52°48'.00E

(11)25°14′·00N 52°48′·00E

(12)25°26′·50N 53°14′·00E

(13)25°24′-92N 53°17′-40E

SERVICES:

Das VTIS provides the following services:

- (1) Information Service
- (2) Traffic Organisation Service
- (3) Navigational Assistance Service

CONTACT DETAILS:

Call: Das VTIS

VHF Channel: Ch 16; 12 **23** Telephone: +971(0)2 6021727 +971(0)2 6021728 Fax: +971(0)2 6021600

E-mail: vtisdas@adnoc.ae Website: https://ppa.adnoc.ae https://adnoc.ae/en

HOURS: H24 PROCEDURE:

20

- (1) **Active Participant Vessels:** The following vessels, calling at any of the Petroleum Ports, for whatever purpose, in passage through the VTIS Area shall be designated as an "Active Participant":
 - (a) Vessels of 50m LOA or above
 - (b) Vessels carrying dangerous cargo, irrespective of its size
 - (c) Vessels carrying passengers, irrespective of its size
- (2) Passive Participant Vessels: The following vessels shall be designated as a "Passive Participant":
 - (a) Vessels less than 50m LOA, calling at any of the petroleum ports, not carrying dangerous cargoes, or passengers
 - (b) Vessels on passage through the PPA-VTIS Area

REPORTING (ACTIVE PARTICIPANT):

- (1) Active Participant vessels shall submit SP-1 and SP-2 reports, in writing through their agent or direct to the applicable VTIS sector.
- (2) Any changes to the Sailing Plan shall be immediately reported to the VTIS without any delay.
- (3) Reports shall be properly prepared in the standard format and sent to the VTIS in a timely manner.

continued on next page

- (4) Vessels shall maintain a record of reporting details and all information provided by the VTIS in the ship's log.
- (5) Sailing Plan-1 (SP-1 report) shall be provided:
 - (a) 72h before entering the VTIS sector
 - (b) 2h before departure from the port
- (6) Sailing Plan-2 (SP-2 report) shall be provided:
 - (a) 48h before entering the VTIS sector
 - (b) 24h before entering the VTIS sector
- (7) All Active Participants shall report through their agent or directly to the relevant VTIS sector.
- (8) Reporting can also be carried out on the respective VHF channel of each sector when within range:
 - (a) 6h before entering the VTIS Area/Sector, (by VHF, or as soon as in range)
 - (b) 2h or 20 n miles (whichever comes first), thereafter at the time of entry into VTIS Sectors
 - (c) 2h before leaving the Terminal and entering VTIS Area through agent and/or by VHF directly to the VTIS
- (9) SP-1 reports are submitted using the following format:
 - (a) Vessel's name
 - (b) Vessel's call sign and IMO number.
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Request a Pilot (Y/N), Pilot Station (East Ghashā/Ghashā)
 - (e) Port/terminal bound for
 - (f) Reporting position (name of Reporting Point)
 - (g) Any deficiencies
- (10) SP-2 reports are submitted using the following format:
 - (a) Vessel's name
 - (b) Vessel's position
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Any deficiencies
- (11) Reporting Points: Active Participant vessels in passage through the VTIS area should provide a Call Point Position Report via VHF, to the VTIS, at the positions designated. Furthermore, vessels should provide this report on any change of sector. The following format should be used:
 - (a) Vessel's name
 - (b) Position

(12) Inward-bound vessels using the Zaqqum Channel report at the following positions:

Name	Position	Description
RP 1	25°06′-50N 53°25′-00E	Zaqqum Lt buoy
RP 2	25°02′.5N 53°19′.60E	Zaqqum East Lt buoy
RP 3	24°56′-70N 52°59′-80E	Zaqqum West Lt buoy

(13) Outward-bound vessels using the Zaqqum Channel report at the following positions:

Name	Position	Description
RP 1	24°56′·70N 52°59′·80E	Zaqqum West Lt buoy
RP 2	25°02′.5N 53°19′.60E	Zaqqum East Lt buoy
RP 3	25°06′.50N 53°25′.00E	Zaqqum Lt buoy

REPORTING (PASSIVE PARTICIPANT):

- (1) Passive Participant Vessels are required to actively participate in the VTIS reporting and are advised to communicate their movements to the relevant VTIS centre, such vessels shall continuously monitor the VHF channel of the relevant VTIS and shall ensure that the advice given by the VTIS is followed.
- (2) Passive Participant vessels shall submit a Sailing Report through their agent or on VHF directly to the VTIS 2h prior to and upon entering the VTIS area, in the following format:
 - (a) Vessel's name, call sign and flag
 - (b) Vessel's position
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Any deficiencies

continued on next column

Port

CONTACT DETAILS:

Port Control

Call: Das Port Control VHF Channel: Ch 16; 12 Telephone: +971(0)2 6021726 +971(0)2 6028996 +971(0)2 8733029 E-mail: pctas.offshore@adnoc.ae

Hr Mr/PFSO

Telephone: +971(0)2 6021722 +971(0)2 6021723 Fax: +971(0)2 6028950 E-mail: ppadas@adnoc.ae

Senior Vice President Petroleum Ports Authority - Abu Dhabi

Telephone: +971(0)2 7071222 E-mail: jalkhamiri@adnoc.ae Website: https://ppa.adnoc.ae https://adnoc.ae/en

Zirku ADNOC Offshore Agency

Telephone: +971(0)2 6080716 +971(0)2 6056251 Fax: +971(0)2 6080718 +971(0)2 6056251

E-mail: osogszirku.offshore@adnoc.ae

HOURS: H24

PROCEDURE:

- (1) **Notice of ETA:** Vessels should advise ETA to the Das Hr Mr by e-mail at least 72h prior to arrival.
- (2) Vessels should confirm or amend such information 48h, 24h and 12h prior to arrival.
- (3) Vessels should confirm their final ETA to Port Control on VHF Ch 16 or 12, 4h prior to arrival.
- (4) Vessels anchoring should advise Port Control on VHF Ch 16 or 12 of their anchoring time (LT)
- (5) All vessels at anchor should maintain a continuous listening watch on VHF Chs 16 and 12.
- (6) Vessels departing from the anchorage must obtain prior approval from Port Control by stating the following information:
 - (a) Intended time of heaving up anchor
 - (b) Reason for departure
 - (c) Time of departure

ADNOC correspondence, (RSDRA2022000003036), 4/22

VOLUME 1, NP281(1), Second Edition, 2021 Published Wk 42/21

(Last Updates: Weekly Edition No. 50 dated 16 December 2021)

MARITIME RADIO STATIONS

PAGE 70, below CHANNEL ISLANDS (UK) section.

						COMOROS
COMOROS MARITIME OPE	RATIONAL CENTRE (CNOM	IC)				
Control Centre: 11°43′-00S 43°	15'-00E					
Telephone: +269 7737964 +269 3217913						
			Email:	comorosmoc@gmail.com		
RT (HF)						
	Position	Trar	nsmits	Receives		Hours of Watch
		6	216	6216		H24

SHOM Publication 92 2022 Edition. (RSDRA2022000002816) 5/22

VOLUME 2, NP282(1), Second Edition, 2021

Published Wk 11/21 (Last Updates: Weekly Edition No. 4 dated 27 January 2022)

RADAR BEACONS

PAGE 54, UNITED ARAB EMIRATES (Persian Gulf Coast), below 77220 Price Shoal. Insert:

Mugharraq Port Entrance Channel Safe Water Lt Buoy	24°12′-40N 52°31′-90E	3 & 10				М		77240
---	-----------------------	--------	--	--	--	---	--	-------

AD Ports Group Notice 16/2021 and AD Ports Group correspondence (RSDRA2022000003201 & RSDRA2022000003203) 5/22

AUTOMATIC IDENTIFICATION SYSTEM (AIS)

PAGE 146, SPAIN (Mediterranean Coast), below Port de Llançà South Breakwater Lt Bn. Insert:

Port Industrial d'Alcanar Inner Dock Lt Bn	40°34′·37N 0°33′·12E	992241121	Real	
Port Industrial d'Alcanar Outer Dock Lt Bn	40°34′-30N 0°33′-38E	992241120	Real	

(former update 4/22)

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

BA (3+4)22 22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de Blanes Outer Breakwater Lt Bn.

Insert:

Puerto de Cambrils East Breakwater Lt Bn	41°03′-61N 1°03′-63E	992241130	Real	
Puerto de Cambrils West Breakwater Lt Bn	41°03′·76N 1°03′·72E	992241131	Real	

(former update 4/22)

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de la Selva Muelle de Punta Trench Lt Bn.

Insert:

Puerto de L'Ametila de Mar East Breakwater Lt Bn	40°52′.65N 0°48′.17E	992241122	Real	
Puerto de L'Ametlla de Mar West Breakwater Lt Bn	40°52′-76N 0°48′-12E	992241123	Real	
Puerto de L'Ampolla East Breakwater Lt Bn	40°48′-46N 0°42′-63E	992241124	Real	
Puerto de L'Ampolla West Breakwater Lt Bn	40°48′-56N 0°42′-58E	992241125	Real	
Puerto de Les Cases de Alcanar Inner Breakwater Lt Bn	40°33′·11N 0°31′·94E	992241133	Real	
Puerto de Les Cases de Alcanar Outer Breakwater Lt Bn	40°33′·12N 0°32′·05E	992241132	Real	
Puerto de Málaga East Breakwater Lt Bn	36°41′-93N 4°24′-91W	992242001	Real	

(former update 4/22)

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 146, SPAIN (Mediterranean Coast), below Puerto de San Feliú de Guíxols Breakwater Lt Bn.

Insert:

Puerto de Tarragona Repsol	41°04′·93N 1°12′·46E		Real	
Refinery Dock Lt Bn	41 04 00141 12 402		rioui	

(former update 4/22)

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 148, SPAIN (Mediterranean Coast), below Puerto Deportivo de L'Estartit West Breakwater Lt Bn.

Insert:

Puerto Pesquero de Deltebre East Breakwater Lt Bn	40°43′·05N 0°50′·73E	992241134	Real	
Puerto Pesquero de Deltebre West Breakwater Lt Bn	40°43′·04N 0°50′·67E	992241135	Real	

(former update 4/22)

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 148, SPAIN (Mediterranean Coast), below Río Llobregat Lt.

Insert

Sant Carles de la Rápita Commercial Port Breakwater Lt Bn	40°36′-83N 0°35′-94E	992241150	Real	
Sant Carles de la Rápita East Breakwater Lt Bn	40°36′-93N 0°36′-21E	992241151	Real	

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 148, SPAIN (Mediterranean Coast), below Sant Carles de la Rápita Lt.

Insert:

Sant Carles de la Rápita South Breakwater Lt Bn	40°36′-55N 0°36′-27E	992241149	Real	
Sant Carles de la Rápita West Breakwater Lt Bn	40°36′-97N 0°36′-14E	992241152	Real	

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 148, SPAIN (North Coast), below Biscay Marine Energy Platform Lt Buoy No 4.

Insert:

Biscay Marine Energy Platform Lt Buoy No 5	43°28′·64N 2°51′·76W	992241012	Real	
Biscay Marine Energy Platform Lt Buoy No 6	43°28′-63N 2°52′-90W	992241011	Real	
Biscay Marine Energy Platform Lt Buoy No 7	43°27′-87N 2°53′-69W	992241010	Real	

(former update 4/22)

Spanish Bulletin 2/22 (RSDRA2022000003574) 5/22

PAGE 152, SPAIN (South West Coast), below Broa de Sanlucar Galonera South Lt Buoy No 7.

Insert:

Broa de Sanlucar La Jara Lt Buoy No 11	36°46′-96N 6°22′-91W			Real	
---	----------------------	--	--	------	--

Spanish Bulletin 52/21 (RSDRA2021000355215) 5/22

PAGE 186, UNITED ARAB EMIRATES (Persian Gulf Coast), below Mubarraz Lt Buoy M18. Insert:

Mugharraq Port Entrance Channel Lt Buoy No MW-01	24°11′.43N 52°33′.09E	994701258	Real	
Mugharraq Port Entrance Channel Lt Buoy No MW-02	24°11′.53N 52°33′.19E	994701259	Real	
Mugharraq Port Entrance Channel Lt Buoy No MW-09	24°11′·06N 52°33′·96E	994701260	Real	
Mugharraq Port Entrance Channel Lt Buoy No MW-10	24°11′·15N 52°33′·90E	994701261	Real	

24

former	update	13/21)

AD Ports Group Notice 16/2021 and AD Ports Group correspondence (RSDRA2022000003201 & RSDRA2022000003203) 5/22

BA (3+4)22

VOLUME 6, NP286(8), Second Edition, 2021

Published Wk 13/21

(Last Updates: Weekly Edition No. 4 dated 27 January 2022)

PAGES 209 & 210, UNITED ARAB EMIRATES, FUJAIRAH (FUJAYRAH).

Delete entry and replace by:

FUJAIRAH (FUJAYRAH) UNCTAD LOCODE: AE FJR 25°12′N 56°22′E

Pilots

CONTACT DETAILS:

VHF Channel: Ch 09

Telephone: +971(0)9 2070808 +971(0)9 2228777

E-mail: pilot_pof@fujairahport.ae

HOURS: H24

PROCEDURE:

(1) Pilotage is compulsory for all vessels except the following:

(a) UAE Coastguard vessels

(b) Vessels holding exemption licences

(2) Pilot boards in the following positions:

(a) 25°08'·80N 56°24'·00E

(b) 25°18′.90N 56°35′.00E (SPM Terminals)

Port

CONTACT DETAILS:

Port Control

Call: Fujairah Port Control VHF Channel: Ch 16; 12 Telephone: +971(0)9 2070808 +971(0)9 2228777 Fax: +971(0)9 2070861 (Office Hours)

+971(0)9 2070862 (AOH)

E-mail: mo_pof@fujairahport.ae (Office hours) ct_pof@fujairahport.ae (AOH)

Offshore Control

VHF Channel: Ch 10

Port Services

VHF Channel: Ch 12

Port Emergency

VHF Channel: Ch 69

Hr Mi

Telephone: +971(0)9 2070800

+971(0)50 9040407 (Mobile)

E-mail: hm_pof@fujairahport.ae

Marine Office

Telephone: +971(0)9 2070802

E-mail: mo_pof@fujairahport.ae (Office hours)

VOPAK (VHFL) Terminal

Telephone: +971(0)9 2281800 (Terminal Manager)

+971(0)50 4890411 (Terminal Manager Mobile)

Fax: +971(0)9 2281371

Website: www.vopakhorizonfujairah.com

ADNOC Onshore Terminal

Telephone: +971(0)2 6079303 (Operations Manager)

+971(0)50 8555979 (Operations Manager Mobile)

Fax: +971(0)9 2235761 Website: www.adnoc.ae

continued on next column

FAPCO SPM Terminal

Telephone: +971(0)9 2086131 (Control Room) +971(0)9 2086132 (Control Room) +971(0)9 2086133 (Control Room) +971(0)9 2086134 (Control Room) E-mail: controlroomengineers@fapco.ae

Dibā Port

Telephone: +971(0)9 2442300

HOURS: H24

PROCEDURE:

(1) **Notice of ETA:** Vessels should send ETA 72h before arrival confirming 48h, 24h and 12h in advance through the agent, stating:

(a) ETA

(b) Arrival draught

(2) Tankers visiting the oil terminal must send a Tanker Pre-arrival Information Form via the agent, at least 72h in advance of ETA.

(3) Vessels should contact Fujairah Port Control on VHF Ch 16 or 12 when within VHF range.

(4) **Notice of ETD:** Vessels should give 2h notice of ETD immediately upon completion of loading arm disconnection. Requests for Pilots should also be forwarded at this time.

ADNOC correspondence, (RSDRA2022000003039), 5/22

PAGE 212, UNITED ARAB EMIRATES, JABAL AZ ZANNAH (JEBEL DHANNA TERMINAL, including Ar Ru'ays (Ruwais)), Vessel Traffic and Information Service, REPORTING (ACTIVE PARTICIPANT), section (10).

Delete and replace by:

(10) SP-2 reports are submitted using the following format:

(a) Vessel's name

(b) Vessel's position

(c) Date, time and point of entry into VTIS area (UTC)

(d) Any deficiencies

ADNOC correspondence, (RSDRA2022000002922), 5/22

PAGE 214, UNITED ARAB EMIRATES, JABAL AZ ZANNAH (JEBEL DHANNA TERMINAL, including Ar Ru'ays (Ruwais)), Vessel Traffic and Information Service, REPORTING (PASSIVE PARTICIPANT), section (2).

Delete and replace by:

- (2) Passive Participant vessels shall submit a Sailing Report through their agent or on VHF directly to the VTIS 2h prior to and upon entering the VTIS area, in the following format:
 - (a) Vessel's name, call sign and flag
 - (b) Vessel's position
 - (c) Date, time and point of entry into VTIS area (UTC)
 - (d) Any deficiencies

ADNOC correspondence, (RSDRA2022000002922), 5/22

PAGE 214, UNITED ARAB EMIRATES, JABAL AZ ZANNAH (JEBEL DHANNA TERMINAL, including Ar Ru'ays (Ruwais)), Port, CONTACT DETAILS section.

Delete and replace by:

CONTACT DETAILS:

Port Control

Call: Ruwais Port Control VHF Channel: Ch 16; 09 Telephone: +971(0)2 6021666 +971(0)2 6021777 +971(0)2 6021606 +971(0)2 6021607

Fax: +971(0)2 6021600 E-mail: ruwaispc@adnoc.ae

Hr Mr/PFSO

Telephone: +971(0)2 6021717 +971(0)2 6021771 +971(0)2 6021721 Fax: +971(0)2 6021700 E-mail: pparuwais@adnoc.ae

Senior Vice President Petroleum Ports Authority - Abu Dhabi

Telephone: +971(0)2 7071222 E-mail: jalkhamiri@adnoc.ae Website: https://ppa.adnoc.ae www.adnoc.ae/en

ADNOC correspondence, (RSDRA2022000002922), 5/22

PAGES 217 & 218, UNITED ARAB EMIRATES, KHOR PORT, Ra's al Khaymah.

Delete entry.

RAK Ports correspondence, (RSDRA2022000003045), 5/22

PAGES 219 & 220, UNITED ARAB EMIRATES, MĪNĀ' SAQR.

Delete entry and replace by:

MĪNĀ' SAQR

UNCTAD LOCODE: AE MSA

25°59′N 56°03′E

Pilots

HOURS: H24

PROCEDURE:

- (1) Pilotage is compulsory and is available H24.
- (2) ETAs may be sent to Saqr Port Pilots via the Saqr Port Authority Port Control Tower.
- (3) **Pilot boards** in the following positions:
 - (a) 26°01'.00N 56°02'.48E
 - (b) 26°01'·80N 56°00'·21E (Deepwater Bulk Terminal)

Port

CONTACT DETAILS:

Port Control

Call: Saqr Port Control VHF Channel: Ch 16; 14 Telephone: +971(0)7 2056161 +971(0)7 2056163 +971(0)7 2056160

E-mail: spatower@rakports.ae

continued on next column

Marine Ops

VHF Channel: Ch 09

Marine Documentation

Telephone: +971(0)7 2056164 +971(0)7 2056264 Website: https://rakports.ae/marine/

Port Authority

Telephone: +971(0)7 2056000 E-mail: info@rakports.ae Website: www.rakports.ae

Hr Mr

Telephone: +971(0)7 2056164 E-mail: mmagee@rakports.ae

HOURS: H24 PROCEDURE:

- (1) **Notice of ETA:** The vessel's local agent shall send Pre-arrival Notification in the defined reporting format. Standardised 'Berthing Request Form' and 'Pre-Arrival Forms' are available for download at the Marine section of RAK Ports website https:// rakports.ae/marine. They must be fully completed and sent to Control Tower no later than 48h prior to arrival. If the duration of the voyage is less than 48h, then these must be provided no later than the time of departure from the previous port.
- (2) The Master or vessel's agent should send an updated ETA, 48h, 24h, and 12h in advance to the Control Tower, then with the amendments at 6h and 3h notice on VHF Ch 14
- (3) Vessel should maintain a continuous listening watch on VHF Ch 16 when within 12 hours of arrival.
- (4) A continuous listening watch on VHF Chs 14 and 16 should be maintained at all times when the vessel is within the port limits.
- (5) Vessel must confirm arrival to Saqr Port Control on VHF Ch 14 when the vessel is within the port limits stating the following information:
 - (a) Vessel's name
 - (b) Position (by bearing and distance from the breakwater)
 - (c) ETA to Pilot Station
 - (d) Type, IMO number
 - (e) Flag
 - (f) Class
 - (g) LOA
 - (h) Beam
 - (i) gt
 - (j) nt
 - (k) Arrival draught (forward & aft)
 - (I) Last port of call
 - (m) Security level
 - (n) Arms and ammunition declaration (if applicable)
 - (o) Dangerous cargo details (if applicable)
 - (p) Defects or deficiency details (if applicable)
 - (q) Stowaway details (if applicable)
 - (r) Number of passengers and crew (only applicable for passenger vessels)
 - (s) Crew/passenger health conditions
- (6) RAK Ports has introduced a **Dangerous Goods Approved Code of Practice** to assist port users in implementing the requirements of RAK Ports, regarding safe transport, handling and short-term storage of Dangerous Goods within the jurisdiction of the RAK Ports. The code and associated forms can be downloaded from Marine section of the Port Authority's website.

NOTE:

- (1) The Master must confirm that the vessel's Pilot ladder is safe to use and complies with all international regulations.
- (2) Masters of all vessels and their agents are advised that a failure to report defects, Pre-arrival and Arrival Reports at port limits, may result in a delayed entry into the Port.

RAK Ports correspondence, (RSDRA2022000003041), 5/22

PAGE 226, UNITED ARAB EMIRATES, below RAK MARITIME CITY entry.

Insert new entry:

RAS AL KHAIMAH (KHOR) PORT

25°49'N 55°57'E

UNCTAD LOCODE: AE MSA

Pilots

HOURS: H24

PROCEDURE:

- (1) Pilotage is compulsory and is available H24.
- (2) ETAs may be sent to Ras Al Khaimah (Khor) Port Pilots via the Ras Al Khaimah (Khor) Port Control Tower.
- (3) Pilot boards in the vicinity of the Fairway Lt buoy (25°50′-50N 55°56′-05E).

Port

CONTACT DETAILS:

Port Control

Call: Ras al Khaimah (Khor) Port Control

VHF Channel: Ch 16; 71 Telephone: +971(0)7 2029807 E-mail: khrtower@rakports.ae

Port Authority

Telephone: +971(0)7 2056000 E-mail: info@rakports.ae Website: www.rakports.ae

Hr Mr

Telephone: +971(0)7 2056164 E-mail: mmagee@rakports.ae

HOURS: H24 PROCEDURE:

- (1) **Notice of ETA:** The vessel's local agent shall send Pre-arrival Notification in the defined reporting format. Standardised 'Berthing Request Form' and 'Pre-Arrival Forms' are available for download at the Marine section of RAK Ports website https:// rakports.ae/marine. They must be fully completed and sent to Control Tower no later than 48h prior to arrival. If the duration of the voyage is less than 48h, then these must be provided no later than the time of departure from the previous port.
- (2) The Master or vessel's agent should send an updated ETA, 48h, 24h, and 12h in advance to the Control Tower, then with the amendments at 6h and 3h notice on VHF Ch 71
- (3) Vessel should maintain a continuous listening watch on VHF Ch 16 when within 12 hours of arrival.
- (4) A continuous listening watch on VHF Chs 71 and 16 should be maintained at all times when the vessel is within the port limits.
- (5) Vessel must confirm arrival to Ras Al Khaimah (Khor) Port Control on VHF Ch 71 when the vessel is within the port limits stating the following information:
 - (a) Vessel's name
 - (b) Position (by bearing and distance from the breakwater)
 - (c) ETA to Pilot Station
 - (d) Type, IMO number
 - (e) Flag
 - (f) Class
 - (g) LOA
 - (h) Beam
 - (i) gt
 - (j) nt
 - (k) Arrival draught (forward & aft)
 - (I) Last port of call
 - (m) Security level
 - (n) Arms and ammunition declaration (if applicable)
 - (o) Dangerous cargo details (if applicable)
 - (p) Defects or deficiency details (if applicable)
 - (q) Stowaway details (if applicable)
 - (r) Number of passengers and crew (only applicable for passenger vessels)
 - (s) Crew/passenger health conditions

continued on next column

(6) RAK Ports has introduced a **Dangerous Goods Approved Code of Practice** to assist port users in implementing the requirements of RAK Ports, regarding safe transport, handling and short-term storage of Dangerous Goods within the jurisdiction of the RAK Ports. The code and associated forms can be downloaded from Marine section of the Port Authority's website.

NOTE

- (1) The Master must confirm that the vessel's Pilot ladder is safe to use and complies with all international regulations.
- (2) Masters of all vessels and their agents are advised that a failure to report defects, Pre-arrival and Arrival Reports at port limits, may result in a delayed entry into the Port.

RAK Ports correspondence, (RSDRA2022000003045), 5/22

ADMIRALTY CHART AGENT / DISTRIBUTOR INFORMATION

NP131 - Catalogue of ADMIRALTY Charts (NP131), 2022 Edition

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors

Page 5, Distributor Section,

Amend:

OneOcean (Singapore)
230 Victoria Street
Level 15 Bugis Junction Towers
188024
T: +65 6545 9880
F: +65 6545 8892
singapore@oneocean.com
www.oneocean.com
Paper, Digital
International Marine Services (Pvt) Ltd
No 96, St. Andrews Road
Modara
Colombo 15
T: +94 71 072 2846
srilanka@elcome.com
www.elcome.com
Paper, Digital, POD

This is an amendment to a current listing.

NP131 - Catalogue of ADMIRALTY Charts (NP131), 2022 Edition

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors

Page 6, Distributor Section, Insert:

Weilbach Canada Ltd
#1520,1100 Melville Street
Vancouver
V6E 4A6
Canada
T: +1 604 563 1100
operations@weilbach.com
http://www.weilbach.com
Paper, Digital, POD

Page 7, ADMIRALTY Technical Solution Providers, Insert:

HiFleet
Room 403, Building 16
218 HaiJiLiu Road
Nanhui, New City, Pudong
Shanghai
201306
China
T: +86 021 58991269
F:
sales@hifleet.com
https://www.hifleet.com
AVCSOnline

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors (continued)

Page 4, Distributor Section, Amend:

Bogerd Martin (Tianjin) Marine Equipment
Co., Ltd
RM 408, RuiWan International Center, No.1
RD, XinGang
TangGu BinHai, New District
Tianjin
300456
T: +86 22 257 62721
F: +86 22 257 62722
charts.tianjin@bogerdmartin.com
www.bogerdmartin.com
Paper, Digital, POD

This is an amendment to a current listing.

Page 4, Distributor Section, Amend:

Bogerd Martin Marine (Hong Kong) Ltd
2501 Ever Gain Plaza
88 Container Port Road
Kwai Chung
Hong Kong
T: +852 3565 4410
F: +852 3565 4414
sales.hongkong@bogerdmartin.com
www.bogerdmartin.com
Paper, Digital, POD

This is an amendment to a current listing.

Page 4, Distributor Section, Amend:

Bogerd-Martin NV
Oude Leeuwenrui 37
B-2000
Antwerpen
T: +32 (0)3 213 4170
F: +32 (0)3 232 6167
sales@bogerdmartin.com
www.bogerdmartin.com
Paper, Digital, POD

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors (continued)

Page 4, Distributor Section,

Amend:

Shenzhen Goldsailocean Navigation Article
Co., Ltd
17F, United Bldg., No. 1069 Nanhai
Boulevard
Nanshan District
Shenzhen, 518066
T: +86 755 2682 0209
F: +86 755 2667 7308
shipser@gsocn.com
www.gsocn.com
Paper, Digital, POD

This is an amendment to a current listing.

Page 4, Distributor Section, Amend:

Shenzhen Goldsailocean Navigation Article Co., Ltd
Rm. 1603, Gangyue International Building Free Trade Port Area, No. 89 Huanhai Road, Shandong Zhifu District, Yantai
T: +86 535 680 0050
F: +86 535 680 0052
ytshipping@gsocn.com
www.gsocn.com
Paper, Digital

This is an amendment to a current listing.

Page 4, Distributor Section, Amend:

Shenzhen Goldsailocean Navigation Article
Co., Ltd
Room D, 56F, Tower 3B Cullian West 2
No. 28, Sham Mong Road
Sham Shui Po
Hong Kong
T: +852 6944 6153
hk@gsocn.com
www.gsocn.com
Paper, Digital

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors (continued)

Page 5, Distributor Section, Amend:

The Tyneside Nav Charts & Publications
Shop 11 John Ross House
22 Margaret Mncadi Avenue
Durban, 4001
T: +27 3133 77005
F: +27 3133 28139
admin@tyneside.co.za
www.tyneside.co.za
Paper, Digital, POD

This is an amendment to a current listing.

Page 5, Distributor Section, Amend:

Viking Life-Saving Equipment Iceland ehf
Ishella 7
Hafnarfjordur
220
T: +354 544 2270
F: +354 544 2271
sjokort@viking-life.com
www.viking-life.com
Paper, Digital, POD

This is an amendment to a current listing.

Page 5, Distributor Section, Amend:

Charts International
Unit 23 Foregate Square
Table Bay Boulevard
Cape Town
T: +27 21 419 7700
F: +27 21 419 0580
info@chartsinternational.co.za
www.chartsinternational.co.za
Paper, Digital, POD

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors (continued)

Page 5, Distributor Section, Amend:

CNC
1st Floor, 25 Bank Street
Fort, Mumbai
400023
T: +91 222 660 525
F: +91 222 670 896
sales@emariner.net
www.ccmarine.in
Paper, Digital, POD

This is an amendment to a current listing.

Page 5, Distributor Section, Amend:

Datema Delfzijl
Zeesluizen 8
Farmsum
Delfzijl
9936 HX
T: +31 596 635 252
F: +31 596 615 245
sales@datema.nl
www.datema.nl
Paper, Digital, POD

This is an amendment to a current listing.

Page 5, Distributor Section, Amend:

Japan Hydrographic Charts & Publications Co. Ltd
Bay Wing Kobe Bldg. 8F, 85-I
Edomachi, Chuo-Ku, Kobe 650-0033
T: +81 78 331 4888
F: +81 78 392 4648
jhc-all@molgroup.com
www.jhchart.co.jp
Paper, Digital, POD

 $Amendments\ to\ Part\ 1, \textbf{ADMIRALTY}\ \textbf{Authorised}\ \textbf{Chart}\ \textbf{Agents}\ /\ \textbf{Distributors}\ (\textbf{continued})$

Page 5, Distributor Section, Amend:

Navtor Nautic AB	
Svalörtsgatan 16 Västra Frölunda 42668	
T: +46 3169 5550	
F: +46 3171 15357	
nautic@navtor.com	
www.navtor.com	
Paper, Digital, POD	

This is an amendment to a current listing.

Page 5, Distributor Section, Amend:

RST Navigation
Room No. 5, Third Floor
192-194, Bazar Gate
(Perin Nariman Street)
Fort, Mumbai
400001
T: +91 22 6237 1136
F: +91 22 6639 0113
mumbaisales@rstnavigation.com
www.rstnavigation.com
Paper, Digital

This is an amendment to a current listing.

Page 6, Distributor Section, Amend:

Martek Marine Ltd.
Adwick Park, Manvers
Rotherham, South Yorkshire S63 5AB
T: +44 1709 599 222
F: +44 1709 871 873
sales@martek-marine.com
www.martek-marine.com
Digital

Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors (continued)

Page 6, Distributor Section, Amend:

Akademi Denizcilik
Evliya Celebi Mah. Genc Osman Cad.
No:45-B
Istanbul, Tuzla
34944
T: +90 212 249 6731
F: +90 212 243 6794
admin@akademidenizcilik.com
www.akademidenizcilik.com
Paper, Digital, POD

This is an amendment to a current listing.

Page 6, Distributor Section, Amend:

Voyager Worldwide Yasden Denizcilik A.S
Yayla Mah, Ayisigi Sok
Rumeli Evleri A Blok No:13/A
No. 21/22, Tuzla
Istanbul, 34933
T: +90 216 493 7401
F: +90 216 493 7402
customerservice@voyagerww.com.tr
www.voyagerww,com.tr
Paper, Digital, POD

This is an amendment to a current listing.

Page 6, Distributor Section, Amend:

StormGeo AS
Unit 1375 Aztec West
Bristol
BS32 4RX
T: +44 1454 617636
shipping.orders@stormgeo.com
www.stormgeo.com
Paper, Digital, POD


NP131 - Catalogue of ADMIRALTY Charts (NP131), 2022 Edition Amendments to Part 1, ADMIRALTY Authorised Chart Agents / Distributors (continued)


Page 6, Distributor Section, Amend:


StormGeo AS
Universitetsgata 8
Oslo
N-0164
T: +47 2200 8500
F: +47 2200 8501
shipping.orders@stormgeo.com
www.stormgeo.com
Digital

This is an amendment to a current listing.


• denotes chart available in the ADMIRALTY Raster Chart Service series.








Folio 40	NM	283/22	2 - 1 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0				NC/NE APR. 15		
Tracing Size		ious Update	-UK-		X		APR. 15		3713 ³ of 4
240 x 185 mm	<u> </u>	31/22					© British Crown Cop	yright 2022	
	24°33′N								
									/
									,/
				//					
			Jul. T			/&\)	(n		
					Q La	Ĺ .			
			(11)	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					
									54° 18′E
									mì
Caution: son	ne computer prin	nters might distort the trac	ings Users are	adviser	l to ch	eck ar	nd if necessary adi	ust settings on	their printer





Folio Chart No NE/NE NM 283/22 3715 ¹ of 2 40 SEP. 19 Previous Update Tracing Size 240 x 185 mm 31/22 © British Crown Copyright 2022 24°


Caution: some computer printers might distort the tracings. Users are advised to check and, if necessary, adjust settings on their printer.


Folio 40	NM 305/2	22	X	NC/NE OCT. 19	Chart No 2847
Tracing Size	Previous Update 249/22	·uk·		© British Crown Copy	
			<u> </u>		-
					30°00′N
		[8]			
	50°	00'E			
Caution: som	ne computer printers might distort th	ne tracings. Users are a	advised to check	and, if necessary, adju	st settings on their printer.

Folio	NM	305/22				X		/NE	Chart No	
40		ious Update					JUN	I . 16	2884	
Tracing Size 120 x 185 mm		416/21					■ British Crown Copyright 2022			
CTI										
50° 00′E									_	
mì										
		[8]								
								30°00′N		
								Ď,		
Caution: son	ne computer prir	nters might distort the trac	ings. Users are a	dvised	d to ch	eck ar	nd, if nece	essary, adju	ıst settings on their printer.	

Folio 40	NM 333/22	APPAZO OFFI		NC/NE Chart No MAR. 19 2444
Tracing Size	Previous Update	- UK.	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
120 x 185 mm	2123/21		X	© British Crown Copyright 2022
25°10′N				
		X ⁺ >,		
		()		
			52°	.° 50′E
Caution: son	ne computer printers might distort the tra	acings. Users are a	dvised to c	check and, if necessary, adjust settings on their printer.

Folio 40	NM Previ	333/22 ous Update	\$ \$\frac{1}{4} \\ \frac{1}{4} \\ \fr			X	NE/NE MAR. 19	Chart No 3179
Tracing Size 120 x 185 mm		278/22					│ ◎ British Crown Copy	yright 2022
					52°	50′		
			X T X					
			()					
Caution: som	ne computer prin	ters might distort the traci	ings. Users are a	dvise	d to ch	eck ar	nd, if necessary, adju	st settings on their printer.





Folio 40	NM 354/22	ORO ORO ORO ORO ORO ORO ORO ORO ORO ORO		1	NE R. 19	Chart No 3178
Tracing Size 120 x 185 mm	Previous Update 2977/21	ý k	X	-	h Crown Copy	
24°10′N		6				
		66				
				//29		
				9		
				53°	30'E	
Caution: som	ne computer printers might distort the trace	ings. Users are a	dvised to check a	nd, if ned	essary, adju	st settings on their printer.

Folio 40	NM 366/22	APA-IC OFF				NE/NE MAY 19	Cha	rt No 3734 ⁴ of
Tracing Size	Previous Update 340/20	·UK·		Χ		© British Crown Cop	vriaht 2022	4
120 X 100 HIIII	3 . 3 . = 3			<u> </u>		S British Crown Cop	yngni 2022	
								26°10′N
						114		
50°	42´E							
Caution: som	ne computer printers might distort the trace	cings. Users are a	dvised	to ch	eck ar	nd, if necessary, adju	ıst settings o	on their printer.

Folio 40

NM 366/22

NC/NE Chart No MAY 19 3734

3734 ² of

Tracing Size 240 x 185 mm	Previous Update 340/20	·uk·							4
240 x 185 mm	340/20	-3/A/A				© British Crown Cop	yright 202	22 I	
								26°12′N	
								12.7	
								_	
		(9							
		$(9_5)\odot$							
50									
50° 44′E									
щ									
Caution: som	e computer printers might distort the traci	ngs. Users are a	dvise	to ch	eck ar	nd, if necessary, adju	ust setting	gs on their prin	iter.

Folio 40

NM 366/22

Previous Update

NC/NE MAY 19

Chart No 3734 ³ of

Tracing Size 40 x 185 mm	340/20	© British Crown Copyright 2022
		26°
		=
		in lieu in lieu justin lieu justin lieu
		in lieu FI. x.4s in lieu j kso. y=o}
	I	
	~ <u>~</u>	
	<u></u>	

	Folio 40 Tracing Size 240 x 185 mm	NM 366/22 Previous Update 340/20	2	X			NC/NE MAY 19		art No 3734 of 4
					, વ	o <u>m</u> *	and the second	, room room	
				استهامه المساور	Burjed 39	, •			
	26 °12′N								
		"SULB" "SULB" "Minar							
	,								
		DO.R AN BS2							
								50°	42´E
	Caution: som	ne computer printers might distort the	tracings. Users are	advise	d to ch	eck ar	nd, if necessary, adju	ust settings	on their printer.

Folio 40	NM	366/22	A STATE OF THE STA			NC/NE JUN. 18	Char	t No 3737
Tracing Size		evious Update 1556/20	Š		X	© British Crown Copy		3101
	50° 40′E							
		DO.R			(9 ₅)⊙			
								26°10′N
Caution: som	l ne computer p	printers might distort the traci	ngs. Users are a	advised to ch	neck ar	nd, if necessary, adju	st settings on	their printer.

Folio	NM	400/22	APA,C				NC/NE	
40	Prev	vious Update	N. UK.				MAR. 19	2887
Tracing Size 120 x 185 mm		5078/21				Χ	© British Crown Cop	l pyright 2022
							55 ° 30′	Έ
		**	9					
			8/ -					
25°30′N								
Caution: son	ne computer pri	nters might distort the trac	ings. Users are a	dvise	d to ch	eck ar	nd, if necessary, adj	ust settings on their printer.

40 Tracing Size 120 x 185 mm Previous Update 5282/21 X	Folio	NM 400/22	APAIR OF				NC/N	- 1	Chart No
55° 30′E	40 Tracing Size		·uk·				NOV. Z		2888
	120 x 185 mm	J202/21					© British Crowr	Сору	right 2022
							55°	30 E	
			80						
25°30′N			-7						
25°30′N									
20 30 N	QE°00M								
	23 30 N								
Caution: some computer printers might distort the tracings. Users are advised to check and, if necessary, adjust settings on their printers	Caution: som	e computer printers might distort the trac	ings Users are	advised	to ch	eck an	d if necessary	adius	st settings on their printer

Folio	NM 400/22	SAPA, CO			X	NC/NE		Chart No
40	Previous Update					MAR. 1	9	2889
Tracing Size 120 x 185 mm	4596/21					© British Crown	I Copyr	ight 2022
						55°	30′E	
		9						
		6/						
25°30′N								
							<u> </u>	
Caution: son	ne computer printers might distort the tra	cings. Users are a	advised	d to ch	eck ar	nd, it necessary,	adjus	t settings on their printer.

Folio 40	NM 400/22	2			X	NC/NE		Chart No 2889
Tracing Size 120 x 185 mm	Previous Update 4596/21	· uk.				© British Crown		
				•		55°	30′E	
		9						
25°30′N								
Caution: son	ne computer printers might distort the	racings. Users are	advised	I to ched	ck ar	nd, if necessary,	adjust :	settings on their printer.

51 BA (3+4)22

Folio 40 Tracing Size 240 x 185 mm	NM 40 Previous Upo 30/22	0/22 date	- Single Control of the Control of t	X	NC/NE NOV. 21	3175
		·				
25 °40′N						
	9/// 9///		= 8) =	// 		
			đ	9"= 9"=	9 ==	
Caution: som	ne computer printers might	distort the tracings. U	Jsers are advis		° 20'E I, if necessary, adju	st settings on their printer.