NIHVA

| | | |
|---|---|---|
| **CLIENT** | **:** | **CIAL** |
| **PROJECT** | **:** | **Installation of door for hanger at Cochin Airport** |
| **LOCATION** | **:** | **Kochi, Kerala** |
| **PROJECT NO.** | **:** | **1714** |
| **DOCUMENT NO.** | **:** | **STATIC-REPORT-001** |

NIHVA

## TABLE OF CONTENTS


| Sr. No | Contents | Page No. |
|---|---|---|
| **1** | **Design Philosophy** | 3 |
| **2** | **Design Codes and Standards** | 4 |
| **3** | **Material Specifications Construction** | 4 |
| **4** | **Load Calculations** | 5-6 |
| 4.1 | Dead Load | |
| 4.2 | Live Load | |
| 4.3 | Equipment Loads | |
| 4.4 | Wind Load Calculations | |
| 4.5 | Seismic Load Calculation | |
| 5 | **Primary Loads and Load Combinations** | 7 |
| 6 | Annexture A- STDD Output | 7-196 |
| | | |
| | | |

## 1. Introduction purpose and scope

Cochin International Airport is located in Cochin city, Kerala state of India. The airport has two hangers for maintenance of planes adjacent to each other viz. 'Hanger 1' and 'Hanger 2'. Hanger 2 has a sliding door installed. Purpose of the door is to achieve weather protection from all sides in working area. Hanger 1 currently has no door and concerned authority wants to install new doors. NIHVA Technologies has been appointed to install the doors.

Purpose of this document to establish design and assumptions structural framing system to support the door. Currently there is an existing roof truss below which the door should be installed. In this calculation it will be established that existing roof truss can take additional dead load and operating load due to the door. Also, wind load will be applied and will be transferred to MWFRS of existing building. Additional framing is required to install the door. This framing will be connected to existing truss through bolted connections.

## 2. Design Philosophy

As door is installed on new framing, various DL and operating loads acting at different points on frame are transferred to existing truss. By truss action, the loads are then transferred to nearest columns and then the load is dispersed to foundation. The lateral loads due to wind shall be acting when door is closed. Wind braces are provided at locations mentioned in drawing. Lateral load is partially transferred through mullion to its foundation and partially to wind braces. Lateral load in braces is transferred through main wind force resisting system of roof truss. The end frames of structure are braced, which in turn will transfer load to respective foundations. The complete arrangement is modeled as 3D frame and analyzed/designed for worst combination of loads through STAAD.pro. Input and output files are enclosed which are self-explanatory. From the STAAD output, the support reactions for various primary load cases are tabulated accordingly.


## 3. Design Codes and Standards

Design and fabrication of equipment will be carried out as per following codes and standards.

| Material Specifications | | | | |
|---|---|---|---|---|
| **Sr. No.** | **Materials** | | **Specification** | **Minimum Strength** |
| 1 | Hot Rolled | Tubes | Indian Standards | Fy = 310 N/mm$^2$ |
| | | Channels | Indian Standards | Fy = 250 N/mm$^2$ |
| | | Beams, Columns, Plates, Angles, Bars | Indian Standards | Fy = 250 N/mm$^2$ |
| 2 | Cold Formed | Handrail Pipe | Indian Standards | Fy = 230 N/mm$^2$ |
| 3 | High Strength Bolts | | Indian Standards | Fy = 630 N/mm$^2$ |
| 4 | Nuts | | Indian Standards | - |
| 5 | Washers | | Indian Standards | - |
| 6 | Taper Washers | | Indian Standards | - |
| 7 | Grating (Hot Dip Galvanized) | | Bearing Bar 25x5 @ 30 C/C & 6 mm square twisted bar @ 100 mm C/C | - |

## A .Dead load

Self-weight of various structural members is applied using “selfweight” command in STAAD Pro.
Dead load is applied for roof sheeting on existing roof truss
Assuming spacing of adjacent truss as 2.5m and assuming dead load of sheeting as 0.2kN/sqm
DL=0.2x2.5 = 0.5kN/m




## b. Live load

Live load on top of existing truss is applied in live load case.
Assuming live load of 0.75kN/m2
LL = 2.5x0.75 = 1.875kN/m


## c. Door closed case

All dead loads for door are provided by ASSA ABLOY in drawing number 77249
Other dead loads of the door are applied in 2 cases
Case 1: Door closed




### d. Operating load

Case 2: Door open




### e. Testing load

Additional load to be applied during testing procedure is applied in “testing” load case.



### f. Wind load

Wind load shall be acting on the door and will be transferred to existing truss through 2 points where mullions will be installed.



## 5. Primary Loads and Load Combinations

### Primary loads

- Load 1 Dead Load (DL)
- Load 2 Live Load (LL)
- Load 3 Door Open
- Load 4 Door Closed
- Load 5 Testing load
- Load 6 Wind load

### Load combinations

- LOAD COMB **101** 1.5DL+1.5LL+1.5DOOR OPEN
- LOAD COMB **102** 1.5DL+1.5LL+1.5DOOR CLOSED
- LOAD COMB **103** 1.5DL+1.5TESTING
- LOAD COMB **104** 1.2DL+1.2DOOR CLOSED+1.2WIND LOAD
- LOAD COMB **201** DL+LL+DOOR OPEN

# ANNEXURE A – STAAD OUTPUT

```
*****************************************************
*                                                   *
*           STAAD.Pro CONNECT Edition               *
*           Version 22.02.00.26                     *
*           Proprietary Program of                  *
*           Bentley Systems, Inc.                   *
*           Date=     JUN 24, 2022                  *
*           Time=     19:17:51                      *
*                                                   *
*  Licensed to: only @ ::LAVTeam:: (R)              *
*****************************************************
```

```
     1. STAAD SPACE
INPUT FILE: C:\Users\HARSHA~1\OneDrive\1714CO~1\staad\cochin.STD
     2. START JOB INFORMATION
     3. ENGINEER DATE 28-MAY-22
     4. END JOB INFORMATION
     5. INPUT WIDTH 79
     6. UNIT METER KN
     7. JOINT COORDINATES
     8. 1 0 0 0; 2 49.4501 0 0; 3 24.7251 3.63301 0; 5 16.625 -0.920002 0
     9. 6 32.8251 -0.920002 0; 9 16.625 2.44282 0; 10 32.8251 2.44282 0
    10. 11 1.38542 0.203568 0; 12 2.77084 0.407137 0; 13 4.15626 0.610705 0
    11. 14 5.54168 0.814274 0; 15 6.9271 1.01784 0; 16 8.31252 1.22141 0
    12. 17 9.69794 1.42498 0; 18 11.0834 1.62855 0; 19 12.4688 1.83212 0
    13. 20 13.8542 2.03568 0; 21 15.2396 2.23925 0; 22 13.8542 -0.920002 0
    14. 23 11.0834 -0.920002 0; 24 8.31252 -0.920002 0; 25 5.54168 -0.920002 0
    15. 26 6.9271 -0.920002 0; 27 4.15626 -0.920002 0; 28 2.77084 -0.920002 0
    16. 29 1.38542 -0.920002 0; 30 9.69794 -0.920002 0; 31 12.4688 -0.920002 0
    17. 32 15.2396 -0.920002 0; 33 24.7251 1.92282 0; 34 17.975 2.64119 0
    18. 35 19.325 2.83955 0; 36 20.675 3.03791 0; 37 22.025 3.23628 0
    19. 38 23.375 3.43464 0; 39 23.375 1.92282 0; 40 22.025 1.92282 0
    20. 41 20.675 1.92282 0; 42 19.325 1.92282 0; 43 17.975 1.92282 0
    21. 44 48.0647 0.203568 0; 45 46.6793 0.407137 0; 46 45.2938 0.610705 0
    22. 47 43.9084 0.814274 0; 48 42.523 1.01784 0; 49 41.1376 1.22141 0
    23. 50 39.7522 1.42498 0; 51 38.3667 1.62855 0; 52 36.9813 1.83212 0
    24. 53 35.5959 2.03568 0; 54 34.2105 2.23925 0; 55 35.5959 -0.920002 0
    25. 56 38.3667 -0.920002 0; 57 41.1376 -0.920002 0; 58 43.9084 -0.920002 0
    26. 59 42.523 -0.920002 0; 60 45.2938 -0.920002 0; 61 46.6793 -0.920002 0
    27. 62 48.0647 -0.920002 0; 63 39.7522 -0.920002 0; 64 36.9813 -0.920002 0
    28. 65 34.2105 -0.920002 0; 66 31.4751 2.64118 0; 67 30.1251 2.83955 0
    29. 68 28.7751 3.03791 0; 69 27.4251 3.23628 0; 70 26.0751 3.43464 0
    30. 71 26.0751 1.92282 0; 72 27.4251 1.92282 0; 73 28.7751 1.92282 0
    31. 74 30.1251 1.92282 0; 75 31.4751 1.92282 0; 76 0 0 -0.900002
    32. 77 49.4501 0 -0.900002; 78 24.7251 3.63301 -0.900002
    33. 79 16.625 -0.920002 -0.900002; 80 32.8251 -0.920002 -0.900002
    34. 81 16.625 2.44282 -0.900002; 82 32.8251 2.44282 -0.900002
    35. 83 1.38542 0.203568 -0.900002; 84 2.77084 0.407137 -0.900002
    36. 85 4.15626 0.610705 -0.900002; 86 5.54168 0.814274 -0.900002
    37. 87 6.9271 1.01784 -0.900002; 88 8.31252 1.22141 -0.900002
    38. 89 9.69794 1.42498 -0.900002; 90 11.0834 1.62855 -0.900002
```

39. 91 12.4688 1.83212 -0.900002; 92 13.8542 2.03568 -0.900002
40. 93 15.2396 2.23925 -0.900002; 94 13.8542 -0.920002 -0.900002
41. 95 11.0834 -0.920002 -0.900002; 96 8.31252 -0.920002 -0.900002
42. 97 5.54168 -0.920002 -0.900002; 98 6.9271 -0.920002 -0.900002
43. 99 4.15626 -0.920002 -0.900002; 100 2.77084 -0.920002 -0.900002
44. 101 1.38542 -0.920002 -0.900002; 102 9.69794 -0.920002 -0.900002
45. 103 12.4688 -0.920002 -0.900002; 104 15.2396 -0.920002 -0.900002
46. 105 24.7251 1.92282 -0.900002; 106 17.975 2.64119 -0.900002
47. 107 19.325 2.83955 -0.900002; 108 20.675 3.03791 -0.900002
48. 109 22.025 3.23628 -0.900002; 110 23.375 3.43464 -0.900002
49. 111 23.375 1.92282 -0.900002; 112 22.025 1.92282 -0.900002
50. 113 20.675 1.92282 -0.900002; 114 19.325 1.92282 -0.900002
51. 115 17.975 1.92282 -0.900002; 116 48.0647 0.203568 -0.900002
52. 117 46.6793 0.407137 -0.900002; 118 45.2938 0.610705 -0.900002
53. 119 43.9084 0.814274 -0.900002; 120 42.523 1.01784 -0.900002
54. 121 41.1376 1.22141 -0.900002; 122 39.7522 1.42498 -0.900002
55. 123 38.3667 1.62855 -0.900002; 124 36.9813 1.83212 -0.900002
56. 125 35.5959 2.03568 -0.900002; 126 34.2105 2.23925 -0.900002
57. 127 35.5959 -0.920002 -0.900002; 128 38.3667 -0.920002 -0.900002
58. 129 41.1376 -0.920002 -0.900002; 130 43.9084 -0.920002 -0.900002
59. 131 42.523 -0.920002 -0.900002; 132 45.2938 -0.920002 -0.900002
60. 133 46.6793 -0.920002 -0.900002; 134 48.0647 -0.920002 -0.900002
61. 135 39.7522 -0.920002 -0.900002; 136 36.9813 -0.920002 -0.900002
62. 137 34.2105 -0.920002 -0.900002; 138 31.4751 2.64118 -0.900002
63. 139 30.1251 2.83955 -0.900002; 140 28.7751 3.03791 -0.900002
64. 141 27.4251 3.23628 -0.900002; 142 26.0751 3.43464 -0.900002
65. 143 26.0751 1.92282 -0.900002; 144 27.4251 1.92282 -0.900002
66. 145 28.7751 1.92282 -0.900002; 146 30.1251 1.92282 -0.900002
67. 147 31.4751 1.92282 -0.900002; 148 0 2.50001 0; 149 49.4501 2.50001 0
68. 150 24.7251 6.13301 0; 151 16.625 4.94283 0; 152 32.8251 4.94283 0
69. 153 1.38542 2.70357 0; 154 2.77084 2.90714 0; 155 4.15626 3.11071 0
70. 156 5.54168 3.31428 0; 157 6.9271 3.51785 0; 158 8.31252 3.72142 0
71. 159 9.69794 3.92498 0; 160 11.0834 4.12855 0; 161 12.4688 4.33212 0
72. 162 13.8542 4.53569 0; 163 15.2396 4.73926 0; 164 17.975 5.14119 0
73. 165 19.325 5.33955 0; 166 20.675 5.53792 0; 167 22.025 5.73628 0
74. 168 23.375 5.93465 0; 169 48.0647 2.70357 0; 170 46.6793 2.90714 0
75. 171 45.2938 3.11071 0; 172 43.9084 3.31428 0; 173 42.523 3.51785 0
76. 174 41.1376 3.72142 0; 175 39.7522 3.92498 0; 176 38.3667 4.12855 0
77. 177 36.9813 4.33212 0; 178 35.5959 4.53569 0; 179 34.2105 4.73926 0
78. 180 31.4751 5.14119 0; 181 30.1251 5.33955 0; 182 28.7751 5.53792 0
79. 183 27.4251 5.73628 0; 184 26.0751 5.93465 0; 186 0 2.50001 -0.900002
80. 187 49.4501 2.50001 -0.900002; 188 24.7251 6.13301 -0.900002
81. 189 16.625 4.94283 -0.900002; 190 32.8251 4.94283 -0.900002
82. 191 1.38542 2.70357 -0.900002; 192 2.77084 2.90714 -0.900002
83. 193 4.15626 3.11071 -0.900002; 194 5.54168 3.31428 -0.900002
84. 195 6.9271 3.51785 -0.900002; 196 8.31252 3.72142 -0.900002
85. 197 9.69794 3.92498 -0.900002; 198 11.0834 4.12855 -0.900002
86. 199 12.4688 4.33212 -0.900002; 200 13.8542 4.53569 -0.900002
87. 201 15.2396 4.73926 -0.900002; 202 17.975 5.14119 -0.900002
88. 203 19.325 5.33955 -0.900002; 204 20.675 5.53792 -0.900002
89. 205 22.025 5.73628 -0.900002; 206 23.375 5.93465 -0.900002
90. 207 48.0647 2.70357 -0.900002; 208 46.6793 2.90714 -0.900002
91. 209 45.2938 3.11071 -0.900002; 210 43.9084 3.31428 -0.900002
92. 211 42.523 3.51785 -0.900002; 212 41.1376 3.72142 -0.900002
93. 213 39.7522 3.92498 -0.900002; 214 38.3667 4.12855 -0.900002
94. 215 36.9813 4.33212 -0.900002; 216 35.5959 4.53569 -0.900002

95. 217 34.2105 4.73926 -0.900002; 218 31.4751 5.14119 -0.900002
96. 219 30.1251 5.33955 -0.900002; 220 28.7751 5.53792 -0.900002
97. 221 27.4251 5.73628 -0.900002; 222 26.0751 5.93465 -0.900002
98. 223 16.625 0.686409 0; 224 16.625 0.686409 -0.900002; 225 32.8251 0.686409 0
99. 226 32.8251 0.686409 -0.900002; 227 16.625 2.5 -6.40001
100. 228 32.8251 2.5 -6.40001; 229 16.625 1.92282 0; 230 16.625 1.92282 -0.900002
101. 231 32.8251 1.92282 0; 232 32.8251 1.92282 -0.900002; 233 25.2251 1.92282 0
102. 234 25.2251 1.92282 -0.900002; 235 24.225 1.92282 0
103. 236 24.225 1.92282 -0.900002
104. MEMBER INCIDENCES
105. 1 1 11; 2 3 70; 3 1 29; 7 6 65; 8 5 223; 9 6 225; 10 9 34; 11 10 54; 12 229 43
106. 13 11 12; 14 12 13; 15 13 14; 16 14 15; 17 15 16; 18 16 17; 19 17 18; 20 18 19
107. 21 19 20; 22 20 21; 23 21 9; 24 22 32; 25 20 22; 26 23 31; 27 18 23; 28 24 30
108. 29 16 24; 30 25 26; 31 14 25; 32 26 24; 33 15 26; 34 27 25; 35 13 27; 36 28 27
109. 37 12 28; 41 24 15; 42 26 14; 43 25 13; 44 27 12; 45 29 28; 46 11 29; 47 30 23
110. 48 17 30; 49 31 22; 50 19 31; 51 22 19; 52 31 18; 53 23 17; 54 30 16; 55 32 5
111. 56 21 32; 57 5 21; 58 32 20; 59 33 233; 61 34 35; 62 35 36; 63 36 37; 64 37 38
112. 65 38 3; 66 39 235; 67 38 39; 68 40 39; 69 37 40; 70 41 40; 71 36 41; 72 42 41
113. 73 35 42; 74 43 42; 75 34 43; 76 235 38; 77 39 37; 78 40 36; 79 41 35
114. 80 42 34; 81 44 2; 82 45 44; 83 46 45; 84 47 46; 85 48 47; 86 49 48; 87 50 49
115. 88 51 50; 89 52 51; 90 53 52; 91 54 53; 92 55 64; 93 56 63; 94 57 59; 95 58 60
116. 96 59 58; 97 60 61; 98 61 62; 99 62 2; 100 63 57; 101 64 56; 102 65 55
117. 103 66 10; 104 67 66; 105 68 67; 106 69 68; 107 70 69; 108 71 72; 109 72 73
118. 110 73 74; 111 74 75; 112 75 231; 113 53 55; 114 51 56; 115 49 57; 116 47 58
119. 117 48 59; 118 46 60; 119 45 61; 120 57 48; 121 59 47; 122 58 46; 123 60 45
120. 124 44 62; 125 50 63; 126 52 64; 127 55 52; 128 64 51; 129 56 50; 130 63 49
121. 131 54 65; 132 6 54; 133 65 53; 134 70 71; 135 69 72; 136 68 73; 137 67 74
122. 138 66 75; 139 233 70; 140 71 69; 141 72 68; 142 73 67; 143 74 66; 144 1 76
123. 145 2 77; 146 3 78; 147 5 79; 148 6 80; 149 9 81; 150 10 82; 151 11 83
124. 152 12 84; 153 13 85; 154 14 86; 155 15 87; 156 16 88; 157 17 89; 158 18 90
125. 159 19 91; 160 20 92; 161 21 93; 162 22 94; 163 23 95; 164 24 96; 165 25 97
126. 166 26 98; 167 27 99; 168 28 100; 169 29 101; 170 30 102; 171 31 103
127. 172 32 104; 173 33 105; 174 34 106; 175 35 107; 176 36 108; 177 37 109
128. 178 38 110; 179 39 111; 180 40 112; 181 41 113; 182 42 114; 183 43 115
129. 184 44 116; 185 45 117; 186 46 118; 187 47 119; 188 48 120; 189 49 121
130. 190 50 122; 191 51 123; 192 52 124; 193 53 125; 194 54 126; 195 55 127
131. 196 56 128; 197 57 129; 198 58 130; 199 59 131; 200 60 132; 201 61 133
132. 202 62 134; 203 63 135; 204 64 136; 205 65 137; 206 66 138; 207 67 139
133. 208 68 140; 209 69 141; 210 70 142; 211 71 143; 212 72 144; 213 73 145
134. 214 74 146; 215 75 147; 216 76 83; 217 78 142; 218 76 101; 219 80 137
135. 220 79 224; 221 80 226; 222 81 106; 223 82 126; 224 230 115; 225 83 84
136. 226 84 85; 227 85 86; 228 86 87; 229 87 88; 230 88 89; 231 89 90; 232 90 91
137. 233 91 92; 234 92 93; 235 93 81; 236 94 104; 237 92 94; 238 95 103; 239 90 95
138. 240 96 102; 241 88 96; 242 97 98; 243 86 97; 244 98 96; 245 87 98; 246 99 97
139. 247 85 99; 248 100 99; 249 84 100; 250 96 87; 251 98 86; 252 97 85; 253 99 84
140. 254 101 100; 255 83 101; 256 102 95; 257 89 102; 258 103 94; 259 91 103
141. 260 94 91; 261 103 90; 262 95 89; 263 102 88; 264 104 79; 265 93 104
142. 266 79 93; 267 104 92; 268 105 234; 270 106 107; 271 107 108; 272 108 109
143. 273 109 110; 274 110 78; 275 111 236; 276 110 111; 277 112 111; 278 109 112
144. 279 113 112; 280 108 113; 281 114 113; 282 107 114; 283 115 114; 284 106 115
145. 285 236 110; 286 111 109; 287 112 108; 288 113 107; 289 114 106; 290 116 77
146. 291 117 116; 292 118 117; 293 119 118; 294 120 119; 295 121 120; 296 122 121
147. 297 123 122; 298 124 123; 299 125 124; 300 126 125; 301 127 136; 302 128 135
148. 303 129 131; 304 130 132; 305 131 130; 306 132 133; 307 133 134; 308 134 77
149. 309 135 129; 310 136 128; 311 137 127; 312 138 82; 313 139 138; 314 140 139
150. 315 141 140; 316 142 141; 317 143 144; 318 144 145; 319 145 146; 320 146 147

151. 321 147 232; 322 125 127; 323 123 128; 324 121 129; 325 119 130; 326 120 131
152. 327 118 132; 328 117 133; 329 129 120; 330 131 119; 331 130 118; 332 132 117
153. 333 116 134; 334 122 135; 335 124 136; 336 127 124; 337 136 123; 338 128 122
154. 339 135 121; 340 126 137; 341 80 126; 342 137 125; 343 142 143; 344 141 144
155. 345 140 145; 346 139 146; 347 138 147; 348 234 142; 349 143 141; 350 144 140
156. 351 145 139; 352 146 138; 353 1 148; 354 2 149; 355 3 150; 356 9 151
157. 357 10 152; 358 11 153; 359 12 154; 360 13 155; 361 14 156; 362 15 157
158. 363 16 158; 364 17 159; 365 18 160; 366 19 161; 367 20 162; 368 21 163
159. 369 34 164; 370 35 165; 371 36 166; 372 37 167; 373 38 168; 374 44 169
160. 375 45 170; 376 46 171; 377 47 172; 378 48 173; 379 49 174; 380 50 175
161. 381 51 176; 382 52 177; 383 53 178; 384 54 179; 385 180 66; 386 67 181
162. 387 68 182; 388 69 183; 389 70 184; 391 76 186; 392 77 187; 393 78 188
163. 394 81 189; 395 82 190; 396 83 191; 397 84 192; 398 85 193; 399 86 194
164. 400 87 195; 401 88 196; 402 89 197; 403 90 198; 404 91 199; 405 92 200
165. 406 93 201; 407 106 202; 408 107 203; 409 108 204; 410 109 205; 411 110 206
166. 412 116 207; 413 117 208; 414 118 209; 415 119 210; 416 120 211; 417 121 212
167. 418 122 213; 419 123 214; 420 124 215; 421 125 216; 422 126 217; 423 218 138
168. 424 139 219; 425 140 220; 426 141 221; 427 142 222; 429 148 153; 430 150 184
169. 431 151 164; 432 152 179; 433 153 154; 434 154 155; 435 155 156; 436 156 157
170. 437 157 158; 438 158 159; 439 159 160; 440 160 161; 441 161 162; 442 162 163
171. 443 163 151; 444 164 165; 445 165 166; 446 166 167; 447 167 168; 448 168 150
172. 449 169 149; 450 170 169; 451 171 170; 452 172 171; 453 173 172; 454 174 173
173. 455 175 174; 456 176 175; 457 177 176; 458 178 177; 459 179 178; 460 180 152
174. 461 181 180; 462 182 181; 463 183 182; 464 184 183; 466 186 191; 467 188 222
175. 468 189 202; 469 190 217; 470 191 192; 471 192 193; 472 193 194; 473 194 195
176. 474 195 196; 475 196 197; 476 197 198; 477 198 199; 478 199 200; 479 200 201
177. 480 201 189; 481 202 203; 482 203 204; 483 204 205; 484 205 206; 485 206 188
178. 486 207 187; 487 208 207; 488 209 208; 489 210 209; 490 211 210; 491 212 211
179. 492 213 212; 493 214 213; 494 215 214; 495 216 215; 496 217 216; 497 218 190
180. 498 219 218; 499 220 219; 500 221 220; 501 222 221; 503 187 149; 504 188 150
181. 505 189 151; 506 190 152; 507 191 153; 508 192 154; 509 193 155; 510 194 156
182. 511 195 157; 512 196 158; 513 197 159; 514 198 160; 515 199 161; 516 200 162
183. 517 201 163; 518 202 164; 519 203 165; 520 204 166; 521 205 167; 522 206 168
184. 523 207 169; 524 208 170; 525 209 171; 526 210 172; 527 211 173; 528 212 174
185. 529 213 175; 530 214 176; 531 215 177; 532 216 178; 533 217 179; 534 218 180
186. 535 219 181; 536 220 182; 537 221 183; 538 222 184; 540 186 148; 541 1 153
187. 542 11 154; 543 12 155; 544 13 156; 545 14 157; 546 15 158; 547 16 159
188. 548 17 160; 549 18 161; 550 19 162; 551 20 163; 552 21 151; 553 9 164
189. 554 34 165; 555 35 166; 556 36 167; 557 37 168; 558 38 150; 559 2 169
190. 560 44 170; 561 45 171; 562 46 172; 563 47 173; 564 48 174; 565 49 175
191. 566 50 176; 567 51 177; 568 52 178; 569 53 179; 570 54 152; 571 10 180
192. 572 66 181; 573 67 182; 574 68 183; 575 69 184; 576 70 150; 577 76 191
193. 578 83 192; 579 84 193; 580 85 194; 581 86 195; 582 87 196; 583 88 197
194. 584 89 198; 585 90 199; 586 91 200; 587 92 201; 588 93 189; 589 81 202
195. 590 106 203; 591 107 204; 592 108 205; 593 109 206; 594 110 188; 595 77 207
196. 596 116 208; 597 117 209; 598 118 210; 599 119 211; 600 120 212; 601 121 213
197. 602 122 214; 603 123 215; 604 124 216; 605 125 217; 606 126 190; 607 82 218
198. 608 138 219; 609 139 220; 610 140 221; 611 141 222; 612 142 188; 613 148 191
199. 614 191 154; 615 154 193; 616 193 156; 617 156 195; 618 195 158; 619 158 197
200. 620 197 160; 621 160 199; 622 199 162; 623 162 201; 624 201 151; 625 151 202
201. 626 202 165; 627 165 204; 628 204 167; 629 167 206; 630 206 150; 631 149 207
202. 632 207 170; 633 170 209; 634 209 172; 635 172 211; 636 211 174; 637 174 213
203. 638 213 176; 639 176 215; 640 215 178; 641 178 217; 642 217 152; 643 152 218
204. 644 218 181; 645 181 220; 646 220 183; 647 183 222; 648 222 150; 649 1 83
205. 650 83 12; 651 12 85; 652 85 14; 653 14 87; 654 87 16; 655 16 89; 656 89 18
206. 657 18 91; 658 91 20; 659 20 93; 660 93 9; 661 9 106; 662 106 35; 663 35 108

```
207. 664 108 37; 665 37 110; 666 110 3; 667 2 116; 668 116 45; 669 45 118
208. 670 118 47; 671 47 120; 672 120 49; 673 49 122; 674 122 51; 675 51 124
209. 676 124 53; 677 53 126; 678 126 10; 679 10 138; 680 138 67; 681 67 140
210. 682 140 69; 683 69 142; 684 142 3; 685 1 101; 686 101 28; 687 28 99; 688 99 25
211. 689 25 98; 690 98 24; 691 24 102; 692 102 23; 693 23 103; 694 103 22
212. 695 22 104; 696 104 5; 697 230 43; 698 43 114; 699 114 41; 700 41 112
213. 701 112 39; 702 39 105; 703 2 134; 704 134 61; 705 61 132; 706 132 58
214. 707 58 131; 708 131 57; 709 57 135; 710 135 56; 711 56 136; 712 136 55
215. 713 55 137; 714 137 6; 715 232 75; 716 75 146; 717 146 73; 718 73 144
216. 719 144 71; 720 71 105; 721 223 229; 722 224 230; 723 224 223; 724 5 224
217. 725 224 9; 726 225 231; 727 226 232; 728 226 225; 729 6 226; 730 226 10
218. 731 79 227; 732 80 228; 733 66 75; 734 138 147; 735 229 9; 737 230 81
219. 739 231 10; 741 232 82; 742 233 71; 743 234 143; 744 235 33; 745 236 105
220. DEFINE PMEMBER
221. 1 13 TO 23 PMEMBER 1
222. 10 61 TO 65 PMEMBER 2
223. START GROUP DEFINITION
224. MEMBER
225. _EXISTING 1 2 10 11 13 TO 23 61 TO 65 81 TO 91 103 TO 107 144 TO 146 -
226. 149 TO 161 174 TO 178 184 TO 194 206 TO 210 216 217 222 223 225 TO 235 270 -
227. 271 TO 274 290 TO 300 312 TO 316 353 TO 389 391 TO 427 429 TO 464 466 TO 501 -
228. 503 TO 538 540 TO 684 703 735 737
229. END GROUP DEFINITION
230. DEFINE MATERIAL START
231. ISOTROPIC STEEL
232. E 1.99947E+08
233. POISSON 0.3
234. DENSITY 76.8191
235. ALPHA 6.5E-06
236. DAMP 0.03
237. TYPE STEEL
238. STRENGTH RY 1.5 RT 1.2
239. END DEFINE MATERIAL
240. MEMBER PROPERTY INDIAN
241. 1 2 10 11 13 TO 23 61 TO 65 81 TO 91 103 TO 107 216 217 222 223 225 TO 235 -
242. 270 TO 274 290 TO 300 312 TO 316 429 TO 464 466 TO 500 -
243. 501 TABLE LD ISA100X100X12
244. 144 TO 146 149 TO 215 503 TO 538 540 547 TO 558 565 TO 576 583 TO 594 601 -
245. 602 TO 612 TABLE LD ISA65X65X8
246. MEMBER PROPERTY TATASTRUCTURA
247. 25 27 29 31 33 35 37 41 TO 44 46 48 50 TO 54 56 58 67 69 71 73 75 TO 80 113 -
248. 114 TO 131 133 TO 143 237 239 241 243 245 247 249 TO 253 255 257 259 TO 263 -
249. 265 267 276 278 280 282 284 TO 289 322 TO 340 342 TO 352 735 737 739 -
250. 741 TABLE ST 50X50X2.9SHS
251. 3 7 TO 9 12 24 26 28 30 32 34 36 45 47 49 55 57 59 66 68 70 72 74 92 TO 102 -
252. 108 TO 112 132 147 148 218 TO 221 224 236 238 240 242 244 246 248 254 256 -
253. 258 264 266 268 275 277 279 281 283 301 TO 311 317 TO 321 341 721 TO 730 -
254. 742 TO 745 TABLE ST 72X72X3.2SHS
255. MEMBER PROPERTY INDIAN
256. 613 TO 720 TABLE ST ISA65X65X8
257. 353 TO 389 391 TO 427 541 TO 546 559 TO 564 577 TO 582 595 TO 600 733 -
258. 734 TABLE LD ISA100X100X8
259. MEMBER PROPERTY TATASTRUCTURA
260. 731 732 TABLE ST 150X150X6.0SHS
261. CONSTANTS
262. MATERIAL STEEL ALL
```

```
263. SUPPORTS
264. 1 2 76 77 FIXED
265.  227  228 PINNED
266.  MEMBER RELEASE
267. 1 145 146 149 TO 161 174 TO 178 184 TO 194 206 TO 210 216 355 TO 389 -
268. 393 TO 427 503 TO 538 540 TO 684 731 732 START MY MZ
269. 81 145 146 149 TO 161 174 TO 178 184 TO 194 206 TO 210 290 355 TO 389 393 -
270. 394 TO 427 503 TO 538 540 TO 684 END MY MZ
271.  LOAD 1 LOADTYPE DEAD TITLE  DL
**WARNING- MEMBERS       733  &       138 ARE BETWEEN THE SAME  JOINTS.
**WARNING- MEMBERS       347  &       734 ARE BETWEEN THE SAME  JOINTS.
272.  SELFWEIGHT Y  -1
273.  MEMBER LOAD
274. 429 TO 464 466 TO 501 UNI GY -0.5
275.  LOAD 2 LOADTYPE LIVE TITLE  LL
276.  MEMBER LOAD
277. 429 TO 464 466 TO 501 UNI GY -1.875
278.  LOAD 3 LOADTYPE NONE TITLE DOOR CLOSED
279.  MEMBER LOAD
280. 144 145 CON GY -0.3
281.  164 170 197 203 CON GY -2.3
282.  173 CON GY -3.3
283.  149 150 CON GY -22.8
284.  LOAD 4 LOADTYPE NONE TITLE DOOR OPEN
285.  MEMBER LOAD
286.  144 145 147 148 CON GY -18
287.  145 147 CON GX -18
288.  144 145 148 CON GX 18
289.  164 173 197 CON GY -3.3
290.  170 203 CON GY -12.2
291.  149 150 CON GY -12.3
292.  149 150 CON GY -21.5
293.  150 CON GX -21.5
294.  149 CON GX 21.5
295.  LOAD 5 LOADTYPE NONE TITLE TESTING LOAD
296.  MEMBER LOAD
297.  147 148 CON GY -55
298.  LOAD 6 LOADTYPE NONE TITLE WIND LOAD
299.  MEMBER LOAD
300.  147 148 CON GZ -213
301.  LOAD COMB 101 1.5(DL+LL+DOOR OPEN)
302.  1 1.5 2 1.5 4 1.5
303.  LOAD COMB 102 1.5(DL+LL+DOOR CLOSED)
304.  1 1.5 2 1.5 3 1.5
305.  LOAD COMB 103 1.5DL+1.5TESTING
306.  1 1.5 5 1.5
307.  LOAD COMB 104 1.2DL+1.2DOOR CLOSED+1.2WIND LOAD
308.  1 1.2 3 1.2 6 1.2
309.  LOAD COMB 201 DL+LL+DOOR OPEN
310.  1 1.0 2 1.0 4 1.0
311.  PERFORM ANALYSIS
```

P R O B L E M S T A T I S T I C S

| | | | |
|---|---|---|---|
| NUMBER OF JOINTS | 232 | NUMBER OF MEMBERS | 729 |
| NUMBER OF PLATES | 0 | NUMBER OF SOLIDS | 0 |
| NUMBER OF SURFACES | 0 | NUMBER OF SUPPORTS | 6 |

Using 64-bit analysis engine.

SOLVER USED IS THE IN-CORE ADVANCED MATH SOLVER

TOTAL PRIMARY LOAD CASES = 6, TOTAL DEGREES OF FREEDOM = 1362
TOTAL LOAD COMBINATION CASES = 5 SO FAR.

312. PARAMETER 1
313. CODE IS800 LSD
314. FYLD 250000 ALL
315. CHECK CODE ALL

STEEL DESIGN

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 1 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.562 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 2 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.349 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 3 | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.274 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 7 | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.255 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 8 | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.586 | Critical Load Case: | 103 | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 9 | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.586 | Critical Load Case: | 103 | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 10 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.268 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 11 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.187 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 12 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.088 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: | Sec. 8.2.1.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 13 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.485 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 14 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.440 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 15 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.372 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 16 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.337 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 17 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.280 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 18 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.269 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 19 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.231 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 20 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.212 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 21 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.184 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 22 | | | | |
| Member Section: | LD ISA100X100X12 (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.175 | Critical Load Case: | 104 | Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 23 | | | | |
| Member Section: | LD ISA100X100X12 (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.180 | Critical Load Case: | 104 | Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 24 | | | | |
| Member Section: | ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.065 | Critical Load Case: | 4 | Location: 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 25 | | | | |
| Member Section: | ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.063 | Critical Load Case: | 104 | Location: 0.00 |
| Critical Condition: Sec. 6.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 26 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.045 | Critical Load Case: | 102 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 27 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.196 | Critical Load Case: | 102 | Location: | 2.55 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 28 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.066 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 29 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.193 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 30 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.121 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 31 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.208 | Critical Load Case: | 101 | Location: | 1.73 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 32 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.117 | Critical Load Case: | 104 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 33 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.228 | Critical Load Case: | 101 | Location: | 1.94 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 34 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.141 | Critical Load Case: | 104 | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 35 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.158 | Critical Load Case: | 101 | Location: | 1.53 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 36 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.202 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 37 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.046 | Critical Load Case: | 104 | Location: | 1.33 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 41 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.215 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 42 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.194 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 43 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.181 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 44 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.162 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 45 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.167 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 46 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.105 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 47 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.088 | Critical Load Case: | 6 | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 48 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.213 | Critical Load Case: | 101 | Location: | 2.34 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 49 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.068 | Critical Load Case: | 6 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 50 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.139 | Critical Load Case: | 102 | Location: | 2.75 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 51 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.265 | Critical Load Case: | 104 | Location: | 3.08 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 52 | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.237 | Critical Load Case: | 6 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 53 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.211 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 54 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.190 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 55 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.254 | Critical Load Case: | 101 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 56 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.081 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 57 | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | |
| Status: PASS | Ratio: | 0.206 | Critical Load Case: | 103 | Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 58 | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | |
| Status: PASS | Ratio: | 0.378 | Critical Load Case: | 104 | Location: 3.26 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 59 | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | |
| Status: PASS | Ratio: | 0.524 | Critical Load Case: | 104 | Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 61 | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | |
| Status: PASS | Ratio: | 0.237 | Critical Load Case: | 104 | Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 62 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.243 | Critical Load Case: | 104 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 63 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.252 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 64 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.279 | Critical Load Case: | 104 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 65 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.349 | Critical Load Case: | 104 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 66 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.487 | Critical Load Case: | 104 | Location: | 0.85 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 67 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.180 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 68 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.407 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 69 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.143 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 70 | | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.272 | Critical Load Case: | 104 | Location: | 1.35 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 71 | | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.122 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 72 | | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.161 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 73 | | | | | |
| Member Section: | ST 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.112 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 74 | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.006 | Critical Load Case: | 103 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 75 | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.118 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 76 | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.053 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 77 | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: | 0.474 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 78 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.393 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 79 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.326 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 80 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.336 | Critical Load Case: | 104 | Location: | 1.53 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 81 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.562 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 82 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.485 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 83 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.440 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 84 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.371 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 85 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.337 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 86 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.280 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 87 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.268 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 88 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.231 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 89 | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.212 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 90 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.183 | Critical Load Case: 101 | | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 91 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.176 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 92 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.068 | Critical Load Case: 6 | | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 93 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.088 | Critical Load Case: 6 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 94 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.117 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 95 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.141 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 96 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.120 | Critical Load Case: | 101 | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 97 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.202 | Critical Load Case: | 101 | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 98 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.167 | Critical Load Case: | 104 | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 99 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.274 | Critical Load Case: | 101 | Location: | 1.66 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 100 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.066 | Critical Load Case: | 104 | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: | 101 | | | | |
| Member Section: | ST 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.045 | Critical Load Case: | 102 | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 102 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.065 | Critical Load Case: 4 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 103 | | | | | |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.276 | Critical Load Case: 104 | | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 104 | | | | | |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.237 | Critical Load Case: 104 | | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 105 | | | | | |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.241 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 106 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.252 | Critical Load Case: | 104 | Location: | 1.36 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 107 | | | | | | |
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.279 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 108 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.411 | Critical Load Case: | 104 | Location: | 1.35 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 109 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.275 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 110 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.164 | Critical Load Case: 104 | Location: | 1.35 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 111 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.038 | Critical Load Case: 104 | Location: | 1.35 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 112 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.100 | Critical Load Case: 104 | Location: | 1.35 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 113 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.063 | Critical Load Case: 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 114 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.196 | Critical Load Case: | 102 | Location: | 2.55 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 115 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.193 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 116 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.208 | Critical Load Case: | 101 | Location: | 1.73 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 117 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.228 | Critical Load Case: | 101 | Location: | 1.94 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 118 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.158 | Critical Load Case: 101 | | Location: | 1.53 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 119 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.046 | Critical Load Case: 104 | | Location: | 1.33 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 120 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.216 | Critical Load Case: 6 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 121 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.194 | Critical Load Case: 6 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 122 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.181 | Critical Load Case: | 6 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 123 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.162 | Critical Load Case: | 6 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 124 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.105 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: | Sec. 6.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 125 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.213 | Critical Load Case: | 101 | Location: | 2.34 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 126 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.139 | Critical Load Case: 102 | | Location: | | 2.75 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 127 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.265 | Critical Load Case: 104 | | Location: | | 3.08 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 128 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.237 | Critical Load Case: 6 | | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 129 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.211 | Critical Load Case: 6 | | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 130 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.190 | Critical Load Case: | 6 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 131 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.081 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 132 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.206 | Critical Load Case: | 103 | Location: | 0.00 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 133 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.378 | Critical Load Case: | 104 | Location: | 3.26 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 134 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.181 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 135 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.144 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 136 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.121 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 137 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.110 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 138 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.049 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 139 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.053 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 140 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.478 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 141 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.395 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 142 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.328 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 143 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.321 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 144 | | | | | |
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.806 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 145 | | | | | |
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.897 | Critical Load Case: 101 | | Location: | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 146 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.007 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| * Member Number: 147 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: FAIL | Ratio: | 5.559 | Critical Load Case: | 103 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| * Member Number: 148 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: FAIL | Ratio: | 5.560 | Critical Load Case: | 103 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| * Member Number: 149 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: FAIL | Ratio: | 2.539 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| * Member Number: | 150 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | FAIL | Ratio: | 2.539 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 151 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.016 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 152 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.020 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 153 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.019 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 154 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.016 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 155 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.015 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 156 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.013 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 157 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.012 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 158 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.011 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 159 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.010 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 160 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.009 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 161 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.008 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 162 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.018 | Critical Load Case: | 103 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 163 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.041 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 164 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.160 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 165 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.047 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 166 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.035 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 167 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.029 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 168 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.027 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 169 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.032 | Critical Load Case: | 101 | Location: | 0.90 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 170 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.499 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 171 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.018 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 172 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.084 | Critical Load Case: | 103 | Location: | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 173 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.141 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 174 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.009 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 175 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 176 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 177 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 178 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.009 | Critical Load Case: | 101 | Location: | | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 179 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.045 | Critical Load Case: | 104 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 180 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.042 | Critical Load Case: | 104 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 181 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.021 | Critical Load Case: | 104 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 182 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.018 | Critical Load Case: | 104 | Location: | 0.90 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 183 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.016 | Critical Load Case: | 103 | Location: | 0.00 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 184 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.016 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 185 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.020 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: | Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 186 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.019 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 187 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.016 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 188 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.015 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 189 |
|---|
| Member Section: LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.013 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: Sec. 9.3.1.1 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 190 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.012 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 191 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.011 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 192 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 193 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.009 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 194 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.008 | Critical Load Case: 101 | | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 195 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.018 | Critical Load Case: 103 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 196 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.041 | Critical Load Case: 101 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 197 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.160 | Critical Load Case: 101 | | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 198 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.047 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 199 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.035 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 200 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.029 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 201 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.027 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 202 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.032 | Critical Load Case: | 101 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 203 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.499 | Critical Load Case: | 101 | Location: | | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 204 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.018 | Critical Load Case: | 104 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 205 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.084 | Critical Load Case: | 103 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 206 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.009 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 207 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 208 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 209 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.010 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 210 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.009 | Critical Load Case: | 101 | Location: | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 211 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.045 | Critical Load Case: | 104 | Location: | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 212 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.043 | Critical Load Case: | 104 | Location: | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 213 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.023 | Critical Load Case: | 104 | Location: | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 214 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.021 | Critical Load Case: | 104 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 215 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.031 | Critical Load Case: | 104 | Location: | | 0.90 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 216 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.810 | Critical Load Case: | 104 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 217 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.237 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 218 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.570 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 219 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.309 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 220 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.692 | Critical Load Case: | 103 | Location: | 0.00 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 221 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.691 | Critical Load Case: | 103 | Location: | 0.00 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 222 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.127 | Critical Load Case: 101 | | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 223 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.096 | Critical Load Case: 101 | | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 224 | | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.035 | Critical Load Case: 101 | | Location: 0.00 | | | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 225 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.717 | Critical Load Case: 104 | | Location: 1.40 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 226 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.668 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 227 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.523 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 228 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.499 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 229 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.371 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 230 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.359 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 231 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.234 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 232 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.212 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 233 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.156 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 234 | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.133 | Critical Load Case: 101 | | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 235 | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.097 | Critical Load Case: 101 | | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 236 | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.053 | Critical Load Case: 101 | | Location: | 0.58 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 237 | | | | | |
| Member Section: ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | |
| Status: PASS | Ratio: 0.295 | Critical Load Case: 104 | | Location: | 2.96 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 238 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.073 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 239 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.435 | Critical Load Case: 104 | Location: | 2.55 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 240 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.160 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 241 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.375 | Critical Load Case: 104 | Location: | 2.14 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 242 | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.267 | Critical Load Case: 104 | | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 243 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.258 | Critical Load Case: 104 | | Location: | | 1.73 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 244 | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.234 | Critical Load Case: 104 | | Location: | | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 245 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.324 | Critical Load Case: 104 | | Location: | | 1.94 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 246 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.343 | Critical Load Case: 104 | | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 247 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.156 | Critical Load Case: 104 | | Location: | 1.53 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 248 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.358 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 249 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.052 | Critical Load Case: 104 | | Location: | 1.33 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 250 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.185 | Critical Load Case: 104 | | Location: | 2.38 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 251 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.176 | Critical Load Case: 104 | | Location: | 2.22 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 252 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.153 | Critical Load Case: 104 | | Location: | 2.06 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 253 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.092 | Critical Load Case: 101 | | Location: | 1.92 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 254 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.369 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 255 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.276 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 256 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.131 | Critical Load Case: 104 | | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 257 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.446 | Critical Load Case: 104 | | Location: | 2.34 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 258 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.085 | Critical Load Case: 6 | | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 259 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.378 | Critical Load Case: 104 | | Location: | 2.75 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 260 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.261 | Critical Load Case: 101 | | Location: | 0.51 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 261 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.139 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 262 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.165 | Critical Load Case: 104 | | Location: | 2.72 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 263 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.197 | Critical Load Case: 104 | | Location: | 2.55 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 264 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.308 | Critical Load Case: 101 | | Location: | 1.39 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 265 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.207 | Critical Load Case: 6 | | Location: | 3.16 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 266 | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.329 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 267 | | | | | | |
| Member Section: ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.430 | Critical Load Case: | 101 | Location: | 0.27 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 268 | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.324 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 270 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.134 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 271 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.150 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 272 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.161 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 273 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.183 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 274 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.237 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 275 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.285 | Critical | Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 276 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.131 | Critical | Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 277 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.203 | Critical | Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 278 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.091 | Critical | Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 279 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.115 | Critical Load Case: | 101 | Location: | 1.35 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 280 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.056 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 281 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.047 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 282 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.030 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 283 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.006 | Critical Load Case: | 103 | Location: | 0.00 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 284 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.037 | Critical Load Case: | 104 | Location: | 0.72 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 285 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.037 | Critical Load Case: | 101 | Location: | 1.73 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 286 | | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.342 | Critical Load Case: | 101 | Location: | 1.88 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 287 | | | | | | |
| Member Section: ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.243 | Critical Load Case: 101 | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 288 | | | | | | |
| Member Section: ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.145 | Critical Load Case: 101 | Location: 0.41 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 289 | | | | | | |
| Member Section: ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.082 | Critical Load Case: 101 | Location: 1.53 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 290 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.810 | Critical Load Case: 104 | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 291 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.717 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 292 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.668 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 293 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.523 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 294 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.499 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 295 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.371 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 296 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.358 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 297 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.234 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 298 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.212 | Critical Load Case: | 104 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 299 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.156 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 300 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.133 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 301 | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.084 | Critical Load Case: | 6 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 302 | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.131 | Critical Load Case: | 104 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 303 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.234 | Critical Load Case: 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 304 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.343 | Critical Load Case: 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 305 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.267 | Critical Load Case: 104 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 306 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.358 | Critical Load Case: 104 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 307 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.369 | Critical Load Case: 104 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 308 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.570 | Critical Load Case: 101 | Location: | 1.66 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 309 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.160 | Critical Load Case: 101 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 310 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.073 | Critical Load Case: 101 | Location: | 1.39 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 311 | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.052 | Critical Load Case: 101 | | Location: | 0.81 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 312 | | | | | | |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.126 | Critical Load Case: 101 | | Location: | 1.36 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 313 | | | | | | |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.135 | Critical Load Case: 101 | | Location: | 1.36 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 314 | | | | | | |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.150 | Critical Load Case: 101 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 315 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.161 | Critical Load Case: | 101 | Location: | | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 316 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.183 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 317 | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.203 | Critical Load Case: | 101 | Location: | | 1.35 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 318 | | | | | | |
| Member Section: ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: PASS | Ratio: 0.114 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 319 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.047 | Critical Load Case: | 101 | Location: | 1.35 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 320 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.008 | Critical Load Case: | 104 | Location: | 1.35 |
| Critical Condition: | Sec. 8.2.1.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 321 | | | | | | |
| Member Section: | ST | 72X72X3.2SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.036 | Critical Load Case: | 101 | Location: | 1.35 |
| Critical Condition: | Sec. 8.2.1.2 | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 322 | | | | | | |
| Member Section: | ST | 50X50X2.9SHS | (TATA STRUCTURA SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.294 | Critical Load Case: | 104 | Location: | 2.96 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 323 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.435 | Critical Load Case: 104 | | Location: | 2.55 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 324 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.375 | Critical Load Case: 104 | | Location: | 2.14 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 325 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.258 | Critical Load Case: 104 | | Location: | 1.73 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 326 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.324 | Critical Load Case: 104 | | Location: | 1.94 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 327 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.156 | Critical Load Case: 104 | | Location: | 1.53 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 328 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.052 | Critical Load Case: 104 | | Location: | 1.33 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 329 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.185 | Critical Load Case: 104 | | Location: | 2.38 | |
| Critical Condition: Sec. 6.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 330 | | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.176 | Critical Load Case: 104 | | Location: | 2.22 | |
| Critical Condition: Sec. 6.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 331 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.154 | Critical Load Case: 104 | | Location: | 2.06 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 332 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.091 | Critical Load Case: 101 | | Location: | 1.92 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 333 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.276 | Critical Load Case: 104 | | Location: | 0.00 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 334 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.446 | Critical Load Case: 104 | | Location: | 2.34 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 335 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.378 | Critical Load Case: 104 | | Location: | 2.75 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 336 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.261 | Critical Load Case: 101 | | Location: | 0.51 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 337 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.139 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 338 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.165 | Critical Load Case: 104 | | Location: | 2.72 |
| Critical Condition: Sec. 6.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 339 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.198 | Critical Load Case: 104 | | Location: | 2.55 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 340 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.207 | Critical Load Case: 6 | | Location: | 3.16 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 341 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.331 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 342 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.431 | Critical Load Case: 101 | | Location: | 0.27 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 343 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.129 | Critical Load Case: 101 | Location: 0.00 | | |
| Critical Condition: Sec. 6.2 | | | | | |

| Member Number: 344 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.089 | Critical Load Case: 101 | Location: 0.00 | | |
| Critical Condition: Sec. 6.2 | | | | | |

| Member Number: 345 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.054 | Critical Load Case: 101 | Location: 0.00 | | |
| Critical Condition: Sec. 6.2 | | | | | |

| Member Number: 346 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.029 | Critical Load Case: 104 | Location: 0.92 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 347 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.007 | Critical Load Case: 104 | Location: | 0.00 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 348 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.037 | Critical Load Case: 101 | Location: | 1.73 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 349 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.340 | Critical Load Case: 101 | Location: | 1.88 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 350 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.240 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 351 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.143 | Critical Load Case: 101 | Location: | 0.27 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 352 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.074 | Critical Load Case: 101 | Location: | 0.51 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 353 | | | | | |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.131 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.3 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 354 | | | | | |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.053 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.3 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 355 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.145 | Critical Load Case: | 104 | Location: | 0.00 | | |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 356 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.058 | Critical Load Case: | 104 | Location: | 2.50 | | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 357 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.058 | Critical Load Case: | 104 | Location: | 2.50 | | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 358 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.208 | Critical Load Case: | 101 | Location: | 2.50 | | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 359 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.181 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 360 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.151 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 361 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.132 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 362 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.117 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 363 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.102 | Critical Load Case: | 101 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 364 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.084 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 365 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.080 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 366 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.078 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 367 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.076 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 368 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.073 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 369 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.147 | Critical Load Case: | 104 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| Member Number: 370 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.122 | Critical Load Case: | 104 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 371 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.124 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| Member Number: 372 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.130 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| Member Number: 373 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.125 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| Member Number: 374 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.208 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 375 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.181 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 376 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.151 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 377 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.132 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 378 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.117 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 379 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.102 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 380 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.084 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 381 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.080 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 382 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.078 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 383 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.076 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 384 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.073 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 385 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.147 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 386 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.122 | Critical Load Case: | 104 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 387 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.125 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

| Member Number: 388 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.131 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

| Member Number: 389 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.126 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

| Member Number: 391 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.098 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 9.3.1.3 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 392 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.041 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.1.3 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 393 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.089 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 394 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.027 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 395 | | | | | | | |
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.027 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 396 |
| --- |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.205 Critical Load Case: 101 Location: 2.50 |
| Critical Condition: Sec. 6.2 |

| Member Number: 397 |
| --- |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 104 Location: 2.50 |
| Critical Condition: Sec. 6.2 |

| Member Number: 398 |
| --- |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.138 Critical Load Case: 101 Location: 2.50 |
| Critical Condition: Sec. 6.2 |

| Member Number: 399 |
| --- |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.117 Critical Load Case: 101 Location: 2.50 |
| Critical Condition: Sec. 6.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 400 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.102 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 401 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.086 | Critical Load Case: | 101 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 402 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.071 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 403 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.065 | Critical Load Case: | 104 | Location: | | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 404 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.062 | Critical Load Case: | 104 | Location: | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | |

| Member Number: 405 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.060 | Critical Load Case: | 104 | Location: | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | |

| Member Number: 406 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.061 | Critical Load Case: | 104 | Location: | 2.50 |
| Critical Condition: Sec. 6.2 | | | | | | |

| Member Number: 407 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.101 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 408 |
|---|
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.112 Critical Load Case: 104 Location: 0.00 |
| Critical Condition: Sec. 7.1.2 |

| Member Number: 409 |
|---|
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.109 Critical Load Case: 104 Location: 0.00 |
| Critical Condition: Sec. 7.1.2 |

| Member Number: 410 |
|---|
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.106 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 7.1.2 |

| Member Number: 411 |
|---|
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.104 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 7.1.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 412 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.205 | Critical Load Case: | 101 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 413 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.148 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 414 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.138 | Critical Load Case: | 101 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 415 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.117 | Critical Load Case: | 101 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 416 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.102 | Critical Load Case: | 101 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 417 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.086 | Critical Load Case: | 101 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 418 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.071 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 419 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.065 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 420 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.062 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 421 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.060 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 422 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.061 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| Member Number: 423 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.099 | Critical Load Case: | 104 | Location: | 2.50 | |
| Critical Condition: Sec. 7.1.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 424 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.112 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

| Member Number: 425 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.109 | Critical Load Case: | 104 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

| Member Number: 426 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.107 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

| Member Number: 427 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.105 | Critical Load Case: | 101 | Location: | 0.00 |
| Critical Condition: Sec. 7.1.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 429 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.068 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 430 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.573 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 431 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.729 Critical Load Case: 101 Location: 1.36 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 432 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.722 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 433 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.161 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 434 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.254 | Critical Load Case: 101 | | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 435 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.338 | Critical Load Case: 101 | | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 436 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.414 | Critical Load Case: 101 | | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 437 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.486 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 438 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.538 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 439 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.584 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 440 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.628 | Critical Load Case: | 101 | Location: | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 441 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.659 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 442 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.697 | Critical Load Case: | 101 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 443 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.722 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 444 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.703 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 445 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.668 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 446 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.639 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 447 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.610 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 448 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.573 | Critical Load Case: | 101 | Location: | 1.36 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 449 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.068 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 450 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.162 | Critical Load Case: 101 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 451 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.254 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 452 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.338 | Critical Load Case: 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 453 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.414 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 454 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.486 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 455 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.538 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 456 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.584 | Critical Load Case: 101 | | Location: | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 457 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.628 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 458 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.659 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 459 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.697 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 460 | | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.729 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 461 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.703 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 462 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.669 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 463 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.640 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 464 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.610 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 466 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.063 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 467 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.516 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 468 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.646 | Critical Load Case: | 101 | Location: | | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 469 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.644 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 470 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.155 | Critical Load Case: | 101 | Location: | | 0.00 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 471 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.241 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 472 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.315 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 473 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.387 | Critical Load Case: | 101 | Location: | | 1.40 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 474 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.448 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 475 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.496 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 476 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.534 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 477 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.572 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 478 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.594 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 479 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.627 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 480 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.643 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 481 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.632 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 482 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.604 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 483 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.584 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 484 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.556 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 485 | | | | | | |
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.516 | Critical Load Case: | 101 | Location: | 1.36 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 486 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.063 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.1.1 |

| Member Number: 487 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.155 Critical Load Case: 101 Location: 1.40 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 488 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.241 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 489 |
|---|
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.315 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 490 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.387 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 491 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.448 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 492 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.497 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

| Member Number: 493 |
| --- |
| Member Section: LD ISA100X100X12 (INDIAN SECTIONS) |
| Status: PASS Ratio: 0.534 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 9.3.2.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 494 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.572 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 495 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.595 | Critical Load Case: | 101 | Location: | 1.40 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 496 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.627 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 497 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.646 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 498 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.632 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 499 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.605 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 500 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.584 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 501 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X12 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.556 | Critical Load Case: | 101 | Location: | 1.36 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 503 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.004 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 504 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.012 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 505 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.027 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 506 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.027 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 507 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.006 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 508 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.009 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 509 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.012 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 510 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.015 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 511 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.017 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 512 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.020 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 513 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.021 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 514 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.023 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 515 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.024 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 516 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.025 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 517 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.026 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 518 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.027 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 519 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.026 | Critical Load Case: | 101 | Location: | | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 520 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.025 | Critical Load Case: | 101 | Location: | | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 521 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.023 | Critical Load Case: | 101 | Location: | | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 522 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.017 | Critical Load Case: | 101 | Location: | | 0.45 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 523 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.006 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 524 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.009 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 525 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.012 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 526 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.015 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 527 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.017 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 528 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.020 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 529 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.021 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 530 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.023 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 531 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.024 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 532 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.025 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 533 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.026 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 534 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.027 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 535 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.026 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 536 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.025 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 537 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.023 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 538 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.017 | Critical Load Case: | 101 | Location: | 0.45 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | |
|---|---|
| Member Number: | 540 |
| Member Section: | LD ISA65X65X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: | 0.004 Critical Load Case: 101 Location: 0.45 |
| Critical Condition: | Sec. 9.3.1.1 |

***WARNING: THE VALUE OF MOMENT AMPLIFICATION FACTORS KY OR KZ IS GREATER THAN 1.4
FOR MEMBER # 541 FOR LOADCASE- 101. SECOND-ORDER ELASTIC ANALYSIS MUST BE PERFORMED AS PER SECTION 4.4.2 of IS800-2007. ALSO, ENSURE THAT THE TYPE OF COMBINATION USED IS REPEAT LOAD OR REFERENCE LOAD INSTEAD OF THE LOAD COMBINATION SYNTAX EXCEPT FOR RESPONSE SPECTRUM LOAD CASES.

| | |
|---|---|
| Member Number: | 541 |
| Member Section: | LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: | 0.561 Critical Load Case: 101 Location: 1.52 |
| Critical Condition: | Sec. 9.3.2.2 |

| | |
|---|---|
| Member Number: | 542 |
| Member Section: | LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: | 0.486 Critical Load Case: 101 Location: 1.52 |
| Critical Condition: | Sec. 9.3.2.2 |

| | |
|---|---|
| Member Number: | 543 |
| Member Section: | LD ISA100X100X8 (INDIAN SECTIONS) |
| Status: PASS Ratio: | 0.413 Critical Load Case: 101 Location: 1.52 |
| Critical Condition: | Sec. 9.3.2.2 |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 544 | | | | | |
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.364 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 545 | | | | | |
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.325 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 546 | | | | | |
| Member Section: | LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.289 | Critical Load Case: | 101 | Location: | 1.27 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

***WARNING: THE VALUE OF MOMENT AMPLIFICATION FACTORS KY OR KZ IS GREATER THAN 1.4
FOR MEMBER # 547 FOR LOADCASE- 101. SECOND-ORDER ELASTIC ANALYSIS MUST BE PERFORMED AS PER SECTION 4.4.2 of IS800-2007. ALSO, ENSURE THAT THE TYPE OF COMBINATION USED IS REPEAT LOAD OR REFERENCE LOAD INSTEAD OF THE LOAD COMBINATION SYNTAX EXCEPT FOR RESPONSE SPECTRUM LOAD CASES.

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: | 547 | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: | 0.695 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

***WARNING: THE VALUE OF MOMENT AMPLIFICATION FACTORS KY OR KZ IS GREATER THAN 1.4
FOR MEMBER # 548 FOR LOADCASE- 104. SECOND-ORDER ELASTIC ANALYSIS MUST BE PERFORMED AS PER SECTION 4.4.2 of IS800-2007. ALSO, ENSURE THAT THE TYPE OF COMBINATION USED IS REPEAT LOAD OR REFERENCE LOAD INSTEAD OF THE LOAD COMBINATION SYNTAX EXCEPT FOR RESPONSE SPECTRUM LOAD CASES.

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 548 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.653 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

***WARNING: THE VALUE OF MOMENT AMPLIFICATION FACTORS KY OR KZ IS GREATER THAN 1.4
FOR MEMBER # 549 FOR LOADCASE- 104. SECOND-ORDER ELASTIC ANALYSIS MUST BE PERFORMED AS PER SECTION 4.4.2 of IS800-2007. ALSO, ENSURE THAT THE TYPE OF COMBINATION USED IS REPEAT LOAD OR REFERENCE LOAD INSTEAD OF THE LOAD COMBINATION SYNTAX EXCEPT FOR RESPONSE SPECTRUM LOAD CASES.

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 549 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.637 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

***WARNING: THE VALUE OF MOMENT AMPLIFICATION FACTORS KY OR KZ IS GREATER THAN 1.4
FOR MEMBER # 550 FOR LOADCASE- 104. SECOND-ORDER ELASTIC ANALYSIS MUST BE PERFORMED AS PER SECTION 4.4.2 of IS800-2007. ALSO, ENSURE THAT THE TYPE OF COMBINATION USED IS REPEAT LOAD OR REFERENCE LOAD INSTEAD OF THE LOAD COMBINATION SYNTAX EXCEPT FOR RESPONSE SPECTRUM LOAD CASES.

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 550 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.617 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

***WARNING: THE VALUE OF MOMENT AMPLIFICATION FACTORS KY OR KZ IS GREATER THAN 1.4
FOR MEMBER # 551 FOR LOADCASE- 104. SECOND-ORDER ELASTIC ANALYSIS MUST BE PERFORMED AS PER SECTION 4.4.2 of IS800-2007. ALSO, ENSURE THAT THE TYPE OF COMBINATION USED IS REPEAT LOAD OR REFERENCE LOAD INSTEAD OF THE LOAD COMBINATION SYNTAX EXCEPT FOR RESPONSE SPECTRUM LOAD CASES.
THERE MAY BE MORE SUCH CASES. ADDITIONAL SUCH MESSAGES ARE SUPPRESSED.

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 551 | | | | | | |
| Member Section: | LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: | PASS | Ratio: | 0.606 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| Member Number: 552 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.464 | Critical Load Case: | 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 553 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.172 | Critical Load Case: | 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 554 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.145 | Critical Load Case: | 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 555 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.144 | Critical Load Case: | 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 556 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.143 | Critical Load Case: | 101 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 557 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.148 | Critical Load Case: | 101 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 558 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.218 | Critical Load Case: | 101 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 559 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.561 | Critical Load Case: | 101 | Location: | | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 560 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.486 | Critical Load Case: | 101 | Location: | | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 561 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.413 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 562 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.364 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 563 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.325 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 564 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.290 | Critical Load Case: 101 | Location: | 1.27 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 565 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.696 | Critical Load Case: | 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 566 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.653 | Critical Load Case: | 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 567 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.637 | Critical Load Case: | 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 568 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.617 | Critical Load Case: | 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 569 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.607 | Critical Load Case: | 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 570 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.463 | Critical Load Case: | 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 571 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.172 | Critical Load Case: | 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 572 | | | | | | |
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.144 | Critical Load Case: | 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 573 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.145 | Critical Load Case: | 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 574 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.143 | Critical Load Case: | 101 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 575 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.149 | Critical Load Case: | 101 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 576 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.219 | Critical Load Case: | 101 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 577 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.553 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 578 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.400 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 579 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.379 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 580 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.327 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 581 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.287 | Critical Load Case: 101 | | Location: | 1.27 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 582 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.249 | Critical Load Case: 101 | | Location: | 1.27 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 583 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.580 | Critical Load Case: 101 | | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 584 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.532 | Critical Load Case: 104 | | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 585 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.512 | Critical Load Case: 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 586 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.499 | Critical Load Case: 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 587 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.503 | Critical Load Case: 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 588 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.283 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 589 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.120 | Critical Load Case: | 104 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 590 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.133 | Critical Load Case: | 104 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 591 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.130 | Critical Load Case: | 104 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 592 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.124 | Critical Load Case: | 104 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 593 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.123 | Critical Load Case: 101 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 594 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.180 | Critical Load Case: 101 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 595 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.553 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 596 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.400 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 597 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.379 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 598 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.327 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 599 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.288 | Critical Load Case: | 101 | Location: | 1.27 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 600 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA100X100X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.249 | Critical Load Case: | 101 | Location: | 1.27 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 601 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.581 | Critical Load Case: | 101 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 602 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.532 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 603 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.512 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 604 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.499 | Critical Load Case: | 104 | Location: | 1.52 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 605 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.503 | Critical Load Case: 104 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 606 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.285 | Critical Load Case: 101 | Location: | 1.52 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 607 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.119 | Critical Load Case: 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 608 | | | | | |
|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | |
| Status: PASS | Ratio: 0.134 | Critical Load Case: 104 | Location: | 1.51 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 609 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.130 | Critical Load Case: | 104 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 610 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.125 | Critical Load Case: | 104 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 611 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.123 | Critical Load Case: | 101 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 612 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: LD | ISA65X65X8 | (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: | 0.181 | Critical Load Case: | 101 | Location: | | 1.51 |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 613 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.028 | Critical Load Case: 101 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 614 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.061 | Critical Load Case: 101 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 615 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.102 | Critical Load Case: 101 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 616 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.135 | Critical Load Case: 101 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 617 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: 0.167 | Critical Load Case: 101 | Location: 0.83 | | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 618 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: 0.193 | Critical Load Case: 101 | Location: 0.83 | | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 619 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: 0.217 | Critical Load Case: 101 | Location: 0.83 | | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 620 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: 0.235 | Critical Load Case: 101 | Location: 0.83 | | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 621 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.252 | Critical Load Case: 101 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 622 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.264 | Critical Load Case: 101 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 623 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.276 | Critical Load Case: 101 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 624 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.283 | Critical Load Case: 101 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 625 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.280 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 626 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.275 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 627 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.263 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 628 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.249 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 629 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.220 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 630 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.113 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 631 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.028 | Critical Load Case: 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 632 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.062 | Critical Load Case: 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 633 | | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.102 | Critical Load Case: | 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 634 | | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.136 | Critical Load Case: | 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 635 | | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.167 | Critical Load Case: | 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 636 | | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.193 | Critical Load Case: | 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 637 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.217 | Critical Load Case: 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 638 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.235 | Critical Load Case: 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 639 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.252 | Critical Load Case: 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 640 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.264 | Critical Load Case: 101 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 641 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.276 | Critical Load Case: 101 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 642 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.284 | Critical Load Case: 101 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 643 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.280 | Critical Load Case: 101 | Location: 0.82 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 644 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.275 | Critical Load Case: 101 | Location: 0.82 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 645 | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: | 0.263 | Critical Load Case: | 101 | Location: | 0.82 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 646 | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: | 0.249 | Critical Load Case: | 101 | Location: | 0.82 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 647 | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: | 0.220 | Critical Load Case: | 101 | Location: | 0.82 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 648 | | | | | | |
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: | 0.113 | Critical Load Case: | 101 | Location: | 0.82 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 649 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.173 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 650 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.737 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 651 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.135 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 652 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.731 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 653 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.151 | Critical Load Case: 104 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 654 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.706 | Critical Load Case: 104 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 655 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.165 | Critical Load Case: 104 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 656 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.682 | Critical Load Case: 104 | Location: 0.83 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 657 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.176 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 658 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.654 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 659 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.187 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 660 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.606 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 661 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.064 | Critical Load Case: 101 | Location: 0.82 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 662 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.089 | Critical Load Case: 101 | Location: 0.82 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 663 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.079 | Critical Load Case: 101 | Location: 0.82 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 664 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.095 | Critical Load Case: 101 | Location: 0.82 | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 665 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.090 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 666 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.059 | Critical Load Case: 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 667 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.173 | Critical Load Case: 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | |

| Member Number: 668 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.739 | Critical Load Case: 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 669 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.135 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 670 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.732 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 671 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.152 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 672 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.707 | Critical Load Case: | 104 | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 673 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.165 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 674 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.683 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 675 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.176 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 676 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.655 | Critical Load Case: 104 | Location: 0.83 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 677 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.188 | Critical Load Case: 104 | | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 678 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.606 | Critical Load Case: 104 | | Location: | 0.83 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 679 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.068 | Critical Load Case: 101 | | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 680 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.092 | Critical Load Case: 101 | | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 681 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.076 | Critical Load Case: | 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 682 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.098 | Critical Load Case: | 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 683 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.088 | Critical Load Case: | 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 684 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.061 | Critical Load Case: | 101 | Location: | 0.82 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 685 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.221 | Critical Load Case: 104 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 686 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.155 | Critical Load Case: 101 | | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 687 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.113 | Critical Load Case: 104 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 688 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.128 | Critical Load Case: 101 | | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 689 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.114 | Critical Load Case: 104 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 690 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.115 | Critical Load Case: 101 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 691 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.107 | Critical Load Case: 6 | | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 692 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.119 | Critical Load Case: 101 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 693 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: | PASS | Ratio: | 0.105 | Critical Load Case: | 6 | Location: | 1.65 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| Member Number: 694 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: | PASS | Ratio: | 0.081 | Critical Load Case: | 101 | Location: | 1.65 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| Member Number: 695 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: | PASS | Ratio: | 0.113 | Critical Load Case: | 6 | Location: | 1.65 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

| Member Number: 696 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: | ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: | PASS | Ratio: | 0.299 | Critical Load Case: | 101 | Location: | 1.65 |
| Critical Condition: | Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 697 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.023 | Critical Load Case: 104 | | Location: | 0.54 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 698 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.040 | Critical Load Case: 104 | | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 699 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.020 | Critical Load Case: 104 | | Location: | 0.27 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 700 | | | | | | |
| Member Section: ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: 0.060 | Critical Load Case: 104 | | Location: | 1.62 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 701 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.063 | Critical Load Case: 101 | Location: 1.62 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 702 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.094 | Critical Load Case: 101 | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 703 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.221 | Critical Load Case: 104 | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 704 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.155 | Critical Load Case: 101 | Location: 1.65 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 705 | | | | | | |
| Member Section: | ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.113 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 706 | | | | | | |
| Member Section: | ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.128 | Critical Load Case: | 101 | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 707 | | | | | | |
| Member Section: | ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.114 | Critical Load Case: | 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: | 708 | | | | | | |
| Member Section: | ST | ISA65X65X8 | (INDIAN SECTIONS) | | | | |
| Status: PASS | Ratio: | 0.115 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 709 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.107 | Critical Load Case: | 6 | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 710 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.120 | Critical Load Case: | 101 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 711 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.105 | Critical Load Case: | 6 | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 712 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.081 | Critical Load Case: | 101 | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 713 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.112 | Critical Load Case: | 6 | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 714 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.298 | Critical Load Case: | 101 | Location: | 1.65 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

| Member Number: 715 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.024 | Critical Load Case: | 104 | Location: | 0.14 | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | | |

| Member Number: 716 | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.051 | Critical Load Case: | 104 | Location: | 1.62 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 717 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.023 | Critical Load Case: 104 | Location: 0.27 | | | |
| Critical Condition: Sec. 9.3.1.1 | | | | | | |

| Member Number: 718 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.065 | Critical Load Case: 104 | Location: 1.62 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 719 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.060 | Critical Load Case: 101 | Location: 1.62 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| Member Number: 720 | | | | | | |
|---|---|---|---|---|---|---|
| Member Section: ST ISA65X65X8 (INDIAN SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.097 | Critical Load Case: 101 | Location: 0.00 | | | |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 721 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.222 | Critical Load Case: 104 | | Location: | 1.24 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 722 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.163 | Critical Load Case: 104 | | Location: | 1.24 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 723 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.143 | Critical Load Case: 103 | | Location: | 0.90 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 724 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.562 | Critical Load Case: 103 | | Location: | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 725 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.250 | Critical Load Case: | 104 | Location: | 1.97 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 726 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.223 | Critical Load Case: | 104 | Location: | 1.24 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 727 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.161 | Critical Load Case: | 104 | Location: | 1.24 | |
| Critical Condition: Sec. 6.2 | | | | | | | |

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member Number: 728 | | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | | |
| Status: PASS | Ratio: | 0.143 | Critical Load Case: | 103 | Location: | 0.90 | |
| Critical Condition: Sec. 8.2.1.2 | | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 729 | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.562 | Critical Load Case: 103 | | Location: | | 0.00 |
| Critical Condition: Sec. 8.2.1.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 730 | | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.252 | Critical Load Case: 104 | | Location: | | 1.97 |
| Critical Condition: Sec. 6.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 731 | | | | | | |
| Member Section: ST 150X150X6.0SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.757 | Critical Load Case: 104 | | Location: | | 3.24 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

| | | | | | | |
|---|---|---|---|---|---|---|
| Member Number: 732 | | | | | | |
| Member Section: ST 150X150X6.0SHS (TATA STRUCTURA SECTIONS) | | | | | | |
| Status: PASS | Ratio: 0.757 | Critical Load Case: 104 | | Location: | | 3.24 |
| Critical Condition: Sec. 9.3.2.2 | | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 733 | | | | | |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS Ratio: 0.089 Critical Load Case: 104 Location: | | | | | 0.72 |
| Critical Condition: Sec. 9.3.1.3 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 734 | | | | | |
| Member Section: LD ISA100X100X8 (INDIAN SECTIONS) | | | | | |
| Status: PASS Ratio: 0.028 Critical Load Case: 101 Location: | | | | | 0.72 |
| Critical Condition: Sec. 9.3.1.3 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 735 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS Ratio: 0.357 Critical Load Case: 104 Location: | | | | | 0.52 |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 737 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS Ratio: 0.267 Critical Load Case: 104 Location: | | | | | 0.52 |
| Critical Condition: Sec. 6.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 739 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.357 | Critical Load Case: 104 | Location: | 0.52 | |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 741 | | | | | |
| Member Section: ST 50X50X2.9SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.263 | Critical Load Case: 104 | Location: | 0.52 | |
| Critical Condition: Sec. 6.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 742 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.487 | Critical Load Case: 104 | Location: | 0.00 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| | | | | | |
|---|---|---|---|---|---|
| Member Number: 743 | | | | | |
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.284 | Critical Load Case: 101 | Location: | 0.85 | |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.1)
**********

| Member Number: 744 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.524 | Critical Load Case: 104 | | Location: | 0.50 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

| Member Number: 745 | | | | | |
|---|---|---|---|---|---|
| Member Section: ST 72X72X3.2SHS (TATA STRUCTURA SECTIONS) | | | | | |
| Status: PASS | Ratio: 0.325 | Critical Load Case: 101 | | Location: | 0.50 |
| Critical Condition: Sec. 9.3.2.2 | | | | | |

316. STEEL MEMBER TAKE OFF LIST 3 7 TO 9 12 24 TO 37 41 TO 59 66 TO 80 92 TO 102 -

STEEL TAKE OFF

STEEL TAKE-OFF

| PROFILE | LENGTH(METE) | WEIGHT(KN ) |
|---|---|---|
| 317. 108 TO 143 147 148 162 TO 173 179 TO 318. 224 236 TO 268 275 TO 289 301 TO 311 319. 742 TO 745 | | 183 195 TO 205 211 TO 215 218 TO 221 - 317 TO 352 685 TO 732 735 737 739 741 - |
| ST 72X72X3.2SHS | 136.41 | 8.949 |
| ST 50X50X2.9SHS | 245.15 | 9.887 |
| LD ISA65X65X8 | 29.70 | 4.454 |
| ST ISA65X65X8 | 59.60 | 4.468 |
| ST 150X150X6.0SHS | 12.95 | 3.346 |
| | TOTAL = | 31.104 |

| MEMBER | PROFILE | LENGTH (METE) | WEIGHT (KN ) |
|---|---|---|---|
| 3 | ST 72X72X3.2SHS | 1.66 | 0.109 |
| 7 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 8 | ST 72X72X3.2SHS | 1.61 | 0.105 |
| 9 | ST 72X72X3.2SHS | 1.61 | 0.105 |
| 12 | ST 72X72X3.2SHS | 1.35 | 0.089 |
| 24 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 25 | ST 50X50X2.9SHS | 2.96 | 0.119 |
| 26 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 27 | ST 50X50X2.9SHS | 2.55 | 0.103 |
| 28 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 29 | ST 50X50X2.9SHS | 2.14 | 0.086 |
| 30 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 31 | ST 50X50X2.9SHS | 1.73 | 0.070 |
| 32 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 33 | ST 50X50X2.9SHS | 1.94 | 0.078 |
| 34 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 35 | ST 50X50X2.9SHS | 1.53 | 0.062 |
| 36 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 37 | ST 50X50X2.9SHS | 1.33 | 0.054 |
| 41 | ST 50X50X2.9SHS | 2.38 | 0.096 |
| 42 | ST 50X50X2.9SHS | 2.22 | 0.090 |
| 43 | ST 50X50X2.9SHS | 2.06 | 0.083 |
| 44 | ST 50X50X2.9SHS | 1.92 | 0.077 |
| 45 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 46 | ST 50X50X2.9SHS | 1.12 | 0.045 |
| 47 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 48 | ST 50X50X2.9SHS | 2.34 | 0.095 |
| 49 | ST 72X72X3.2SHS | 1.39 | 0.091 |
| 50 | ST 50X50X2.9SHS | 2.75 | 0.111 |
| 51 | ST 50X50X2.9SHS | 3.08 | 0.124 |
| 52 | ST 50X50X2.9SHS | 2.90 | 0.117 |
| 53 | ST 50X50X2.9SHS | 2.72 | 0.110 |
| 54 | ST 50X50X2.9SHS | 2.55 | 0.103 |

| | | | | |
|---|---|---|---|---|
| 55 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 56 | ST | 50X50X2.9SHS | 3.16 | 0.127 |
| 57 | ST | 72X72X3.2SHS | 3.45 | 0.226 |
| 58 | ST | 50X50X2.9SHS | 3.26 | 0.132 |
| 59 | ST | 72X72X3.2SHS | 0.50 | 0.033 |
| 66 | ST | 72X72X3.2SHS | 0.85 | 0.056 |
| 67 | ST | 50X50X2.9SHS | 1.51 | 0.061 |
| 68 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 69 | ST | 50X50X2.9SHS | 1.31 | 0.053 |
| 70 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 71 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 72 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 73 | ST | 50X50X2.9SHS | 0.92 | 0.037 |
| 74 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 75 | ST | 50X50X2.9SHS | 0.72 | 0.029 |
| 76 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 77 | ST | 50X50X2.9SHS | 1.88 | 0.076 |
| 78 | ST | 50X50X2.9SHS | 1.75 | 0.071 |
| 79 | ST | 50X50X2.9SHS | 1.63 | 0.066 |
| 80 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 92 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 93 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 94 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 95 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 96 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 97 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 98 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 99 | ST | 72X72X3.2SHS | 1.66 | 0.109 |
| 100 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 101 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 102 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 108 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 109 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 110 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 111 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 112 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 113 | ST | 50X50X2.9SHS | 2.96 | 0.119 |
| 114 | ST | 50X50X2.9SHS | 2.55 | 0.103 |
| 115 | ST | 50X50X2.9SHS | 2.14 | 0.086 |
| 116 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 117 | ST | 50X50X2.9SHS | 1.94 | 0.078 |
| 118 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 119 | ST | 50X50X2.9SHS | 1.33 | 0.054 |
| 120 | ST | 50X50X2.9SHS | 2.38 | 0.096 |
| 121 | ST | 50X50X2.9SHS | 2.22 | 0.090 |
| 122 | ST | 50X50X2.9SHS | 2.06 | 0.083 |
| 123 | ST | 50X50X2.9SHS | 1.92 | 0.077 |
| 124 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 125 | ST | 50X50X2.9SHS | 2.34 | 0.095 |
| 126 | ST | 50X50X2.9SHS | 2.75 | 0.111 |
| 127 | ST | 50X50X2.9SHS | 3.08 | 0.124 |
| 128 | ST | 50X50X2.9SHS | 2.90 | 0.117 |
| 129 | ST | 50X50X2.9SHS | 2.72 | 0.110 |
| 130 | ST | 50X50X2.9SHS | 2.55 | 0.103 |
| 131 | ST | 50X50X2.9SHS | 3.16 | 0.127 |
| 132 | ST | 72X72X3.2SHS | 3.45 | 0.226 |

| | | | | |
|---|---|---|---|---|
| 133 | ST | 50X50X2.9SHS | 3.26 | 0.132 |
| 134 | ST | 50X50X2.9SHS | 1.51 | 0.061 |
| 135 | ST | 50X50X2.9SHS | 1.31 | 0.053 |
| 136 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 137 | ST | 50X50X2.9SHS | 0.92 | 0.037 |
| 138 | ST | 50X50X2.9SHS | 0.72 | 0.029 |
| 139 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 140 | ST | 50X50X2.9SHS | 1.88 | 0.076 |
| 141 | ST | 50X50X2.9SHS | 1.75 | 0.071 |
| 142 | ST | 50X50X2.9SHS | 1.63 | 0.066 |
| 143 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 147 | ST | 72X72X3.2SHS | 0.90 | 0.059 |
| 148 | ST | 72X72X3.2SHS | 0.90 | 0.059 |
| 162 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 163 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 164 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 165 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 166 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 167 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 168 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 169 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 170 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 171 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 172 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 173 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 179 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 180 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 181 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 182 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 183 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 195 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 196 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 197 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 198 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 199 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 200 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 201 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 202 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 203 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 204 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 205 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 211 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 212 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 213 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 214 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 215 | LD | ISA65X65X8 | 0.90 | 0.135 |
| 218 | ST | 72X72X3.2SHS | 1.66 | 0.109 |
| 219 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 220 | ST | 72X72X3.2SHS | 1.61 | 0.105 |
| 221 | ST | 72X72X3.2SHS | 1.61 | 0.105 |
| 224 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 236 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 237 | ST | 50X50X2.9SHS | 2.96 | 0.119 |
| 238 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 239 | ST | 50X50X2.9SHS | 2.55 | 0.103 |
| 240 | ST | 72X72X3.2SHS | 1.39 | 0.091 |

| | | | | |
|---|---|---|---|---|
| 241 | ST | 50X50X2.9SHS | 2.14 | 0.086 |
| 242 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 243 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 244 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 245 | ST | 50X50X2.9SHS | 1.94 | 0.078 |
| 246 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 247 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 248 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 249 | ST | 50X50X2.9SHS | 1.33 | 0.054 |
| 250 | ST | 50X50X2.9SHS | 2.38 | 0.096 |
| 251 | ST | 50X50X2.9SHS | 2.22 | 0.090 |
| 252 | ST | 50X50X2.9SHS | 2.06 | 0.083 |
| 253 | ST | 50X50X2.9SHS | 1.92 | 0.077 |
| 254 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 255 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 256 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 257 | ST | 50X50X2.9SHS | 2.34 | 0.095 |
| 258 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 259 | ST | 50X50X2.9SHS | 2.75 | 0.111 |
| 260 | ST | 50X50X2.9SHS | 3.08 | 0.124 |
| 261 | ST | 50X50X2.9SHS | 2.90 | 0.117 |
| 262 | ST | 50X50X2.9SHS | 2.72 | 0.110 |
| 263 | ST | 50X50X2.9SHS | 2.55 | 0.103 |
| 264 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 265 | ST | 50X50X2.9SHS | 3.16 | 0.127 |
| 266 | ST | 72X72X3.2SHS | 3.45 | 0.226 |
| 267 | ST | 50X50X2.9SHS | 3.26 | 0.132 |
| 268 | ST | 72X72X3.2SHS | 0.50 | 0.033 |
| 275 | ST | 72X72X3.2SHS | 0.85 | 0.056 |
| 276 | ST | 50X50X2.9SHS | 1.51 | 0.061 |
| 277 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 278 | ST | 50X50X2.9SHS | 1.31 | 0.053 |
| 279 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 280 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 281 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 282 | ST | 50X50X2.9SHS | 0.92 | 0.037 |
| 283 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 284 | ST | 50X50X2.9SHS | 0.72 | 0.029 |
| 285 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 286 | ST | 50X50X2.9SHS | 1.88 | 0.076 |
| 287 | ST | 50X50X2.9SHS | 1.75 | 0.071 |
| 288 | ST | 50X50X2.9SHS | 1.63 | 0.066 |
| 289 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 301 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 302 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 303 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 304 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 305 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 306 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 307 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 308 | ST | 72X72X3.2SHS | 1.66 | 0.109 |
| 309 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 310 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 311 | ST | 72X72X3.2SHS | 1.39 | 0.091 |
| 317 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 318 | ST | 72X72X3.2SHS | 1.35 | 0.089 |

| | | | | |
|---|---|---|---|---|
| 319 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 320 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 321 | ST | 72X72X3.2SHS | 1.35 | 0.089 |
| 322 | ST | 50X50X2.9SHS | 2.96 | 0.119 |
| 323 | ST | 50X50X2.9SHS | 2.55 | 0.103 |
| 324 | ST | 50X50X2.9SHS | 2.14 | 0.086 |
| 325 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 326 | ST | 50X50X2.9SHS | 1.94 | 0.078 |
| 327 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 328 | ST | 50X50X2.9SHS | 1.33 | 0.054 |
| 329 | ST | 50X50X2.9SHS | 2.38 | 0.096 |
| 330 | ST | 50X50X2.9SHS | 2.22 | 0.090 |
| 331 | ST | 50X50X2.9SHS | 2.06 | 0.083 |
| 332 | ST | 50X50X2.9SHS | 1.92 | 0.077 |
| 333 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 334 | ST | 50X50X2.9SHS | 2.34 | 0.095 |
| 335 | ST | 50X50X2.9SHS | 2.75 | 0.111 |
| 336 | ST | 50X50X2.9SHS | 3.08 | 0.124 |
| 337 | ST | 50X50X2.9SHS | 2.90 | 0.117 |
| 338 | ST | 50X50X2.9SHS | 2.72 | 0.110 |
| 339 | ST | 50X50X2.9SHS | 2.55 | 0.103 |
| 340 | ST | 50X50X2.9SHS | 3.16 | 0.127 |
| 341 | ST | 72X72X3.2SHS | 3.45 | 0.226 |
| 342 | ST | 50X50X2.9SHS | 3.26 | 0.132 |
| 343 | ST | 50X50X2.9SHS | 1.51 | 0.061 |
| 344 | ST | 50X50X2.9SHS | 1.31 | 0.053 |
| 345 | ST | 50X50X2.9SHS | 1.12 | 0.045 |
| 346 | ST | 50X50X2.9SHS | 0.92 | 0.037 |
| 347 | ST | 50X50X2.9SHS | 0.72 | 0.029 |
| 348 | ST | 50X50X2.9SHS | 1.73 | 0.070 |
| 349 | ST | 50X50X2.9SHS | 1.88 | 0.076 |
| 350 | ST | 50X50X2.9SHS | 1.75 | 0.071 |
| 351 | ST | 50X50X2.9SHS | 1.63 | 0.066 |
| 352 | ST | 50X50X2.9SHS | 1.53 | 0.062 |
| 685 | ST | ISA65X65X8 | 1.89 | 0.142 |
| 686 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 687 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 688 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 689 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 690 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 691 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 692 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 693 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 694 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 695 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 696 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 697 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 698 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 699 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 700 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 701 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 702 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 703 | ST | ISA65X65X8 | 1.89 | 0.142 |
| 704 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 705 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 706 | ST | ISA65X65X8 | 1.65 | 0.124 |

| | | | | |
|---|---|---|---|---|
| 707 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 708 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 709 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 710 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 711 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 712 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 713 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 714 | ST | ISA65X65X8 | 1.65 | 0.124 |
| 715 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 716 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 717 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 718 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 719 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 720 | ST | ISA65X65X8 | 1.62 | 0.122 |
| 721 | ST | 72X72X3.2SHS | 1.24 | 0.081 |
| 722 | ST | 72X72X3.2SHS | 1.24 | 0.081 |
| 723 | ST | 72X72X3.2SHS | 0.90 | 0.059 |
| 724 | ST | 72X72X3.2SHS | 1.84 | 0.121 |
| 725 | ST | 72X72X3.2SHS | 1.97 | 0.129 |
| 726 | ST | 72X72X3.2SHS | 1.24 | 0.081 |
| 727 | ST | 72X72X3.2SHS | 1.24 | 0.081 |
| 728 | ST | 72X72X3.2SHS | 0.90 | 0.059 |
| 729 | ST | 72X72X3.2SHS | 1.84 | 0.121 |
| 730 | ST | 72X72X3.2SHS | 1.97 | 0.129 |
| 731 | ST | 150X150X6.0SHS | 6.48 | 1.673 |
| 732 | ST | 150X150X6.0SHS | 6.48 | 1.673 |
| 735 | ST | 50X50X2.9SHS | 0.52 | 0.021 |
| 737 | ST | 50X50X2.9SHS | 0.52 | 0.021 |
| 739 | ST | 50X50X2.9SHS | 0.52 | 0.021 |
| 741 | ST | 50X50X2.9SHS | 0.52 | 0.021 |
| 742 | ST | 72X72X3.2SHS | 0.85 | 0.056 |
| 743 | ST | 72X72X3.2SHS | 0.85 | 0.056 |
| 744 | ST | 72X72X3.2SHS | 0.50 | 0.033 |
| 745 | ST | 72X72X3.2SHS | 0.50 | 0.033 |
| | | | TOTAL = | 31.104 |

********** END OF DATA FROM INTERNAL STORAGE **********

320. FINISH

********** END OF THE STAAD.Pro RUN **********

**** DATE= JUN 24,2022 TIME= 19:18:16 ****


```
************************************************************
*    For technical assistance on STAAD.Pro, please visit   *
*    http://www.bentley.com/en/support/                    *
*                                                          *
*    Details about additional assistance from              *
*    Bentley and Partners can be found at program menu     *
*    Help->Technical Support                               *
*                                                          *
*       Copyright (c) 1997-2017 Bentley Systems, Inc.      *
*                  http://www.bentley.com                  *
************************************************************
```