

The current tree placement is obstructing the proposed sliding gate layout. To accommodate both the sliding and fixed gate mechanisms, we may need to extend the gate alignment closer to the roadside to gain additional width



EARLIER DESIGN



PROPOSED DESIGN