



At this position Mounting bracket of rolling shutter can not be installed Because there is no enough space available to the both side. Structure should be installed from inside to I-beam column


At this position Mounting bracket of
rolling shutter can not be installed
Because there is no enough
space available to the both side
structure should be installed from
inside to I-beam column



Structure for rolling shutter
should be installed from inside
to I-beam column



At this position MS bracket of rolling shutter can not be installed Because there is no enough space available to the both side structure should be installed from inside to I-beam column


No space available for Mounting Bracket
of rolling shutter structure should be installed
from inside to I-beam column


No space available for Mounting Bracket
of rolling shutter structure should be
installed from inside to I-beam column


There is no enough headroom available
for shaft & hood cover of the rolling shutter
structure should be installed from inside
to I-beam column