Preventive Maintenance Manufacturer's Specification

ASSA ABLOY Entrance Systems

Enhance the durability of your High Performance Door Albany RR200

Key benefit

Safety

Cost-Savings

Just as a car's tires and oil must be changed regularly, your Albany High Performance Doors have key components that periodically need replacing. Whether it's a spring or a sprocket, changing them before they break is an integral part of Pro-Active Care.

We at ASSA ABLOY Entrance Systems believe in Pro-Active Care. Letting us replace components before they fail keeps your warranty valid and your equipment compliant with regulations. Even more importantly, it ensures the safety and functionality of your equipment, so that you can avoid accidents and losses in productivity.



Instructions for table usage:

Qualified person
The manufacturer's recommendation for exchange of components is subject to the findings of a qualified person. We strongly recommend that inspections are performed by a qualified person within the recommended service intervals (according to the user manual of the door).

Recommendations for exchange
The manufacturer's recommendations are based on a door with average size, installed under regular environmental conditions. Doors dimensioned close to maximum size of the door type or doors installed in harsh environmental conditions, need particular observation by a qualified person as the recommended intervals might be shorter.

Components specified as wear and tear related do not have a recommended exchange interval, indications for exchange or wear can be derived from the corresponding fact sheets.

Subject to technical modifications without notice. Errors and omissions excepted.

ASSA ABLOY ENTRANCE SYSTEMS
Maintenance & Modernization

Preventive Maintenance
Manufacturer's Specification

ASSA ABLOY

Albany RR200

Product group	Description	150.000 cycles or 2 years	200.000 cycles or 3 years	250.000 cycles or 3 years	300.000 cycles or 3 years	300.000 cycles or 5 years	500.000 cycles	1.000.000 cycles	10 years	wear / tear related
Actuators	Photocell receiver + 20 m cable								●	
	Photocell transmitter + 20 m cable								●	
Safety	Wireless receiver for WDD								●	
Curtain	Curtain with WDD without receiver									●
	Zipper repairkit (1 tooth)								●	
	kit DBD cpl - rh/lh - cable 10m									●
Top roll	Bearing 25 mm						●			
Bottom profile	WDD2 Upgrade Kit Full					●				
	WDD2 Maintenance kit	●								
Sliding/Guiding	Reintroduction block		●							
	Cpl side guide D121, L=4m				●					
Drive unit	limit switch block, 6 contacts incl. Cams								●	
	Gear motor with MCC encoder							●		
	Gear motor with FC							●		
Brake	Brake - frequency converter							●		
Encoder	Limit swich, digital			●						

≤150.000 cycles: ±10.000 cycles; >150.000 cycles: ±20.000 cycles
≤5 years: ±6 months; >5 years: ±1 year

Technical data subject to change without notice
© ASSA ABLOY Entrance Systems AB PL.MAN/Albany RR200/DEU.EN-1.1/1606 / 64 100 701

ASSA ABLOY ENTRANCE SYSTEMS
Maintenance & Modernization