

We observed that the cutout is open on one side up to one floor level.
To ensure safety & prevent roof uplift during wind or storm conditions, this
side needs to be closed. The other side can be closed as part of the NIHVA Scope.