NIHVA

INSTALLATION CHECKLIST FOR GEAR OPERATED ROLLING SHUTTER

Rolling shutter location :- B 500.	Date :-
Rolling shutter No. :-	Format No.:-
Rolling shutter size :- 4000 x 5000 mm	Issue No. Date: -

	INSPECTION POINTS	YES	NO
1	Guide greasing	☑	☐
2	Worm gear greasing	☑	☐
3	Bearing greasing	☑	☐
4	Gear box greasing	☑	☐
5	Slats ok	☑	☐
6	Bottom rubber gasket ok	☐	NA
7	Guide ok	☑	☐
8	Worm gear drive ok	☑	☐
9	Hood cover ok	☑	☐
10	Bracket welding / fasteners ok	☑	☐
11	Guide welding / fasteners ok	☑	☐
12	Bottom profile ok	☑	☐
13	Gear box welding / fasteners ok	☑	☐
14	Spring tension ok	☑	☐
15	Lock working properly	☑	☐

Remarks (if any) :-

NIHVA Engineer Name :- Sumit Jumde.

NIHVA Engineer Sign :-

Client Name & Mob. No. :- Makarand Jadhav

Client sign :-

NIHVA

INSTALLATION CHECKLIST FOR GEAR OPERATED ROLLING SHUTTER

Rolling shutter location :- B 500.	Date :-
Rolling shutter No. :-	Format No.:-
Rolling shutter size :- 2445 X 3000 mm	Issue No. Date: -

	INSPECTION POINTS	YES	NO
1	Guide greasing	☑	☐
2	Worm gear greasing	☑	☐
3	Bearing greasing	☑	☐
4	Gear box greasing	☑	☐
5	Slats ok	☑	☐
6	Bottom rubber gasket ok	☑	NA
7	Guide ok	☑	☐
8	Worm gear drive ok	☑	☐
9	Hood cover ok	☑	☐
10	Bracket welding / fasteners ok	☑	☐
11	Guide welding / fasteners ok	☑	☐
12	Bottom profile ok	☑	☐
13	Gear box welding / fasteners ok	☑	☐
14	Spring tension ok	☑	☐
15	Lock working properly	☑	☐

Remarks (if any) :-

NIHVA Engineer Name :- Sumit Jumale.

NIHVA Engineer Sign :-

Client Name & Mob. No. :- Makarand Jadhav

Client sign :-