
NIHVA TECHNOLOGIES PVT. LTD.

| | | |
|---|---|---|
| **CLIENT** | **:** | **NTPL** |
| **SITE** | **:** | **Gujarat** |
| **LOCATION** | **:** | **Gujarat** |
| **NO.** | **:** | **10012** |
| **DOCUMENT NO.** | **:** | **10012-DBR-R00** |


| | | | | | |
|---|---|---|---|---|---|
| R01 | 10-02-2025 | Design report | R.H.B | H.A.B | H.A.B |
| R00 | 06-01-2025 | Design report | R.H.B | H.A.B | H.A.B |
| **Rev No.** | **Date** | **Description** | **Prepared By** | **Checked By** | **Approved By** |

# TABLE OF CONTENTS



| Sr. No | Contents |
|---|---|
| 1 | Design Philosophy |
| 2 | Design Codes and Standards |
| 3 | Material Specifications Construction |
| 4 | Load Calculations |
| 4.1 | Dead Load |
| 4.2 | Live Load |
| 4.3 | Wind Load Calculations |
| 5 | Deflection Check |
| 6 | Primary Loads and Load Combinations |
| 7 | Annexure 1 ( Staad output) |
| | |




SNAP 3D MODEL (SLIDING FRAME)




SNAP 3D MODEL (BASE STRUCTURE)




SNAP 3D MODEL (MID FRAME)

# 1. Design Philosophy

This document pertains to structural design of sliding panel door at NTPL, Gujarat. The overall size of the single retractable frame is 2.038 x 4.56 x 6m. Retractable frame is provided on an existing structure. Both the structures are modelled and analysed in staad pro software. The wind load is worked out from IS 875 Part III. The various DL and LL acting at different points on frame are transferred to the nearest columns through the grid of beams.

The complete frame is modelled as 3D frame and analysed/designed for worst combination of loads through STAAD.pro. Input and output files are enclosed which are self-explanatory. From the STAAD output, the support reactions for various primary load cases are tabulated and the base plate, shear keys and foundation bolts are designed accordingly. Foundation design shall be done using appropriate load combinations for reactions given in this document.

# 2. DESIGN CODES AND STANDARDS

| Code / Standard | Applicability | Remark |
|---|---|---|
| IS800-2007 | Design of steel structures | -- |
| IS 875-Part III | For wind load calculation | -- |
| | | |

# 3. MATERIAL SPECIFICATION FOR CONSTRUCTION


| Sr.no | Material | Specification | Minimum Strength |
|---|---|---|---|
| 1 | Steel | IS 2062 | Fy = 310 N/mm$^2$ |

# 4. LOAD CALCULATIONS


## 4.1 DEAD LOAD

SELFWEIGHT FACTOR = 1


Dead load for polycarbonate sheet = 4.8 Kg/m$^2$ i.e. 0.047 kN/m$^2$





Dead load applied in staad model





Dead load applied in staad model




Self-weight factor applied in staad model




Self-weight factor applied in staad model





Self-weight factor applied in staad model

## 4.2 LIVE LOAD

**No live load applicable on retractable frame.**

**No live load applicable on MID frame.**

Live load on bottom structure walkway = 200 Kg/m




Live load applied in staad model


## 4.4 RETRACTABLE FRAME LOAD

100% panel retractable frame weight at the ends = 3kN/m


85% panel retractable frame weight at the ends = 2.5kN/m

60% panel retractable frame weight at the ends = 2kN/m


30% panel retractable frame weight at the ends = 1kN/m





100% frame load on end in staad model





85% frame load in staad model




60% frame load in staad model




30% frame load in staad model




Frame load in staad model (MID FRAME)

## 5. Deflection check at building top in Z direction

Refer node no. –16 of staad file for all load cases

Max. Deflection in Z dir. = 21 mm < H/150 = 5800/150 = 40mm (IS 800-2007 table 6)

.... Hence ok.

## 6. PRIMARY LOADS & LOAD COMBINATIONS

### 6.1 PRIMARY LOADS

Load 1 Dead Load (DL)

Load 2 Live Load (LL)

Load 3 Panel load (PL)

## 6.2 LOAD COMBINATIONS

Load Combination for strength:-

1.5 DL + 1.5 LL + 1.5 PL

Load Combination for serviceability:-

DL + LL + PL

# Annexure A

# Staad output for retractable frame

PAGE NO. 1

```
 **************************************************
 *                                    *
 *     STAAD.Pro 2023                 *
 *     Version  23.00.03.25           *
 *     Proprietary Program of         *
 *     Bentley Systems, Inc.          *
 *     Date=    JAN  6, 2025          *
 *     Time=    12: 5:10              *
 *                                    *
 *  Licensed to: only @::LAVteam::®           *
 **************************************************

    1. STAAD SPACE
INPUT FILE: D:\SALT\1873_TRANSFORMERS & RECTIFIERS LTD\STAAD\ASSEMBLY LINE\FRAME_1.STD
    2. START JOB INFORMATION
    3. ENGINEER DATE 06-JAN-25
    4. END JOB INFORMATION
    5. INPUT WIDTH 79
    6. UNIT METER KN
    7. JOINT COORDINATES
    8. 1 0 0 0; 2 0 4.52601 0; 3 5.86001 4.62601 0; 4 6.83701 4.62601 0; 5 0 0 1.022
    9. 6 0 4.52601 1.022; 7 5.86001 4.62601 1.022; 8 6.83701 4.62601 1.022
   10. 9 0 0 -1.016; 10 0 4.52601 -1.016; 11 5.86001 4.62601 -1.016
   11. 12 6.83701 4.62601 -1.016; 13 0.976669 4.54268 0; 14 1.95334 4.55934 0
   12. 15 2.93001 4.57601 0; 16 3.90667 4.59268 0; 17 4.88334 4.60934 0
   13. 18 0.976669 4.54268 1.022; 19 1.95334 4.55934 1.022; 20 2.93001 4.57601 1.022
   14. 21 3.90667 4.59268 1.022; 22 4.88334 4.60934 1.022; 23 0.976669 4.54268 -1.016
   15. 24 1.95334 4.55934 -1.016; 25 2.93001 4.57601 -1.016
   16. 26 3.90667 4.59268 -1.016; 27 4.88334 4.60934 -1.016; 28 0 0.905202 0
   17. 29 0 1.8104 0; 30 0 2.71561 0; 31 0 3.62081 0; 32 0 0.905202 1.022
   18. 33 0 1.8104 1.022; 34 0 2.71561 1.022; 35 0 3.62081 1.022
   19. 36 0 0.905202 -1.016; 37 0 1.8104 -1.016; 38 0 2.71561 -1.016
   20. 39 0 3.62081 -1.016
   21. MEMBER INCIDENCES
   22. 1 1 28; 2 2 13; 3 3 4; 4 1 5; 5 2 6; 6 3 7; 7 4 8; 8 5 32; 9 6 18; 10 7 8
   23. 11 1 9; 12 2 10; 13 3 11; 14 4 12; 15 9 36; 16 10 23; 17 11 12; 18 13 14
   24. 19 14 15; 20 15 16; 21 16 17; 22 17 3; 23 18 19; 24 19 20; 25 20 21; 26 21 22
   25. 27 22 7; 28 23 24; 29 24 25; 30 25 26; 31 26 27; 32 27 11; 33 23 13; 34 13 18
   26. 35 24 14; 36 14 19; 37 25 15; 38 15 20; 39 26 16; 40 16 21; 41 27 17; 42 17 22
   27. 43 28 29; 44 29 30; 45 30 31; 46 31 2; 47 32 33; 48 33 34; 49 34 35; 50 35 6
   28. 51 36 37; 52 37 38; 53 38 39; 54 39 10; 55 36 28; 56 28 32; 57 37 29; 58 29 33
   29. 59 38 30; 60 30 34; 61 39 31; 62 31 35
   30. DEFINE MATERIAL START
```

```
  31. ISOTROPIC STEEL
  32. E 1.99947E+08
  33. POISSON 0.3
  34. DENSITY 76.8191
  35. ALPHA 6.5E-06
  36. DAMP 0.03
  37. G 7.7221E+07
  38. TYPE STEEL
_   STAAD SPACE                              -- PAGE NO.    2

  39. STRENGTH RY 1.5 RT 1.2
  40. END DEFINE MATERIAL
  41. MEMBER PROPERTY TATASTRUCTURA
  42. 1 TO 3 8 TO 10 15 TO 32 43 TO 54 TABLE ST 80X40X2.6RHS
  43. 4 TO 7 11 TO 14 33 TO 42 55 TO 62 TABLE ST 50X25X2.0RHS
  44. CONSTANTS
  45. MATERIAL STEEL ALL
  46. SUPPORTS
  47. 1 4 5 8 9 12 PINNED
  48. LOAD 1 LOADTYPE DEAD  TITLE DEAD LOAD
  49. SELFWEIGHT Y -1
  50. MEMBER LOAD
  51. 1 TO 3 8 TO 10 15 TO 32 43 TO 54 UNI GY -0.05
  52. PERFORM ANALYSIS
_

        P R O B L E M   S T A T I S T I C S
        -----------------------------------

    NUMBER OF JOINTS        39  NUMBER OF MEMBERS      62
    NUMBER OF PLATES         0  NUMBER OF SOLIDS        0
    NUMBER OF SURFACES       0  NUMBER OF SUPPORTS      6

        Using 64-bit analysis engine.

        SOLVER USED IS THE IN-CORE ADVANCED MATH SOLVER

  TOTAL     PRIMARY LOAD CASES =     1, TOTAL DEGREES OF FREEDOM =     216
  TOTAL LOAD COMBINATION  CASES =     0  SO FAR.
_

  53. PARAMETER 1
  54. CODE IS800 LSD
  55. FYLD 310000 ALL
  56. CHECK CODE ALL
_STEEL DESIGN   _

|-------------------------------------------------------------------------------|
| _Member Number:      1 _                                                      |
| Member Section:  ST   80X40X2.6RHS         (TATA STRUCTURA SECTIONS)          |
| Status: PASS  Ratio:   0.305  Critical Load Case:     1  Location:       0.00  |
| Critical Condition: Slenderness (Compression)                                 |
|-------------------------------------------------------------------------------|

_   STAAD SPACE                              -- PAGE NO.    3

_
                STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
              ***************************************************
_
|-------------------------------------------------------------------------------|
| _Member Number:      2 _                                                      |
| Member Section:  ST   80X40X2.6RHS         (TATA STRUCTURA SECTIONS)          |
| Status: PASS  Ratio:   0.329  Critical Load Case:     1  Location:       0.00  |
| Critical Condition: Slenderness (Compression)                                 |
|-------------------------------------------------------------------------------|

|-------------------------------------------------------------------------------|
```

| _Member Number: 3 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 4 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.252 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 5 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 6 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 7 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.252 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 8 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 9 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 10 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 11 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.251 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 12 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 13 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 14 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.251 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 15 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 16 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 17 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 18 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 19 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 20 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 21 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 8

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 22 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 23 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 24 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 25 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 9

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 26 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 27 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|---|
| _Member Number: 28 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 29 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 10

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 30 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 31 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 32 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 33 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 11

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 34 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 35 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.251 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 36 _ |

| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.252 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 37 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 12

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 38 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 39 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 40 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 41 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.251 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 13

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 42 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.252 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 43 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 44 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |

| Critical Condition: Slenderness (Compression) |
|---|

| _Member Number: 45 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 14

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 46 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 47 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 48 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 49 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 15

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 50 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 51 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 52 _ |
|---|
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 53 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 16

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 54 _ |
| Member Section: ST 80X40X2.6RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.305 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 55 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 56 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 57 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.251 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 17

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 58 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.252 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 59 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.557 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 60 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.561 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|

| _Member Number: 61 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.251 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 18

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 62 _ |
| Member Section: ST 50X25X2.0RHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.252 Critical Load Case: 1 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

57. FINISH

********** END OF THE STAAD.Pro RUN **********

**** DATE= JAN 6,2025 TIME= 12: 5:12 ****

_ STAAD SPACE -- PAGE NO. 19

**********
* For technical assistance on STAAD.Pro, please visit *
* http://www.bentley.com/en/support/ *
* *
* Details about additional assistance from *
* Bentley and Partners can be found at program menu *
* Help->Technical Support *
* *
* Copyright (c) Bentley Systems, Inc. *
* http://www.bentley.com *
**********

# Annexure B

# Staad output for Bottom structure



```
 **************************************************
 *                                                *
 *        STAAD.Pro 2023                          *
 *        Version  23.00.03.25                    *
 *        Proprietary Program of                  *
 *        Bentley Systems, Inc.                   *
 *        Date=    JAN  8, 2025                   *
 *        Time=    11:51:18                       *
 *                                                *
 *  Licensed to: only @::LAVteam::®               *
 **************************************************

    1. STAAD SPACE
INPUT FILE: D:\SALT\1873_TRANSFORMERS & RECTIFIERS LTD\STAAD\ASSEMBLY LINE\ASSEMBLY LINE - Copy.STD
    2. START JOB INFORMATION
    3. ENGINEER DATE 03-MAY-24
    4. END JOB INFORMATION
    5. INPUT WIDTH 79
    6. UNIT METER KN
    7. JOINT COORDINATES
    8. 1 0 0 0; 3 0 2.70001 0; 5 0 0 -3.00001; 7 0 2.70001 -3.00001; 9 0 0 -6.00001
    9. 11 0 2.70001 -6.00001; 13 0 0 -9.00002; 15 0 2.70001 -9.00002; 17 0 0 -12
   10. 19 0 2.70001 -12; 20 5.75001 0 0; 21 5.75001 2.70001 0; 22 5.75001 0 -3.00001
   11. 23 5.75001 2.70001 -3.00001; 24 5.75001 0 -6.00001
   12. 25 5.75001 2.70001 -6.00001; 26 5.75001 0 -9.00002
   13. 27 5.75001 2.70001 -9.00002; 28 5.75001 0 -12; 29 5.75001 2.70001 -12
   14. 30 -0.250001 0 0; 31 -0.250001 2.70001 0; 32 -0.250001 0 -3.00001
   15. 33 -0.250001 2.70001 -3.00001; 34 -0.250001 0 -6.00001
   16. 35 -0.250001 2.70001 -6.00001; 36 -0.250001 0 -9.00002
   17. 37 -0.250001 2.70001 -9.00002; 38 -0.250001 0 -12; 39 -0.250001 2.70001 -12
   18. 40 6.00001 0 0; 41 6.00001 2.70001 0; 42 6.00001 0 -3.00001
   19. 43 6.00001 2.70001 -3.00001; 44 6.00001 0 -6.00001
   20. 45 6.00001 2.70001 -6.00001; 46 6.00001 0 -9.00002
   21. 47 6.00001 2.70001 -9.00002; 48 6.00001 0 -12; 49 6.00001 2.70001 -12
   22. 50 -0.250001 1.9 0; 51 0 1.9 0; 52 -0.250001 1.1 0; 53 0 1.1 0
   23. 54 -0.250001 0.300001 0; 55 0 0.300001 0; 56 5.75001 1.9 0; 57 6.00001 1.9 0
   24. 58 5.75001 1.1 0; 59 6.00001 1.1 0; 60 5.75001 0.300001 0
   25. 61 6.00001 0.300001 0; 62 -0.250001 1.9 -3.00001; 63 0 1.9 -3.00001
   26. 64 -0.250001 1.1 -3.00001; 65 0 1.1 -3.00001; 66 -0.250001 0.300001 -3.00001
   27. 67 0 0.300001 -3.00001; 68 5.75001 1.9 -3.00001; 69 6.00001 1.9 -3.00001
   28. 70 5.75001 1.1 -3.00001; 71 6.00001 1.1 -3.00001; 72 5.75001 0.300001 -3.00001
   29. 73 6.00001 0.300001 -3.00001; 74 -0.250001 1.9 -6.00001; 75 0 1.9 -6.00001
   30. 76 -0.250001 1.1 -6.00001; 77 0 1.1 -6.00001; 78 -0.250001 0.300001 -6.00001
   31. 79 0 0.300001 -6.00001; 80 5.75001 1.9 -6.00001; 81 6.00001 1.9 -6.00001
   32. 82 5.75001 1.1 -6.00001; 83 6.00001 1.1 -6.00001; 84 5.75001 0.300001 -6.00001
```

33. 85 6.00001 0.300001 -6.00001; 86 -0.250001 1.9 -9.00002; 87 0 1.9 -9.00002
34. 88 -0.250001 1.1 -9.00002; 89 0 1.1 -9.00002; 90 -0.250001 0.300001 -9.00002
35. 91 0 0.300001 -9.00002; 92 5.75001 1.9 -9.00002; 93 6.00001 1.9 -9.00002
36. 94 5.75001 1.1 -9.00002; 95 6.00001 1.1 -9.00002; 96 5.75001 0.300001 -9.00002
37. 97 6.00001 0.300001 -9.00002; 98 -0.250001 1.9 -12; 99 0 1.9 -12
38. 100 -0.250001 1.1 -12; 101 0 1.1 -12; 102 -0.250001 0.300001 -12



39. 103 0 0.300001 -12; 104 5.75001 1.9 -12; 105 6.00001 1.9 -12
40. 106 5.75001 1.1 -12; 107 6.00001 1.1 -12; 108 5.75001 0.300001 -12
41. 109 6.00001 0.300001 -12; 110 -0.250001 2.25 0; 111 -0.250001 2.25 -3.00001
42. 112 -0.250001 2.25 -0.750002; 113 -0.250001 2.70001 -0.750002
43. 114 -0.250001 2.25 -1.5; 115 -0.250001 2.70001 -1.5; 116 -0.250001 2.25 -2.25
44. 117 -0.250001 2.70001 -2.25; 118 5.75001 2.70001 -0.750002; 119 5.75001 2.25 0
45. 120 5.75001 2.25 -0.750002; 121 5.75001 2.25 -1.5; 122 5.75001 2.70001 -1.5
46. 123 5.75001 2.25 -2.25; 124 5.75001 2.70001 -2.25; 125 5.75001 2.25 -3.00001
47. 126 -0.250001 2.70001 -3.75001; 127 -0.250001 2.25 -3.75001
48. 128 -0.250001 2.25 -4.50001; 129 -0.250001 2.70001 -4.50001
49. 130 -0.250001 2.25 -5.25001; 131 -0.250001 2.70001 -5.25001
50. 132 -0.250001 2.25 -6.00001; 133 5.75001 2.70001 -3.75001
51. 134 5.75001 2.25 -3.75001; 135 5.75001 2.25 -4.50001
52. 136 5.75001 2.70001 -4.50001; 137 5.75001 2.25 -5.25001
53. 138 5.75001 2.70001 -5.25001; 139 5.75001 2.25 -6.00001
54. 140 -0.250001 2.70001 -6.75001; 141 -0.250001 2.25 -6.75001
55. 142 -0.250001 2.25 -7.50002; 143 -0.250001 2.70001 -7.50002
56. 144 -0.250001 2.25 -8.25002; 145 -0.250001 2.70001 -8.25002
57. 146 -0.250001 2.25 -9.00002; 147 5.75001 2.70001 -6.75001
58. 148 5.75001 2.25 -6.75001; 149 5.75001 2.25 -7.50002
59. 150 5.75001 2.70001 -7.50002; 151 5.75001 2.25 -8.25002
60. 152 5.75001 2.70001 -8.25002; 153 5.75001 2.25 -9.00002
61. 154 -0.250001 2.70001 -9.75002; 155 -0.250001 2.25 -9.75002
62. 156 -0.250001 2.25 -10.5; 157 -0.250001 2.70001 -10.5
63. 158 -0.250001 2.25 -11.25; 159 -0.250001 2.70001 -11.25
64. 160 -0.250001 2.25 -12; 161 5.75001 2.70001 -9.75002
65. 162 5.75001 2.25 -9.75002; 163 5.75001 2.25 -10.5; 164 5.75001 2.70001 -10.5
66. 165 5.75001 2.25 -11.25; 166 5.75001 2.70001 -11.25; 167 5.75001 2.25 -12
67. 170 6.75001 2.70001 0; 171 6.75001 2.70001 -3.00001
68. 173 6.75001 2.70001 -6.00001; 175 6.75001 2.70001 -9.00002
69. 177 6.75001 2.70001 -12; 178 -0.550001 0 0; 179 -0.550001 0.300001 0
70. 180 -0.550001 0 -3.00001; 181 -0.550001 0.300001 -3.00001
71. 182 -0.550001 0 -6.00001; 183 -0.550001 0.300001 -6.00001
72. 184 -0.550001 0 -9.00002; 185 -0.550001 0.300001 -9.00002; 186 -0.550001 0 -12
73. 187 -0.550001 0.300001 -12; 188 -0.800002 0 0; 189 -0.800002 0.300001 0
74. 190 -0.800002 0 -3.00001; 191 -0.800002 0.300001 -3.00001
75. 192 -0.800002 0 -6.00001; 193 -0.800002 0.300001 -6.00001
76. 194 -0.800002 0 -9.00002; 195 -0.800002 0.300001 -9.00002; 196 -0.800002 0 -12
77. 197 -0.800002 0.300001 -12; 198 -0.800002 2.70001 0; 199 -0.550001 2.70001 0
78. 200 -0.800002 1.9 0; 201 -0.800002 2.25 0; 202 -0.550001 1.9 0
79. 203 -0.800002 1.1 0; 204 -0.550001 1.1 0; 205 -0.800002 2.70001 -3.00001
80. 206 -0.550001 2.70001 -3.00001; 207 -0.800002 1.9 -3.00001
81. 208 -0.800002 2.25 -3.00001; 209 -0.550001 1.9 -3.00001
82. 210 -0.800002 1.1 -3.00001; 211 -0.550001 1.1 -3.00001
83. 212 -0.800002 2.70001 -6.00001; 213 -0.550001 2.70001 -6.00001
84. 214 -0.800002 1.9 -6.00001; 215 -0.800002 2.25 -6.00001
85. 216 -0.550001 1.9 -6.00001; 217 -0.800002 1.1 -6.00001
86. 218 -0.550001 1.1 -6.00001; 219 -0.800002 2.70001 -9.00002
87. 220 -0.550001 2.70001 -9.00002; 221 -0.800002 1.9 -9.00002
88. 222 -0.800002 2.25 -9.00002; 223 -0.550001 1.9 -9.00002
89. 224 -0.800002 1.1 -9.00002; 225 -0.550001 1.1 -9.00002
90. 226 -0.800002 2.70001 -12; 227 -0.550001 2.70001 -12; 228 -0.800002 1.9 -12
91. 229 -0.800002 2.25 -12; 230 -0.550001 1.9 -12; 231 -0.800002 1.1 -12
92. 232 -0.550001 1.1 -12; 233 -0.800002 2.70001 -0.750002
93. 234 -0.800002 2.25 -0.750002; 235 -0.800002 2.25 -1.5
94. 236 -0.800002 2.70001 -1.5; 237 -0.800002 2.25 -2.25



95. 238 -0.800002 2.70001 -2.25; 239 -0.800002 2.70001 -3.75001
96. 240 -0.800002 2.25 -3.75001; 241 -0.800002 2.25 -4.50001
97. 242 -0.800002 2.70001 -4.50001; 243 -0.800002 2.25 -5.25001
98. 244 -0.800002 2.70001 -5.25001; 245 -0.800002 2.70001 -6.75001

99. 246 -0.800002 2.25 -6.75001; 247 -0.800002 2.25 -7.50002
100. 248 -0.800002 2.70001 -7.50002; 249 -0.800002 2.25 -8.25002
101. 250 -0.800002 2.70001 -8.25002; 251 -0.800002 2.70001 -9.75002
102. 252 -0.800002 2.25 -9.75002; 253 -0.800002 2.25 -10.5
103. 254 -0.800002 2.70001 -10.5; 255 -0.800002 2.25 -11.25
104. 256 -0.800002 2.70001 -11.25; 257 -7.80002 0 0; 258 -7.80002 0.300001 0
105. 259 -7.80002 0 -3.00001; 260 -7.80002 0.300001 -3.00001
106. 261 -7.80002 0 -6.00001; 262 -7.80002 0.300001 -6.00001
107. 263 -7.80002 0 -9.00002; 264 -7.80002 0.300001 -9.00002; 265 -7.80002 0 -12
108. 266 -7.80002 0.300001 -12; 267 -8.05002 0 0; 268 -8.05002 0.300001 0
109. 269 -8.05002 0 -3.00001; 270 -8.05002 0.300001 -3.00001
110. 271 -8.05002 0 -6.00001; 272 -8.05002 0.300001 -6.00001
111. 273 -8.05002 0 -9.00002; 274 -8.05002 0.300001 -9.00002; 275 -8.05002 0 -12
112. 276 -8.05002 0.300001 -12; 277 -8.05002 2.70001 0; 278 -7.80002 2.70001 0
113. 279 -8.05002 1.9 0; 280 -8.05002 2.25 0; 281 -7.80002 1.9 0
114. 282 -8.05002 1.1 0; 283 -7.80002 1.1 0; 284 -8.05002 2.70001 -3.00001
115. 285 -7.80002 2.70001 -3.00001; 286 -8.05002 1.9 -3.00001
116. 287 -8.05002 2.25 -3.00001; 288 -7.80002 1.9 -3.00001
117. 289 -8.05002 1.1 -3.00001; 290 -7.80002 1.1 -3.00001
118. 291 -8.05002 2.70001 -6.00001; 292 -7.80002 2.70001 -6.00001
119. 293 -8.05002 1.9 -6.00001; 294 -8.05002 2.25 -6.00001
120. 295 -7.80002 1.9 -6.00001; 296 -8.05002 1.1 -6.00001
121. 297 -7.80002 1.1 -6.00001; 298 -8.05002 2.70001 -9.00002
122. 299 -7.80002 2.70001 -9.00002; 300 -8.05002 1.9 -9.00002
123. 301 -8.05002 2.25 -9.00002; 302 -7.80002 1.9 -9.00002
124. 303 -8.05002 1.1 -9.00002; 304 -7.80002 1.1 -9.00002; 305 -8.05002 2.70001 -12
125. 306 -7.80002 2.70001 -12; 307 -8.05002 1.9 -12; 308 -8.05002 2.25 -12
126. 309 -7.80002 1.9 -12; 310 -8.05002 1.1 -12; 311 -7.80002 1.1 -12
127. 312 -8.05002 2.70001 -0.750002; 313 -8.05002 2.25 -0.750002
128. 314 -8.05002 2.25 -1.5; 315 -8.05002 2.70001 -1.5; 316 -8.05002 2.25 -2.25
129. 317 -8.05002 2.70001 -2.25; 318 -8.05002 2.70001 -3.75001
130. 319 -8.05002 2.25 -3.75001; 320 -8.05002 2.25 -4.50001
131. 321 -8.05002 2.70001 -4.50001; 322 -8.05002 2.25 -5.25001
132. 323 -8.05002 2.70001 -5.25001; 324 -8.05002 2.70001 -6.75001
133. 325 -8.05002 2.25 -6.75001; 326 -8.05002 2.25 -7.50002
134. 327 -8.05002 2.70001 -7.50002; 328 -8.05002 2.25 -8.25002
135. 329 -8.05002 2.70001 -8.25002; 330 -8.05002 2.70001 -9.75002
136. 331 -8.05002 2.25 -9.75002; 332 -8.05002 2.25 -10.5
137. 333 -8.05002 2.70001 -10.5; 334 -8.05002 2.25 -11.25
138. 335 -8.05002 2.70001 -11.25; 341 -8.80002 2.70001 0
139. 342 -8.80002 2.70001 -3.00001; 343 -8.80002 2.70001 -6.00001
140. 344 -8.80002 2.70001 -9.00002; 345 -8.80002 2.70001 -12
141. 350 -0.250001 2.70001 -11.4; 351 -0.250001 2.70001 -10.8
142. 352 -0.250001 2.70001 -10.2; 353 -0.250001 2.70001 -9.60002
143. 354 -7.80002 2.25 0; 355 -7.21669 2.70001 0; 356 -6.63335 2.70001 0
144. 357 -6.05002 2.70001 0; 358 -5.46668 2.70001 0; 359 -4.88335 2.70001 0
145. 360 -4.30001 2.70001 0; 361 -3.71668 2.70001 0; 362 -3.13334 2.70001 0
146. 363 -2.55001 2.70001 0; 364 -1.96667 2.70001 0; 365 -1.38334 2.70001 0
147. 366 -7.21669 2.25 0; 367 -6.63335 2.25 0; 368 -6.05002 2.25 0
148. 369 -5.46668 2.25 0; 370 -4.88335 2.25 0; 371 -4.30001 2.25 0
149. 372 -3.71668 2.25 0; 373 -3.13334 2.25 0; 374 -2.55001 2.25 0
150. 375 -1.96667 2.25 0; 376 -1.38334 2.25 0; 377 0 2.25 0; 378 5.17501 2.70001 0



151. 379 4.60001 2.70001 0; 380 4.02501 2.70001 0; 381 3.45001 2.70001 0
152. 382 2.87501 2.70001 0; 383 2.3 2.70001 0; 384 1.725 2.70001 0
153. 385 1.15 2.70001 0; 386 0.575001 2.70001 0; 387 5.17501 2.25 0
154. 388 4.60001 2.25 0; 389 4.02501 2.25 0; 390 3.45001 2.25 0; 391 2.87501 2.25 0
155. 392 2.3 2.25 0; 393 1.725 2.25 0; 394 1.15 2.25 0; 395 0.575001 2.25 0
156. 396 -7.21669 2.70001 -12; 397 -7.80002 2.25 -12; 398 -7.21669 2.25 -12
157. 399 -6.63335 2.70001 -12; 400 -6.05002 2.70001 -12; 401 -5.46668 2.70001 -12
158. 402 -4.88335 2.70001 -12; 403 -4.30001 2.70001 -12; 404 -3.71668 2.70001 -12
159. 405 -3.13334 2.70001 -12; 406 -2.55001 2.70001 -12; 407 -1.96667 2.70001 -12
160. 408 -1.38334 2.70001 -12; 409 -6.63335 2.25 -12; 410 -6.05002 2.25 -12
161. 411 -5.46668 2.25 -12; 412 -4.88335 2.25 -12; 413 -4.30001 2.25 -12
162. 414 -3.71668 2.25 -12; 415 -3.13334 2.25 -12; 416 -2.55001 2.25 -12
163. 417 -1.96667 2.25 -12; 418 -1.38334 2.25 -12; 419 5.17501 2.70001 -12
164. 420 5.17501 2.25 -12; 421 4.60001 2.70001 -12; 422 4.02501 2.70001 -12
165. 423 3.45001 2.70001 -12; 424 2.87501 2.70001 -12; 425 2.3 2.70001 -12
166. 426 1.725 2.70001 -12; 427 1.15 2.70001 -12; 428 0.575001 2.70001 -12

167. 429 4.60001 2.25 -12; 430 4.02501 2.25 -12; 431 3.45001 2.25 -12
168. 432 2.87501 2.25 -12; 433 2.3 2.25 -12; 434 1.725 2.25 -12; 435 1.15 2.25 -12
169. 436 0.575001 2.25 -12; 437 0 2.25 -12
170. MEMBER INCIDENCES
171. 1 1 55; 3 5 67; 5 9 79; 7 13 91; 9 17 103; 10 20 60; 11 22 72; 12 24 84
172. 13 26 96; 14 28 108; 15 30 54; 16 32 66; 17 34 78; 18 36 90; 19 38 102
173. 20 40 61; 21 42 73; 22 44 85; 23 46 97; 24 48 109; 26 31 3; 27 50 110
174. 28 51 377; 29 50 51; 30 52 50; 31 53 51; 32 52 53; 33 54 52; 34 55 53
175. 35 54 55; 37 21 41; 38 56 119; 39 57 41; 40 56 57; 41 58 56; 42 59 57
176. 43 58 59; 44 60 58; 45 61 59; 46 60 61; 47 33 7; 48 62 111; 49 63 7; 50 62 63
177. 51 64 62; 52 65 63; 53 64 65; 54 66 64; 55 67 65; 56 66 67; 57 23 43
178. 58 68 125; 59 69 43; 60 68 69; 61 70 68; 62 71 69; 63 70 71; 64 72 70
179. 65 73 71; 66 72 73; 67 35 11; 68 74 132; 69 75 11; 70 74 75; 71 76 74
180. 72 77 75; 73 76 77; 74 78 76; 75 79 77; 76 78 79; 77 25 45; 78 80 139
181. 79 81 45; 80 80 81; 81 82 80; 82 83 81; 83 82 83; 84 84 82; 85 85 83; 86 84 85
182. 87 37 15; 88 86 146; 89 87 15; 90 86 87; 91 88 86; 92 89 87; 93 88 89
183. 94 90 88; 95 91 89; 96 90 91; 97 27 47; 98 92 153; 99 93 47; 100 92 93
184. 101 94 92; 102 95 93; 103 94 95; 104 96 94; 105 97 95; 106 96 97; 107 39 19
185. 108 98 160; 109 99 437; 110 98 99; 111 100 98; 112 101 99; 113 100 101
186. 114 102 100; 115 103 101; 116 102 103; 117 29 49; 118 104 167; 119 105 49
187. 120 104 105; 121 106 104; 122 107 105; 123 106 107; 124 108 106; 125 109 107
188. 126 108 109; 128 31 113; 129 110 31; 130 111 33; 131 110 112; 132 112 114
189. 133 113 115; 134 112 113; 135 114 116; 136 115 117; 137 114 115; 138 116 111
190. 139 117 33; 140 116 117; 141 111 117; 142 116 115; 143 114 113; 144 112 31
191. 145 21 118; 146 119 21; 147 119 120; 148 120 121; 149 118 122; 150 120 118
192. 151 121 123; 152 122 124; 153 121 122; 154 125 23; 155 123 125; 156 124 23
193. 157 123 124; 158 125 124; 159 123 122; 160 121 118; 161 120 21; 162 33 126
194. 163 111 127; 164 127 128; 165 126 129; 166 127 126; 167 128 130; 168 129 131
195. 169 128 129; 170 132 35; 171 130 132; 172 131 35; 173 130 131; 174 132 131
196. 175 130 129; 176 128 126; 177 127 33; 178 23 133; 179 125 134; 180 134 135
197. 181 133 136; 182 134 133; 183 135 137; 184 136 138; 185 135 136; 186 139 25
198. 187 137 139; 188 138 25; 189 137 138; 190 139 138; 191 137 136; 192 135 133
199. 193 134 23; 194 35 140; 195 132 141; 196 141 142; 197 140 143; 198 141 140
200. 199 142 144; 200 143 145; 201 142 143; 202 146 37; 203 144 146; 204 145 37
201. 205 144 145; 206 146 145; 207 144 143; 208 142 140; 209 141 35; 210 25 147
202. 211 139 148; 212 148 149; 213 147 150; 214 148 147; 215 149 151; 216 150 152
203. 217 149 150; 218 153 27; 219 151 153; 220 152 27; 221 151 152; 222 153 152
204. 223 151 150; 224 149 147; 225 148 25; 226 37 353; 227 146 155; 228 155 156
205. 229 154 352; 230 155 154; 231 156 158; 232 157 351; 233 156 157; 234 160 39
206. 235 158 160; 236 159 350; 237 158 159; 238 160 159; 239 158 157; 240 156 154



207. 241 155 37; 242 27 161; 243 153 162; 244 162 163; 245 161 164; 246 162 161
208. 247 163 165; 248 164 166; 249 163 164; 250 167 29; 251 165 167; 252 166 29
209. 253 165 166; 254 167 166; 255 165 164; 256 163 161; 257 162 27; 260 41 170
210. 261 43 171; 263 45 173; 265 47 175; 267 49 177; 268 178 179; 269 180 181
211. 270 182 183; 271 184 185; 272 186 187; 273 188 189; 274 190 191; 275 192 193
212. 276 194 195; 277 196 197; 278 198 199; 279 200 201; 280 202 199; 281 200 202
213. 282 203 200; 283 204 202; 284 203 204; 285 189 203; 286 179 204; 287 189 179
214. 288 205 206; 289 207 208; 290 209 206; 291 207 209; 292 210 207; 293 211 209
215. 294 210 211; 295 191 210; 296 181 211; 297 191 181; 298 212 213; 299 214 215
216. 300 216 213; 301 214 216; 302 217 214; 303 218 216; 304 217 218; 305 193 217
217. 306 183 218; 307 193 183; 308 219 220; 309 221 222; 310 223 220; 311 221 223
218. 312 224 221; 313 225 223; 314 224 225; 315 195 224; 316 185 225; 317 195 185
219. 318 226 227; 319 228 229; 320 230 227; 321 228 230; 322 231 228; 323 232 230
220. 324 231 232; 325 197 231; 326 187 232; 327 197 187; 328 198 233; 329 201 198
221. 330 208 205; 331 201 234; 332 234 235; 333 233 236; 334 234 233; 335 235 237
222. 336 236 238; 337 235 236; 338 237 208; 339 238 205; 340 237 238; 341 208 238
223. 342 237 236; 343 235 233; 344 234 198; 345 205 239; 346 208 240; 347 240 241
224. 348 239 242; 349 240 239; 350 241 243; 351 242 244; 352 241 242; 353 215 212
225. 354 243 215; 355 244 212; 356 243 244; 357 215 244; 358 243 242; 359 241 239
226. 360 240 205; 361 212 245; 362 215 246; 363 246 247; 364 245 248; 365 246 245
227. 366 247 249; 367 248 250; 368 247 248; 369 222 219; 370 249 222; 371 250 219
228. 372 249 250; 373 222 250; 374 249 248; 375 247 245; 376 246 212; 377 219 251
229. 378 222 252; 379 252 253; 380 251 254; 381 252 251; 382 253 255; 383 254 256
230. 384 253 254; 385 229 226; 386 255 229; 387 256 226; 388 255 256; 389 229 256
231. 390 255 254; 391 253 251; 392 252 219; 393 257 258; 394 259 260; 395 261 262
232. 396 263 264; 397 265 266; 398 267 268; 399 269 270; 400 271 272; 401 273 274
233. 402 275 276; 403 277 278; 404 279 280; 405 281 354; 406 279 281; 407 282 279
234. 408 283 281; 409 282 283; 410 268 282; 411 258 283; 412 268 258; 413 284 285

235. 414 286 287; 415 288 285; 416 286 288; 417 289 286; 418 290 288; 419 289 290
236. 420 270 289; 421 260 290; 422 270 260; 423 291 292; 424 293 294; 425 295 292
237. 426 293 295; 427 296 293; 428 297 295; 429 296 297; 430 272 296; 431 262 297
238. 432 272 262; 433 298 299; 434 300 301; 435 302 299; 436 300 302; 437 303 300
239. 438 304 302; 439 303 304; 440 274 303; 441 264 304; 442 274 264; 443 305 306
240. 444 307 308; 445 309 397; 446 307 309; 447 310 307; 448 311 309; 449 310 311
241. 450 276 310; 451 266 311; 452 276 266; 453 277 312; 454 280 277; 455 287 284
242. 456 280 313; 457 313 314; 458 312 315; 459 313 312; 460 314 316; 461 315 317
243. 462 314 315; 463 316 287; 464 317 284; 465 316 317; 466 287 317; 467 316 315
244. 468 314 312; 469 313 277; 470 284 318; 471 287 319; 472 319 320; 473 318 321
245. 474 319 318; 475 320 322; 476 321 323; 477 320 321; 478 294 291; 479 322 294
246. 480 323 291; 481 322 323; 482 294 323; 483 322 321; 484 320 318; 485 319 284
247. 486 291 324; 487 294 325; 488 325 326; 489 324 327; 490 325 324; 491 326 328
248. 492 327 329; 493 326 327; 494 301 298; 495 328 301; 496 329 298; 497 328 329
249. 498 301 329; 499 328 327; 500 326 324; 501 325 291; 502 298 330; 503 301 331
250. 504 331 332; 505 330 333; 506 331 330; 507 332 334; 508 333 335; 509 332 333
251. 510 308 305; 511 334 308; 512 335 305; 513 334 335; 514 308 335; 515 334 333
252. 516 332 330; 517 331 298; 523 341 277; 524 342 284; 525 343 291; 526 344 298
253. 527 345 305; 533 350 39; 535 351 159; 537 352 157; 539 353 154; 541 278 355
254. 542 354 278; 543 354 366; 544 355 356; 545 356 357; 546 357 358; 547 358 359
255. 548 359 360; 549 360 361; 550 361 362; 551 362 363; 552 363 364; 553 364 365
256. 554 365 198; 555 366 367; 556 367 368; 557 368 369; 558 369 370; 559 370 371
257. 560 371 372; 561 372 373; 562 373 374; 563 374 375; 564 375 376; 565 376 201
258. 566 366 355; 567 367 356; 568 368 357; 569 369 358; 570 370 359; 571 371 360
259. 572 372 361; 573 373 362; 574 374 363; 575 375 364; 576 376 365; 577 354 355
260. 578 366 356; 579 367 357; 580 368 358; 581 369 359; 582 370 360; 583 371 361
261. 584 372 362; 585 373 363; 586 374 364; 587 375 365; 588 376 198; 589 21 378
262. 590 377 3; 591 119 387; 592 378 379; 593 379 380; 594 380 381; 595 381 382



263. 596 382 383; 597 383 384; 598 384 385; 599 385 386; 600 386 3; 601 387 388
264. 602 388 389; 603 389 390; 604 390 391; 605 391 392; 606 392 393; 607 393 394
265. 608 394 395; 609 395 377; 610 387 378; 611 388 379; 612 389 380; 613 390 381
266. 614 391 382; 615 392 383; 616 393 384; 617 394 385; 618 395 386; 619 377 386
267. 620 395 385; 621 394 384; 622 393 383; 623 392 382; 624 391 381; 625 390 380
268. 626 389 379; 627 388 378; 628 387 21; 629 306 396; 630 397 306; 631 397 398
269. 632 396 399; 633 399 400; 634 400 401; 635 401 402; 636 402 403; 637 403 404
270. 638 404 405; 639 405 406; 640 406 407; 641 407 408; 642 408 226; 643 398 409
271. 644 409 410; 645 410 411; 646 411 412; 647 412 413; 648 413 414; 649 414 415
272. 650 415 416; 651 416 417; 652 417 418; 653 418 229; 654 398 396; 655 409 399
273. 656 410 400; 657 411 401; 658 412 402; 659 413 403; 660 414 404; 661 415 405
274. 662 416 406; 663 417 407; 664 418 408; 665 397 396; 666 398 399; 667 409 400
275. 668 410 401; 669 411 402; 670 412 403; 671 413 404; 672 414 405; 673 415 406
276. 674 416 407; 675 417 408; 676 418 226; 677 29 419; 678 167 420; 679 419 421
277. 680 421 422; 681 422 423; 682 423 424; 683 424 425; 684 425 426; 685 426 427
278. 686 427 428; 687 428 19; 688 420 429; 689 429 430; 690 430 431; 691 431 432
279. 692 432 433; 693 433 434; 694 434 435; 695 435 436; 696 437 19; 697 436 437
280. 698 420 419; 699 429 421; 700 430 422; 701 431 423; 702 432 424; 703 433 425
281. 704 434 426; 705 435 427; 706 436 428; 707 437 428; 708 436 427; 709 435 426
282. 710 434 425; 711 433 424; 712 432 423; 713 431 422; 714 430 421; 715 429 419
283. 716 420 29
284. DEFINE MATERIAL START
285. ISOTROPIC STEEL
286. E 1.99947E+08
287. POISSON 0.3
288. DENSITY 76.8191
289. ALPHA 6.5E-06
290. DAMP 0.03
291. TYPE STEEL
292. STRENGTH RY 1.5 RT 1.2
293. END DEFINE MATERIAL
294. MEMBER PROPERTY TATASTRUCTURA
295. 128 131 TO 145 147 TO 153 155 TO 169 171 TO 185 187 TO 201 203 TO 217 219 -
296. 220 TO 233 235 TO 249 251 TO 257 328 331 TO 352 354 TO 368 370 TO 384 386 -
297. 387 TO 392 453 456 TO 477 479 TO 493 495 TO 509 511 TO 517 533 535 537 539 -
298. 541 543 TO 589 591 TO 629 631 TO 695 697 TO 716 TABLE ST 40X40X3.2SHS
299. 1 3 5 7 9 TO 24 26 TO 28 30 31 33 34 37 TO 39 41 42 44 45 47 TO 49 51 52 54 -
300. 55 57 TO 59 61 62 64 65 67 TO 69 71 72 74 75 77 TO 79 81 82 84 85 87 TO 89 -
301. 91 92 94 95 97 TO 99 101 102 104 105 107 TO 109 111 112 114 115 117 TO 119 -
302. 121 122 124 125 129 130 146 154 170 186 202 218 234 250 260 261 263 265 267 -

303. 268 TO 280 282 283 285 286 288 TO 290 292 293 295 296 298 TO 300 302 303 305 -
304. 306 308 TO 310 312 313 315 316 318 TO 320 322 323 325 326 329 330 353 369 -
305. 385 393 TO 405 407 408 410 411 413 TO 415 417 418 420 421 423 TO 425 427 -
306. 428 430 431 433 TO 435 437 438 440 441 443 TO 445 447 448 450 451 454 455 -
307. 478 494 510 523 TO 527 542 590 630 696 TABLE ST 100X100X4.0SHS
308. 29 32 35 40 43 46 50 53 56 60 63 66 70 73 76 80 83 86 90 93 96 100 103 106 -
309. 110 113 116 120 123 126 281 284 287 291 294 297 301 304 307 311 314 317 321 -
310. 324 327 406 409 412 416 419 422 426 429 432 436 439 442 446 449 -
311. 452 TABLE ST 50X50X3.6SHS
312. CONSTANTS
313. MATERIAL STEEL ALL
314. SUPPORTS
315. 1 5 9 13 17 20 22 24 26 28 30 32 34 36 38 40 42 44 46 48 178 180 182 184 186 -
316. 188 190 192 194 196 257 259 261 263 265 267 269 271 273 275 FIXED
317. LOAD 1 LOADTYPE DEAD TITLE DL
_ STAAD SPACE -- PAGE NO. 7

**WARNING- THIS STRUCTURE IS DISJOINTED. IGNORE IF
CONTROL/DEPENDENT OR IF UNCONNECTED JOINTS.
318. SELFWEIGHT Y -1 LIST ALL
319. LOAD 2 LOADTYPE LIVE TITLE LL
320. MEMBER LOAD
321. 26 37 47 57 67 77 87 97 107 117 260 261 263 265 267 278 288 298 308 318 403 -
322. 413 423 433 443 523 TO 527 UNI GY -2
323. LOAD 3 LOADTYPE NONE TITLE EQP
324. MEMBER LOAD
325. 107 117 128 133 136 139 162 165 168 172 194 197 200 204 226 229 232 236 267 -
326. 318 328 333 336 339 345 348 351 355 361 364 367 371 377 380 383 387 443 527 -
327. 533 535 537 539 UNI GY -3
328. 87 97 265 308 433 526 UNI GY -2.5
329. 67 77 263 298 423 525 UNI GY -2
330. 26 37 47 57 260 261 278 288 403 413 523 524 UNI GY -1.
331. LOAD COMB 101 ULC, 1.5 DEAD + 1.5 LIVE
332. 1 1.5 2 1.5
333. LOAD COMB 102 ULC, 1.2 DEAD + 1.2 LIVE
334. 1 1.2 2 1.2
335. LOAD COMB 103 ULC, 1.5 DEAD
336. 1 1.5
337. LOAD COMB 104 ULC, 0.9 DEAD
338. 1 0.9
339. LOAD COMB 105 ULC, 1 DEAD + 0.35 LIVE
340. 1 1.0 2 0.35
341. LOAD COMB 106 ULC, 1 DEAD + 1 LIVE
342. 1 1.0 2 1.0
343. LOAD COMB 107 ULC, 1 DEAD + 0.8 LIVE
344. 1 1.0 2 0.8
345. LOAD COMB 108 ULC, 1 DEAD
346. 1 1.0
347. PERFORM ANALYSIS
_

P R O B L E M S T A T I S T I C S
---

NUMBER OF JOINTS 414 NUMBER OF MEMBERS 690
NUMBER OF PLATES 0 NUMBER OF SOLIDS 0
NUMBER OF SURFACES 0 NUMBER OF SUPPORTS 40

Using 64-bit analysis engine.

SOLVER USED IS THE IN-CORE ADVANCED MATH SOLVER

TOTAL PRIMARY LOAD CASES = 3, TOTAL DEGREES OF FREEDOM = 2244
TOTAL LOAD COMBINATION CASES = 8 SO FAR.
_

348. LOAD LIST 101 TO 108
349. PARAMETER 1

_ STAAD SPACE -- PAGE NO. 8

350. CODE IS800 LSD
351. FYLD 210000 ALL
352. CHECK CODE ALL
_STEEL DESIGN _

|---|
| _Member Number: 1 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 3 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 5 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 7 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 9

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 9 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 10 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 11 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 12 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 10

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 13 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 14 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 15 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 16 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 17 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 18 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 19 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 20 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 21 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 22 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 23 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 24 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 13

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 26 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.016 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 27 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 28 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 29 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 14

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 30 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 31 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 32 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 33 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 15

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 34 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 35 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 37 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.049 Critical Load Case: 101 Location: 0.25 |
| Critical Condition: Sec. 8.2.1.2 |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 38 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 16

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|

| _Member Number: 39 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 40 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 41 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 42 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

| _Member Number: 43 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 44 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 45 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 46 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

| _Member Number: 47 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.036 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 48 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 49 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 50 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|





|---|
| _Member Number: 51 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 52 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 53 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 54 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|





|---|
| _Member Number: 55 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|

|---|
| _Member Number: 56 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 57 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.065 Critical Load Case: 101 Location: 0.25 |
| Critical Condition: Sec. 8.2.1.2 |
|---|

|---|
| _Member Number: 58 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 59 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 60 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 61 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 62 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 63 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 64 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 65 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 66 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 23

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 67 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.036 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 68 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 69 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 70 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 24

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 71 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 72 _ |

| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 73 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 74 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 75 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 76 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 77 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.066 Critical Load Case: 101 Location: 0.25 |
| Critical Condition: Sec. 8.2.1.2 |
|---|

|---|
| _Member Number: 78 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 79 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 80 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Compression) |
|---|

| _Member Number: 81 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 82 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 83 _ |
|---|
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 84 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 85 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 86 _ |
|---|
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 87 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.036 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 88 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 89 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 90 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





_

|---|
| _Member Number: 91 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 92 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 93 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 94 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





_

|---|
| _Member Number: 95 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 96 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|

| _Member Number: 97 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.065 Critical Load Case: 101 Location: 0.25 |
| Critical Condition: Sec. 8.2.1.2 |

| _Member Number: 98 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





_
| _Member Number: 99 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 100 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 101 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 102 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





_
| _Member Number: 103 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 104 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 105 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 106 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 107 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.016 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 108 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 109 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 110 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|



_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 111 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 112 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 113 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 114 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 35

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 115 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 116 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 117 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.049 Critical Load Case: 101 Location: 0.25 |
| Critical Condition: Sec. 8.2.1.2 |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 118 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 36

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 119 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 120 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 121 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|---|
| _Member Number: 122 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 37

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 123 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 124 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 125 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 126 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 38

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 128 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 129 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 130 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 131 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

| _Member Number: 132 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 133 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 134 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 135 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

| _Member Number: 136 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 137 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 138 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 139 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 41

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 140 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 141 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 142 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 143 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 42

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 144 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 145 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 146 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 147 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 43

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 148 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 149 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 150 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 151 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 44

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 152 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 153 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 154 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 155 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 45

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 156 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 157 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 158 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 159 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 46

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 160 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 161 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 162 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 163 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 47

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 164 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 165 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 166 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 167 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

_ STAAD SPACE -- PAGE NO. 48

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 168 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 169 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 170 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 171 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

_ STAAD SPACE -- PAGE NO. 49

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 172 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 173 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 174 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 175 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 50

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 176 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 177 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 178 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 179 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 51

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|

| _Member Number: 180 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 181 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 182 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 183 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 184 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 185 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 186 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 187 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 188 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 189 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 190 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 191 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 54

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 192 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 193 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 194 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 195 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 55

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 196 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|----------|

|----------|
| _Member Number: 197 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 198 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 199 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|----------|
| _Member Number: 200 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 201 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 202 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 203 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|----------|
| _Member Number: 204 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|---|
| _Member Number: 205 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 206 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 207 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 58

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 208 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 209 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 210 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 211 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 59

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 212 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 213 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 214 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 215 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 216 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 217 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 218 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 219 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 220 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 221 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Tension) |
|---|

| _Member Number: 222 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 223 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 224 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 225 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 226 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.226 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 227 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 228 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 229 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 230 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 231 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





|---|
| _Member Number: 232 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.113 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 233 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 234 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 235 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





|---|
| _Member Number: 236 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.025 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 237 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|

| _Member Number: 238 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 239 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 240 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 241 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 242 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 243 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 244 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 245 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 246 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 247 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 68

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 248 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 249 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 250 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 251 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 69

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 252 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 253 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 254 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|----------|

|----------|
| _Member Number: 255 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 70

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 256 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 257 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 260 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------|

|----------|
| _Member Number: 261 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------|

_ STAAD SPACE -- PAGE NO. 71

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 263 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------|

|----------|
| _Member Number: 265 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------|

|----------|
| _Member Number: 267 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------|

|---|
| _Member Number: 268 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 72

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 269 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 270 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 271 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 272 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 73

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 273 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 274 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 275 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 276 _ |

| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 74

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 277 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 278 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.016 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 279 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 280 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.051 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 75

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 281 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 282 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 283 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.051 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 284 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 76

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 285 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 286 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 287 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 288 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.036 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 77

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 289 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 290 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 291 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 292 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 78

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 293 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 294 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 295 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 296 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 79

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 297 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 298 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.036 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 299 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 300 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 80

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 301 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 302 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 303 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 304 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 81

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 305 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 306 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 307 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 308 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.036 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 82

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 309 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 310 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 311 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 312 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 83

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 313 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 314 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 315 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 316 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 84

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 317 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 318 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.016 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 319 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 320 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.051 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 85

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 321 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 322 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 323 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.051 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 324 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 86

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|

| _Member Number: 325 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 326 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 327 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 328 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 329 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 330 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 331 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 332 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 333 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 334 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 335 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 336 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 89

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 337 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 338 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 339 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 340 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 90

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 341 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---------------------------------------------------------------------------|

|---------------------------------------------------------------------------|
| _Member Number: 342 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---------------------------------------------------------------------------|

|---------------------------------------------------------------------------|
| _Member Number: 343 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---------------------------------------------------------------------------|

|---------------------------------------------------------------------------|
| _Member Number: 344 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---------------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 91

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---------------------------------------------------------------------------|
| _Member Number: 345 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---------------------------------------------------------------------------|

|---------------------------------------------------------------------------|
| _Member Number: 346 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---------------------------------------------------------------------------|

|---------------------------------------------------------------------------|
| _Member Number: 347 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---------------------------------------------------------------------------|

|---------------------------------------------------------------------------|
| _Member Number: 348 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---------------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 92

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---------------------------------------------------------------------------|
| _Member Number: 349 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---------------------------------------------------------------------------|

|---|
| _Member Number: 350 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 351 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 352 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





|---|
| _Member Number: 353 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 354 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 355 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 356 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





|---|
| _Member Number: 357 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 358 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 359 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 360 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 361 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 362 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 363 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 364 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 365 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 366 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Tension) |
|---|

| _Member Number: 367 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 368 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 369 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 370 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 371 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 372 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 373 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 374 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 375 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 376 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 377 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 378 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 379 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 380 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 381 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 382 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|

| _Member Number: 383 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 384 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 385 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 386 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 387 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 388 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 389 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 390 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 391 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 392 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 103

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 393 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 394 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 395 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 396 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 104

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 397 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 398 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 399 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|

|---|
| _Member Number: 400 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 105

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 401 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 402 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.043 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 403 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.045 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|---|

|---|
| _Member Number: 404 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 106

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 405 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 406 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 407 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|----------------------------------------------------------------------|
| _Member Number: 408 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 107

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 409 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 410 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 411 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 412 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 108

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 413 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.065 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 414 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 415 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 416 _ |

| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 109

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 417 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 418 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 419 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 420 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 110

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 421 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 422 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 423 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.065 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |

| _Member Number: 424 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 111

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 425 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 426 _ |
|---|
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 427 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 428 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 112

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 429 _ |
|---|
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 430 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 431 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 432 _ |
|---|
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 113

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 433 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.065 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|---|

|---|
| _Member Number: 434 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 435 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 436 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 114

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 437 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 438 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 439 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 440 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 115

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 441 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 442 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 443 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.045 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Sec. 8.2.1.2 |
|----------|

|----------|
| _Member Number: 444 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 116

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 445 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.050 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 446 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 447 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 448 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 117

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 449 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.033 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 450 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 451 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.114 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 452 _ |
| Member Section: ST 50X50X3.6SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.074 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 453 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 454 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 455 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 456 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 457 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 458 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 459 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 460 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 120

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 461 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 462 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 463 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 464 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 121

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|

| _Member Number: 465 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 466 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 467 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 468 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 469 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 470 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 471 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 472 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 473 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 474 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 475 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 476 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 124

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 477 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 478 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 479 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 480 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 125

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 481 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|

|---|
| _Member Number: 482 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 483 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 484 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 485 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 486 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 487 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 488 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 489 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|----------------------------------------------------------------------|
| _Member Number: 490 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 491 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 492 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 128

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 493 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 494 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 495 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 496 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 129

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**************************************************

_
|----------------------------------------------------------------------|
| _Member Number: 497 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 498 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 499 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 500 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|



_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 501 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 502 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 503 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 504 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|



_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 505 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 506 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Compression) |
|---|

| _Member Number: 507 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 508 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.282 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 509 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 510 _ |
|---|
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 511 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 512 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.127 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 513 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 514 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 515 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.329 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 516 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





_
|---|
| _Member Number: 517 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.148 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 523 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.75 |
| Critical Condition: Sec. 8.2.1.2 |

|---|
| _Member Number: 524 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.75 |
| Critical Condition: Sec. 8.2.1.2 |

|---|
| _Member Number: 525 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.75 |
| Critical Condition: Sec. 8.2.1.2 |





_
|---|
| _Member Number: 526 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.75 |
| Critical Condition: Sec. 8.2.1.2 |

|---|
| _Member Number: 527 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.088 Critical Load Case: 101 Location: 0.75 |
| Critical Condition: Sec. 8.2.1.2 |

|---|

| _Member Number: 533 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.101 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 535 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 537 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.113 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 539 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.056 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 541 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 542 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 543 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 544 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 545 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.219 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 546 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 138

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 547 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 548 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 549 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 550 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 139

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 551 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 552 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 553 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|

|---|
| _Member Number: 554 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 140

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 555 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 556 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 557 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 558 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 141

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 559 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 560 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 561 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 562 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 142

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 563 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 564 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 565 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 566 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 143

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 567 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 568 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 569 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 570 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

| _Member Number: 571 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 572 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 573 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 574 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

| _Member Number: 575 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 576 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 577 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 578 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 146

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 579 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 580 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 581 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 582 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 147

_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

| _Member Number: 583 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 584 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 585 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 586 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 148

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 587 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 588 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 589 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 590 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 149

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 591 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 592 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 593 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 594 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 150

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 595 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 596 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 597 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 598 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 151

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

|----------|
| _Member Number: 599 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 600 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 601 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 602 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 152

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 603 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 604 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 605 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 606 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

_ STAAD SPACE -- PAGE NO. 153

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 607 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 608 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 609 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 610 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 154

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 611 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 612 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 613 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 614 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 155

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|
| _Member Number: 615 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 616 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 617 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

|----------------------------------------------------------------------|
| _Member Number: 618 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------------------------------------------------------------------|

_ STAAD SPACE -- PAGE NO. 156

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------------------------------------------------------------------|

| _Member Number: 619 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 620 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 621 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 622 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 623 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 624 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 625 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 626 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 627 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 628 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 629 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 630 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 159

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 631 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 632 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 633 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 634 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 160

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 635 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|----------|

|----------|
| _Member Number: 636 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 637 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 638 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|----------|
| _Member Number: 639 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 640 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 641 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 642 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|----------|
| _Member Number: 643 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|---|
| _Member Number: 644 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 645 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 646 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 647 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 648 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 649 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 650 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 651 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.099 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 652 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 653 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.219 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 654 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 655 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 656 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 657 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 658 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |





| _Member Number: 659 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 660 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |

| Critical Condition: Slenderness (Compression) |
|---|

| _Member Number: 661 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 662 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 663 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 664 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 665 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 666 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |





| _Member Number: 667 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 668 _ |
|---|
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 669 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 670 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 671 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.277 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 672 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 673 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 674 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |



_

STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_

|---|
| _Member Number: 675 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 676 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.125 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|

| _Member Number: 677 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 678 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 171

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 679 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 680 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 681 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 682 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 172

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 683 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 684 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 685 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |

| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 686 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

_ STAAD SPACE -- PAGE NO. 173

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 687 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 688 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 689 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|---|

|---|
| _Member Number: 690 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

_ STAAD SPACE -- PAGE NO. 174

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 691 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 692 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|---|

|---|
| _Member Number: 693 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|----------|

|----------|
| _Member Number: 694 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

_ STAAD SPACE -- PAGE NO. 175

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 695 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.097 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |
|----------|

|----------|
| _Member Number: 696 _ |
| Member Section: ST 100X100X4.0SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.064 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 697 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.216 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 698 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

_ STAAD SPACE -- PAGE NO. 176

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|----------|
| _Member Number: 699 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 700 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|----------|
| _Member Number: 701 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |
|----------|

|---|
| _Member Number: 702 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.169 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 177

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 703 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 704 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 705 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

|---|
| _Member Number: 706 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.076 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 178

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
|---|
| _Member Number: 707 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 708 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 709 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

|---|
| _Member Number: 710 _ |

| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

_ STAAD SPACE -- PAGE NO. 179

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 711 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.274 Critical Load Case: 103 Location: 0.00 |
| Critical Condition: Slenderness (Compression) |

| _Member Number: 712 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 713 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 714 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

_ STAAD SPACE -- PAGE NO. 180

_
STAAD.PRO CODE CHECKING - IS-800-2007-LSD (V2.2)
**********

_
| _Member Number: 715 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

| _Member Number: 716 _ |
| Member Section: ST 40X40X3.2SHS (TATA STRUCTURA SECTIONS) |
| Status: PASS Ratio: 0.124 Critical Load Case: 101 Location: 0.00 |
| Critical Condition: Slenderness (Tension) |

353. FINISH

********** END OF THE STAAD.Pro RUN **********

**** DATE= JAN 8,2025 TIME= 11:51:23 ****

_ STAAD SPACE -- PAGE NO. 181

**********
* For technical assistance on STAAD.Pro, please visit *

```
*   http://www.bentley.com/en/support/                  *
*                                                       *
*   Details about additional assistance from            *
*   Bentley and Partners can be found at program menu   *
*   Help->Technical Support                             *
*                                                       *
*         Copyright (c) Bentley Systems, Inc.           *
*              http://www.bentley.com                   *
*********************************************************
```

# Annexure C

# Staad output for MID frame

PAGE NO. 1

```
*****************************************************
*                                                   *
*         STAAD.Pro 2023                            *
*         Version  23.00.03.25                      *
*         Proprietary Program of                    *
*         Bentley Systems, Inc.                     *
*         Date=    FEB 10, 2025                     *
*         Time=    11:34:24                         *
*                                                   *
*  Licensed to: only @::LAVteam::®                  *
*****************************************************
```

1. STAAD SPACE
INPUT FILE: D:\SALT\1873_TRANSFORMERS & RECTIFIERS LTD\STAAD\ASSEMBLY LINE\central frame.STD
2. START JOB INFORMATION
3. ENGINEER DATE 10-FEB-25
4. END JOB INFORMATION
5. INPUT WIDTH 79
6. UNIT METER KN
7. JOINT COORDINATES
8. 1 0 0 0; 2 0 0 12; 3 0 0 3.00001; 4 0 0 6.00001; 5 0 0 9.00002; 6 0 5.22001 0
9. 7 0 5.22001 12; 8 0 5.22001 3.00001; 9 0 5.22001 6.00001; 10 0 5.22001 9.00002
10. 11 0 3.80001 0; 12 0 3.80001 3.00001; 13 0 3.80001 6.00001
11. 14 0 3.80001 9.00002; 15 0 3.80001 12; 16 0 1.42 0; 17 0 1.42 3.00001
12. 18 0 1.42 6.00001; 19 0 1.42 9.00002; 20 0 1.42 12; 21 0 2.61001 0
13. 22 0 2.61001 3.00001; 23 0 2.61001 6.00001; 24 0 2.61001 9.00002
14. 25 0 2.61001 12
15. MEMBER INCIDENCES
16. 1 1 3; 2 3 4; 3 4 5; 4 5 2; 5 1 16; 6 2 20; 7 3 17; 8 4 18; 9 5 19; 10 6 8
17. 11 8 9; 12 9 10; 13 10 7; 14 11 6; 15 12 8; 16 11 12; 17 13 9; 18 12 13
18. 19 14 10; 20 13 14; 21 15 7; 22 14 15; 23 16 21; 24 17 22; 25 16 17; 26 18 23
19. 27 17 18; 28 19 24; 29 18 19; 30 20 25; 31 19 20; 32 21 11; 33 22 12; 34 23 13
20. 35 24 14; 36 25 15; 37 21 22; 38 22 23; 39 23 24; 40 24 25
21. DEFINE MATERIAL START
22. ISOTROPIC STEEL
23. E 1.99947E+08
24. POISSON 0.3
25. DENSITY 76.8191
26. ALPHA 6.5E-06
27. DAMP 0.03
28. G 7.7221E+07
29. TYPE STEEL
30. STRENGTH RY 1.5 RT 1.2
31. END DEFINE MATERIAL
32. MEMBER PROPERTY APLAPOLLOTUBES

```
  33. 1 TO 40 TABLE ST 80X80X5.0SHS
  34. CONSTANTS
  35. MATERIAL STEEL ALL
  36. SUPPORTS
  37. 1 TO 5 7 PINNED
  38. LOAD 1 LOADTYPE DEAD  TITLE DEAD LOAD
_   STAAD SPACE                                -- PAGE NO.    2

  39. MEMBER LOAD
  40. 1 TO 4 10 TO 13 16 18 20 22 25 27 29 31 37 TO 40 UNI GY -0.07
  41. SELFWEIGHT Y -1 LIST ALL
  42. LOAD 2 LOADTYPE NONE  TITLE OPERATING
  43. MEMBER LOAD
  44. 10 TO 13 UNI GY -2.5
  45. LOAD COMB 201 1.5DL+1.5 OPERATING
  46. 1 1.5 2 1.5
  47. PERFORM ANALYSIS
_

        P R O B L E M   S T A T I S T I C S
        -----------------------------------

    NUMBER OF JOINTS        25  NUMBER OF MEMBERS      40
    NUMBER OF PLATES         0  NUMBER OF SOLIDS       0
    NUMBER OF SURFACES       0  NUMBER OF SUPPORTS      6

        Using 64-bit analysis engine.

        SOLVER USED IS THE IN-CORE ADVANCED MATH SOLVER

  TOTAL     PRIMARY LOAD CASES =     2, TOTAL DEGREES OF FREEDOM =     132
  TOTAL LOAD COMBINATION  CASES =     1  SO FAR.
_

  48. LOAD LIST 201
  49. PARAMETER 1
  50. CODE AISC UNIFIED 2016
  51. FYLD 310000 ALL
  52. CHECK CODE ALL

_PARAMETER 1
_   STAAD SPACE                                -- PAGE NO.    3

_
                STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)
             *******************************************************

_
ALL UNITS ARE - KN   METE (UNLESS OTHERWISE Noted).
***NOTE : AISC 360-16 Design Statement for STAAD.Pro.


_
*** AXIS CONVENTION ***:
 ========================

_
The capacity results and intermediate results in the report follow the notations
and axes labels as defined in the AISC 360-16 code.
The analysis results are reported in STAAD.Pro axis convention and the AISC 360:16
design results are reported in AISC 360-16 code axis convention.

  AISC Spec.      STAAD.Pro      Description
 ------------    ------------    -------------
      X               Z         Axis typically parallel to the sections principal major axis.
      Y               Y         Axis typically parallel to the sections principal minor axis.
      Z               X         Longitudinal axis perpendicular to the cross section.

SECTION FORCES AXIS MAPPING: -
```

| AISC Spec. | STAAD.Pro | Description |
|---|---|---|
| Pz | FX | Axial force. |
| Vy | FY | Shear force along minor axis. |
| Vx | FZ | Shear force along major axis. |
| Tz | MX | Torsional moment. |
| My | MY | Bending moment about minor axis. |
| Mx | MZ | Bending moment about major axis. |

*** DESIGN MESSAGES ***:

1. Section classification reported is for the cross section and loadcase that produced the worst case design ratio for flexure/compression Capacity results.
2. Results for any Capacity/Check that is not relevant for a section/loadcase based on the code clause in AISC 360-16 will not be shown in the report.
3. Bending results are reported as being "about" the relevant axis (X/Y), while the results for shear are reported as being for shear forces "along" the axis. E.g : Mx indicates bending about the X axis, while Vx indicates shear along the X axis.

*** ABBREVIATIONS ***:

F-T-B = Flexural-Torsional Buckling
L-T-B = Lateral-Torsional Buckling
F-L-B = Flange Local Buckling
W-L-B = Web Local Buckling
L-L-B = Leg Local Buckling
C-F-Y = Compression Flange Yielding
T-F-Y = Tension Flange Yielding



STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)

ALL UNITS ARE - KN METE (UNLESS OTHERWISE Noted).

- Member : 1

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 1 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.021 | Loadcase: | 201 | | |
| Location: | 3.00 | Ref: | Cl.F7.1 | | | | |
| Pz: | 0.000 | T | Vy: | -.4346 | Vx: | -0.000 | |
| Tz: | -0.000 | | My: | -0.000 | Mx: | 0.2281 | |

- Member : 2

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 2 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.019 | Loadcase: | 201 | | |
| Location: | 0.00 | Ref: | Cl.F7.1 | | | | |
| Pz: | 0.000 | T | Vy: | 0.4083 | Vx: | 0.000 | |
| Tz: | 0.000 | | My: | 0.000 | Mx: | 0.2090 | |

- Member : 3

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 3 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.019 | Loadcase: | 201 | | |
| Location: | 3.00 | Ref: | Cl.F7.1 | | | | |
| Pz: | 0.000 | T | Vy: | -.4119 | Vx: | -0.000 | |
| Tz: | -0.000 | | My: | -0.000 | Mx: | 0.2143 | |

- Member : 4

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 4 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.020 | Loadcase: | 201 | | |
| Location: | 0.00 | Ref: | Cl.F7.1 | | | | |
| Pz: | 0.000 | T | Vy: | 0.4302 | Vx: | 0.000 | |

| Tz: 0.000 My: 0.000 Mx: 0.2220 |
|---|
_- Member : 5_
| Member No: 5 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.024 Loadcase: 201 |
| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 7.704 C Vy: 0.000 Vx: 0.1635 |
| Tz: 0.000 My: -.1415 Mx: 0.000 |
_- Member : 6_
| Member No: 6 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.015 Loadcase: 201 |
| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 1.062 C Vy: 0.000 Vx: -.1735 |
| Tz: 0.000 My: 0.1485 Mx: 0.000 |
_- Member : 7_
| Member No: 7 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.046 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 15.81 C Vy: 0.000 Vx: -.1657E-01 |
| Tz: 0.000 My: 0.1905E-01 Mx: 0.000 |


_
STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)
**********
_
ALL UNITS ARE - KN METE (UNLESS OTHERWISE Noted).
_- Member : 8_
| Member No: 8 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.044 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 15.27 C Vy: 0.000 Vx: -.6889E-02 |
| Tz: 0.000 My: 0.5263E-02 Mx: 0.000 |
_- Member : 9_
| Member No: 9 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.046 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 15.78 C Vy: 0.000 Vx: 0.1077E-02 |
| Tz: 0.000 My: -.7698E-02 Mx: 0.000 |
_- Member : 10_
| Member No: 10 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.311 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |
| Pz: 1.901 C Vy: -6.492 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 3.402 |
_- Member : 11_
| Member No: 11 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.287 Loadcase: 201 |
| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 1.662 C Vy: 6.094 Vx: 0.000 |
| Tz: 0.000 My: 0.000 Mx: 3.143 |
_- Member : 12_
| Member No: 12 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE\|SECTIONS) |
| Status: PASS Ratio: 0.287 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |

| Pz: 1.662 C Vy: -6.093 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 3.140 |
|---|
_- Member : 13_
|---|
| Member No: 13 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.310 Loadcase: 201 |
| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 1.886 C Vy: 6.482 Vx: 0.000 |
| Tz: 0.000 My: 0.000 Mx: 3.387 |
|---|
_- Member : 14_
|---|
| Member No: 14 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.190 Loadcase: 201 |
| Location: 1.42 Ref: Eq.H1-1b |
| Pz: 5.569 C Vy: -0.000 Vx: 1.901 |
| Tz: -0.000 My: 2.018 Mx: -0.000 |
|---|
_ STAAD SPACE -- PAGE NO. 6

_
STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)
**********
_
ALL UNITS ARE - KN METE (UNLESS OTHERWISE Noted).
_- Member : 15_
|---|
| Member No: 15 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.042 Loadcase: 201 |
| Location: 1.42 Ref: Eq.H1-1b |
| Pz: 12.59 C Vy: -0.000 Vx: -.2390 |
| Tz: -0.000 My: -.2598 Mx: -0.000 |
|---|
_- Member : 16_
|---|
| Member No: 16 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.037 Loadcase: 201 |
| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 2.162 T Vy: 0.4846 Vx: 0.000 |
| Tz: 0.000 My: 0.000 Mx: 0.3751 |
|---|
_- Member : 17_
|---|
| Member No: 17 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.035 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 12.17 C Vy: 0.000 Vx: -.3371E-03 |
| Tz: 0.000 My: 0.1425E-03 Mx: 0.000 |
|---|
_- Member : 18_
|---|
| Member No: 18 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.023 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |
| Pz: 1.807 T Vy: -.4272 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 0.2253 |
|---|
_- Member : 19_
|---|
| Member No: 19 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.040 Loadcase: 201 |
| Location: 1.42 Ref: Eq.H1-1b |
| Pz: 12.57 C Vy: -0.000 Vx: 0.2236 |
| Tz: -0.000 My: 0.2466 Mx: -0.000 |
|---|
_- Member : 20_
|---|
| Member No: 20 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.022 Loadcase: 201 |

| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 1.811 T Vy: 0.4256 Vx: 0.000 |
| Tz: 0.000 My: 0.000 Mx: 0.2225 |
|---|
_- Member : 21_
|---|
| Member No: 21 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.185 Loadcase: 201 |
| Location: 1.42 Ref: Eq.H1-1b |
| Pz: 1.102 T Vy: -0.000 Vx: -1.918 |
| Tz: -0.000 My: -2.033 Mx: -0.000 |
|---|


_
STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)
**********

_
ALL UNITS ARE - KN METE (UNLESS OTHERWISE Noted).
_- Member : 22_
|---|
| Member No: 22 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.038 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |
| Pz: 2.166 T Vy: -.4959 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 0.3923 |
|---|
_- Member : 23_
|---|
| Member No: 23 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.024 Loadcase: 201 |
| Location: 1.19 Ref: Eq.H1-1b |
| Pz: 6.873 C Vy: -0.000 Vx: 0.2173 |
| Tz: -0.000 My: 0.1597 Mx: -0.000 |
|---|
_- Member : 24_
|---|
| Member No: 24 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.041 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 14.76 C Vy: 0.000 Vx: -.3950E-01 |
| Tz: 0.000 My: 0.1203E-01 Mx: 0.000 |
|---|
_- Member : 25_
|---|
| Member No: 25 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.019 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |
| Pz: 0.5372E-01 T Vy: -.4128 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 0.2110 |
|---|
_- Member : 26_
|---|
| Member No: 26 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.039 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 14.22 C Vy: 0.000 Vx: -.4834E-02 |
| Tz: 0.000 My: 0.2507E-02 Mx: 0.000 |
|---|
_- Member : 27_
|---|
| Member No: 27 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)
| Status: PASS Ratio: 0.019 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |
| Pz: 0.3079E-01 T Vy: -.4106 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 0.2091 |
|---|
_- Member : 28_
|---|
| Member No: 28 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS)

| Status: PASS Ratio: 0.041 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 14.73 C Vy: 0.000 Vx: 0.2366E-01 |
| Tz: 0.000 My: -.3660E-02 Mx: 0.000 |

_ STAAD SPACE -- PAGE NO. 8

_
STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)
**********

_
ALL UNITS ARE - KN METE (UNLESS OTHERWISE Noted).
_- Member : 29_

| Member No: 29 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.018 Loadcase: 201 |
| Location: 0.00 Ref: Eq.H1-1b |
| Pz: 0.3285E-01 T Vy: 0.4060 Vx: 0.000 |
| Tz: 0.000 My: 0.000 Mx: 0.2021 |

_- Member : 30_

| Member No: 30 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.015 Loadcase: 201 |
| Location: 1.19 Ref: Eq.H1-1b |
| Pz: 0.2227 C Vy: -0.000 Vx: -.2289 |
| Tz: -0.000 My: -.1679 Mx: -0.000 |

_- Member : 31_

| Member No: 31 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.018 Loadcase: 201 |
| Location: 3.00 Ref: Eq.H1-1b |
| Pz: 0.5543E-01 T Vy: -.4070 Vx: -0.000 |
| Tz: -0.000 My: -0.000 Mx: 0.2024 |

_- Member : 32_

| Member No: 32 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.036 Loadcase: 201 |
| Location: 1.19 Ref: Eq.H1-1b |
| Pz: 6.289 C Vy: -0.000 Vx: -.2607 |
| Tz: -0.000 My: -.3067 Mx: -0.000 |

_- Member : 33_

| Member No: 33 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.038 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 13.73 C Vy: 0.000 Vx: 0.1160 |
| Tz: 0.000 My: -.3626E-01 Mx: 0.000 |

_- Member : 34_

| Member No: 34 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.037 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 13.22 C Vy: 0.000 Vx: -.3794E-02 |
| Tz: 0.000 My: 0.1806E-02 Mx: 0.000 |

_- Member : 35_

| Member No: 35 Profile: ST 80X80X5.0SHS (APL APOLLOTUBE|SECTIONS) |
| Status: PASS Ratio: 0.038 Loadcase: 201 |
| Location: 0.00 Ref: Cl.E3 |
| Pz: 13.71 C Vy: 0.000 Vx: -.1318 |
| Tz: 0.000 My: 0.4468E-01 Mx: 0.000 |

_ STAAD SPACE -- PAGE NO. 9

STAAD.PRO CODE CHECKING - AISC 360-16 LRFD (V1.2)
**********

ALL UNITS ARE - KN METE (UNLESS OTHERWISE Noted).

- Member : 36

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 36 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.027 | Loadcase: | 201 | | |
| Location: | 1.19 | Ref: | Eq.H1-1b | | | | |
| Pz: | 0.3712 | T | Vy: | -0.000 | Vx: | 0.2480 | |
| Tz: | -0.000 | My: | 0.2981 | Mx: | -0.000 | | |

- Member : 37

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 37 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.020 | Loadcase: | 201 | | |
| Location: | 3.00 | Ref: | Eq.H1-1b | | | | |
| Pz: | 0.4779 | C | Vy: | -.4241 | Vx: | -0.000 | |
| Tz: | -0.000 | My: | -0.000 | Mx: | 0.2112 | | |

- Member : 38

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 38 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.020 | Loadcase: | 201 | | |
| Location: | 0.00 | Ref: | Eq.H1-1b | | | | |
| Pz: | 0.3224 | C | Vy: | 0.4099 | Vx: | 0.000 | |
| Tz: | 0.000 | My: | 0.000 | Mx: | 0.2125 | | |

- Member : 39

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 39 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.020 | Loadcase: | 201 | | |
| Location: | 3.00 | Ref: | Eq.H1-1b | | | | |
| Pz: | 0.3214 | C | Vy: | -.4131 | Vx: | -0.000 | |
| Tz: | -0.000 | My: | -0.000 | Mx: | 0.2169 | | |

- Member : 40

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| Member No: | 40 | Profile: | ST 80X80X5.0SHS | | (APL APOLLOTUBE\|SECTIONS) | | |
| Status: | PASS | Ratio: | 0.019 | Loadcase: | 201 | | |
| Location: | 0.00 | Ref: | Eq.H1-1b | | | | |
| Pz: | 0.4769 | C | Vy: | 0.4143 | Vx: | 0.000 | |
| Tz: | 0.000 | My: | 0.000 | Mx: | 0.1967 | | |

53. FINISH

********** END OF THE STAAD.Pro RUN **********

**** DATE= FEB 10,2025 TIME= 11:34:26 ****

**********
* For technical assistance on STAAD.Pro, please visit *
* http://www.bentley.com/en/support/ *
* *
* Details about additional assistance from *
* Bentley and Partners can be found at program menu *
* Help->Technical Support *
* *
* Copyright (c) Bentley Systems, Inc. *
* http://www.bentley.com *
**********