A guide to preventative maintenance for Albany High Performance Doors

ASSA ABLOY

ASSA ABLOY Entrance Systems

The global leader in door opening solutions



Encoder/ Limit switch

What is the function?

- To monitor the door position

What is the manufacturer's specification?

To make sure the manufacturer's specifications are observed, replace every:

- MCC Encoder with magnetic rings: 10 years on electronic
- Digital limit switch (MCS): 3 years / 250.000 cycles

Can I also replace it earlier?

- Yes, if there is no exact positioning in the upper or lower position of the door

How do they wear?

During the lifetime of the encoder/limit switch there will be wear and tear due to:

- The aging of electrical components on the MCC encoder due to environmental effects
- Wearing of slip ring and slip ring contactor on the digital limit switch (MCS)
- Mechanical wear on the limit switch due to actuation and environmental effects

What is the risk of not replacing?

When not following the manufacturer's specifications the customer is taking the responsibility for unintended breakdown, e.g.:

- The door may override the end positions, and can lead to the mechanical damage of the door
- The door may stop

Top reasons for preventive maintenance

- Keeps the warranty valid
- Prevents unexpected and expensive break-downs
- Prolongs lifetime
- Cost saving
- Minimises risk of personal injury
- Minimises energy loss
- Fulfills legal requirements
- Improves working environment

©ASSA ABLOY Entrance Systems AB/PL.MAP/DEU-EN-1.0/1504

Maintenance & Modernization